

Surveyor:

REF: CS3/msh17017371/Grb²-1

Special Instruction:

Melimen

ASSIGNMENT (Office)

US: \$ 9150.00

From (Person): Lionel Tan of msh Date/Time: 16-03-2018

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: Automax Survey

Workshop: Eng Soon

OD (TP Re-inspection) / Evaluation

To Inspect Vehicle No: SKW 4434D

Insured: FBB 9801L

at Workshop m/s Eng Soon

Tel: 6760 6271

of Bk 4 Tew Tee Ind Est 393-J

Policy No: Claim No: MSC/V/17-001380

Sum Insured: Excess:

Make of Veh: D.O.A. 05092017

(Client's Record)

23-03-2018 (Friday) @ 9.30am

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 5 days)

Date/Time: 12/4/18 Submit Final Fig 1150, 3 days (Red \$ 8000 / 87%; Original 5 days)

Date/Time	Action/Instruction
	SKW 4434D - CS3 / msh17017371 / (Bbed)
	FBB 9801L - X
	Submit TP - Reinspection report
	MV: \$ 76K, LTA: \$ 52,824.00, NV: \$ 23176.00
	RECEIVED 12 APR 2018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Date:

Basic & Add
Transport
Photos
Others
Total

1) Date/Time 12/4/18 File Pass to tjks

2) Date/Time File Return to

3) Date/Time File Pass to

4) Date/Time File Return to

5) Date/Time File Pass to

6) Date/Time File Return to

REF:

SWAN

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$76K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKW 4434D

Yr Regn:

29 Oct 2015

Type: ☒ M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

C.C.

1496

Colour:

Silver

A/C

Insured / Std / NI / NA

Sp Reading:

49751

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6BM 42A 86 03/9043

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / S/D A/Rim or

Tyre Size:

F:

205/60R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6/6

mm

R/Bal.

6

mm

L/Bal.

6/6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

23-03-18

Survey held at

IDAC ubi 9:30am

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Report Format:

Lump Sum / I.B.I. (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) \$+RS \$

) Photos:

) Others:

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG17017371/rb-1

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 22-03-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	FBB 9801L	Veh. Inspected	SKW 4434D
Policy No.		Coverage (\$)	0.00
Claim No.	MSC/V/17-001380	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	16/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/09/2017	Inspection Date	23/03/2018
Survey held at	ENG SOON PAINTING SVC BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: Lionel Tan <lionel_tan@sg.msig-asia.com>
Sent: Friday, 16 March, 2018 3:27 PM
To: 'Catherine Chong (LKK Auto)'
Cc: SUR; 'assignments'; 'bonnie kwok'
Subject: FW: Our Ref: BK/18383.18, Yr Ref: MSC/V/17-001380, Acc Inv: SKW 4434 D & FBB 9801 L ON 5 SEPTEMBER 2017,

Dear Catherine,

Please attend to the re-inspection notice.

Kindly acknowledge. Thank you.

Regards

Lionel Tan

From: bonnie kwok [mailto:litigation@bonniekwok.com]
Sent: Friday, 16 March, 2018 2:29 PM
To: Lionel Tan <lionel_tan@sg.msig-asia.com>
Subject: Our Ref: BK/18383.18, Yr Ref: MSC/V/17-001380, Acc Inv: SKW 4434 D & FBB 9801 L ON 5 SEPTEMBER 2017,

Dear Lionel,

We refer to your letter dated 12 February 2018.

Kindly have your surveyor attend at Block 4 Yew Tee Ind Est 393-J Woodlands Road Singapore 677978 on 23 March 2018 at 9.30 a.m. for the re-survey of our client's vehicle.

Kindly ensure that your surveyor attends punctually.

Kindly let us know which surveyor you have appointed so that we may inform our client accordingly.

Please let us have your offer of settlement as soon as possible.

Regards,
June

BONNIE KWOK LLC
Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

You are returning to a previous page. This page may be outdated.
Please click 'Refresh' to refresh the page.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Reinspection

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Sep 2017		07 Sep 2017 15:53 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	RAJENDRAN PRAKASH, ID: G5358476X, Tel: +6590158450		
Main Claimant:	PHOON TUCK MEI, ID: S7587715C		
Vehicle Reg. No.:	SKW4434D	Date of Loss:	05/09/2017 11:00 - :59
Claim Type:	TP / MSC/V/17-001380	Policy/Cover Note No.:	72019770 (Third Party Only) Coverage: 15/08/2017 - 14/08/2018
Vehicle Reg. No. (Insured):	FBB9801L	Policy No. (Claimant):	
		Excess:	
Repairer:	Eng Soon Painting Services (HQ) 393J WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/03/2018]		
Driver/Custodian (Insured):	RAJENDRAN PRAKASH (29 / Male), NRIC: G5358476X, Tel: +6590158450		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

- MSIG_SG (16/03/2018): Report Send Back Alerts - SKW4434D (TP)



ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/09/2017 16:25
Date Of Accident	05/09/2017 11:55
Exact Location Of Accident	PIE TOWARD LORNIE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW4434D
Insured/Policyholder	
Name Of Registered Owner	PHOON TUCK MEI
NRIC No	S7587715C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98556879
Alternative Phone No	OTHERS-98556879

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100435919
Cover Note Number	

Driver

Name of Driver	FONG KOK HENG
NRIC No	S7218037B
Date Of Birth	31/05/1972
Occupation	OUTDOOR
Date Of Driving Pass	16/03/1994
Driving Experience	23 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98556879
Fax Number	
Contact Number	OTHERS-98556879
Email Address	NOEMAIL

Address	BLK 110 BEDOK RESERVOIR ROAD #07-280
Postcode	470110
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN & STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBB9801L
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	RAJENDRAN PRAKASH
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



A = SKW 44340

B = FRB 9801L

Describe Circumstances of the Accident

On 5/9/2017 at 11.55 am, I was travelling P&E
 towards Lamine Road. In front of our vehicles
 there was an accident. My car came to a
 halt and suddenly a motorcycle hit my left
 side portion.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
 Time

Driver's Signature (If driver is not the policyholder) / Date
 & Time

Witnessed by Reporting Centre
 Personnel

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road, #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Billing To: Phoon Tuck Mei
c/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

Invoice no.: TP17090016

Date: 23 JAN 2018

Vehicle no: SKW 4434 D

Model : MAZDA3 4-DOOR SEDAN 1.5L

ITEM	DESCRIPTION	AMOUNT
1	Date of Inspection : 08 September 2017 Copies of the inspection / survey report Correspondence, postages and etc.	\$ 690.00
2	Photography Services Develop photographs Storage of digital photographs	
3	To submit report by hand.	
4	Charges on photocopies, posting, faxes and others incidental works entrusted.	
5	Transportation Charges	
6	Reinspection Charges	
TOTAL :		\$ 690.00

Notes :



All cheque payment should be "crossed" and made payable to "Automax Survey".
Please contact us if there are further enquiries on the invoice.

Official Stamp

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Report Ref : TP17090016

Date: 23 JAN 2018

*Phoon Tuck Mei
c/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969*

THIRD PARTY SURVEY
ACCIDENT OCCURED ON 05 September 2017

Workshop Name and Address

Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

As per your instruction dated 08 September 2017 with regard to the above matter.
We have carried out a physical inspection on the said SKW 4434 D
We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SKW 4434 D
Model : MAZDA3 4-DOOR SEDAN 1.5L
Year / Capacity : 2015 / 1496 cc
Chassis No : JM6BM42A8G0319043

Engine No : P520318431
Mileage : N.A km
Colour : Metallic silver

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	205/55/R16	Bridgestone	9.00 mm	Sport
REAR O/S :	205/55/R16	Bridgestone	9.00 mm	Sport
FRONT N/S :	205/55/R16	Bridgestone	9.00 mm	Sport
REAR N/S :	205/55/R16	Bridgestone	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the side portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 05 working days to complete
5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SKW 4434 D

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
<u>List Items</u>				
1 pc	Rear fender - LH	bend/distorted	\$ 941.85	\$ X 941.85 repair
1 pc	Rear door assy - LH	dent/distorted	\$ 1,174.45	\$ X 1,174.45 repair
1 pc	Rear door protector	deformed	\$ 132.10	\$ X 132.10
1 pc	Rear door quarter glass moulding	wrapped/deformed	\$ 174.45	\$ X 174.45
1 pc	Rear door inner trim board	bend/deformed	\$ 588.10	\$ X 588.10
cs	Rear door inner trim board clips	necessary	\$ 103.20	\$ X 103.20
1 pc	Rear door weatherstrip	wrapped/deformed	\$ 182.40	\$ X 182.40
1 pc	Front door assy - LH	dent/distorted	\$ 1,072.85	\$ X 1,072.85 repair
1 pc	Front door weatherstrip	wrapped/deformed	\$ 182.10	\$ X 182.10
1 pc	Front door outer handle	bent/distorted	\$ 174.10	\$ X 174.10
1 pc	Side mirror - LH	grazed/distorted	\$ 987.70	\$ X 987.70
1 pc	Side mirror cover	grazed/distorted	\$ 121.10	\$ X 121.10
1 pc	Front fender	bend/distorted	\$ 591.60	\$ X 591.60 repair
Parts Sub-Total			\$ 6,426.00	\$ 6,426.00
Discount 20.00%			\$ 1,285.20	\$ 1,285.20
			\$ 5,140.80	\$ 5,140.80

Vehicle Number : SKW 4434 D

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
<u>Special Nett Items</u>				
1 pc	Rear windscreen glass sealant	necessary	\$ 60.00	\$ 60.00
1 pc	Rear door window glass solar film (ACC)	necessary	\$ 120.00	\$ 120.00
1 pc	Front windscreen glass sealant	wrapped/deformed	\$ 60.00	\$ 60.00
1 pc	Front rim assy (Sport)	bent/distorted	\$ 600.00	\$ 600.00
1 pc	Front tyre	grazed/deformed	\$ 320.00	\$ 300.00
1 pc	Front fog lamp cover	grazed/deformed	\$ 250.00	\$ 250.00
1 pc	Front fender spoiler	necessary	\$ 83.50	\$ 83.50
Special Nett Sub-Total			\$ 1,493.50	\$ 1,473.50
Spare Parts Total			\$ 6,634.30	\$ 6,614.30

83.5

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
------	------------------	---------------------------	------------------------------

Spare Parts Total c/f \$ 6,634.30 \$ 6,614.30

1	Towing fees	\$ 120.00	\$ 120.00 X
2	To tuff coat affected areas	\$ 180.00	\$ 150.00 X
(To remove replace interior upholstery	\$ 180.00	\$ 150.00 X
4	To check & adjust computer wheel alignment . (Before & After)	\$ 150.00	\$ 120.00 X
5	To respray affected areas	\$ 1,400.00	\$ 1,200.00 ✓
6	To remove & rerox front & rear windscreen glass to assist repair	\$ 150.00	\$ 120.00 X NN
7	To renew damaged parts, straighten and repair door pillar rear fender inner panel and aligned all parts	\$ 1,600.00	\$ 1,400.00 200
8	To supply & install solar flim on doors	\$ 300.00	\$ 280.00 X NN

Total \$ 10,714.30 \$ 10,154.30

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 9,150.00

Fong Kok Heng
Qualified Appraiser



1483.5

20% : 1150.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7715C
Vehicle Details	
Vehicle No.:	SKW4434D
Vehicle to be Exported:	No
Intended De-registration Date:	11 Apr 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	P520318431
Chassis No.:	JM6BM42A8G0319043
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$17,996.00
Original Registration Date:	29 Oct 2015
First Registration Date:	29 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$12,996.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Oct 2025
PARF Rebate Amount:	\$9,747.00
Intended COE Rebate Details	
COE Expiry Date:	28 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,089.00
COE Rebate Amount:	\$43,077.00
Total Rebate Amount:	\$52,824.00

The information contained herein is correct as at 11 Apr 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

Reinspection

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Sep 2017		07 Sep 2017 15:53 Edit Adj Rpt	S\$1,150.00 Edit Estimates	S\$1,150.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

RAJENDRAN PRAKASH, ID: G5358476X, Tel: +6590158450

Main Claimant:

PHOON TUCK MEI, ID: S7587715C

Vehicle Reg. No.:

SKW4434D

Claim Type:

TP / MSC/V/17-001380

Vehicle Reg. No. (Insured):

FBB9801L

Repairer:

Eng Soon Painting Services (HQ) 3933 WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/03/2018]

Driver/Custodian (Insured):

RAJENDRAN PRAKASH (29 / Male), NRIC: G5358476X, Tel: +6590158450

Date of Loss:

05/09/2017 11:00 - :59
[22 Months and 7 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

72019770 (Third Party Only)
Coverage: 15/08/2017 - 14/08/2018

Policy No. (Claimant):

Excess:

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- MSIG_SG (16/03/2018): Report Send Back Alerts - SKW4434D (TP)

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)



















































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									















Claim Documents

***SKW4434D (MSC/V/17-001380)**
[FBB9801L]

TP
PHOON TUCK MEI
Sep 5 2017 11:00AM
[RAJENDRAN PRAKASH]
Eng Soon Painting Services

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print	
1	06/09/17 16:06	Accident Statement From: SC - Reg. No: FBB9801L, Claimant: RAJENDRAN PRAKASH				1	Load HTM		
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
2	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
3	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
4	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
5	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
6	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
7	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
8	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
9	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
10	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
11	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
12	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
13	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
14	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
15	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
16	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
17	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
18	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
19	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
20	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
21	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
22	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
23	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
24	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
25	13/10/17 14:22	General View				1	Load JPG	<input checked="" type="checkbox"/>	
26	13/10/17 14:22	Chassis Number				1	Load JPG	<input checked="" type="checkbox"/>	
27	13/10/17 14:22	Odometer Reading				1	Load JPG	<input checked="" type="checkbox"/>	
28	13/10/17 14:22	Photographs of Damaged Parts				1	Load JPG	<input checked="" type="checkbox"/>	
29	13/10/17 14:22	Photographs of Damaged Parts				1	Load JPG	<input checked="" type="checkbox"/>	
30	13/10/17 14:22	Photographs of Damaged Parts				1	Load JPG	<input checked="" type="checkbox"/>	
31	13/10/17 14:22	Photographs of Damaged Parts				1	Load JPG	<input checked="" type="checkbox"/>	
32	13/10/17 14:22	Photographs of Damaged Parts				1	Load JPG	<input checked="" type="checkbox"/>	
33	13/10/17 14:22	Photographs of Damaged Parts				1	Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	13/10/17 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	13/10/17 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	13/10/17 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	13/10/17 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	13/10/17 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	13/10/17 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	13/10/17 14:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	11/04/18 18:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/09/17 16:06	TPD SKW4434D GIA REPORT <small>From: SC - Reg. No: FBB9801L, Claimant: RAJENDRAN PRAKASH</small>	 Load PDF	
2	06/09/17 16:11	Pre-Repair Survey	 Load PDF	
3	13/02/18 13:32	TPD SKW4434D - REPAIR TAX INVOICE	 Load PDF	
4	13/02/18 13:32	TPD SKW4434D - SURVEY REPORT & TAX INVOICE	 Load PDF	
5	13/02/18 13:32	TPD SKW4434D - COLOUR PHOTO	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/04/18 15:52	PRS Invoice	 Load PDF	
2	12/04/18 15:53	PHOTO	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17017371/GRBE2-1
Date: 12/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 72019770
 Claimant Vehicle No: SKW4434D Insured Vehicle No: FBB9801L
 Date of Loss: 05/09/2017 Nature of Claim: TP Claim No: MSC/V/17-001380

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW4434D Engine No: P520318431
 Make & Model: MAZDA 3, 1.5 4 DOOR SEDAN SP (A) Chassis No: JM6BM42A8G0319043
 Reg. Date: 29/10/2015 (Man. Year: 2015) Odometer: 49751 km
 Colour: Silver
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,634.30	83.50	6,550.80	98.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,080.00	1,400.00	2,680.00	65.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,714.30	1,483.50	9,230.80	86.15
Approved Total (Overridden) (S\$)		1,150.00		
Nett Amount (S\$)	10,714.30	1,150.00	9,564.30	89.27

INSPECTION

Date of Assignment: 07/09/2017
 Date Inspected: 23/03/2018 Inspected At: Eng Soon Painting Services (HQ)
 BLK 4 YEW TEE IND EST 393 - J
 WOODLANDS ROAD
 SINGAPORE 677969

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$76,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$52,824.00=NETT VALUE: \$23,176.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Apr 2018)
Parts:	143	MAZDA 3 1.5 4 DOOR SEDAN SP (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW4434D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER - LH	Repaired	941.85 FL	*- F
2	1		*REAR DOOR ASSY - LH	Repaired	1,174.45 FL	*- F
3	1		*REAR DOOR PROTECTOR	Not Necessary	132.10 FL	*- F
4	1		*REAR DOOR QUARTER GLASS MOULDING	Not Necessary	174.45 FL	*- F
5	1		*REAR DOOR INNER TRIM BOARD	Not Necessary	588.10 FL	*- F
6	1		*REAR DOOR INNER TRIM BOARD CLIPS	Not Necessary	103.20 FL	*- F
7	1		*REAR DOOR WEATHERSTRIP	Not Necessary	182.40 FL	*- F
8	1		*FRONT DOOR ASSY - LH	Repaired	1,072.85 FL	*- F
9	1		*FRONT DOOR WEATHERSTRIP	Not Necessary	182.10 FL	*- F
10	1		*FRONT DOOR OUTER HANDLE	Not Necessary	174.10 FL	*- F
11	1		*SIDE MIRROR - LH	Not Necessary	987.70 FL	*- F
12	1		*SIDE MIRROR COVER	Repaired	121.10 FL	*- F
13	1		*FRONT FENDER	Repaired	591.60 FL	*- F
14	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	60.00 FS	*- FS
15	1		*REAR DOOR WINDOW GLASS SOLAR FILM (ACC)	Not Necessary	120.00 FS	*- FS
16	1		*FRONT WINDSCREEN GLASS SEALANT	Not Necessary	60.00 FS	*- FS
17	1		*FRONT RIM ASSY (SPORT)	Not Necessary	600.00 FS	*- FS
18	1		*FRONT TYRE	Not Necessary	320.00 FS	*- FS
19	1		*FRONT FOG LAMP COVER	Not Changed	250.00 FS	*- FS
20	1		*FRONT FENDER SPOILER	Necessary	83.50 FS	*83.50 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,919.50	83.50
- List Item Discount on L Items 20.00/0.00% (\$\$)	1,285.20	0.00
Total Parts (\$\$)	6,634.30	83.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEES	New	120.00	0.00
2	TO TUFF COAT AFFECTED AREAS	New	180.00	0.00
3	TO REMOVE REPLACE INTERIOR UPHOLSTERY	New	180.00	0.00
4	TO CHECK & ADJUST COMPUTER WHEEL ALIGNMENT (BEFORE & AFTER)	New	150.00	0.00
5	TO RESPRAY AFFECTED AREAS	New	1,400.00	1,200.00
6	TO REMOVE & RERIX FRONT & REAR WINDSCREEN GLASS TO ASSIST REPAIR	New	150.00	0.00
7	TO RENEW DAMAGED PARTS, STRAIGHTEN AND REPAIR DOOR PILLAR REAR FENDER INNER PANEL AND ALIGNED ALL PARTS	New	1,600.00	200.00
8	TO SUPPLY & INSTALL SOLAR FILM ON DOORS	New	300.00	0.00
Gross Labour Cost (S\$)			4,080.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >