

21/03/2018

ASS. REC. BY:

REF:

CS/MSG18005378/Gvd3/4

Special Instruction:

Surveyor

Merimen

Froth (Person):

Lionel Tan

ASSIGNMENT (Office)

of

MSIG

Date/Time:

22/8/2018 @ 8.43am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No:

SLJ 7089D

Insured:

SKR 5271B

at Workshop m/s

Motor Image

Tel:

92992693 / 90903323

of

25 Leng Kee Rd

9073 2232 Jeff

Policy No:

28672148 QMY

Claim No:

552214

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/03/2018

CA / REV / REP. / REV 24 HRS

wop

26/03/2018 : Insp: 19 towing 8 for payoh

H.O.D. Endorsement:

Date/Time:

10.35am @ 22/3/18

Person Contacted:

Kuan

Vehicle IN ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLJ 7089D - X
	SKR 5271B - CS/MSG18002867/U/d3
	D.O.A: 8/2/2018
31/3/18	Send preli revised by merimen
19/6/18	Recd email from Jeff Teh vehicle convert to OD claim
19/6/18	Submit DR01: report

Signature
Merimen

Xke.

REF: msh

ASSIGNMENT

From: Date: 26032018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLJ 7089D
at Workshop n/s Motor Image
of 25 Leng Kee Rd

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: Jeff

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLJ 7089D Yr Regn: 22 Dec 2016

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Subaru Forester c.c 1995

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 34209 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JF1SJ5KC50G081910

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size: F: 225/60 R17
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. D.O.I. 26-03-18

Survey held at W/S 2030pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 20 JUN 2018

Date/Time, File Pass to?

☒ Preli. Report
☐ Final Report

Days Of Repair: 5

Resurvey No. of Trip: -

Survey Fee:

Transportation

S + RE \$

Photos

Others

TOTAL

1) Date/Time, File Return to?

2) 19/6 - typist

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech Invs (\$

☐ Weekend (\$

Report Format: Merimen

Lump Sum / I.B.t. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18005378/Gvd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 22-03-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKR 5271B	Veh. Inspected	SLJ 7089D
Policy No.	28672148QMY	Coverage (\$)	0.00
Claim No.	552214	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	22/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/03/2018	Inspection Date
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 . SINGAPORE 319255	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

1. SGT 8059R-DOA: 7/5/2018 (FCIL TP)
2. SCF 3278D-DOA:25/5/2018 (AIG OD)
3. SJF 4939R-DOA: 27/5/20218 (AIG OD)
4. SLJ 7089D-DOA: 10/3/2018 (MSIG TP) (REF :INS/IC/LHI/014/2018)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Friday, 4 May 2018 2:59 PM

To: 'Sayedinah' <sayedinah@motorimage.net>; Daniel Lim <daniellim@motorimage.net>

Cc: David Koh <davidkoh@motorimage.net>; 'dennisleong@motorimage.net' <dennisleong@motorimage.net>; 'maggiewong@motorimage.net' <maggiewong@motorimage.net>; 'siewchan@motorimage.net' <siewchan@motorimage.net>

Subject: RE: PENDING FOR FINALIZE

Dear Sayed,

Check already ?

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sayedinah [mailto:sayedinah@motorimage.net]

Sent: Wednesday, 25 April 2018 3:48 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Daniel Lim <daniellim@motorimage.net>

Cc: Sayedinah <sayedinah@motorimage.net>; David Koh <davidkoh@motorimage.net>

Subject: Re: PENDING FOR FINALIZE

Hi Veron,

Will revert tomorrow ya.

Regards

Sent from my Samsung Galaxy smartphone.

----- Original message -----

From: "Veron Chen (LKKAuto)" <veronchen@lkkauto.com>

Date: 25/04/2018 15:35 (GMT+08:00)

To: Daniel Lim <daniellim@motorimage.net>

Cc: Sayedinah <sayedinah@motorimage.net>, David Koh <davidkoh@motorimage.net>

Subject: PENDING FOR FINALIZE

Dear Daniel,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

1. SFL 9959R-DOA: 3/12/2017 (MSIG OD)
2. SKS 5045H-DOA: 17/1/2018 (MSIG OD)
3. SLS 9489Y-DOA: 19/12/2017 (ERGO TP)
4. SLT 2968Y-DOA: 25/1/2018 (FCIL TP)
5. SLJ 7089D-DOA: 10/3/2018 (MSIG TP)
6. SFX 4848Y-DOA: 5/3/2018 (CHINA TAIPING TP)


Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Lionel Tan Tian Pei	Date: 31 Mar 2018
<u>Preliminary Advice</u>	

Insured Vehicle No	: SKR5271B	Accident Date	: 10/03/2018
TP Vehicle No	: SLJ7089D	Assignment Date	: 22/03/2018
Make	: SUBARU FORESTER	Est. Duration of Repair	: 5.00
Date of Inspection	: 26/03/2018		
Inspection At	: MOTORIMAGE ENTERPRISE PTE LTD (HQ) 25 LENG KEE ROAD SINGAPORE 159097		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,184.32
Revised Amount	:S\$	5,794.20
Check Items (Estimated)	:S\$	69.12
Total	:S\$	5,863.32
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

☐	The vehicle is economical/not economical for repair.
☒	The above survey was conducted on a 'without prejudice' basis.

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SLJ7089D
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover
Vehicle Attachment 1 :	With Sun Roof
Vehicle Scheme :	Normal
Vehicle Make :	SUBARU
Vehicle Model :	FORESTER 2.0I-L CVT AWD SR
Chassis No. :	JF1SJ5KC5GG081910
Propellant :	Petrol
Engine No. :	FB20Y508237
Engine Capacity :	1995 cc
Maximum Power Output :	110.0 kW (147 bhp)
Maximum Laden Weight :	2015 kg
Unladen Weight :	1566 kg
Year Of Manufacture :	2016
Original Registration Date :	22 Dec 2016
Lifespan Expiry Date :	-
COE Category :	B - Car above 1600cc or 97kW (130bhp)
Quota Premium :	\$56,206.00
COE Expiry Date :	21 Dec 2026
Road Tax Expiry Date :	21 Jun 2018
PARF Eligibility Expiry Date :	21 Dec 2026
Inspection Due Date :	21 Dec 2019
Intended Transfer Date :	29 Mar 2018
CO2 Emission :	182.00 (g/km)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/03/2018 12:10
Date Of Accident	10/03/2018 14:45
Exact Location Of Accident	THOMSON ROAD AFTER ANDREW ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ7089D
Insured/Policyholder	
Name Of Registered Owner	KOK HOCK HENG
NRIC No	S1565680H
Email Address	KOH96469149@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96469149
Alternative Phone No	OTHERS-96469149

Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 I-L (SJ) (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100494652-01
Cover Note Number	

Driver

Name of Driver	LOK LAI LING
NRIC No	S1621410H
Date Of Birth	15/09/1963
Occupation	INDOOR
Date Of Driving Pass	25/04/2000
Driving Experience	17 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-94797400
Fax Number	
Contact Number	OTHERS-94797400
Email Address	KOH96469149@GMAIL.COM

Address	APT BLK 524 BUKIT BATOK STEERT 52 #06-753
Postcode	650524
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHOO AH MOI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer Sketch Plan

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

Singapore Accident Statement

Accident Date & Time: 10 March 2018 14:54hrs 2:45pm	
Accident Location: Thomson Road after Androm Road	
Vehicle Number: SLJ 7089 D	Make/Model: Forester 2.0 1L
Policyholder Name: Koh Hock Heng	
NRIC: S156568014	Mobile: 96469145
Email: Koh.96469145@gmail.com	
Insurance Company: AIG	
Policy Number: 2100454652-01	Cover Note:
Policy Coverage: Comprehensive(✓) Third Party() Third Party Fire & Theft()	
State Action Taken: Claim Own Policy() Claim Third Party(✓) Reporting Only()	
Driver Name: Lok Lai Lim	
NRIC: S16214104	Mobile: 9479 7400
Date Of Birth: 15/05/1963	Driving Pass Date: 25 Apr 2000
Gender: Male() Female(✓)	Occupation: Indoor() Outdoor() Home Worker
Address: Blk 524 Bukit Batok St 53 #06-753 S' 650524	
Is driver an employee of the Insured's Company: Yes() No(✓)	
If No, Relationship of the Driver with the Insured:	
Owner() Spouse(✓) Friend() Relative() Children() Sibling()	
Weather Conditions: Clear(✓) Raining() Others()	
Road Surface: Dry(✓) Wet() Others()	
Was any foreign vehicle involved in this accident? Yes() No(✓)	
Was any body injured in the Accident? Yes() No(✓)	
Was there any video captured by Car Camera? Yes(✓) No()	
Number of Passengers (Including Driver): Two	
Was the accident reported to the police? Yes() No(✓) Attach Police Report, if any	
3 rd Party Name: Ng Yen Hui, ELINOR	
Vehicle Number: SKR 5271 B	Make & Model: Qashgari
NRIC: S802727061	Mobile: 94761559
Witness Details (if any):	
Other Details (if any):	
Passenger 1: Choo AH Moi	
Gender: Female	

Sketch Plan Pg. 2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating this accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature] 12/03/17
Policyholder's Signature / Date & Time

[Signature] 12/3/17
Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]
Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident:

Describe Circumstances of the Accident:

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

今天是星期六 (10 March 2018), 我准备到 Thomson Road, Far Florist Pte Ltd, 买花。

我从 PIE 转到 Thomson Road 行驶在道路的中间线上, 这是我的习惯开车方式不驶入 bus lane. Thomson Road 是我非常熟悉的一条道路, 也知道它的一般交通状况, 行驶时速在于 60KM/hr. 到这一带买花也已有十多年的时间了。

当我行驶在 Thomson Road 的中间线, 一直到 Andrew Road 之前, 我就亮着左边的讯号灯, 准备靠左, 在此同时也查看左边的后视镜, 确保这条左车道是空无一车才驶入的。在当时有察觉到, 我未靠左之前有一辆车子在中间线紧跟随我的车很近。

当我靠左的当下, 左边车道是确定没有车行驶的, 当我靠左不到一两秒就与后来的车产生碰撞, 车祸就这样发生了。(时间是: 2.45pm 左右)


过后当我查看车内的 Record Video 才知道后面的来车是突然用左车道超车, (她说她在赶时间) 而且完全没有亮起讯号灯, 她的这种举措是我始料不及的 (有 Record Video 为证据并以呈上

以上是我所知道和看到的陈述。

LOK LAI LING I/C NO 'S1621410 H
driver's signature:
12/03/18.

Policyholder's signature =
12/03/2018

Witness's Signature:
12-03-2018



* 25 ft in riding surface at

1450 ft

1440 ft

Far East Flora

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/LHI/014/2018
DATE : 20-MAR-2018

MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
#24-01 HONG LEOH BUILDING
S(048581)
TEL : 66431335/6827 7880
FAX : 66431349/6827 7809
7313 DAVID

OWNER'S NAME : KOH HOCK HENG
ADDRESS : APT BLK 524 BUKIT BATOK STREET 52
#06-753
S(650524)
TELEPHONE NO : 9646 9149

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100494652-01
VEHICLE NO : SLJ7089D
MODEL CODE : SJ5DK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20Y508237
CHASSIS NO : JF1SJ5KC5GG08191D
MILEAGE : 1 KM
DATE IN : 20/03/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : JEFF TEH TENG CHUEN
ACCIDENT DATE : 20/03/2018

Print Date : 20/03/2018
Print Time : 20:08:22

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLJ7089D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	1W0001W	TO CONDUCT 4-WHEEL ALIGNMENT	250.00	185
2	ZZ/001	TO SUPPLY AND REPLACE FRONT BUMPER AND FRONT LHS FENDER	1680.00	1120
3	ZZ/002	TO SPRAY FRONT BUMPER ASSY AND FRONT LHS FENDER	1260.00	880
4	ZZ/003	TO CONDUCT FRONT LIGHTING TEST	60.00	40
5	ZZ/004	TO TRANSFER AND BALANCE FRONT LHS TYRE & RIM	70.00	50.
6	ZZ/005	SUNDRIES <i>per</i>	80.00	20.
TOTAL LABOUR CHARGES			3400.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLJ70890

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT
1	DISC WHEEL AL 17 / <i>Cut</i>	28111SG130	900.00		
2	FRT FENDER LH <i>Repair x</i> (W/O SIGNAL LP)	57120SG0309P	270.00		
3	BUMPER FACE F NA / <i>Cut</i>	57709SG030	594.00		
4	MUD GUARD ASSY F LH ? SEE SG030	59110SG031	86.40		
5	LAMP ASSY HEAD EDF / <i>Cut</i> (SUPP)	84002SG230	2380.00		
6	FENDER FLARE SJG TB W/O F U/SPOIL / <i>Cut</i>	E2010SG020			400.00
SUB TOTAL			4230.40	0.00	400.00
LESS DISCOUNT (NETT-20 %)			846.08	0.00	0.00
GRAND TOTAL			3384.32	0.00	400.00
OVERALL TOTAL			3784.32		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLJ70890

TOTAL LABOUR CHARGES	3400.00
TOTAL SPARE PARTS CHARGES	3784.32
GRAND TOTAL	7184.32 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE :
LIABILITY :
REMARKS :

Guo Qiang - 8288282
Guo Qiang @ lkk auto. com
before paint photos.
26/3/18.
5 Days.


2/4/18

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Auto Consultants hence notify the Repairer of the following:

- To resurvey before & after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No fix or modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2018		22 Mar 2018 08:43 Edit Adj Rpt	S\$5,794.20 Edit Estimates	S\$5,794.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: NG YEN HUI ELINOR (HUANG YANHUI ELINOR) , ID: S8027270G, Tel: +6594761589, Email: elinor03@yahoo.com									
Main Claimant: KOK HOCK HENG , ID: S1565680H									
Vehicle Reg. No.: SLJ7089D		Date of Loss: 10/03/2018 14:00 - :59 [14 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 552214		Policy/Cover Note No.: 28672148QMY (Comprehensive) Coverage: 12/02/2018 - 11/02/2019							
Vehicle Reg. No. (Insured): SKR5271B		Policy No. (Claimant): Excess: S\$500.00							
Repairer: Motorimage Enterprise Pte Ltd (HQ) 25 LENG KEE ROAD, 159097 Leng Kee - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/04/2018]									
Driver/Custodian (Insured): NG YEN HUI ELINOR (HUANG YANHUI ELINOR) (37 / Female), NRIC: S8027270G, Tel: +6594761589									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLJ7089D (552214)**

[SKR5271B]

TP

KOK HOCK HENG

Mar 10 2018 2:00PM

[NG YEN HUI ELINOR (HUANG YANHUI ELINOR)]

Motorimage Enterprise Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Video				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	16/05/18 09:55	Video - Accident (Rear)	Load MP4		
2	16/05/18 09:59	Video - Accident From:OD - Reg. No: SKR5271B, Claimant: NG YEN HUI ELINOR (HUANG YANHUI ELINOR)	Load MP4		

Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	21/03/18 14:41	Accident Statement From:OD - Reg. No: SKR5271B, Claimant: NG YEN HUI ELINOR (HUANG YANHUI ELINOR)	Load HTM		
LKK Auto Consultants Pte Ltd (HQ)					
1	31/03/18 10:59	Adjuster Immediate Advice	Load HTM		

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	31/03/18 10:55	General View	Load JPG	☒	
2	31/03/18 10:55	General View	Load JPG	☒	
3	31/03/18 10:55	General View	Load JPG	☒	
4	31/03/18 10:55	General View	Load JPG	☒	
5	31/03/18 10:55	General View	Load JPG	☒	
6	31/03/18 10:55	General View	Load JPG	☒	
7	31/03/18 10:55	General View	Load JPG	☒	
8	31/03/18 10:55	General View	Load JPG	☒	
9	31/03/18 10:55	General View	Load JPG	☒	
10	31/03/18 10:55	General View	Load JPG	☒	
11	31/03/18 10:55	General View	Load JPG	☒	
12	31/03/18 10:55	General View	Load JPG	☒	
13	31/03/18 10:55	General View	Load JPG	☒	
14	31/03/18 10:55	General View	Load JPG	☒	
15	31/03/18 10:55	General View	Load JPG	☒	
16	31/03/18 10:55	General View	Load JPG	☒	
17	31/03/18 10:55	General View	Load JPG	☒	
18	31/03/18 10:55	General View	Load JPG	☒	
19	31/03/18 10:55	General View	Load JPG	☒	
20	31/03/18 10:55	General View	Load JPG	☒	

Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	21/03/18 14:34	TPD SLJ7089D EST	Load PDF		
2	21/03/18 14:40	TPD SLJ7089D GIA REPORT - PART 1.	Load PDF		
3	21/03/18 14:40	TPD SLJ7089D GIA REPORT - PART 2.	Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005378/GVD3Q2

Date: 25/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 28672148QMY
 Claimant Vehicle No: SLJ7089D Insured Vehicle No: SKR5271B
 Date of Loss: 10/03/2018 Nature of Claim: TP Claim No: 552214

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLJ7089D
 Make & Model: SUBARU FORESTER, 2.0 I-L CVT AWD SR (A) Engine No: FB20Y508237
 Reg. Date: 22/12/2016 (Man. Year: 2016) Chassis No: JF1SJ5KC5GG081910
 Colour: White Odometer: 34209 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/60 R17 Rear Tyre Size: 225/60 R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,864.32	3,519.20	345.12	8.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,320.00	2,275.00	1,045.00	31.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,184.32	5,794.20	1,390.12	19.35
+ GST 7.00/7.00% (S\$)	502.90	405.59	97.31	19.35
Nett Amount (S\$)	7,687.22	6,199.79	1,487.43	19.35

INSPECTION

Date of Assignment: 22/03/2018
 Date Inspected: 26/03/2018 Inspected At: Motorimage Enterprise Pte Ltd (HQ)
 25 LENG KEE ROAD
 Singapore 159097
 Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

PLEASE BE INFORMED THAT VEHICLE CONVERT TO OD CLAIM.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$69.12 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jun 2018)
Parts:	M1-SUV	SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ7089D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DISC WHEEL AL 17	Cut	900.00 FN	*900.00 FN
2	1		*FRT FENDER LH	Repair	270.00 FN	*- FN
3	1		*BUMPER FACE F NA	Cut	594.00 FN	*594.00 FN
4	1		*MUD GUARD ASSY F LH	*Check	86.40 FN	*- FN
5	1		*LAMP ASSY HEAD EOF	Cut	2,380.00 FN	*2,380.00 FN
6	1		*FENDER FLARE SJG TB W/O F U/SPOIL	Cut	400.00 FS	*400.00 FS
7	1		*SUNDRIES	Necessary	80.00 FS	*20.00 FS
					Sub Total (S\$)	4,710.40
					- Nett Item Discount on N Items 20.00/20.00% (S\$)	846.08
					Total Parts (S\$)	3,864.32

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CONDUCT 4-WHEEL ALIGNMENT	New	250.00	185.00
2	TO SUPPLY AND REPLACE FRONT BUMPER AND FRONT LHS FENDER	New	1,680.00	1,120.00
3	TO SPRAY FRONT BUMPER ASSY AND FRONT LHS FENDER	New	1,260.00	880.00
4	TO CONDUCT FRONT LIGHTING TEST	New	60.00	40.00
5	TO TRANSFER AND BALANCE FRONT LHS TYRE & RIM	New	70.00	50.00
Gross Labour Cost (S\$)			3,320.00	2,275.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >