

ASS. REC. BY

REF

CS/MSG18005380/Tlgd3et

Special Instructions

Survey of

Merimen

Taufik

ASSIGNMENT (Office)

From (Person):

Monica chung

of

MSG

Date/Time:

2/13/18 @ 3:27pm

Estimated Cost:

Bill to:

OD / TP

WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJH 9326R

Insured:

SJB 5028J

at Workshop n/:

Xinya Auto Services

Tel:

6270 3181

of

81K1002 # 01-75 Bkt Merah Lane 3

Policy No:

A80355633QMX

Claim No:

552952

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/03/2018

CA / REV / REP. / REV 24 HRS

lup?

H.O.D. Endorsement:

Date/Time:

10:58 am @ 22/3/18

Person Contacted:

Mei

Vehicle:

IN/DUT

Date/Time

Action/Instruction (✓) Estimate

SJH 9326R - NBA/INC18005312/Y

D.O.A: 19/3/2018

SJB 5028J - NBA/INC18005312/Y

D.O.A 19/3/18

2/13/18 @ 3:15pm

revised to Monica chung via Merimen.

09/6/18 @ 3:25pm

confirmed with May 15 \$ 2100, 4 days by email.
(Red \$ 1589.38, 43%)

REF:

ASSIGNMENT

From: _____ Date: **21/3/18**

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: **SS4 9326R** Yr Regn: **2008 Aug.**

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: **Toyota Axio** c.c. **1496**

Colour: **Grey** A/C: Insured / Std / NI / NA

Sp. Reading: **165420.** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **NZE 1416082466**

Gen. Cond: **3** / Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: **185/70R14**

R: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **4** days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS **lwp**

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or **Non-hub**

Front		Rear
R/Bal. 6 mm		R/Bal. 6 mm
L/Bal. 6 mm		L/Bal. 6 mm
D.O.A.		D.O.I. 21/3/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or **ent o/s**

The UIC / Chassis frame / Body Structure affected due to collision.

[Signature]
13/6/2018

RECEIVED 14 JUN 2018

Date/Time: File Pass to? Preli. Report
 Final Report

Date/Time: File Return to? _____

Days Of Repair: **4**

Resurvey No. of Trip: _____

Report Format: **MER-TP**

Lump Sum **1181.15** **2100**

Add Fee: Site Insp \$
 Interview \$
 Tech Insp \$
 Wheel and \$

Survey Fee:	200
Transportation:	
1. 3+RR \$	
2. Reps:	
3. Other:	10
TOTAL:	210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18005380/T1qd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 22-03-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJB 5028J	Veh. Inspected	SJH 9326R
Policy No.	A80355633QMX	Coverage (\$)	0.00
Claim No.	552952	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	22/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	19/03/2018	Inspection Date	22/03/2018
Survey held at	XINYA AUTO SERVICES PTE LTD BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Mar 2018		21 Mar 2018 15:27 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	CHNG BUAY HUANG, ID: S01908823		
Main Claimant:	TODDS PARTNERS PTE. LTD., Co. Reg. No.: 201533177E		
Vehicle Reg. No.:	SJH9326R	Date of Loss:	19/03/2018 15:00 - :59
Claim Type:	TP / 552952	Policy/Cover Note No.:	A80355633QMX (Comprehensive) Coverage: 15/07/2017 - 14/07/2018
Vehicle Reg. No. (Insured):	SJB5028J	Policy No. (Claimant):	
		Excess:	
Repairer:	Xinya Auto Services Pte Ltd (HQ) Blk 1002, #01-75, Bukit Merah Lane 3, 159719 Bukit Merah - Tel: 6270 3481		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/03/2018]		
Driver/Custodian (Insured):	MABEL CHONG BUAY HOON {}, NRIC: S1570122F, Tel: +6593388481		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Xinya Auto Services <xinyaauto@singnet.com.sg>
Sent: Saturday, 9 June 2018 3:25 PM
To: Shiau Chan (LKKAuto)
Subject: RE: FINALISE OF VEHICLE SJH 9326R (DOA: 19/03/2018)

Hi Shiau Chan

Thank for the offer client is agreeable pls have matter close.

Thank you.

Regards
May

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Monday, June 4, 2018 5:29 PM
To: Xinya Auto Services <xinyaauto@singnet.com.sg>
Subject: FINALISE OF VEHICLE SJH 9326R (DOA: 19/03/2018)

Dear May/Kelvin,

Offer Lump Sum \$2,100.00 before GST and 4 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Virus-free. www.avg.com

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 26 Mar 2018

Preliminary Advice

Insured Vehicle No	: SJB5028J	Accident Date	: 19/03/2018
TP Vehicle No	: SJH9326R	Assignment Date	: 21/03/2018
Make	: TOYOTA COROLLA	Est. Duration of Repair	: 4.00
Date of Inspection	: 21/03/2018		
Inspection At	: XINYA AUTO SERVICES PTE LTD (HQ) BLK 1002, #01-75, BUKIT MERAH LANE 3 SINGAPORE 159719		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,689.38
Revised Amount	:S\$	2,724.25
Check Items (Estimated)	:S\$	201.38
Total	:S\$	2,925.63
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 3177E

Vehicle Details

Vehicle No.: SJH9326R
Vehicle to be Exported: No
Intended De-registration Date: 21 Mar 2018
Vehicle Make: TOYOTA
Vehicle Model: COROLLA AXIO 1.5X A
Primary Colour: Grey
Manufacturing Year: 2008
Engine No.: 1NZD050501
Chassis No.: NZE1416082466
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$12,135.00
Original Registration Date: 28 Aug 2008
First Registration Date: 28 Aug 2008
Transfer Count: 1
Actual ARF Paid: \$7,659.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Aug 2018
PARF Rebate Amount: \$3,829.00

Intended COE Rebate Details

COE Expiry Date: 27 Aug 2018
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$12,501.00
COE Rebate Amount: \$541.00
Total Rebate Amount: \$4,370.00

The information contained herein is correct as at 21 Mar 2018

OK

- Unusual or rare cars
- Anodising of alloy rims
- Which brand and model for Smart TV? So many until blur...

toyota axio Price Range Depreciation 3008 Vehicle Type [Advanced Search](#)

Home > Used Cars > 88 Motor Trading > Toyota Corolla Axio 1.5A X

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle


Commercial Vehicle



Toyota Corolla Axio 1.5A X

Overview Financial Accessories Similar Research Photos Map

88 汽车贸易 MOTOR TRADING



Add to Shortlist Add to Compare Add a Note Report Error

More Actions Share

Car Details

Price	\$9,800	
Depreciation	-	
Reg Date	03-Sep-2008 (Smiths 12days COE left)	
Manufactured	2008	
Mileage	-	
Transmission	Auto	
Engine Cap	1,496 cc	
Road Tax	\$682 /yr	
Power	81.0 kW (108 bhp) View specs of the Toyota Corolla Axio (2007-2012)	
Curb Weight	1,130 kg	
Features	-	
Accessories	-	
Description	\$0 Down Payment Available! Balloon Scheme Available! We Are sgCarMart Premium Dealer 2015-2017! Buy With Confidence! No Hidden Cost! Low Mileage! 100% Accident Free! In House Loan Or Bank Loan Available! No Need Guarantor Or Minimum Income! Fast And Easy Loan Approval! High Loan Or Over Trade Welcome! All Our Vehicles Has Undergone A 120 Points Safety Check By Our In House Mechanics!	
COE	\$7,918	
OMV	\$11,657	
ARF	\$10,158	
Derog Value	\$5,437 as of today (change)	
No. of Owners	5	
Type of Veh	Mid-Size Sedan	
Category	PARF Car	
Availability	Available	



Seller Information

Company	88 Motor Trading = dealer's pricelist = 218 vehs sold 118 vehs available	
Address	200 Jalan Sultan #02-38/Level 7 Carpark Search cars nearby this location	
Location	Textile Centre	
Office No	62911187	
Contact Person(s)	Mr Ho	96811390
	Ben	90913551
	Jeremy	97625070
	Alan	96900054

Add to Shortlist Add to Compare Add a Note

Posted on: 20-Mar-2018 | Last Updated on: 20-Mar-2018
Tags: Toyota Corolla, 2008 Toyota Corolla, Toyota, Corolla, Used Toyota

Upfront Payment [+ more Financial info](#)

Compare

Transfer Fee \$25

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/03/2018 17:40
Date Of Accident	19/03/2018 15:00
Exact Location Of Accident	TAMPINES AVE 5 BESIDE MASJID DARUL GHUFRAN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJH9326R
Insured/Policyholder	
Name Of Registered Owner	TODDS PARTNERS PTE. LTD.
Co Reg No	201533177E
Email Address	THENZG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-85228291
Alternative Phone No	OFFICE-85228291

Vehicle Particulars

Manufacturer	TOYOTA
Model	AXIO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096197639
Cover Note Number	

Driver

Name of Driver	SAMAD BIN ALI
NRIC No	S1389386A
Date Of Birth	25/07/1959
Occupation	INDOOR
Date Of Driving Pass	06/08/1980
Driving Experience	37 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85228291
Fax Number	
Contact Number	OTHERS-85228291
Email Address	THENZG@GMAIL.COM

Address	BLK 775 WOODLANDS CRESCENT #06-18
Postcode	730775
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN (TYPE OF COLLISION IS HEAD TO SIDE)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJB5028J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MABEL CHONG BUAI HOON
NRIC/Passport Number	S1570122F
Contact Number	90086707
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be completed by the **Policyholder** and/or the authorized driver.
3. Information provided must be as **truthful and accurate** as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance company is not an admission of policy liability on the part of the insurance company.
5. Any **fraud** reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurer to the Civil Aviation Management Centre established by the General Insurance Association of Singapore (GIAS) for processing and that Insurer will for a fee do major accident report application to relevant authority.
7. By the lodging of this report to the Insurer, you hereby consent to the archiving of this report and to its content being made available wherever.
8. **Consent under the Personal Data Protection Act (PDPA)**

I, undersigned, acknowledge, agree and consent that

- 18A. My Insurer, my working and the General Insurance Association of Singapore ("GIAS") may use permitted to collect, use, disclose and/or provide my personal data (including information set out in this form) and any other personal information provided to me or assumed by my Insurer collecting the "Personal Information" and disclose and transfer such Personal Information to all insurance adjusters involved with this matter or the adjuster (if insured) who have insured vehicles involved in this accident and be collectively referred to as the "Insurers", the Insurer, Insurance Firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - a) processing, handling and dealing with the claim involving the settlement of the claim and any relevant investigations relating to the claim;
 - b) investigating the accident under the claim;
 - c) carrying out and/or dealing with the investigation of reporting to any enquiries by me;
 - d) administering my claim (including the making of compensation, statements, checks, reports or other documents which could involve disclosure of certain personal data about me to third parties outside of the claim as well as on the external cover of involved/involved parties); and/or
 - e) complying with applicable law or administering, processing, handling and/or dealing with my claim concerning the "Purpose".
- 18B. If Insurers who have insured vehicles involved in this accident and the Insurer (including third parties) are permitted to collect, use, disclose and/or provide the Personal Information for one or more of the above Purposes, (a)
- 18C. My Personal Information may be disclosed by any of the Insurers within 24 hours after this party gives consent or agreement to the Insurers, law firms, which may be done outside of Singapore for one or more of the above Purposes;
- 18D. My Personal Information will also be collected and used to complete claim history for the purpose of fraud detection, investigation and management in present and all future claims;
- 18E. The information so collected under 18B above may be shared / disclosed:
 - 18E.1 to all Insurers and/or any other third parties that need it in conducting, investigating, processing or managing fraud, inquiries, law enforcement and government agencies as reasonably required for the purposes stated; or
 - 18E.2 for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time

Driver's Signature
(If different to the policyholder)
Date & Time


Claiming Centre Representative's Signature
Name: Rasli Athar
MST/CR No.

Accident Sketch Plan

SKETCH PLAN TAMPAWATER AVE 5 BESIDE MASJID JALAL GILUKRANG CIBUPATIR



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I had drive out of the parking lot. Suddenly opposite of me I saw a vehicle coming forward without stopping at the stop line. I immediately stop my car however the lady driver still move forward towards my direction and bumped my.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Date & Time:

[Signature]
 Date & Time:

[Signature]
 Name: *[Name]*
 No. of License: *[No. of License]*

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail : xinyaauto@singnet.com.sg

Tel: 6270 3481 Fax: 6278 7522

Date : 20-Mar-18

Address : TODDS PARTNERS PTE LTD
BLK 1002 BUKIT MERAH LANE 3
01-75
SINGAPORE 159719

Reference : TP 1151/03/18
Vehicle No : SJH 9326R
Make/Model : TOYOTA AXIO
Insurance Co. : NTUC

RE : QUOTATION REPAIRS TO SJH 9326R FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>		<u>QTY</u>	<u>AMT \$</u>
1)	FRONT BUMPER	1	\$ 425.80 <i>del -</i>
2)	FRONT BUMPER RETAINER	1	\$ 107.20 <i>del -</i>
3)	FRONT BUMPER ENFORCEMENT	1	\$ 268.50 <i>? photo - x nn</i>
4)	FRONT BUMPER CLIPS	10	\$ 40.00 <i>del -</i>
5)	FRONT FENDER RH	1	\$ 475.00 <i>del -</i>
6)	FENDER COWLING	1	\$ 125.00 <i>x nn</i>
7)	HEADLAMP	1	\$ 646.00 <i>del -</i>
8)	FOG LAMP COVER	1	\$ 48.90 <i>del -</i>
9)	ENGINE UNDER COVER	1	\$ 135.40 <i>del -</i>
10)	FRONT FGRILLE	1	\$ 340.70 <i>del -</i>

LIST PRICE TOTAL	\$	2,087.50 <i>2612.50</i>
LESS DISCOUNT 25%	\$	521.88
LIST PRICE TOTAL AFTER LESS	\$	1,565.63 <i>1959.38</i>

NETT PRICE TOTAL **\$0.00**

TOTAL PARTS COST **\$1,565.63**

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE FRONT BUMPER, FENDER, HEADLAMP AND TO PANEL BEAT & ADJUST.	\$	1,000.00 <i>600</i> (5 days)
2)	TO PUTTY & SPRAY PAINT FRONT BUMPER AND FENDER	\$	400.00 <i>✓</i> (2 PANEL)
3)	TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP	\$	100.00 <i>30</i>
4)	TUFF KOTE	\$	230.00 <i>30</i>

LABOUR TOTAL **\$ 1,730.00**

TOTAL ESTIMATED REPAIR COST **\$ 3,295.63** *3689.38*

LKK Auto Considers the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanferm 97495749
21/3/18 @ 1650
4 days
Resurvey after repair.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Mar 2018		21 Mar 2018 15:27 Edit Adj Rpt	S\$2,100.00 Edit Estimates	S\$2,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHNG BUAY HUANG , ID: S0190882J								
Main Claimant:	TODDS PARTNERS PTE. LTD. , Co. Reg. No.: 201533177E								
Vehicle Reg. No.:	SJH9326R	Date of Loss:	19/03/2018 15:00 - :59 [114 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 552952	Policy/Cover Note No.:	A80355633QMX (Comprehensive) Coverage: 15/07/2017 - 14/07/2018						
Vehicle Reg. No. (Insured):	SJB5028J	Policy No. (Claimant):							
		Excess:							
Repairer:	Xinya Auto Services Pte Ltd (HQ) Blk 1002, #01-75, Bukit Merah Lane 3, 159719 Bukit Merah - Tel: 6270 3481								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 20/04/2018]								
Driver/Custodian (Insured):	MABEL CHONG BUAY HOON (), NRIC: S1570122F, Tel: +6593388481								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJH9326R (552952)**
[SJB5028J]
TP
TODDS PARTNERS PTE. LTD.
Mar 19 2018 3:00PM
[CHNG BUAY HUANG]
Xinya Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/03/18 14:37	Accident Statement <small>From: SC - Reg. No: SJB5028J, Claimant: CHNG BUAY HUANG</small>	Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/03/18 15:15	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/06/18 10:12	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
2	13/06/18 10:12	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
4	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
5	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
6	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
7	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
8	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
9	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
10	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
11	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
12	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
13	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
14	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
15	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
16	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
17	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
18	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
19	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
20	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
21	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
22	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
23	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
24	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
25	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
26	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
27	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
28	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
29	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
30	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
31	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
32	13/06/18 10:12	General View	Load JPG	<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
34	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
35	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
36	13/06/18 10:12	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/03/18 14:37	SJH9326R E FILE REPORT From: SC - Reg. No: SJ050281, Claimant: CHNG BUAY HUANG	Load PDF	
2	21/03/18 14:37	PRI Notice	Load PDF	
3	21/03/18 15:26	TP Agree on SJE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005380/T1QD3E2
Date: 18/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80355633QMX
Claimant Vehicle No : SJH9326R	Insured Vehicle No :	SJB5028J
Date of Loss: 19/03/2018	Nature of Claim:	TP
		Claim No: 552952

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH9326R	Engine No:	1NZD050501
Make & Model:	TOYOTA COROLLA, 1.5 X AXIO (A)	Chassis No:	NZE1416082466
Reg. Date:	28/08/2008 (Man. Year: 2008)	Odometer:	165420 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/70 R14	Rear Tyre Size:	185/70 R14
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,959.37	1,664.25	295.12	15.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,730.00	1,060.00	670.00	38.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,689.37	2,724.25	965.12	26.16
Approved Total (Overridden) (S\$)		2,100.00		
Nett Amount (S\$)	3,689.37	2,100.00	1,589.37	43.08

INSPECTION

Date of Assignment:	21/03/2018	
Date Inspected:	21/03/2018	Inspected At: Xinya Auto Services Pte Ltd (HQ) Blk 1002, #01-75, Bukit Merah Lane 3 Singapore 159719
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Jun 2018)
Parts: 143	TOYOTA COROLLA 1.5 X AXIO (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH9326R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	425.80 FL	*425.80 FL
2	1		*FRONT BUMPER RETAINER	Necessary	107.20 FL	*107.20 FL
3	1		*FRONT BUMPER ENFORCEMENT	Not Necessary	268.50 FL	*- FL
4	10		*FRONT BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
5	1		*FRONT FENDER RH	Bent	475.00 FL	*475.00 FL
6	1		*FENDER COWLING	Not Necessary	125.00 FL	*- FL
7	1		*HEADLAMP	Cracked	646.00 FL	*646.00 FL
8	1		*FOG LAMP COVER	Deformed	48.90 FL	*48.90 FL
9	1		*ENGINE UNDER COVER	Torn	135.40 FL	*135.40 FL
10	1		*FRONT GRILLE	Cracked	340.70 FL	*340.70 FL

F=Franchise part, L=ListItemDisc.

Sub Total (S\$)	2,612.50	2,219.00
- List Item Discount on L Items 25.00/25.00% (S\$)	653.13	554.75
Total Parts (S\$)	1,959.37	1,664.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE FRONT BUMPER, FENDER, HEADLAMP AND TO PANEL BEAT & ADJUST	New	1,000.00	600.00
2	TO PUTTY & SPRAY PAINT FRONT BUMPER AND FENDER	New	400.00	400.00
3	TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP	New	100.00	30.00
4	TUFF KOTE	New	230.00	30.00
Gross Labour Cost (S\$)			1,730.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >