

ASS. REC. BY:

REP

CS/MSG18005286 / Utd3

Signed Instruction:

Surveyor

Merris

ASSIGNMENT (Office)

From (Person)

Katherine Wong

of

MSG

Date/Time:

21/3/18 3:31pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SY 691 E

Insured:

FX 2003 G

at Workshop m/s:

Torque 5

Tel:

9147 8841

of

8 Kaki Bkt Ave 4 # 01-50

Policy No:

MSD/VMS/17-371830-CA

Claim No:

MSC/v/18-000421

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20/03/2018

23/03/2018

CA / REV / REP. / REV 24 HRS

hwp

H.O.D. Endorsement:

Date/Time:

10:50am @ 22/3/18

Person Contacted:

Wynn

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SY 691 E - x

FX 2003 G - x

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 554691at Workshop m/s 20yr 5

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 30k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 28/10/2018

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: 554691E Yr Regn: 30/10 ofType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 120i c.c. 1995Colour: Black A/C: Insured / Std / NI / NASp. Reading: 115863 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBANT12040CX28601Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 245/40 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 20/3/18 D.O.I. 23/3/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Roly

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 7 mth. 28/13 7:43L1A23120 net 688025/4/18/5 @ 4400 confirmed with stephane (led: 1754189, 797)

RECEIVED 25 APR 2018

Date/Time, File Pass to?



: Prel. Report

25/4 Typist

: Final Report

Date/Time, File Return to?

2)

Report Format: TPLump Sum / I.B.I: (\$) 4400Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:



: Site Insp

(\$



: Interview

(\$



: Tech. Invs

(\$



: Weekend

(\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Inc Auth'd	Status
Main	21 Mar 2018		21 Mar 2018 15:31 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Mohd Fahmie Bin Senen, ID: S7602667Z		
Main Claimant:	Yep Cheong Kui, ID: S6832279J		
Vehicle Reg. No.:	SJY691E	Date of Loss:	20/03/2018 09:00 - :59
Claim Type:	TP / MSC/V/18-000421	Policy/Cover Note No.:	MSD/VMS/17-371830-CA Coverage: 20/09/2017 - 19/09/2018
Vehicle Reg. No. (Insured):	FX2003G	Policy No. (Claimant):	
		Excess:	
Repairer:	Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4,, #01-50, 415875 Kaki Bukit - Tel: 64524457		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/03/2018]		
Adj Asg. Remarks:	Please assign to Mr Adrian Ling. Thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18005386/Utd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 22-03-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FX 2003G	Veh. Inspected	SJY 691E
Policy No.	MSD/VMS/17-371830-CA	Coverage (\$)	0.00
Claim No.	MSC/V/18-000421	Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	22/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/03/2018	Inspection Date
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 2279J

Vehicle Details

Vehicle No.: SJY691E

Vehicle to be Exported: No

Intended De-registration Date: 26 Mar 2018

Vehicle Make: B.M.W.

Vehicle Model: 520I AUTO ABS AIRBAG 2WD XENON HEADLAMP

Primary Colour: Black

Manufacturing Year: 2008

Engine No.: A639I250N46B20BE

Chassis No.: WBANT12040CX29601

Maximum Power Output: 115.0 kW (154 bhp)

Open Market Value: \$45,345.00

Original Registration Date: 30 Oct 2008

First Registration Date: 30 Oct 2008

Transfer Count: 1

Actual ARF Paid: \$45,345.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Oct 2018

PARF Rebate Amount: \$22,672.00

Intended COE Rebate Details

COE Expiry Date: 29 Oct 2018

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$7,589.00

COE Rebate Amount: \$448.00

Total Rebate Amount: \$23,120.00

The information contained herein is correct as at 26 Mar 2018

OK

sgCARMART.COM

Login Sign up

[New Cars](#)
[Used Cars](#)
[Sell My Car](#)
[Directory](#)
[Products](#)
[Insurance](#)
[Articles](#)
[Forum](#)
[Resources](#)
Free Car Valuation

Unsure of how much your car is worth?

Let us tell you how much is the value - no charges & no obligations!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Year Coe Renewal Honda Stream 1.8A RSZ



\$2800 downpayment Monthly
From \$738 Onwards. Lowest
3.68%APR All@GV Cars Financing
GV Credit Pte Ltd - Sprint



Browse by Category

Sort by Date Posted 20 results/page

3 vehicles

bmw 520

Advanced Search Submit

Make	Model	Price	Depreciation	Reg. Cost	Eng. Cap	Mileage	Veh. Type	Status
Search Selection	bmw 520	Any	Any	2008	Any	Any	Any	Available



BMW 5 Series 520i XL (New 10-yr COE)

\$75,000

\$7,490 /yr

26-Jun-2008

1,995 cc

128,000 km

Luxury

Available

High OMV Value Of \$50K! Accident Free! Call Now To View

Contact Owner

Posted: 25-Mar-2018 Tags: 2008 BMW 520i, BMW 520i, BMW, 520i, Used BMW



BMW 5 Series 520i XL (New 10-yr COE)

\$81,800

\$8,170 /yr

30-May-2008

1,995 cc

105,000 km

Luxury

Available

Interest From 3.15% Onwards, View To Believe The Condition, Selling At \$33,800 Without COE Renewal. Low Mileage Unit Done At 10,000KM Yearly Only, Superb Condition, All Wear And Tear Replaced, New 10 ...

Posted: 17-Mar-2018 Tags: 2008 BMW 520i, BMW 520i, BMW, 520i, Used BMW

**BMW 5 Series 520i**

\$32,000

\$14,440 /yr

27-Nov-2008

1,995 cc

170,000 km

Luxury

Available

Well Maintained, Regularly Service. Nice Car No.

Contact Owner

Posted: 16-Feb-2018 Tags: 2008 BMW 520i, BMW 520i, BMW, 520i, Used BMW

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg. Cost	Eng. Cap	Mileage	Veh. Type	Status
------	-------	-------	--------------	-----------	----------	---------	-----------	--------

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classified for popular import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used bmw 520, buy 520 Singapore, used bmw 520 Singapore, used bmw 520i, used vehicles Singapore or even buy used bmw 520 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, movies, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or correct. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/03/2018 18:56
Date Of Accident	20/03/2018 09:10
Exact Location Of Accident	PIE PAYA LEBAR ROAD (PIE TUAS PAYA LEBAR EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJY691E
Insured/Policyholder	
Name Of Registered Owner	YEP CHEONG KUI
NRIC No	S6832279J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82820628
Alternative Phone No	OFFICE-82820628

Vehicle Particulars

Manufacturer	BMW
Model	520I-2.0 ABS AIRBAG 2WD XENON HEADLAMP (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00007260
Cover Note Number	

Driver

Name of Driver	CHEOK WEE NEE
NRIC No	S2606386H
Date Of Birth	24/01/1967
Occupation	INDOOR
Date Of Driving Pass	18/12/1993
Driving Experience	24 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-82820628
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 552 BEDOK NORTH AVENUE 1 #05-494
Postcode	S460552
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BEDOK NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 30 BEDOK NORTH ROAD , POSTCODE: 469676 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2449999 - FAX NO: 62447258
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FX2003G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	XE2433K
Vehicle Make/Model/Colour:	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, vehicle 'A' was travelling on my designated lane on P/E towards Raya lebar road exit. As there was a heavy flow of traffic, I stopped before the dotted line to wait for my turn to turn left. As I was waiting for my turn, vehicle 'C' suddenly turned left, hitting vehicle 'B', which then vehicle 'B' hit into me on my driver side.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:

Email: sm@idac.com.sg

Tel no: 6555 6888 Fax no: 6454 3279

20/3/18
(RTS)

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 20 / 03 / 2018 (dd/mm/yy) Time of Accident: 09 : 10 (24-HR-FORMAT)

Vehicle No.: SJY 691 E Vehicle Make & Model: BMW 520i

Exact location of Accident: PTE Paya Lebar Road CPE tower paya lebar exit

Policyholder's Name / IC No.: Yap Cheong Kwi S 6832279J

Driver's Name / IC No.: Chock Wee Nee S 260638614 (As Above) ☐

Driver's Contact No.: 8282 6622 Company Contact No: _____

Driver's Address: Blk 552 Bedok North Avenue 1 #05-494 S (460552)

Insurance Company: FWD Email address (if any): _____

Relationship between Owner & Driver: (Please **CIRCLE** one only)

Owner / Spouse / Children / Friend / Parents / Sibling / Relative / Employee / Hirer or Others specify: _____

What do you wish to claim? (Please **TICK** one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

Exact purpose for which the vehicle was being used at time of accident?

Occupation (nature of job) ☒ Indoor / ☐ Outdoor

☒ Private use / ☐ Work purpose

No. of Passengers (Including Driver): 01

Weather condition & Road conditions? (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? ☐ Yes / ☒ No

Any Injuries: ☒ Yes / ☐ No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: ☒ Yes / ☐ No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No: _____ Vehicle No: Fx 2003 G (B)

Driver's Contact No: _____ Insurance Company (If any): _____

2. Driver's Name / IC No: _____ Vehicle No: XE 2433 K (C)

Driver's Contact No: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No: _____

Preferred Workshop Name: _____ Contact No: _____

*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, i vehicle 'A' was travelling on my designated lane on PIE tuas Paya lebar road exit. As there was a heavy flow of traffic i stopped before the dotted line to wait for my turn to turn left. As i was waiting for my turn vehicle 'C' suddenly turned left hitting vehicle 'B' which then vehicle 'B' hit into me on my driver side.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

Torque 5 Pte Ltd

ESTIMATION REPORT

Vehicle No : SJY691E
Make & Model : B.M.W., 520i AUTO ABS AIRBAG 2WD XENON
HEADLAMP, WBANT12040CX29601
Year of Manufacture : 2008

Estimation No. : E18030062
DOA : 20/03/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	FRONT BUMPER <i>1 X</i>	1.00	0.00	0.00 1650.00
2	FRONT BUMPER CLIPS <i>44 X</i>	10.00	0.00 50.00	0.00 500.00
3	FRONT BUMPER RETAINER (R) <i>11 X</i>	1.00	0.00	0.00 35.00
4	FRONT BUMPER BRACKET (R) <i>11 X</i>	1.00	0.00	0.00 35.00
5	FRONT BUMPER REINFORCEMENT <i>11 X</i>	1.00	0.00	0.00 750.00
6	FRONT BUMPER SPONGE <i>11 X</i>	1.00	0.00	0.00 58.50
7	FRONT BUMPER INNER CENTRE GARNISH <i>11 X</i>	1.00	0.00	0.00 285.20
8	FRONT BUMPER FOG LAMP (R) <i>11 X</i>	1.00	0.00	0.00 307.10
9	FRONT BUMPER FOG LAMP GARNISH (R) <i>11 X</i>	1.00	0.00	0.00 89.00
10	FRONT BUMPER LOWER GRILLE <i>11 X</i>	1.00	0.00	0.00 95.40
11	FRONT BUMPER SENSOR <i>11 X</i>	2.00	0.00 270.50	0.00 541.00
12	FRONT BUMPER WIPER NOZZLE (R) <i>11 X</i>	1.00	0.00	0.00 175.00
13	FRONT BUMPER WIPER NOZZLE CAP (R) <i>11 X</i>	1.00	0.00	0.00 60.00
14	FRONT KIDNEY GRILLE (R) <i>11 X</i>	1.00	0.00	0.00 272.20
15	FRONT KIDNEY GRILLE CLIPS (R) <i>111 X</i>	5.00	0.00 50.00	0.00 250.00
16	FRONT FENDER (R) <i>11 X</i>	1.00	0.00	0.00 927.50 ✓
17	FRONT FENDER SIGNAL LAMP (R) <i>500 X</i>	1.00	0.00	0.00 49.20 ✓
18	FRONT FENDER COWLING (R) <i>2000 X</i>	1.00	0.00	0.00 161.20 ✓
19	FRONT FENDER COWLING CLIPS (R) <i>11 X</i>	10.00	0.00 50.00	0.00 500.00 ✓
20	FRONT FENDER INNER PANEL (R) <i>R X</i>	1.00	0.00	0.00
21	SIDE MIRROR ASSY (R) <i>11 X</i>	1.00	0.00	0.00
22	ROCKER PANEL (R) <i>garage 11 X</i>	1.00	0.00	0.00 456.7 ✓
23	HEAD LAMP (R) <i>11 X</i>	1.00	0.00	0.00 2820.00
24	HEAD LAMP CLIPS (R) <i>11 X</i>	2.00	0.00 50.00	0.00 100.00

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJY691E
Make & Model : B.M.W., 520i AUTO ABS AIRBAG 2WD XENON
HEADLAMP, WBANT12040CX29601
Year of Manufacture : 2008

Estimation No. : E18030062
DOA : 20/03/2018

No	Description	Qty	U/P	Amt
25	FRONT DOOR (R) <i>DO ✓</i>	1.00	0.00	0.00 <i>1637.90 ✓</i>
26	FRONT DOOR HINGE-UP (R) <i>Tw ✓</i>	1.00	0.00	0.00 <i>215.00 ✓</i>
27	FRONT DOOR HINGE-DOWN (R) <i>Tw ✓</i>	1.00	0.00	0.00 <i>215.00 ✓</i>
28	FRONT DOOR CHECKER (R) <i>11 X</i>	1.00	0.00	0.00 <i>200.00</i>
29	FRONT DOOR WEATHER STRIP (R) <i>RM ✓</i>	1.00	0.00	0.00 <i>250.00 ✓</i>
30	FRONT DOOR INNER WEATHER STRIP (R) <i>RM ✓</i>	1.00	0.00	0.00 <i>189.70 ✓</i>
31	FRONT DOOR POWER WINDOW MOTOR (R) <i>11 X</i>	1.00	0.00	0.00
32	FRONT DOOR POWER WINDOW GEARS (R) <i>11 X</i>	1.00	0.00	0.00
33	FRONT DOOR WINDOW MOULDING (R) <i>11 X</i>	1.00	0.00	0.00
34	FRONT DOOR WINDOW CHROME PIECE (R) <i>11 X</i>	2.00	0.00	0.00
35	FRONT DOOR WINDOW GARNISH - BLACK (R) <i>11 X</i>	1.00	0.00	0.00
36	FRONT DOOR LOCK (R) <i>11 X</i>	1.00	0.00	0.00
37	FRONT RIM (R) <i>R X</i>	1.00	0.00	0.00 <i>955.90</i>
38	FRONT ABSORBER (R) <i>11 X</i>	1.00	0.00	0.00 <i>674.10</i>
39	FRONT KNUCKLE (R) <i>11 X</i>	1.00	0.00	0.00 <i>659.74</i>
40	FRONT BEARING (R) <i>11 X</i>	1.00	0.00	0.00 <i>678.70</i>
41	FRONT LOWER ARM (R) <i>11 X</i>	1.00	0.00	0.00 <i>575.00</i>
42	SUPPORT PANEL <i>11 X</i>	1.00	0.00	0.00 <i>967.00</i>
43	CONDENSER <i>11 X</i>	1.00	0.00	0.00 <i>1130.00</i>
44	RADIATOR <i>11 X</i>	1.00	0.00	0.00 <i>1050.00</i>

Amt S\$ 0.00
Discount (5.00%) S\$ 0.00
Subtotal S\$ 0.00

Section: Special Nett Items

45 FRONT TYRE *11 X* 1.00 600.00 600.00

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Continue on next page...

Noted Abdul
2/3 to 4400
5/3 to 4400
Take photo after 10/3
Maxine (JRE)
PAGE 2 OF 3



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJY691E
Make & Model : B.M.W., 520i AUTO ABS AIRBAG 2WD XENON
HEADLAMP, WBANT12040CX29601
Year of Manufacture : 2008

Estimation No. : E18030062
DOA : 20/03/2018

No	Description	Qty	U/P	Amt
			Amt	S\$ 600.00
			Discount (0.00%)	S\$ 0.00
			Subtotal	S\$ 600.00
Section: Labour Items				
46	TO R&R ACCIDENT AFFECTED AREAS	1.00	1,500.00	1,500.00
47	TO PUTTY & RESPRAY ACCIDENT AFFECTED AREAS	1.00	1,300.00	1,300.00
48	TO RUST PROOF ACCIDENT AFFECTED AREAS	1.00	90.00	90.00
49	TO R&R FRONT BUMPER SENSOR AND CHECK FUNCTION	1.00	80.00	80.00
50	TO R&R FRONT DOOR MECHANISM	1.00	80.00	80.00
51	TO CHECK WIRING LAYOUT & HEAD LAMP FOCUS	1.00	100.00	100.00
52	TO R&R AIRCON CONDENSER AND REFILL GAS	1.00	200.00	200.00
53	TO R&R FRONT UNDERCARRIAGE	1.00	300.00	300.00
54	TO CHECK WATER SEEPAGE	1.00	100.00	100.00
55	TO CHECK WHEEL ALIGNMENT	1.00	180.00	180.00

Amt S\$ 3,930.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 3,930.00

P. 4137.20-57
= 3930.39

SN: 0

2: 1600.80

5510.39

* 1/1 @ 4920 repair day

List Items Subtotal S\$ 0.00
Special Nett Items Subtotal S\$ 600.00
Labour Items Subtotal S\$ 3,930.00
Total S\$ 4,530.00



No 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

Torque 5 Pte Ltd

ESTIMATION REPORT

Vehicle No : SJY691E
Make & Model : B.M.W., 520i AUTO ABS AIRBAG 2WD XENON
HEADLAMP, WBANT12040CX29601
Year of Manufacture : 2008

Estimation No. : E18030062
DOA : 20/03/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	FRONT BUMPER 1 X	1.00	0.00	0.00
2	FRONT BUMPER CLIPS 4 X	10.00	0.00	0.00
3	FRONT BUMPER RETAINER (R) 1 X	1.00	0.00	0.00
4	FRONT BUMPER BRACKET (R) 1 X	1.00	0.00	0.00
5	FRONT BUMPER REINFORCEMENT 1 X	1.00	0.00	0.00
6	FRONT BUMPER SPONGE 1 X	1.00	0.00	0.00
7	FRONT BUMPER INNER CENTRE GARNISH 1 X	1.00	0.00	0.00
8	FRONT BUMPER FOG LAMP (R) 1 X	1.00	0.00	0.00
9	FRONT BUMPER FOG LAMP GARNISH (R) 1 X	1.00	0.00	0.00
10	FRONT BUMPER LOWER GRILLE 1 X	1.00	0.00	0.00
11	FRONT BUMPER SENSOR 1 X	2.00	0.00	0.00
12	FRONT BUMPER WIPER NOZZLE (R) 1 X	1.00	0.00	0.00
13	FRONT BUMPER WIPER NOZZLE CAP (R) 1 X	1.00	0.00	0.00
14	FRONT KIDNEY GRILLE (R) 1 X	1.00	0.00	0.00
15	FRONT KIDNEY GRILLE CLIPS (R) 1 X	5.00	0.00	0.00
16	FRONT FENDER (R) 1 ✓	1.00	0.00	0.00
17	FRONT FENDER SIGNAL LAMP (R) 1 ✓	1.00	0.00	0.00
18	FRONT FENDER COWLING (R) 1 ✓	1.00	0.00	0.00
19	FRONT FENDER COWLING CLIPS (R) 1 ✓	10.00	0.00	0.00
20	FRONT FENDER INNER PANEL (R) 1 X	1.00	0.00	0.00
21	SIDE MIRROR ASSY (R) 1 X	1.00	0.00	0.00
22	ROCKER PANEL (R) 1 X ✓	1.00	0.00	0.00
23	HEAD LAMP (R) 1 X	1.00	0.00	0.00
24	HEAD LAMP CLIPS (R) 1 X	2.00	0.00	0.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJY691E
Make & Model : B.M.W., 520I AUTO ABS AIRBAG 2WD XENON
HEADLAMP, WBANT12040CX29601
Year of Manufacture : 2008

Estimation No. : E18030062
DOA : 20/03/2018

No	Description	Qty	U/P	Amt
25	FRONT DOOR (R) <i>DO ✓</i>	1.00	0.00	0.00
26	FRONT DOOR HINGE-UP (R) <i>Tw ✓</i>	1.00	0.00	0.00
27	FRONT DOOR HINGE-DOWN (R) <i>Tw ✓</i>	1.00	0.00	0.00
28	FRONT DOOR CHECKER (R) <i>11 X</i>	1.00	0.00	0.00
29	FRONT DOOR WEATHER STRIP (R) <i>re ✓</i>	1.00	0.00	0.00
30	FRONT DOOR INNER WEATHER STRIP (R) <i>re ✓</i>	1.00	0.00	0.00
31	FRONT DOOR POWER WINDOW MOTOR (R) <i>11 X</i>	1.00	0.00	0.00
32	FRONT DOOR POWER WINDOW GEARS (R) <i>11 X</i>	1.00	0.00	0.00
33	FRONT DOOR WINDOW MOULDING (R) <i>11 X</i>	1.00	0.00	0.00
34	FRONT DOOR WINDOW CHROME PIECE (R) <i>11 X</i>	2.00	0.00	0.00
35	FRONT DOOR WINDOW GARNISH - BLACK (R) <i>11 X</i>	1.00	0.00	0.00
36	FRONT DOOR LOCK (R) <i>11 X</i>	1.00	0.00	0.00
37	FRONT RIM (R) <i>R X</i>	1.00	0.00	0.00
38	FRONT ABSORBER (R) <i>11 X</i>	1.00	0.00	0.00
39	FRONT KNUCKLE (R) <i>11 X</i>	1.00	0.00	0.00
40	FRONT BEARING (R) <i>11 X</i>	1.00	0.00	0.00
41	FRONT LOWER ARM (R) <i>11 X</i>	1.00	0.00	0.00
42	SUPPORT PANEL <i>11 X</i>	1.00	0.00	0.00
43	CONDENSER <i>11 X</i>	1.00	0.00	0.00
44	RADIATOR <i>11 X</i>	1.00	0.00	0.00

Amt S\$ 0.00
Discount (5.00%) S\$ 0.00
Subtotal S\$ 0.00

Section: Special Nett Items

45	FRONT TYRE <i>11 X</i>	1.00	600.00	600.00
----	------------------------	------	--------	--------

Continue on next page...

Not Authorised

2/3 Saty

Take photo. After 18/3



No.8 Kaki Bukit Ave 4, Premier @ Kaki
Tel: +65 6452 4457 | Fax: +65 6452 4584

ESTII

Estim
DOA

Vehicle No : SJY691E
Make & Model : B.M.W., 520i AUTO ABS AIRBAG 2WD XENON
HEADLAMP, WBANT12040CX29601
Year of Manufacture : 2008

0.0
600.00
800.00
60.00
60.00
20.00
60.00
1,600.00

314
t

No	Description	Qty
----	-------------	-----

Amt	S\$ 600.00
Discount (0.00%)	S\$ 0.00
Subtotal	S\$ 600.00

Section: Labour Items

46	TO R&R ACCIDENT AFFECTED AREAS	1.00	1,500.00	1,500.00
47	TO PUTTY & RESPRAY ACCIDENT AFFECTED AREAS	1.00	1,300.00	1,300.00
48	TO RUST PROOF ACCIDENT AFFECTED AREAS	1.00	90.00	90.00
49	TO R&R FRONT BUMPER SENSOR AND CHECK FUNCTION	1.00	80.00	80.00
50	TO R&R FRONT DOOR MECHANISM	1.00	80.00	80.00
51	TO CHECK WIRING LAYOUT & HEAD LAMP FOCUS	1.00	100.00	100.00
52	TO R&R AIRCON CONDENSER AND REFILL GAS	1.00	200.00	200.00
53	TO R&R FRONT UNDERCARRIAGE	1.00	300.00	300.00
54	TO CHECK WATER SEEPAGE	1.00	100.00	100.00
55	TO CHECK WHEEL ALIGNMENT	1.00	180.00	180.00

Amt	S\$ 3,930.00
Discount (0.00%)	S\$ 0.00
Subtotal	S\$ 3,930.00

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before and after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer
Signature:
Date:

List Items Subtotal	S\$ 0.00
Special Nett Items Subtotal	S\$ 600.00
Labour Items Subtotal	S\$ 3,930.00
Total	S\$ 4,530.00

2194129

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Mar 2018		21 Mar 2018: 15:31 Edit Adj Rpt	\$54,400.00 Edit Estimates	\$54,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Mohd Fahmie Bin Senen , ID: 576026672								
Main Claimant:	Yep Cheong Kul , ID: S68322793								
Vehicle Reg. No.:	SJY691E	Date of Loss:	20/03/2018 09:00 - :59 [112 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-000421	Policy/Cover Note No.:	MSD/VMS/17-371830-CA Coverage: 20/09/2017 - 19/09/2018						
Vehicle Reg. No. (Insured):	FX2003G	Policy No. (Claimant):							
		Excess:							
Repairer:	Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4, #01-50, 415875 Kaki Bukit - Tel: 64524457								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/04/2018]								
Adj Asg. Remarks:	Please assign to Mr Adrian Ling. Thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJY691E (MSC/V/18-000421)**
[FX2003G]
TP
Yep Cheong Kui
Mar 20 2018 9:00AM
[Mohd Fahmie Bin Senen]
Torque 5 Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/04/18 15:52	Adjuster Immediate Advice	 Load HTML	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/03/18 17:51	General View	 Load JPG	☒
2	27/03/18 17:51	General View	 Load JPG	☒
3	27/03/18 17:51	General View	 Load JPG	☒
4	27/03/18 17:51	General View	 Load JPG	☒
5	27/03/18 17:51	General View	 Load JPG	☒
6	27/03/18 17:51	General View	 Load JPG	☒
7	27/03/18 17:51	General View	 Load JPG	☒
8	27/03/18 17:51	General View	 Load JPG	☒
9	27/03/18 17:51	General View	 Load JPG	☒
10	27/03/18 17:51	General View	 Load JPG	☒
11	27/03/18 17:51	General View	 Load JPG	☒
12	27/03/18 17:51	General View	 Load JPG	☒
13	27/03/18 17:51	General View	 Load JPG	☒
14	27/03/18 17:51	General View	 Load JPG	☒
15	27/03/18 17:51	General View	 Load JPG	☒
16	27/03/18 17:51	General View	 Load JPG	☒
17	27/03/18 17:51	General View	 Load JPG	☒
18	27/03/18 17:51	General View	 Load JPG	☒
19	27/03/18 17:51	General View	 Load JPG	☒
20	27/03/18 17:51	General View	 Load JPG	☒
21	27/03/18 17:51	General View	 Load JPG	☒
22	27/03/18 17:51	General View	 Load JPG	☒
23	27/03/18 17:51	General View	 Load JPG	☒
24	27/03/18 17:51	General View	 Load JPG	☒
25	27/03/18 17:51	General View	 Load JPG	☒
26	27/03/18 17:51	General View	 Load JPG	☒
27	27/03/18 17:51	General View	 Load JPG	☒
28	27/03/18 17:51	General View	 Load JPG	☒
29	27/03/18 17:51	General View	 Load JPG	☒
30	27/03/18 17:51	General View	 Load JPG	☒
31	27/03/18 17:51	General View	 Load JPG	☒
32	27/03/18 17:51	General View	 Load JPG	☒
33	27/03/18 17:51	General View	 Load JPG	☒
34	27/03/18 17:51	General View	 Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	27/03/18 17:51	General View	 Load JPG	☒
36	27/03/18 17:51	General View	 Load JPG	☒
37	27/03/18 17:51	General View	 Load JPG	☒
38	27/03/18 17:51	General View	 Load JPG	☒
39	27/03/18 17:51	General View	 Load JPG	☒
40	27/03/18 17:51	Odometer Reading	 Load JPG	☒
41	27/03/18 17:52	General View	 Load JPG	☒
42	27/03/18 17:52	Chassis Number	 Load JPG	☒
43	27/03/18 17:52	General View	 Load JPG	☒
44	27/03/18 17:52	General View	 Load JPG	☒
45	27/03/18 17:52	General View	 Load JPG	☒
46	27/03/18 17:52	General View	 Load JPG	☒
47	27/03/18 17:52	General View	 Load JPG	☒
48	27/03/18 17:52	General View	 Load JPG	☒
49	27/03/18 17:52	General View	 Load JPG	☒
50	27/03/18 17:52	Reinspection Photo	 Load JPG	☒
51	27/03/18 17:52	Reinspection Photo	 Load JPG	☒
52	27/03/18 17:52	Reinspection Photo	 Load JPG	☒
53	27/03/18 17:52	Reinspection Photo	 Load JPG	☒
54	27/03/18 17:52	Reinspection Photo	 Load JPG	☒
55	27/03/18 17:52	Reinspection Photo	 Load JPG	☒
56	27/03/18 17:52	Reinspection Photo	 Load JPG	☒
57	27/03/18 17:52	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/03/18 10:56	SJY691E - GIA REPORT	 Load PDF	
2	21/03/18 10:56	PRI Notice	 Load PDF	
3	21/03/18 15:31	TP Agree on SJE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005386/UTD3Q2

Date: 26/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/17-371830-CA
Claimant Vehicle No :	SJY691E	Insured Vehicle No :	FX2003G
Date of Loss:	20/03/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000421

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY691E		
Make & Model:	BMW 520i, 2.0 ABS AIRBAG 2WD XENON HEADLAMP (A)	Engine No:	A639I250N46B20BE
Reg. Date:	30/10/2008 (Man. Year: 2008)	Chassis No:	WBANT12040CX29601
Colour:	Black	Odometer:	115863 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,818.30	3,930.34	14,887.96	79.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,930.00	1,600.00	2,330.00	59.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,748.30	5,530.34	17,217.96	75.69
Approved Total (Overridden) (S\$)		4,400.00		
(S\$)	22,748.30	4,400.00	18,348.30	80.66
+ GST 7.00/7.00% (S\$)	1,592.38	308.00	1,284.38	80.66
Nett Amount (S\$)	24,340.68	4,708.00	19,632.68	80.66

INSPECTION

Date of Assignment:	21/03/2018		
Date Inspected:	23/03/2018	Inspected At:	Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4., #01-50 Singapore 415875
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Apr 2018)
Parts:	143	BMW 520I 2.0 ABS AIRBAG 2WD XENON HEADLAMP (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY691E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Repair	1,650.00 F	*-FL
2	10	*FRONT BUMPER CLIPS	Not Necessary	50.00 F	*-FL
3	1	*FRONT BUMPER RETAINER (R)	Not Necessary	25.00 F	*-FL
4	1	*FRONT BUMPER BRACKET (R)	Not Necessary	25.00 F	*-FL
5	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	750.00 F	*-FL
6	1	*FRONT BUMPER SPONGE	Not Necessary	58.50 F	*-FL
7	1	*FRONT BUMPER INNER CENTRE GARNISH	Not Necessary	285.20 F	*-FL
8	1	*FRONT BUMPER FOG LAMP (R)	Not Necessary	307.10 F	*-FL
9	1	*FRONT BUMPER FOG LAMP GARNISH (R)	Not Necessary	89.00 F	*-FL
10	1	*FRONT BUMPER LOWER GRILLE	Not Necessary	95.40 F	*-FL
11	2	*FRONT BUMPER SENSOR	Not Necessary	541.00 F	*-FL
12	1	*FRONT BUMPER WIPER NOZZLE (R)	Not Necessary	175.00 F	*-FL
13	1	*FRONT BUMPER WIPER NOZZLE CAP (R)	Not Necessary	60.00 F	*-FL
14	1	*FRONT KIDNEY GRILLE (R)	Not Necessary	272.20 F	*-FL
15	5	*FRONT KIDNEY GRILLE CLIPS (R)	Not Necessary	25.00 F	*-FL
16	1	*FRONT FENDER (R)	Dented	927.50 F	*927.50 FL
17	1	*FRONT FENDER SIGNAL LAMP (R)	Scratched	49.20 F	*49.20 FL
18	1	*FRONT FENDER COWLING (R)	Torn	161.20 F	*161.20 FL
19	10	*FRONT FENDER COWLING CLIPS (R)	Necessary	50.00 F	*50.00 FL
20	1	*FRONT FENDER INNER PANEL (R) (NPA)	Repair	0.00 F	*-FL
21	1	*SIDE MIRROR ASSY(R) (NPA)	Repair	0.00 F	*-FL
22	1	*ROCKER PANEL GARNISH (R)	Cut	456.70 F	*456.70 FL
23	1	*HEAD LAMP (R)	Not Necessary	2,820.00 F	*-FL
24	2	*HEAD LAMP CLIPS (R)	Not Necessary	10.00 F	*-FL
25	1	*FRONT DOOR (R)	Dented	1,622.90 F	*1,622.90 FL
26	1	*FRONT DOOR HINGE -UP(R)	Twisted	215.00 F	*215.00 FL
27	1	*FRONT DOOR HINGE -DOWN(R)	Twisted	215.00 F	*215.00 FL
28	1	*FRONT DOOR CHECKER (R)	Not Necessary	202.00 F	*-FL
29	1	*FRONT DOOR WEATHER STRIP (R)	Necessary	250.00 F	*250.00 FL
30	1	*FRONT DOOR INNER WEATHERSTRIP (R)	Necessary	189.70 F	*189.70 FL
31	1	*FRONT DOOR POWER WINDOW MOTOR (R) (NPA)	Not Necessary	0.00 F	*-FL
32	1	*FRONT DOOR POWER WINDOW GEARS (R) (NPA)	Not Necessary	0.00 F	*-FL
33	1	*FRONT DOOR WINDOW MOULDING (R) (NPA)	Not Necessary	0.00 F	*-FL
34	2	*FRONT DOOR WINDOW CHROME PIECE (R) (NPA)	Not Necessary	0.00 F	*-FL
35	1	*FRONT DOOR WINDOW GARNISH -BLACK (R) (NPA)	Not Necessary	0.00 F	*-FL
36	1	*FRONT DOOR LOCK (R) (NPA)	Not Necessary	0.00 F	*-FL
37	1	*FRONT RIM(R)	Repair	955.70 F	*-FL
38	1	*FRONT ABSORBER (R)	Not Necessary	674.10 F	*-FL
39	1	*FRONT KNUCKLE (R)	Not Necessary	659.70 F	*-FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT BEARING (R)	Not Necessary	628.70 F	*-FL
41	1		*FRONT LOWER ARM (R)	Not Necessary	575.00 F	*-FL
42	1		*SUPPORT PANEL	Not Necessary	967.50 F	*-FL
43	1		*CONDENSER	Not Necessary	1,130.00 F	*-FL
44	1		*RADIATOR	Not Necessary	1,050.00 F	*-FL
45	1		*FRONT TYRE	Not Necessary	600.00 FS	*-FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	18,818.30	4,137.20
				- List Item Discount on L Items 0.00/5.00% (S\$)	0.00	206.86
				Total Parts (S\$)	18,818.30	3,930.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R ACCIDENT AFFECTED AREAS	New	1,500.00	600.00
2	TO PUTTY & RESPRAY ACCIDENT AFFECTED AREAS	New	1,300.00	800.00
3	TO RUST PROOF ACCIDENT AFFECTED AREAS	New	90.00	60.00
4	TO R&R FRONT BUMPER SENSOR AND CHECK FUNCTION	New	80.00	0.00
5	TO R&R FRONT DOOR MECHANISM	New	80.00	60.00
6	TO CHECK WIRING LAYOUT & HEAD FOCUS	New	100.00	20.00
7	TO R&R AIRCON CONDENSER AND REFILL GAS	New	200.00	0.00
8	TO R&R FRONT UNDERCARRIAGE	New	300.00	0.00
9	TO CHECK WATER SEEPAGE	New	100.00	0.00
10	TO CHECK WHEEL ALIGNMENT	New	180.00	60.00
Gross Labour Cost (S\$)			3,930.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >