

ASS. REC. BY:

REF:

CG/SPF18005392/Dgb

Special Instruction:

Survivor: Bryan

ASSIGNMENT (Office)

From (Person): Abdul Rahman

of

SPF

Date/Time:

22032018

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGP 2903P

Insured:

Tp 999Y

at Workshop m/s

Chew Guan Motor

Tel:

6484 1626

of

Blk 10 Amk Ind Park 2A #01-15

Policy No:

Claim No:

AEMD/105/009/2018/028

Sum Insured:

Excess:

Make of Veh:

D.O.A

20032018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

22032018 1025am

Person Contacted:

Grace

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

Do Not Forget

SGP 2903P - x

TP 999Y - x

REF:

REFERENCE

ASSIGNMENT

CoE Dec 2021

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No _____

Claims No _____

Sum Insured _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No SGP 2903 P 1st Regn 2006 Dec
 Type: M/C / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make Toyota Corolla Altis c.c. 1598Colour Blue A/C Insured / Std / NI / NASp. Reading 173815 T/Radio: Insured / Std / NI / NAEng/No 3224620281C/No: MR053ZEC107137369Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRM / STD A/Rim orTyre Size: F: 185/70 R14R: — — —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 20/03/2018 D.O.I. 22/03/2018Survey held at Chew Goon Motor AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SPF TP 999 YMV 24KLTA 19KNL 5K10/04/18

To submit 2/3 32001- with 5 dgs 2 m
 (Red @ 1932.98, 38%)

RECEIVED 10 APR 2018

Date/Time, File Pass to:



: Preli. Report

11/10/18 Amis

: Final Report

Date/Time, File Return to:

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

1. S + PS: 14

1. Phone

1. Other

1. Other

1. Other

Add Fee:



Site Insp. 1\$



Interview 1\$



Tech. Insp. 1\$



Weathered 1\$

Report Format: 71Lump Sum / I.B.F.: 3200

380



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18005392/Dqb		
ACCIDENT CLAIM SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 22-03-2018		
		Code : SPF		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	TP 999Y	Veh. Inspected	SGP 2903P	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2018/028	Excess (\$)	0.00	
Assign From	ABDUL RAHMAN	Assign Date	22/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/03/2018	Inspection Date	22/03/2018	
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/03/2018 10:28
Date Of Accident	20/03/2018 08:20
Exact Location Of Accident	CTE TWDS ANG MO KIO
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGP2903P
Insured/Policyholder	
Name Of Registered Owner	GOH SENG CHAI
NRIC No	S2561230B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98576896
Alternative Phone No	OTHERS-98576896
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5025042894-10 (TPFT)
Cover Note Number	
Driver	
Name of Driver	GOH SENG CHAI
NRIC No	S2561230B
Date Of Birth	05/11/1962
Occupation	INDOOR
Date Of Driving Pass	06/06/1991
Driving Experience	26 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98576896
Fax Number	
Contact Number	OTHERS-98576896
Email Address	NOEMAIL

Address	2-B HONG SAN WALK #12-04
Postcode	689048
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	AMK SOUTH NPC
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT NO. T/20180320/2022 ATTACHED. (ATTENDED BY CHRISTINA)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	TP999Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A - SGP 2903P

B - TP 999Y

DOA - 20/3/18

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

20 MAR 2018

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
HUC/PIN No.:





**SINGAPORE
POLICE FORCE**



T/20180320/2022

1 of 3

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

Report No. T/20180320/2022

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/03/2018 09:55		Vide Report No.: A/20180320/0049		Station Diary No.: 42	
Informant's Particulars					
Name of Informant: GOH SENG CHAI			Address: 2B HONG SAN WALK #12-04 SINGAPORE 689048		
ID Type / ID No.: NRIC NO / S2561230B			Contact No.: Home/Office: Mobile: 98576896		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 55	Date of Birth: 05/11/1962	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: MANAGER			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 20/03/2018 08:20	Type of Location: Straight Road
Location: Along Road 1 CENTRAL EXPRESSWAY				
AFTER SLE > CTE (AYE)				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Colour	Condition	No. of Passenger
SGP2903P	Car	TOYOTA	COROLLA ALTIS 1.6 AUTO	Silver	Slightly Damaged	0
TP999Y	Motorcycle				Slightly Damaged	0

Details of Vehicle Insurance					
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date	
SGP2903P	NTUC Income Insurance Co-Operative Limited	5025042694-10	12/12/2017	11/12/2018	



**SINGAPORE
POLICE FORCE**



T/20180320/2022

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

2 of 3

Report No. T/20180320/2022

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	GOH SENG CHAI	ID No.	S2561230B
Related Vehicle	SGP2903P (Car)	Contact No.	98576896
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 20/03/2018 at about 0820hrs, I was driving my vehicle along CTE towards to Ang Mo Kio at the first lane. The traffic was heavy and slow moving, while I was driving slowly suddenly I felt a small impact from the rear of my car and subsequently, came out of my car and discovered that it was one traffic police riding (TP999Y) who collided to the left bumper of my car and fell to the ground upon colliding. There were 2 vehicles stopped and assisted the traffic police officer and was informed that another traffic police will come to attend to the accident. After which, I was told to lodge a traffic police accident report. Nobody was injured during the accident however, the left bumper of my car was damaged.



**SINGAPORE
POLICE FORCE**



T/20180320/2022

3 of 3

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

Report No. T/20180320/2022

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 NICHOLAS LIM JIE KE	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 20/03/2018 09:55
Officer In Charge Of Case: TP / DDGVT / Staff Sgt LIM JUN HUI, ADRIAN Contact No.: 65476350	Classification Of Case: SN 035
Authentication Stamp NP168	

Policy Information

Page 1 of 1

Policy Information					
Policy No.	5025042894-10		Policyholder Name	GOH SENG CHAI	
Address	2-B HONG SAN WALK #12-04 PALM GARDENS SINGAPORE 689048		Policyholder NRIC	S25612308	
Product Name	PRIVATE CAR INSURANCE	Plan	Group Policy Flag N		
Policy Issue Date	01/12/2017	Effective Date	12/12/2017 00:00		
Third Party Excess	0	Own damage Excess	0	Expiry Date	11/12/2018 23:59
Additional Excess		OS Premium	0	Windscreen Excess	0
Outside Singapore OD Excess	0	Outside Singapore TP Excess	0		
Agent	TELESALES-DIRECT MARKETING		Agent Tel.		
Co-insurance Flag	No			GST Flag	Y
Open Policy Info					
Certificate Info					
Policyholder Mailing Address					
Address 1	2-B HONG SAN WALK		Address 2	#12-04 PALM GARDENS	
Address 4			Address Type	Singapore address	
Unit No.			Related Policy Number	5025042894-10	
Address 3 SINGAPORE 689048					
Post Code 689048					
Insured Object: SGP2903P					
Vehicle No.	SGP2903P	Model	COROLLA ALTIS	Make	TOYOTA
Vehicle Type	396	Date of Registration	12/12/2006		
Classis No.	MR053ZEC107137369	Engine No.	3ZZ4620281	Vehicle Capacity	
No. of Seats	5	Parallel Import	0	Imported/Reconditioned	0
Off peak car	0				
Coverage					
Coverage		Coverage Category	Sum Insured	Excess Description	Remark
Third Party, Fire & Theft	Own Damage by Fire		999,999,999.99		
Third Party, Fire & Theft	Loss or Own Damage by Theft		999,999,999.99		
Third Party, Fire & Theft	TP1		999,999,999.99		
Third Party, Fire & Theft	TP90		5,000,000.00		
Third Party, Fire & Theft		Third Party Fire & Theft Benefit	99,999,999.99		
Driver Information					
Driver Name	ID No.	Date of Birth	Driving License Reg Date	Role	
GOH SENG CHAI	S25612308	05/11/1962	01/01/2000	Main Driver	
Endorsements					
Sequence	Date of Endorsement	Endorsement Type	Endorsement Status	Endorsement Content	
<input type="button" value="Continue"/> <input type="button" value="Cancel"/>					

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2561230B



Name
GOH SENG CHAI

吳承才

Race
CHINESE

Date of Birth
08-11-1962

Sex
M

Country of Birth
MALAYSIA




REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S2561230B

Name
GOH SENG CHAI

Date of Birth: 05 Nov 1962

Issue Date: 23 Sep 2003




AB014882



MRIC No: S2561230B



Nationality
MALAYSIAN

Board Class: A+

Date of Issue: 17-12-1998

28 HONG SAN WALK #12-04
SINGAPORE 689048

MRIC No: S2561230B Date: 27-01-2001 No: 3871668

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	08 Jun 1991

NP428A



Licence No: S2561230B

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5025042894-10

Cover : Third Party, Fire & Theft

- | | |
|--|---------------------|
| 1. Index mark and Registration Number of Vehicle | : SGP2903P |
| Chassis Number | : MR0532EC107137369 |
| 2. Name of Policyholder | : GOH SENG CHAI |
| 3. Effective Date of Insurance | : 12 Dec 2017 |
| 4. Expiry Date of Insurance | : 11 Dec 2018 |

5. Persons or Classes of Persons entitled to drive#

- (a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

- (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

- (a) Use for hire or reward.
(b) Use for racing, pace-making, reliability trial or speed-testing.
(c) Use for the carriage of goods (other than samples) in connection with any trade or business.
(d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: N/A
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
PRIMARY DRIVER	: GOH SENG CHAI
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : TELESALLES-DIRECT MARKETING (00000601661)

Date of Issue : 01 Dec 2017 16:33 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **SPF Accident Claims Section**

Policy No: **Third Party**

Date: **21.03.2018**

Accident Date : 20.03.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Toyota Altis" Reg. No. SGP2903P Claiming Against Your Insured Reg. No. TP999Y			
1pc	Rear Bumper <i>SVL</i>		423.00 ✓
10pcs	Rear Bumper Clips <i>hlc</i>	3.80	38.00 ✓
1pc	Rear Bumper Top Retainer <i>SVL</i>		18.20 X
2pcs	Rear Bumper Corner Holders <i>SVL</i>	10.70	21.40 X
1pc	Taillamp Assy LH <i>mounting cradle</i>		386.00 ✓
1pc	Taillamp Gasket <i>SVL</i>		35.00 X
1pc	Taillamp Panel <i>BT</i>		297.00 ✓
1pc	Taillamp Lower Filler Panel <i>BT</i>		95.00 ✓
4pcs	Taillamp Lower Filler Panel Rivets <i>hlc</i>	2.80	11.20 ✓
1pc	Rear Fender LH <i>SVL</i>		790.00 ✓
1pc	Rear Fender Shield <i>SVL</i>		75.00 X
5pcs	Rear Fender Shield Clips <i>SVL</i>	3.80	19.00 X
1pc	Rear Fender Lower Air Vent <i>SVL</i>		106.00 X
1pc	Rear Windscreen Moulding <i>hlc</i>		75.60 ✓
2pcs	Fuel Lid Rivets <i>NH</i>	2.80	5.60 X
1pc	Boot Badge "1.6" <i>hlc</i>		35.60 ✓
1pc	Boot Badge "E" <i>hlc</i>		40.00 ✓
1pc	Boot Badge "VVTI" <i>hlc</i>		36.70 ✓
1pc	Boot Badge "Corolla" <i>hlc</i>		34.00 ✓
1pc	Boot Badge "Altis" <i>hlc</i>		35.00 ✓
			2,577.30
	Less 25%		644.33
			1,932.98
1pc	Rear Bumper Reverse Sensor <i>wire torn</i>		220/- 280.00 SN ✓
1pc	Rear Windscreen Sealant <i>hlc</i>		40/- 50.00 SN ✓
1pc	Rear Windscreen Sealer <i>hlc</i>		30.00 SN ✓
1pc	Rear Windscreen Fastener <i>4 x 8 NH</i>		50.00 SN X
	To Conduct Electrical Check, Replace Reverse Sensors, Module, Rewiring Etc		120.00 40/-
	To Dismantle / Refit Rear Windscreen Glass		150.00 120/-
	To Dismantle / Transfer Rear Spare Tyre Panel Inner Trims Boards / Garnish and Rear Fenders Inner Trims Boards / Garnish to Facilitate Repair		90.00 60/-
		C/F	2,702.98

2297.10
1722.82

290/-

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **SPF Accident Claims Section**

Policy No: **Third Party**

Date: **21.03.2018**

Accident Date : 20.03.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Altis" Reg. No. SGP2903P Claiming Against Your Insured Reg. No. TP999Y		
		B/F	2,702.98
	To Dismantle / Refit Roof Upholstery		120.00 NN
	To Dismantle / Refit Fuel Tank Inlet Hoses and Piping		100.00 NN
	To Supply Rear Panel Joint Sealant		60.00 40/-
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel	2000/-	50.00 40/-
	Labour Charge - Panel Beating, Replacement Of Boot Lid, Rear Fender Inner Panel, End Panel etc. Cnt. Weld Rear Fender and Parts Replacement		1,200.00 900/-
	To Spray Paint Affected Areas		900.00 800/-
		Total :	5,132.98
			4012.82
			215 3200/-
	22/03/2018 @ 1200m WOT Antennal 2/5mm 2/KK Auto 15 dgs. Photo after rep.		
		KK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18005392/Dqbg2

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE)
1 MOUNT PLEASANT ROAD
BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

Date : 11-04-2018



Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	TP 999Y	Veh. Inspected	SGP 2903P
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/028	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	22/03/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	MR053ZEC107137369	Colour	SILVER
Odometer	173815	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/70 R14	FALKEN	5 mm
L/H Front Tyre	185/70 R14	FALKEN	5 mm
R/H Rear Tyre	185/70 R14	FALKEN	5 mm
L/H Rear Tyre	185/70 R14	FALKEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	20/03/2018	Inspection Date	22/03/2018
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGP 2903P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BUCKLED	423.00	423.00
10	REAR BUMPER CLIPS @\$3.80	NECESSARY	38.00	38.00
1	REAR BUMPER TOP RETAINER	SERVICEABLE	18.20	-
2	REAR BUMPER CORNER HOLDERS @\$10.70	SERVICEABLE	21.40	-
1	TAILLAMP ASSY LH	MTG CRACKED	386.00	386.00
1	TAILLAMP GASKET	SERVICEABLE	35.00	-
1	TAILLAMP PANEL	BENT	297.00	297.00
1	TAILLAMP LOWER FILLER PANEL	BENT	95.00	95.00
4	TAILLAMP LOWER FILLER PANEL RIVETS @\$2.80	NECESSARY	11.20	11.20
1	REAR FENDER LH	BUCKLED	790.00	790.00
1	REAR FENDER SHIELD	SERVICEABLE	75.00	-
5	REAR FENDER SHIELD CLIPS @\$3.80	SERVICEABLE	19.00	-
1	REAR FENDER LOWER AIR VENT	SERVICEABLE	106.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	75.60	75.60
2	FUEL LID RIVETS @\$2.80	NOT NECESSARY	5.60	-
1	BOOT BADGE '1.6'	NECESSARY	35.60	35.60
1	BOOT BADGE 'E'	NECESSARY	40.00	40.00
1	BOOT BADGE 'VVT'	NECESSARY	36.70	36.70
1	BOOT BADGE 'COROLLA'	NECESSARY	34.00	34.00
1	BOOT BADGE 'ALTIS'	NECESSARY	35.00	35.00
	LESS 25% DISCOUNT		-644.33	-574.28
			1,932.97	1,722.82
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER REVERSE SENSOR (SN)	WIRE TORN	280.00	220.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR WINDSCREEN SEALER (SN)	NECESSARY	30.00	30.00
1	REAR WINDSCREEN FASTENER (SN)	NOT NECESSARY	50.00	-
			410.00	290.00
<u>LABOUR</u>				
	TO CONDUCT ELECTRICAL CHECK ,REPLACE REVERSE SENSORS ,MODULE ,REWIRING ETC.		120.00	40.00
	TO DISMANTLE /REFIT REAR WINDSCREEN GLASS.		150.00	120.00

Report Ref No. CS/SPF18005392/Dqbg2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE /TRANSFER REAR SPARE TYRE PANEL INNER TRIMS BOARDS /GARNISH AND REAR FENDERS INNER TRIMS BOARDS /GARNISH TO FACILITATE REPAIR.		90.00	60.00
	TO DISMANTLE /REFIT ROOF UPHOLSTERY.	NOT NECESSARY	120.00	-
	TO DISMANTLE /REFIT FUEL TANK INLET HOSES AND PIPING.	NOT NECESSARY	100.00	-
	TO SUPPLY REAR PANEL JOINT SEALANT .		60.00	40.00
	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL.		50.00	40.00
	LABOUR CHARGE-PANEL BEATING ,REPLACEMENT OF BOOT LID ,REAR FENDER INNER PANEL,EN PANEL ETC.CNT,WELD REAR FENDER AND PARTS REPLACEMENT .		1,200.00	900.00
	TO SPRAY PAINT AFFECTED AREAS.		900.00	800.00
			2,790.00	2,000.00
GRAND TOTAL			5,132.97	4,012.82
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00

Report Ref No. CS/SPF18005392/Dqbg2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.