

ASS. REC. BY:

REF: CS3/CTI18005399/Gd3dr

Special Instruction:

range & days

Surveyor:
Mennen

ASSIGNMENT (Office)

From (Person):

Jowyn Tay

of

CTI

Date/Time:

22/3/18 @ 10:17am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 6758S

Insured:

82851304

at Workshop m/s

TG 2K Spray Painting

Tel:

6841 4220

of

Blk 1010, Blk Merah Lane 3 # 01-117

Policy No:

DMPCS N3003231800

Claim No:

SNM18D 01485C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19/03/2018

(Client's Record)

23/03/2018

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

lwp?

Date/Time:

22pm @ 22/3/18

Person Contacted:

Yeo Ying

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

SLN 6758S - X

8285130 H-CS/FCI18005273/Kgd3

D.O.A.: 19/3/2018

Dismantle: 23/3/2018

After repair: 27/3/2018

PRS

REF: CTI

6585G

ASSIGNMENT

From:

Date: 23/3/18

Estimated Cost:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLN 67585

at Workshop m/s

TG 2K Spray Painting

of BIK 1010, Bkt Merah Lane 3 # 01-117

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{Wp}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SLN 67585

Yr Regn:

12 May 2017

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

C.C. 1597

Colour:

Red

A/C Insured / Std / NI / NA

Sp. Reading:

27611

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR FHF C565 0GT 001 375

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/40 8R18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

23-03-18

Survey held at

W/S

5:30pm

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Repair Estimate : S\$ 3500 - 4500

* 4 days

RECEIVED 21 MAY 2018

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

150

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

150

Report Format:

PRS

Lump Sum / I.B.I. (\$) :

Add Fee:

☐

Site Insp. (\$)

☐

Interview (\$)

☐

Tech. Insp. (\$)

☐

Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Mar 2018		22 Mar 2018 10:17 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SIM BOON KHENG (SHEN WENQING), ID: S7426293G		
Main Claimant:	HO KAY THIAM, ID: S1656585G		
Vehicle Reg. No.:	SLN6758S	Date of Loss:	19/03/2018 08:00 - :59
Claim Type:	TP / SNM18D01485C02	Policy/Cover Note No.:	DMPCSN3003231800 (Comprehensive)
Vehicle Reg. No. (Insured):	SLS5130H	Policy No. (Claimant):	10751083
		Excess:	S\$0.00
Repairer:	Tg 2k Spray Painting Centre () Blk 1010 Bukit Merah Lane 3, #01-117, 159724 Bukit Merah - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/04/2018]		
Driver/Custodian (Insured):	SIM BOON KHENG (SHEN WENQING) (43 / Male), NRIC: S7426293G		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Your Insured's vehicle ; ref: SLS 5130H; SNM18D01485C02

Our client's vehicle ; ref: SLN 6758S; TG /sy

Date : 21 March 2018

China Taiping Insurance (Singapore) Pte Ltd

By Email Only

Dear Sirs,

DATE OF ACCIDENT: 19 MARCH 2018

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email of even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our list of surveyors as appended below:-

S/N	Name of Surveyor	Company Name
1.	Andrew How	Prominent Appraiser Services Pte Ltd
2.	Ananda Kumar	United Appraisal & Management Pte Ltd
3.	Tan Ee Cherng	United Appraisal & Management Pte Ltd
4.	T. Thiyagarajan	ST Appraisal Services
5.	Francis Ng	Prestige Appraisal Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which we will commence repairs thereafter without any further notice or reference to you. Please also let us know if you required a Post-Repair Survey/Inspection for our client's consideration. Please be informed that the said vehicle can be surveyed / inspected at:

Workshop : TG 2K Spray Painting Centre
Address : Block 1010 Bukit Merah Lane 3
#01-117
Singapore 159724
Contact : Karen or Yong Ying / Tel: 6841 4220 / Fax: 6744 2935

Kindly acknowledge upon inspection in the acknowledgement box below.

Yours sincerely,

Acknowledgement

This is to confirm that I _____ [Full Name of Surveyor] of _____ [Surveyor's Company] have completed as follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Signature of Appointed Surveyor _____
Company Stamp _____
Witnessed by: _____
Date _____

(b) Pre- Repair Survey/Inspection (after dismantling) on _____ [Date] at _____ [Time].

Signature of Appointed Surveyor _____
Company Stamp _____
Witnessed by: _____
Date _____

(c) Post - Repair Survey/Inspection on _____ [Date] at _____ [Time].

Signature of Appointed Surveyor _____
Company Stamp _____
Witnessed by: _____
Date _____

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6585G
Vehicle Details	
Vehicle No.:	SLN6758S
Vehicle to be Exported:	No
Intended De-registration Date:	26 Mar 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	R16B21601674
Chassis No.:	MRHFC5650GT001375
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$20,566.00
Original Registration Date:	12 May 2017
First Registration Date:	12 May 2017
Transfer Count:	0
Actual ARF Paid:	\$20,793.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 May 2027
PARF Rebate Amount:	\$15,594.00
Intended COE Rebate Details	
COE Expiry Date:	11 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,000.00
COE Rebate Amount:	\$47,444.00
Total Rebate Amount:	\$63,038.00

The information contained herein is correct as at 26 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/03/2018 15:28
Date Of Accident	19/03/2018 08:45
Exact Location Of Accident	ALONG PUNGGOL RD SLIP RD TO TPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN6758S
Insured/Policyholder	
Name Of Registered Owner	HO KAY THIAM
NRIC No	S1656585G
Email Address	KAYTHIAMHO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97290010
Alternative Phone No	OFFICE-97290010

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC 1.6 1597CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10751083
Cover Note Number	N.A.

Driver

Name of Driver	HO KAY THIAM
NRIC No	S1656585G
Date Of Birth	08/03/1964
Occupation	INDOOR
Date Of Driving Pass	16/04/1984
Driving Experience	33 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97290010
Fax Number	
Contact Number	OFFICE-97290010
Email Address	KAYTHIAMHO@GMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG PUNGGOL RD TOWARDS TPE AND I WAS DRIVING AT THE SLIP RD. I WAS THE FIRST CAR IN FRONT OF THE STOP LINE TO CHECK IN COMING CAR FROM RIGHT. SUDDENLY, I FELT AN IMPACT FROM REAR SO I CAME DOWN AND CHECK. VEHICLE B COLLIDED ONTO MY REAR PORTION. THEN VEHICLE C COLLIDED ONTO VEHICLE B REAR PORTION. WE TOOK PHOTO AND EXCHANGED PARTICULARS. NO INJURIES INVOLVED. THIS IS A THREE VEHICLE CHAIN COLLIDED ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS5130H
Vehicle Make/Model/Colour	LEXUS/ IS250/ BLACK
Details Of Properties	NA
Vehicle Category	PRIVATE CAR
Name of Driver	SIM BOON KHENG
NRIC/Passport Number	S7426293G
Contact Number	91161901
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHD8517H
Vehicle Make/Model/Colour	HYUNDAI/ YELLOW
Details Of Properties	NA
Vehicle Category	TAXI
Name of Driver	PETER LOO KONG SOON
NRIC/Passport Number	S1506768C
Contact Number	97322127
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

19/3/19
12:45

VERIFIED BY AJAX MARS
REPORTING OFFICER
THOMAS NG CHIN CHUN

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

		A: SLN67585 B: SL5130H C: SHD8517H
		TPE

Sketch Plan #2

ACCIDENT STATEMENT (2000 characters)

I WAS DRIVING ALONG PUNGGOL RD TOWARDS TPE AND I WAS DRIVING AT THE SLIP RD. I WAS THE FIRST CAR IN FRONT OF THE STOP LINE TO CHECK IN COMING CAR FROM RIGHT. SUDDENLY, I FELT AN IMPACT FROM REAR SO I CAME DOWN AND CHECK. VEHICLE B COLLIDED ONTO MY REAR PORTION. THEN VEHICLE C COLLIDED ONTO VEHICLE B REAR PORTION. WE TOOK PHOTO AND EXCHANGED PARTICULARS. NO INJURIES INVOLVED. THIS IS A THREE VEHICLE CHAIN COLLIDED ACCIDENT.

Taxi Voucher No.:

Are you claiming your own insurance policy for the repair of your vehicle?

No, Claim 3rd party

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
NG CHIN CHUN

MARS Officer:



Registered Owner or Driver's Signature

Job Complete Date/Time

19 March 2018 at 12:47 PM

Date/Time:

19 March 2018 at 12:47 PM

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Mar 2018		22 Mar 2018 10:17 Edit Adj Rpt	\$40.00 Edit Estimates	\$40.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SIM BOON KHENG (SHEN WENQING), ID: S7426293G								
Main Claimant:	HO KAY THIAM, ID: S1656585G								
Vehicle Reg. No.:	SLN6758S	Date of Loss:	19/03/2018 08:00 - :59 [10 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D01485C02	Policy/Cover Note No.:	DMPCSN3003231800 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLS5130H	Policy No. (Claimant):	10751083						
		Excess:	\$40.00						
Repairer:	Tg 2k Spray Painting Centre () Blk 1010 Bukit Merah Lane 3, #01-117, 159724 Bukit Merah - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 03/04/2018]								
Driver/Custodian (Insured):	SIM BOON KHENG (SHEN WENQING) (43 / Female), NRIC: S7426293G								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
View All Compose Case Mail									
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN6758S (SNM18D01485C02)
[SLS5130H]
TP
HO KAY THIAM
Mar 19 2018 8:00AM
[SIM BOON KHENG (SHEN WENQING)]
Tg 2k Spray Painting Centre

View View in Browser

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

1 per page 1 ☒

Assessment Reports			Thumbnail	Print
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		
1	19/03/18 15:35	Accident Statement	Load HTM	<input checked="" type="checkbox"/>

3 per page 3 ☒

Photos/Images			Thumbnail	Print
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		
1	19/03/18 15:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	19/03/18 15:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	19/03/18 15:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	19/03/18 15:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	19/03/18 15:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	19/03/18 15:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	19/03/18 15:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	19/03/18 15:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	19/03/18 15:34	Driving License [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	19/03/18 15:34	Driving License [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/05/18 10:30	General View	Load PDF	
2	18/05/18 10:31	Photographs of Damaged Parts	Load PDF	
3	18/05/18 10:31	Photo After Spray	Load PDF	

1 per page 1 ☒

Documentation			Thumbnail	Print
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		
1	22/03/18 10:16	PRS	Load PDF	
2	22/03/18 10:16	OI GIA REPORT	Load PDF	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	19/03/18 15:34	Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	19/03/18 15:34	Sketch Plan #2 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View View in Browser

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

1 per page 1 ☒

Assessment Reports			Thumbnail	Print
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		
1	19/03/18 15:35	Accident Statement	Load HTM	<input checked="" type="checkbox"/>

3 per page 3 ☒

Photos/Images			Thumbnail	Print
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	19/03/18 15:34	Accident Photo		<input checked="" type="checkbox"/>
2	19/03/18 15:34	Accident Photo		<input checked="" type="checkbox"/>
3	19/03/18 15:34	Accident Photo		<input checked="" type="checkbox"/>
4	19/03/18 15:34	Accident Photo		<input checked="" type="checkbox"/>
5	19/03/18 15:34	Accident Photo		<input checked="" type="checkbox"/>
6	19/03/18 15:34	Accident Photo		<input checked="" type="checkbox"/>
7	19/03/18 15:34	Accident Photo		<input checked="" type="checkbox"/>
8	19/03/18 15:34	Accident Photo		<input checked="" type="checkbox"/>
9	19/03/18 15:34	Driving License		<input checked="" type="checkbox"/>
10	19/03/18 15:34	Driving License		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	19/03/18 15:34	Sketch Plan		<input checked="" type="checkbox"/>
2	19/03/18 15:34	Sketch Plan #2		<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18005399/GD3E2
Date: 22/05/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN3003231800
 Claimant Vehicle No: SLN6758S Insured Vehicle No: SLS5130H
 Date of Loss: 19/03/2018 Nature of Claim: TP Claim No: SNM18D01485C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLN6758S Engine No: R16B21601674
 Make & Model: HONDA CIVIC, 1.6 (A) Chassis No: MRHFC5650GT001375
 Reg. Date: 12/05/2017 (Man. Year: 2017) Odometer: 27611 km
 Colour: Red
 Engine Capacity: 1597 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18 Rear Tyre Size: 225/40Z R18
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/03/2018
 Date Inspected: 23/03/2018 Inspected At: Tg 2k Spray Painting Centre
 Blk 1010 Bukit Merah Lane 3, #01-117
 Singapore 159724

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_... 22/5/2018

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 - \$4,500.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2018)
Parts:	143	HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN6758S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >