

ASS. REC. BY

REF

CS/CTI18005401/R1vd3

Special Instructions

Surveyor
Waymen

Rasul

ASSIGNMENT (Office)

From (Person)

Joseph Tay

of

CTI

Date/Time

22/3/18 @ 11:06 am

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No.

SGK 1008 G

Insured:

GBE 3633D

at Workshop n/o

Volkswagen

Tel:

6305 7176 / 9236 1399

of

247 Alexandra Road

Policy No.

DMCVSN1671321701

Claim No.

SNM18D0140102

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A.

13/03/2018

CA / REV / REP. / REV 24 HRS

Wp

H.O.D. Endorsement

Date/Time

22/3/18 @ 2:20pm

Person Contacted

Charmaine

Vehicle IN/OUT

OUT

Date/Time	Action/Instruction (✓) Estimate
	SGK 1008 G - CC3/MIG/20/2655/Ugd 1
	GBE 3633D - CC3/CTI/17007210/K/wb3s2
	D.O.A. 25/6/2012
	D.O.A. 9/1/17
17/4/18	@ 4:04pm Charmaine said vehicle just send in for repair
26/4/18	Final fig \$ 6626.23 confirmed by email (Recd 5119.81, 4416)

Surveyor:

Rahul

REF:

6826H

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHK 10086

at Workshop m/s Volkswagen

of 247, ALEXANDRA RD

Insured: CTI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____


(Client's Record)

Make of Veh: _____

(Policy Condition)

10 an

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHK 10086 Yr Regn: 2015 / AIR

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen SHARAN 2.0 c.c 1984

Colour: BLUE

A/C: Insured / Std / NI / NA

Sp. Reading: 49366

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVW222NZFV632907

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/452R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A. 13/03/18

D.O.I. 27/03/18

Survey held at Volkswagen ALEXANDRA

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 26 APR 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 26/4 - typst

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

S + RS \$

Photos

Others

TOTAL

Report Format: meri men

Lump Sum / I.B.I: (\$ 6626.23)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18005401/R1vd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 22-03-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 3633D	Veh. Inspected	SGK 1008G
Policy No.	DMCVSN1671321701	Coverage (\$)	0.00
Claim No.	SNM18D01401C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	22/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/03/2018	Inspection Date
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 247 ALEXANDRA ROAD SINGAPORE 159934	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Mar 2018		22 Mar 2018 11:06 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	BOLSEN CEMENT PRODUCTS PTE LTD, Co. Reg. No.: 197902130K		
Main Claimant:	REEL LOCO PRODUCTIONS PTE LTD		
Vehicle Reg. No.:	SGK1008G	Date of Loss:	13/03/2018 13:00 - :59
Claim Type:	TP / SNM18D01401C02	Policy/Cover Note No.:	DMCVSN1671321701 (Comprehensive)
Vehicle Reg. No. (Insured):	GBE3633D	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Volkswagen Group Singapore Pte Ltd (-) 247 ALEXANDRA ROAD, 159934 Alexandra - Tel: 63057293		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/04/2018]		
Adj Asg. Remarks:	EST \$12,568.26 , CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/03/2018 14:59
Date Of Accident	13/03/2018 13:00
Exact Location Of Accident	BLK 25 TECK WHYE LANE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGK1008G
Insured/Policyholder	
Name Of Registered Owner	REEL LOCO PRODUCTIONS PTE LTD
Co Reg No	200706826H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97430710
Alternative Phone No	OFFICE-97430710

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	SHARAN NF 2.0 TSI (DSG6)+EQP
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	YAHSHNI DEVI D/O MURUGAYAN
NRIC No	S8704069J
Date Of Birth	26/01/1987
Occupation	INDOOR
Date Of Driving Pass	30/08/2007
Driving Experience	10 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97430710
Fax Number	
Contact Number	
Email Address	JOEY@REELLOCO.COM

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 16/3/18

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Accident Photo



Accident Photo



Accident Photo



PDI TUAS

PDI TUAS

REEL LOCO PRODUCTIONS PTE LTD
162 BUKIT MERAH CENTRAL
#06-3555
Singapore, 150162
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV034529
Quote No. SER/QUO/1800454
QuoteDate 16/03/18
Salesperson Reeve Hiah
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Sharan NF 2.0 TSI (DSG6)+EQP	40,485	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SGK1008G	WVWZZZ7NZFV032907	14/04/15	Reeve Hiah
Engine Code	Labor Type	Engine No.	Model Code
	10	CCZ 473650	7N14H3

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	4	UNIT		✓ 1680 3,280.00
P B&P ALEX PAINT	SPRAY PAINT	4	UNIT		✓ 1600 3,200.00
P B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	pcs		✓ 80.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		✓ 480.00
P B&P MECH	ELECT WIRING & MECH COMPO	1	Time Un		✓ 280.00
	Nett				
	Sum Labor				7,400.00
P 7N0807109D	BUMPER REINFORCEMENT Predecessor 7N0807109B	1	Pieces		? 950.01
P 7N0807183A	BUMPER BRACKET LH	1	Pieces		nn ? 28.02
P 7N0807184A	BUMPER BRACKET RH	1	Pieces		? 28.02
P 7N0807192	BUMPER CENTER BRACKET	1	Pieces		? 159.15
P 7N0807217J GRU	FRT BUMPER COVER	1	Pieces		DC- 1,667.36
P 7N0807651	MEMBER	1	Pieces		? 176.29
P 7N0807723	BUMPER SUPP PART LH	1	Pieces		nn ? 30.48
P 7N0807724	BUMPER SUPP PART RH	1	Pieces		? 30.48
P 7N0853101 2ZZ	CENTER LOWER CHROME MOL	1	Pieces		? 235.28
P 7N0853651D 9B9	RADIATOR GRILLE	1	Pieces		CR 571.50
P 7N0853677 9B9	CENTER LOWER GRILLE	1	Pieces		nn ? 202.08
P 7N0919493	SENSOR BRACKET	2	Pieces		nn 62.70
P 7N0919493	SENSOR BRACKET	1	Pieces		nn 19.21
P 7N0919493B GRU	SENSOR BRACKET	1	Pieces		nn 31.35
P D 180KU2A1	2KADHESIVE	1	Pieces		nn 89.84
P D 822150A1	BONDAGENT	1	Pieces		nn 64.27
Sum carried forward					11,746.04

Payments to: - BBN: - Acc.-No.:

Service Order Confirmation

SERVICE ORDER NO: 18P0892
 CUSTOMER NO.: CV034529
 CUSTOMER NAME: REEL LOCO PRODUCTIONS PTE LTD
 TELEPHONE NO.:
 ADDRESS: 162 BUKIT MERAH CENTRAL #06-3555
 Singapore

VEH No.: SGK1008G

Order Date: 05/04/18

Reg Date: 14/04/15 KM: 40,485

VIN NO.: WVVZZZ7N2FV032907 ENGINE NO:

SA: Kong Charmaine

MODEL: Sharan NF 2.0 TSi (D9G6)+EQP MODEL NO.: 7N14H3

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	480		480
2	B&P MECH ELECT WIRING & MECH COMPONENT CHECK NETT	1	TU	280		280
3	B&P NUMBER PLATE B&P NUMBER PLATE -NETT	1	ST	80		80
4	B&P ALEX LABOUR LABOUR	2	UNIT	840		1,680
5	B&P ALEX PAINT SPRAY PAINT	2	UNIT	800		1,600
6	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
Item						
7	7N0807217J GRU FRT BUMPER COVER	1	PCS	1,667.36		1,667.36
8	7N0919493B GRU SENSOR BRACKET	1	PCS	31.35		31.35
9	7N0919493 SENSOR BRACKET	2	PCS	31.35		62.70
10	7N0919493 SENSOR BRACKET	1	PCS	19.21		19.21
11	7N0853651D 9B9 RADIATOR GRILLE	1	PCS	571.50		571.50
12	D 180KU2A1 2KADHESIVE	1	PCS	89.84		89.84
13	D 822150A1 BONDAGENT	1	PCS	64.27		64.27

Remarks : CHINA TAIPIING DIRECT SETTLEMENT

DCA 13/3/2018

SURVEYOR RASUL

TP VEHICLE GBE36330

Service Order Confirmation

SERVICE ORDER NO: 18P0892

CUSTOMER NO.: CV034529

CUSTOMER NAME: REEL LOCO PRODUCTIONS PTE LTD

TELEPHONE NO.:

ADDRESS: 162 BUKIT MERAH CENTRAL #06-3555
Singapore

VEH No.: SGK1008G

Order Date: 05/04/18

Reg Date: 14/04/15 KM: 40,485

VIN NO.: WVVZZZ7NZFV032907 ENGINE NO:

SA: Kong Chamaine

MODEL: Sharan NF 2.0 TSi (DSG6)+EQP MODEL NO.: TN14H3

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
-----	-------------	-----	-----	------------	--------	--------

TOTAL	6,826.23
GST AMOUNT	463.84
TOTAL AMOUNT	7,290.07

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 26 April 2018 10:16 AM
To: Cheong, Pearlyn (VWG Singapore); Rasul (LKKAUTO); Admin A; SUR
Cc: Kong, Charmaine (VWG Singapore); Wong, MeiY (VWG Singapore); Foo, John (VWG Singapore)
Subject: RE: SGK1008G - FINALISE

Dear Pearlyn,

WITHOUT PREJUDICE

Confirmed COR \$6,626.23 before GST

Total 5 working days repairs

Final invoice and all supporting documents sent over to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheong, Pearlyn (VWG Singapore) [mailto:Pearlyn.cheong@vw.com.sg]
Sent: Wednesday, 25 April 2018 7:03 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg>; Wong, MeiY (VWG Singapore) <meiy.wong@vw.com.sg>; Foo, John (VWG Singapore) <John.Foo@vw.com.sg>
Subject: SGK1008G - FINALISE

Dear Rasul,

Please confirmed

COR \$6626.23 before GST

Total 5 working days repairs

Best regards,

Pearlyn Cheong
Service Advisor
Aftersales Body & Paint Department

Volkswagen Group Singapore (Alexandra)
247 Alexandra Road
Singapore 159934

Direct line: +65 6305 7288
• Mobile : +65 9236 1336
Main line: +65 6305 7299
Main Fax: +65 6474 3643
pearlyn.cheong@vw.com.sg
<http://www.vw.com.sg>

New Arteon.

This is high performance art.



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Mar 2018		22 Mar 2018 11:06 Edit Adj Rpt	\$46,626.23 Edit Estimates	\$46,626.23 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	BOLSEN CEMENT PRODUCTS PTE LTD , Co. Reg. No.: 197902130K								
Main Claimant:	REEL LOCO PRODUCTIONS PTE LTD								
Vehicle Reg. No.:	SGK1008G	Date of Loss:	13/03/2018 13:00 - :59 [34 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D01401C02	Policy/Cover Note No.:	DMCVSN1671321701 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBE3633D	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Volkswagen Group Singapore Pte Ltd (-) 247 ALEXANDRA ROAD, 159934 Alexandra - Tel: 63057293								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 03/04/2018]								
Adj Asg. Remarks:	EST \$12,568.26 , CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGK1008G (SNM18D01401C02)
[GBE3633D]
TP
REEL LOCO PRODUCTIONS PTE LTD
Mar 13 2018 1:00PM
[BOLSEN CEMENT PRODUCTS PTE LTD]
Volkswagen Group Singapore Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)		Thumbnail	Print
1	15/03/18 11:05	Accident Statement		 Load HTM	

Photos/Images

3 per page

No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)		Thumbnail	Print
1	15/03/18 10:51	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒
2	15/03/18 10:51	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒
3	15/03/18 10:51	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒
4	15/03/18 10:51	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒
5	15/03/18 10:51	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒

Relabel/Reorder

LKK Auto Consultants Pte Ltd (HQ)

No	Finalized On		Thumbnail	Print
1	26/04/18 10:07	General View	 Load PDF	
2	26/04/18 10:07	Reinspection Photo	 Load PDF	

Documentation

1 per page

No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)		Thumbnail	Print
1	15/03/18 10:46	Sketch Plan [Linked Accident Report Documents]		 Load TIF	
2	15/03/18 10:46	Sketch Plan #2 [Linked Accident Report Documents]		 Load TIF	
3	15/03/18 10:47	DRIVER'S NRIC & DRIVING LICENCE [Linked Accident Report Documents]		 Load TIF	
4	15/03/18 10:47	CERTIFICATE OF INSURANCE [Linked Accident Report Documents]		 Load TIF	

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

No	Finalized On		Thumbnail	Print
1	22/03/18 11:06	REPAIR EST	 Load PDF	
2	22/03/18 11:06	OI GIA REPORT	 Load PDF	

Linked Accident Report Documents

View

View in Browser

Assessment Reports					1 per page	☒
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)		Thumbnail	Print	
1	15/03/18 11:05	Accident Statement		 Load HTM		

Photos/Images

3 per page

☒

No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)		Thumbnail	Print	
1	15/03/18 10:51	Accident Photo		 Load JPG	☒	
2	15/03/18 10:51	Accident Photo		 Load JPG	☒	
3	15/03/18 10:51	Accident Photo		 Load JPG	☒	
4	15/03/18 10:51	Accident Photo		 Load JPG	☒	
5	15/03/18 10:51	Accident Photo		 Load JPG		

Assessment Reports			1 per page	☒
No.	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
				☒
Documentation			1 per page	☒
No.	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	15/03/18 10:46	Sketch Plan	 Load TIF	
2	15/03/18 10:46	Sketch Plan #2	 Load TIF	
3	15/03/18 10:47	DRIVER'S NRIC & DRIVING LICENCE	 Load TIF	
4	15/03/18 10:47	CERTIFICATE OF INSURANCE	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118005401/VD3Q2

Date: 26/04/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1671321701
Claimant Vehicle No :	SGK1008G	Insured Vehicle No :	GBE3633D
Date of Loss:	13/03/2018	Nature of Claim:	TP
		Claim No:	SNM18D01401C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGK1008G	Engine No:	CCZ473650
Make & Model:	VOLKSWAGEN SHARAN, 2.0 TSI (A)	Chassis No:	WVWZZZ7NZFV032907
Reg. Date:	14/04/2015 (Man. Year: 2015)	Odometer:	49366 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R18	Rear Tyre Size:	225/45Z R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,426.04	2,586.23	1,839.81	41.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,320.00	4,040.00	3,280.00	44.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,746.04	6,626.23	5,119.81	43.59
+ GST 7.00/7.00% (S\$)	822.22	463.84	358.38	43.59
Nett Amount (S\$)	12,568.26	7,090.07	5,478.19	43.59

INSPECTION

Date of Assignment:	22/03/2018	
Date Inspected:	27/03/2018	Inspected At: Volkswagen Group Singapore Pte Ltd (-) 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Apr 2018)
Parts:	M1-MPV	VOLKSWAGEN SHARAN 2.0 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGK1008G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REINFORCEMENT	Not Necessary	950.01 FS	*- FS
2	1		*BUMPER BRACKET LH	Not Necessary	28.02 FS	*- FS
3	1		*BUMPER BRACKET RH	Not Necessary	28.02 FS	*- FS
4	1		*BUMPER CENTER BRACKET	Not Necessary	159.15 FS	*- FS
5	1		*FRT BUMPER COVER	Deformed	1,667.36 FS	*1,667.36 FS
6	1		*MEMBER	Not Necessary	176.29 FS	*- FS
7	1		*BUMPER SUPP PART LH	Not Necessary	30.48 FS	*- FS
8	1		*BUMPER SUPP PART RH	Not Necessary	30.48 FS	*- FS
9	1		*CENTER LOWER CHROME MOL	Not Necessary	235.28 FS	*- FS
10	1		*RADIATOR GRILLE	Cracked	571.50 FS	*571.50 FS
11	1		*CENTER LOWER GRILLE	Not Necessary	202.08 FS	*- FS
12	2		*SENSOR BRACKET	Necessary	62.70 FS	*62.70 FS
13	1		*SENSOR BRACKET	Necessary	19.21 FS	*19.21 FS
14	1		*SENSOR BRACKET	Necessary	31.35 FS	*31.35 FS
15	1		*2KADHESIVE	Necessary	89.84 FS	*89.84 FS
16	1		*BONDAGENT	Necessary	64.27 FS	*64.27 FS
17	1		*B&P NUMBER PLATE	Bent	80.00 FS	*80.00 FS
Total Parts (S\$)					4,426.04	2,586.23

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	3,360.00	1,680.00
2	SPRAY PAINT	New	3,200.00	1,600.00
3	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	New	480.00	480.00
4	ELECT WIRING & MECH COMPO	New	280.00	280.00
Gross Labour Cost (S\$)			7,320.00	4,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >