

ASS. REC. BY:

REF: CS/MSG18005402 / Grd3<sup>n2</sup> Special Instruction

Surveys

Merimen

ASSIGNMENT (Office)

From (Person): Lionel Tan of MS1G Date/Time: 22/3/18 @ 10:49am

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 1355D Insured: STE 19215

at Workshop m/s Komoco Motors Tel: 6473 5588

of 253 Alexandra Road

Policy No: MSD / vpcp / 17-001233 Claim No: MSC / v / 18-000414

Sum Insured: Excess:

Make of Veh: D.O.A. 18/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS lwp 23032018 H.O.D. Endorsement:

Date/Time: 2:18pm 22/3/18 Person Contacted: Lee Ying Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 1355D-X
	STE 19215-X
31/3/18	Send preli revised by merimen
18/5/18	Final fig \$ 5971.81 confirmed by email (Recd 986.72, 14/5)

Hand

REF: MSIG

4975H

ASSIGNMENT

From: Date 23/3/18

Estimated Cost:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHD 1355D  
at Workshop mis: Komoco Motors  
of: 253 Alexandra Road

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>1wp</sup>

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SHD 1355D Yr Regn: 31 May 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai i30 cc: 1582

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 89545 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: TMAD281UVHJ127992

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 / 65 R15  
R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MAXXIS

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 26-03-18

Survey held at w/s 3:30pm

Des. of Damages ☒ Frt ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 21 MAY 2018

*[Signature]*

21/5/2018

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2) 21/5 - typist

Report Format: merimen

Lump Sum / I.B./: \$ 5971.81

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp \$

☐ Interview \$

☐ Tech. Insp \$

☐ Weekend \$

Survey Fee:

Transportation

1. S - RE SI

2. Photos

3. Others

TOTAL

200  
10

210



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18005402/Gvd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 22-03-2018

Code : MSG



## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 1921S	Veh. Inspected	SHD 1355D
Policy No.	MSD/VPCP/17-001233	Coverage (\$)	0.00
Claim No.	MSC/V/18-000414	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	22/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	18/03/2018	Inspection Date
Survey held at	KOMOCO MOTORS PTE LTD 253 ALEXANDRA ROAD #01-01 SINGAPORE 159936.	

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 31 Mar 2018

**Preliminary Advice**

Insured Vehicle No	: SLE1921S	Accident Date	: 18/03/2018
TP Vehicle No	: SHD1355D	Assignment Date	: 22/03/2018
Make	: HYUNDAI I30 GDH	Est. Duration of Repair	: 4.00
Date of Inspection	: 26/03/2018		
Inspection At	KOMOCO MOTORS - (ALEXANDRA) (HQ) 253 ALEXANDRA ROAD SINGAPORE 159936		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,958.53
Revised Amount	:S\$	2,419.78
Check Items (Estimated)	:S\$	3,808.75
Total	:S\$	6,228.53

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2018		22 Mar 2018 10:49 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N		
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H		
Vehicle Reg. No.:	SHD1355D	Date of Loss:	18/03/2018 14:00 - :59
Claim Type:	TP / MSC/V/18-000414	Policy/Cover Note No.:	MSD/VPCP/17-001233 (Comprehensive) Coverage: 01/06/2017 - 31/05/2018
Vehicle Reg. No. (Insured):	SLE1921S	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	Komoco Motors - (alexandra) (HQ) 253 Alexandra Road, 159936 Alexandra - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/03/2018]		
Driver/Custodian (Insured):	LIM JOW HUAK (), NRIC: S0017268E		
Adj Asg. Remarks:	Please assign Mr Henry Ng to survey the vehicle. Please also take note that the vehicle is at Komoco Motors. Thank You.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

# 1/ 7

MSIG (SGX CENTRE) :


19-03-18;16:31 :

**PREMIER TAXIS PTE LTD**

23 CHANGI SOUTH AVE 2 #03-02

SINGAPORE 486443

TEL:65446676, 65446689 FAX:62141511



Our Ref: SHD1355D

WITHOUT PREJUDICE

Date: 19 March 2018

Attn: The Motor Claims Department  
MSIG Insurance (Singapore) Pte Ltd  
4, Shenton Way #21-01  
SGX Centre 2  
Singapore 068807

( BY FAX ONLY )

**ACCIDENT INVOLVING SHD1355D & SLE1921S ALONG UPPER CHANGI ROAD ON 18.03.18**

We are the registered owner of vehicle number of SHD1355D which was involved on the above mentioned accident between SLE1921S. (001)

Investigation reveals that the motor vehicle number SLE1921S was insured with you at the material time of the said accident.

As a result of the accident was caused solely and completely by the negligence of your insured vehicle number SLE1921S. Therefore, we are holding you liable for the repair costs and other consequential loss which was sustained by us.

Kindly arrange your representative to survey our vehicle at Komoco Motors, 253 Alexandra Rd, Singapore 159936 within two (2) days from the date hereof as to avoid further LOR/I incur. We enclosed hereby the GIA report of SHD1355D for your kind attention.

Failing which, we have no alternative but to proceed with the necessary repairs and the bill will be forward to you for reimbursement.

Yours Faithfully,



PREMIER TAXIS PTE LTD

Dear all,

Kindly take note of  
the venue for the  
pre-repair inspection

at Komoco Motors.

Thank You.

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Friday, 18 May 2018 10:33 AM  
**To:** 'Goh Wee Dek'  
**Cc:** Gary Shi; SUR  
**Subject:** RE: SHD 1355D-DOA: 18/3/18 (MSIG TP)

Dear Mr Goh,

Noted with thanks,

**Final invoice and all supporting documents sent over to MSIG**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Goh Wee Dek [mailto:weedek.goh@premiertaxi.com]  
**Sent:** Friday, 18 May 2018 8:53 AM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Cc:** Gary Shi <gary.shi@premiertaxi.com>; SUR <sur@lkkauto.com>  
**Subject:** RE: SHD 1355D-DOA: 18/3/18 (MSIG TP)

Dear Veron

Ok confirmed.

Regards

Goh Wee Dek  
Assistant Claims Manager  
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443  
**Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511**  
Visit us at: [www.premiertaxi.com.sg](http://www.premiertaxi.com.sg)

---

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

---

**From:** Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]  
**Sent:** Thursday, 17 May, 2018 12:22 PM  
**To:** Goh Wee Dek; SUR  
**Cc:** Gary Shi  
**Subject:** RE: SHD 1355D-DOA: 18/3/18 (MSIG TP)



Dear Mr Goh,

WITHOUT PREJUDICE

Finalise amount \$5971.81 @ 4 working days.

Please confirmed.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Goh Wee Dek [mailto:weedek.goh@premiertaxi.com]

**Sent:** Tuesday, 15 May 2018 4:07 PM

**To:** SUR <sur@lkkauto.com>

**Cc:** Gary Shi <gary.shi@premiertaxi.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>

**Subject:** RE: SHD 1355D-DOA: 18/3/18 (MSIG TP)

Dear All

Enclosed photos before paint and check items.

Please finalize soonest.

Regards

Goh Wee Dek  
Assistant Claims Manager  
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443  
Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511  
Visit us at: [www.premiertaxi.com.sg](http://www.premiertaxi.com.sg)

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

---

**From:** Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

**Sent:** Tuesday, 15 May, 2018 3:51 PM

**To:** Goh Wee Dek

**Subject:** SHD 1355D-DOA: 18/3/18 (MSIG TP)

Dear Mr Goh,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us and provides us resurvey photos.



Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4975H
Vehicle Details	
Vehicle No.:	SHD1355D
Vehicle to be Exported:	No
Intended De-registration Date:	29 Mar 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	I30 GDH 1.6 TCI 5DR DCT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	D4FBGZ122869
Chassis No.:	TMAD281UVHJ127992
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$20,832.00
Original Registration Date:	31 May 2017
First Registration Date:	31 May 2017
Transfer Count:	0
Actual ARF Paid:	\$13,665.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 May 2025
PARF Rebate Amount:	\$10,248.00
Intended COE Rebate Details	
COE Expiry Date:	30 May 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$40,532.00
COE Rebate Amount:	\$36,323.00
<b>Total Rebate Amount:</b>	<b>\$46,571.00</b>
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 29 Mar 2018

OK

## Enquire Vehicle Registration Details

### Owner Particulars

NRIC/Passport/Company Cert No.: 200304975H  
 Owner ID Type: Company  
 Owner Name: PREMIER TAXIS PTE. LTD.  
 Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443  
 Mailing Address: -  
 Birth Date: -

### Vehicle Particulars

Vehicle No.: SHD1355D  
 Previous Vehicle No.: -  
 Effective Date of Ownership: 31 May 2017  
 Original Regn Date: 31 May 2017  
 Registration Date: 31 May 2017  
 Year of Manufacture: 2016  
 Vehicle Type: Public Transport Taxi (Motor Car)  
 Vehicle Scheme: Taxi (Company)  
 Vehicle Attachment 1: Alr-Con (Taxi)  
 Vehicle Attachment 2: -  
 Vehicle Attachment 3: -  
 Vehicle Make: HYUNDAI  
 Vehicle Model: I30 GDH 1.6 TCI 5DR DCT  
 Primary Colour: Silver  
 Secondary Colour: -  
 Passenger Capacity: 4  
 Chassis No.: TMAD281UVHJ127992  
 Engine No.: D4FBGZ122869  
 Engine Capacity/Power Rating: 1582 cc / -  
 Maximum Power Output: 100.0 kW (134 bhp)  
 Propellant: Diesel  
 Max Unladen Weight: 1496 kg  
 Maximum Laden Weight: 1940 kg  
 Open Market Value: S20,832.00  
 PARF Eligibility: Yes  
 PARF Eligibility Expiry Date: 30 May 2025  
 Minimum PARF Benefit: S8,199.00  
 No. of Transfers: 0  
 IU Label No.: 1050700202  
 COE No.: 2017053101004240M  
 COE Expiry Date: 30 May 2025  
 COE Category: A - Car up to 1600cc & 97kW (130bhp)  
 COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)  
 Quota Premium (QP) / Prevailing Quota Premium: - / \$50,665.00  
 PQP Paid: S40,532.00  
 QP (Regn Cat): -  
 OPC Cash Rebate Eligibility: No

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/03/2018 09:09
Date Of Accident	18/03/2018 14:50
Exact Location Of Accident	UPPER CHANGI ROAD BEFORE SIA TRAINING CENTRE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD1355D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880
<b>Vehicle Particulars</b>	
Manufacturer	HYUNDAI
Model	I30 (FD)-1.6 DOHC (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5095103893
Cover Note Number	
<b>Driver</b>	
Name of Driver	LIM JOW HUAK
NRIC No	S0017268E
Date Of Birth	25/08/1953
Occupation	OUTDOOR
Date Of Driving Pass	10/02/1975
Driving Experience	43 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96349265
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 650 #07-317 HOUGANG AVE 8
Postcode	1953
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

BOTH VEHICLES - NO PAX

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE1921S
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	VEH. B
Vehicle Category	PRIVATE CAR
Name of Driver	ANG AH KIAN
NRIC/Passport Number	S2610828D
Contact Number	94563844
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	DAMAGED ON THE FRONT PORTION
No. Of Passenger (Including Driver)	1

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKZ9235M
-----------------------------	----------

Vehicle Make/Model/Colour	HYUNDAI
Details Of Properties	VEH. C
Vehicle Category	PRIVATE CAR
Name of Driver	MALE CHINESE
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

96349265


19 MAR 2013

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## Sketch Plan Pg. 2

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A: SHD 1355D

B: SLE 1921S

C: SKZ 9235m.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_

Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Describe Circumstance of the Accident.

**\* CHAIN COLLISION \***

ON 18/03/2018 @ 1450HRS, I WAS DRIVING MY TAXI ( SHD 1355 D )  
TRAVELLING ALONG UPPER CHANGI ROAD IN THE EXTREME LEFT LANE.

I SLOWED DOWN MY TAXI AS VEHICLE C ( SKZ 9235 M – HYUNDAI ) WHICH WAS  
IN FRONT OF ME, WERE SLOWING DOWN BUT SUDDENLY I FELT AN IMPACT FROM  
THE REAR. SUBSEQUENTLY DUE TO THE GREAT IMPACT, IT FORCED MY TAXI TO  
SURGE FORWARD – CAUSING THE FRONT PORTION OF MY TAXI TOUCHES ONTO THE  
REAR OF VEHICLE C.

WHEN INSPECTED, I DISCOVERED THAT VEHICLE B ( SLE 1921 S – TOYOTA )  
WHICH WAS BEHIND ME, HAD COLLIDED ONTO THE REAR OF MY TAXI.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE REAR PORTION AND THE  
FRONT PORTION.

VEHICLE B HAD DAMAGES ON THE FRONT AND NO DAMAGES TO VEHICLE C.


NO INJURY INVOLVED.

NO PASSENGERS ONBOARD ALL VEHICLES.

\*VIDEO FOOTAGE CAPTURED.

## CHAIN COLLISION / MULTIPLE VEHICLES

## DAMAGES FOUND ON VEHICLE A, B, C, D, E &amp; F



PREMIER TAXI

THIRD PARTY VEHICLES

*[Signature]* 0617218/5

Driver's Signature & NRIC Number

Monday, March 19, 2018 @ 9:24:30 AM

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG: 200707743D GST REG: 200707743D

hence notify  
the following:  
• To display damaged parts during resurvey  
• Prices are subject to confirmation  
• No modification(s) is allowed  
to final approval from Insurance Company

21-Mar-18

## ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1355 D

1 pc	Emblem I30		\$	27.80
1 pc	Emblem CRDI		\$	29.40
1 pc	Emblem Hyundai		\$	29.40
1 pc	Rear bumper	811.11	\$	811.11
1 pc	Rear bumper sponge		\$	79.20
1 pc	Rear bumper reinforcement	815.64	\$	815.64
1 pc	Rear bumper reinforcement centre		\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20		\$	104.40
2 pcs	Rear bumper n/s & o/s reflector @ \$107.50		\$	215.00
2 pcs	Rear bumper n/s & o/s tail lamp @ \$321.30		\$	642.60
1 pc	Tailgate		\$	2,292.30
1 pc	Tailgate lower garnish		\$	362.61
1 pc	Rear windscreen moulding		\$	87.00

Less 20%

\$ 5,575.66  
\$ 1,115.13  
\$ 4,460.53

### S/NETT

1 set	Rear bumper clips		\$	48.00
1 set	Reverse sensor		\$	280.00
1 set	Tailgate stickers		\$	100.00
1 set	Tailgate lower garnish clips		\$	60.00
1 pc	Rear number plate with casing		\$	50.00
1 pc	Front number plate with casing		\$	50.00
1 pc	Sealant		\$	50.00

Sundry

To dismantle and refit rear windscreen onto new tailgate

To dismantle and replace reverse sensor and test system

To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the same

To putty and spray painting on the rear bumper, tailgate lower garnish, tailgate

To apply rustproofing on the repaired and replaced panels

Total

\$ 6,958.53

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)  
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

4 Days.

to  
paint by post.  
before paint  
photos.

26/3/18

Guo Qiang  
82880282

2/4/18

5417.26

4333.8

48.00

280.00

100.00

60.00

50.00

50.00

50.00

50.00

120.00

120.00

850.00

600.00

120.00

5971.8

## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005402/GVD3N2

Date: 23/05/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/PCP/17-001233
Claimant Vehicle No :	SHD1355D	Insured Vehicle No :	SLE1921S
Date of Loss:	18/03/2018	Nature of Claim:	TP
		Claim No:	MSCV/18-000414

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHD1355D	Engine No:	D4FBGZ122869
Make & Model:	HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M)	Chassis No:	TMAD281UVHJ127992
Reg. Date:	31/05/2017 (Man. Year: 2016)	Odometer:	89545 km
Colour:	Silver		
Engine Capacity:	1582 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,148.53	4,871.81	276.72	5.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,810.00	1,100.00	710.00	39.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>6,958.53</b>	<b>5,971.81</b>	<b>986.72</b>	<b>14.18</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>487.10</b>	<b>418.03</b>	<b>69.07</b>	<b>14.18</b>
<b>Nett Amount (\$\$)</b>	<b>7,445.63</b>	<b>6,389.84</b>	<b>1,055.79</b>	<b>14.18</b>

## INSPECTION

Date of Assignment:	22/03/2018	
Date Inspected:	26/03/2018	Inspected At: Komoco Motors - (alexandra) (HQ) 253 Alexandra Road Singapore 159936
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 23 May 2018)	
<b>Parts:</b>	N/A	HYUNDAI I30 GDH 1.6 D TCI 5DR DCT (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD1355D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM I30	Necessary	27.80 FL	*27.80 FL
2	1		*EMBLEM CRDI	Necessary	29.40 FL	*29.40 FL
3	1		*EMBLEM HYUNDAI	Necessary	29.40 FL	*29.40 FL
4	1		*REAR BUMPER	Deformed	811.11 FL	*811.11 FL
5	1		*REAR BUMPER SPONGE	Not Necessary	79.20 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	815.64 FL	*815.64 FL
7	1		*REAR BUMPER REINFORCEMENT CENTRE	Not Necessary	79.20 FL	*- FL
8	2		*REAR BUMPER N/S & O/S SIDE BRACKET	Necessary	104.40 FL	*104.40 FL
9	2		*REAR BUMPER N/S & O/S REFLECTOR	Cracked	215.00 FL	*215.00 FL
10	2		*REAR BUMPER N/S & O/S TAIL LAMP	Cracked	642.60 FL	*642.60 FL
11	1		*TAILGATE	Buckled	2,292.30 FL	*2,292.30 FL
12	1		*TAILGATE LOWER GARNISH	Deformed	362.61 FL	*362.61 FL
13	1		*REAR WINDSCREEN MOULDING	Necessary	87.00 FL	*87.00 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
15	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
16	1		*SET TAILGATE STICKERS	Necessary	100.00 FS	*100.00 FS
17	1		*SET TAILGATE LOWER GARNISH CLIPS	Necessary	60.00 FS	*60.00 FS
18	1		*REAR NUMBER PLATE WITH CASING	Cracked	50.00 FS	*40.00 FS
19	1		*FRONT NUMBER PLATE WITH CASING	Scratched	50.00 FS	*40.00 FS
20	1		*SEALANT	Necessary	50.00 FS	*50.00 FS
21	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,263.66</b>	<b>5,955.26</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,115.13</b>	<b>1,083.45</b>
<b>Total Parts (\$\$)</b>	<b>5,148.53</b>	<b>4,871.81</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE AND REFIT REAR WINDSCREEN ONTO NEW TAILGATE	New	120.00	100.00
2	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM	New	120.00	40.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING TO KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE OF THE SAME	New	850.00	400.00
4	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER,TAILGATE LOWER GARNISH,TAILGATE	New	600.00	500.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	60.00
Gross Labour Cost (\$\$)			<b>1,810.00</b>	<b>1,100.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >