

Surveyor: laush

ASSIGNMENT (Office)

From (Person): Gerald Poh of LPC Date/Time: 21 03 2018

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YM 8767D Insured: YP 3087A

at Workshop m/s RaySpeed Automobile Tel: 6264 0138

of Blk 5 Pioneer Rd North # 01-35

Policy No: _____ Claim No: 16/16/16/VCOO/019032

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 15/07/2016

(Client's Record) (Woon) 9799 5138 - May

CA / REV / REP. / REV 24 HRS WPI 21 Chia Ping Rd H.O.D. Endorsement: _____

Date/Time: 20/07/2016 9:58am Person Contacted: Raymond Vehicle-IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>YM 8767D - NA /MSG110234156 /W1</u> <u>DAF 24/7/11</u>
	<u>YP 3087A - X</u>
<u>18/8/16</u>	<u>@ 3:17pm May said vehicle has not send in for repair</u>
<u>19/9/16</u>	<u>@ 11:30am May said vehicle has not send in for repair</u>
<u>6/10/16</u>	<u>@ 4:39pm May will check & call back</u>

29/3/18 Submit LS \$950 (Red 250, 2170), 3 days

4/58/950, 3 days

RECEIVED 29 MAR 2018

29/3/2018

no bill

(08/11/13)

Surveyor: Tanaka

REF: 115

CSE 2017 Jan.

ASSIGNMENT

From: _____ Date: 22/10/16

Estimated Cost: _____

OD, WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: YM 8767 D Yr Regn: 2008, July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ISUZU FTR34P c.c 7790

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: R8 959 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SALIFTR34P87 000044

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/70R22.5

R: 275/70R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6/6 mm

R/Bal. 6 mm R/Bal. 6/6 mm

L/Bal. 6 mm L/Bal. 6/6 mm

D.O.A. _____ D.O.I. 20.07.2016 6.15pm

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Ph Woon</u>
<u>7/10/16</u>	<u>@ 1245pm Mxy said vehicle has not send in for repair</u>
<u>19/10/16</u>	<u>@ 425pm Mxy said vehicle has not send in for repair</u>
<u>21/10/16</u>	<u>Submit PRS report</u>

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? 21/10-typer

2) 21/10-typer

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS, \$ _____

Photos _____

Others _____

TOTAL _____




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS3/LPC16013418/T1vb-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 22-03-2018	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 3087A	Veh. Inspected	YM 8767D
Policy No.		Coverage (\$)	0.00
Claim No.	16/16/16/VC00/019032	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	21/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/07/2016	Inspection Date	22/03/2018
Survey held at	RAYSPEED AUTOMOBIL WORKSHOP BLK 5 PIONNER ROAD NORTH #01-35 SINGAPORE 628458		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



LONPAC INSURANCE BHD

(S98FC5635C)

Our Ref : 16/16/16/VC00/019032

Your Ref : CS3/LPC16013418/T1vbs2

16 March 2018

M/s LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Pk
Singapore 408933

Dear Sirs/Madam

PAPER SURVEY OF YM8767D

We refer to the above accident.

We enclose the following documents :-

- a) Survey report & photos of YM8767D
- b) GIA report of YM8767D
- c) GIA report & photos of YP3087A

Kindly study the documents and let us have your opinion on the adjusted repair cost within the next 10 days.

Yours faithfully

GERALD POH
SENIOR EXECUTIVE
(CLAIMS)
Email : mt_claim@lonpac.com

MSIG 6088253 / STA INSPECTION PTE LTD - Boon Lay
ENTRY DATE & TIME 16/07/2016 11:50

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/07/2016 11:50
Date Of Accident	15/07/2016 16:10
Exact Location Of Accident	PENJURU ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YM8767D
Insured/Policyholder	
Name Of Registered Owner	FUJI TRADING (SINGAPORE)PTE LTD
Co Reg No	NA
Email Address	alvinbai@fujifts.com
Mobile Phone No	
Alternative Phone No	Office-62641755
Vehicle Particulars	
Manufacturer	ISUZU
Model	FTR34P
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Commercial Vehicle
Insurance Company	
Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	MSD/VCFT/16-000865-00
Cover Note Number	
Driver	
Name of Driver	LEI XIANG
Passport No/FIN	G6592124W
Date Of Birth	12/11/1988
Occupation	Outdoor
Date Of Driving Pass	19/01/2011
Driving Experience	5 Years And 5 Months
Gender	Male
Mobile Number	(Local) +65-98686781
Fax Number	
Contact Number	Office-62641755
EMail Address	NOEMAIL

Address 24 CHIA PING ROAD
 Postcode 619976
 Was driver an employee of the Insured's Company Yes
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle
 Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident Unknown - VEH B TURNED RIGHT TOO CLOSE & HIT MY VEH
 Weather Conditions Clear
 Road Surface Dry

Other Information

Was any foreign vehicle involved in this accident? No
 Was any body injured in the Accident? No
 Was any other material or property damaged? Yes
 Was there any video captured by Car Camera? No
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? No
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? No
 If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP3087A
 Vehicle Make/Model/Colour
 Details Of Properties RIGHT SIDE
 Name of Driver MURALI NAIDU
 NRIC/Passport Number F7484451X
 Contact Number NA
 Address YAMAMIZU SINGAPORE (COMPANY)
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)
Details of Witness
 Name
 Phone Number
 Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA, Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) I understand, acknowledge, agree and consent that
 - (i) my insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responses to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, periodic reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in the accident and the Insurers' law yers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms) which may be based outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Perijuan Rd



Sketch Plan #2

Describe Circumstances of the Accident

I stopped my veh to go into Penguin Rd (jetty) to load goods while waiting outside the entrance for a pass to go in, veh B going out made a close turn and hit my stationary veh, dragged then stopped. Both of us got down from our vehs to check. Since heavy traffic, I asked him to move to the side to discussed. Veh B driver on hazard lights so I thought he want to park and wait for me after that without notice, I saw he drove off without exchanging particulars. I went to the Security booth to use the details of veh B.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date

[Signature]

Driver's Signature (if driver is not the policyholder) Date

[Signature]

Witnessed by Reporting Centre Personnel

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/07/2016 10:35
Date Of Accident	15/07/2016 16:10
Exact Location Of Accident	ALONG PENJURU RD - OUTSIDE PENJURU LIFTING TERMINA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP3087A
Insured/Policyholder	
Name Of Registered Owner	NG TECK GUAN
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	FP517DR2RDEB-11.9 D (M)
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z/16/VC00/098795
Cover Note Number	

Driver

Name of Driver	MURALI NAIDU A/L MUNIANDY
Work Permit No	519866528
Address	

General Information of the Accident

Type Of Accident	SIDE SWIPE- OPPOSITE DIRECTION
Weather Conditions	CLEAR

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	1

Circumstances of Accident

Please refer to the attached Sketch Plan and the accident details

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM8767D
-----------------------------	---------

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed** by the Policyholder and/or the Authorized Driver.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any **false reporting** may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature
Date & Time

Driver's Signature (If driver is not the policy holder)
Date & Time 10.00 AM

Witness by Reporting Centre
Personnel

Sketch 26/07/2016



A- YP 3087A

B- YM 8767D



LONPAC INSURANCE BHD

Chew Insurance Agency Pte Ltd
271 Bukit Timah Road
#03-10/11 Balmoral Plaza
Singapore 259708
Tel: 67371188
Fax: 67366255

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)
MZ300
(COMPREHENSIVE)

Policy No. **Z/16/VC00/098795** CI No. 16012217

Excess: **AS STATED IN POLICY SCHEDULE.**

- Index Mark and Registration **mitsubishi fuso FM65FM2RDEB**
Number of Vehicle / Chassis **XP 3087A / FM65FMA30063**
- Name of Policy Holder **NG TECK GUAN**
- Period of Insurance **31/05/2016 To 30/05/2017 (Midnight)**
- Persons or Classes of Persons entitled to drive*
(A) THE POLICYHOLDER.
(B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS/THEIR PERMISSION.

*IC No: 50903622A
Tel No: 98361508
hwcc_eng@tym-group.com
9628 5861
Ng Hwee Kai*

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle and provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

- Limitations as to use*
USE IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.
USE FOR THE CARRIAGE OF PASSENGERS (OTHER THAN FOR HIRE OR REWARD) IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.
USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES.

THE POLICY DOES NOT COVER:-
USE FOR HIRE OR REWARD OR FOR RACING, PACEMAKING, RELIABILITY TRIAL OR SPEED TESTING.
USE WHILST DRAWING A TRAILER EXCEPT THE TOWING OF ANY ONE DISABLED MECHANICALLY PROPELLED VEHICLE.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 93 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

HP Co.: MERCEDES-BENZ FINANCIAL SERVICES (SINGAPORE) LTD

LONPAC INSURANCE BHD



AUTHORISED SIGNATORY

REF NO: KCM/67907

Serial No: 12309

Page No: 5/6
Unable to duplicate
this / original copy

Accident Photo




Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/07/2016 10:35
Date Of Accident	15/07/2016 16:10
Exact Location Of Accident	ALONG PENJURU RD - OUTSIDE PENJURU LIFTING TERMINA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP3087A
Insured/Policyholder	
Name Of Registered Owner	NG TECK GUAN
NRIC No	S0903822A
Email Address	HWEE_ENG@TYM-GROUP.COM
Mobile Phone No	(LOCAL) +65-98361508
Alternative Phone No	OFFICE-96255861

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FP517DR2RDEB-11.9 D (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z/16/VC00/098795
Cover Note Number	

Driver

Name of Driver	MURALI NAIDU A/L MUNIANDY
Work Permit No	519866528
Date Of Birth	31/07/1971
Occupation	OUTDOOR
Date Of Driving Pass	04/01/2013
Driving Experience	3 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85012660
Fax Number	
Contact Number	
EMail Address	HWEE_ENG@TYM-GROUP.COM

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-

Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident SIDE SWIPE- OPPOSITE DIRECTION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

Was there any video captured by Car Camera? NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

Please refer to the attached Sketch Plan and the accident details

Are accident photos available for attachment? YES

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YM8767D

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature
Date & Time

Chen 26/07/2016

Driver's Signature (if driver is not the policy holder)
Date & Time 10:00 AM

Witness by Reporting Centre
Personnel

Sketch Plan



A- YP 3087A

B- YM 8767D

Describe Circumstances of the Accident

On July 15, 2016 at about 4.10 pm, I was driving my lorry bearing registration number YP3087A out from the Penjuru Lifting Terminal.

The traffic was heavy then on both sides of the road and when I made the Exit to turn right into the main road, a lorry (later identified as bearing registration number YM8767D) on the opposite direction was waiting for entry into the Penjuru Lifting Terminal and due to the slope, the lorry rolled backward and hit onto my lorry at the right hand side.

I stopped my lorry to investigate and I tried to talk to the driver however he was talking on his phone and we have no chance to exchange particulars.

As there was no injury to all parties, I moved off.

Important note

Under **General Condition – Conduct of Claim** of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

Declaration

I / We declare the foregoing particulars are true in every aspect.

Policyholder's Signature
Date & Time

[Signature] 26/07/2016

Driver's Signature (if driver is not the policy holder)
Date & Time 10:00 AM

Witness by Reporting Centre
Personnel

Work Permit Pg. 1



WORK PERMIT
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer
THONG YONG 2000 MARINE PTE LTD

Sector: **SERVICE**



Name
MURALI NAIDU A/L MUNIANDY
Occupation
DRIVER

Work Permit No.
5 19866528

Date of Application
13-03-2012

Date of Issue
29-02-2016

Date of Expiry
05-06-2017



L6531961

85012660

VISIT PASS
Immigration Regulations

Name
MURALI NAIDU A/L MUNIANDY



Date of Birth	Sex	Nationality
31-07-1971	M	MALAYSIAN
FIN	Date of Issue	Date of Expiry
F7484451X	29-02-2016	05-06-2017

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait of Murali Naidu A/L Muniandy

Licence Number: **F7484451X**
Name: **MURALI NAIDU A/L MUNIANDY**
Birth Date: **31 Jul 1971**
Issue Date: **04 Jan 2013**
Valid Till: **03 Jan 2018**

Barcode: 002138217D

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

		EFFECTIVE DATE
CI	Class 2B Motorcycles =< 200 CC	04 Jan 2013
CI	Class 3 Motor cars =< 3000 kg with =< 7 passengers, exclusive of the driver; and motor tractors/vehicles =< 2500 kg	04 Jan 2013
	Class 4 Heavy motor cars and motor tractors > 2500 kg	26 Aug 2014

F7484451X S / No. 9000208474

Barcode: Licence No: F7484451X

NP 428A

Certificate of Insurance Pg. 1

6 FRI 16:44 FAX +65 62614200 TYM Pte Ltd

0001/001



LONPAC INSURANCE BHD

g Chew Insurance Agency Pte Ltd
271 Bukit Timah Road
#03-10/11 Balmoral Plaza
Singapore 259706
Tel: 67371188
Fax: 67366255

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

MZ300
(COMPREHENSIVE)

Policy No. Z/16/VC00/098795 CI No. 16012217

Excess : AS STATED IN POLICY SCHEDULE.

- 1. Index Mark and Registration **mitsubishi fuso FM65FM2RDEB**
Number of Vehicle / Chassis **YP 3087A / FM65FMA30063**
- 2. Name of Policy Holder **NG TECK GUAN**
- 3. Period of Insurance **31/05/2016 To 30/05/2017 (Midnight)**
- 4. Persons or Classes of Persons entitled to drive*
(A) THE POLICYHOLDER.
(B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS/THEIR PERMISSION.

*IC Nbr: 50903822A
Tel Nbr: 98361508
hwe_eng@tjm-group.com
9625 5861
Nj Hwe Eng*

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle and provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

- 5. Limitations as to use*
USE IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.
USE FOR THE CARRIAGE OF PASSENGERS (OTHER THAN FOR HIRE OR REWARD)
IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.
USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES.

THE POLICY DOES NOT COVER:-

USE FOR HIRE OR REWARD OR FOR RACING, PACEMAKING, RELIABILITY TRIAL OR SPEED TESTING.
USE WHILST DRAWING A TRAILER EXCEPT THE TOWING OF ANY ONE DISABLED MECHANICALLY PROPELLED VEHICLE.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

HP Co. : MERCEDES-BENZ FINANCIAL SERVICES (SINGAPORE) LTD

LONPAC INSURANCE BHD



AUTHORISED SIGNATORY

REP NO: KCM/67967

Serial No: 12309



LONPAC INSURANCE BHD (S98FC5635C)

Our Ref : 15/16/16/VC00/019032

REGISTERED POST

20 July 2016

Mr Ng Teck Guan
1 Soon Lee Street
#02-28 Pioneer Sector
Singapore 627605

Dear Sirs

RECEIVED 22 JUL 2016

**ACCIDENT INVOLVING YP3087A & YM8767D ALONG PENJURU RD ON
15.7.2016**

We refer to the above accident.

We have received a notification of a third party claim from the driver of YM8767D (copy enclosed).

Kindly arrange for Mr Murali Naidu to proceed to our reporting centres/authorized workshop to lodge a report.

Yours faithfully,

GERALD POH
SENIOR EXECUTIVE
(CLAIMS)
Email: geraldpoh@lonpac.com

Cc Sing Chew Insurance Agency

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Addendum Sheet Pg. 1

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MWHM 16090928 Vehicle Registration No : YP 3087 A
Name(as shown in NRIC): Ng Teck Guan
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
NRIC/Passport No : S0903822A
Address : -
Contact (Tel) : - (H/P) : 96255861
(Email) : HWH-Eng@iTM-Group.com
Date of Accident : 15/7/2016 Time of Accident : 1610 hrs
Place of Accident : Along Payun Rd - outside Benjamin Lifting Terminal
Insurance Company : Lompac Insurance Bhd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Insured
To amend the vehicle no. from YN 3087 A
to YP 3087 A

Signature
Signature of Vehicle Owner / Driver
Date: 26/7/16

Enquire Vehicle & Owner Information (Vehicle No. YP3087A As At 15 Jul 2016 / 16:10:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: YM8767D/RS/JP/AK

Current Owner Details

Owner ID Type: Singapore NRIC
Owner ID: S0903822A
Owner Name: NG TECK GUAN
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 15
Registered Street Name: GALISTAN AVENUE
Registered Unit No.: -
Registered Building Name: -
Registered Postal Code: 669689

Current Vehicle Details

Vehicle No.: YP3087A
Make Description/Model: MITSUBISHI / FUSO FM65FM2RDEB
Insurance Company Name: LONPAC INSURANCE BHD



Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution
Copyright © 2016 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)



RaySpeed Automobil Works

Business Reg No. 322191/00M

Your Ref :

Date :

Our Ref :

16.3463.RA

30 January 2018

M/s Fuji Trading (Singapore) Pte Ltd
c/o Block 5 Pioneer Road North
01-35
Singapore 628458

FINAL REPAIR COSTS

YM 8767 D
Isuzu FTR34P

To cost of repair lump sum as recommend by surveyor.....\$1,200.00 NETT

SINGAPORE DOLLARS : ONE THOUSAND AND TWO HUNDRED ONLY



**PRO
PLUS
AUTOMOBILE
ENGINEERS**

221 Balestier Road #10-01, Rocca Balestier, Singapore 329928
Tel: +65 6707 8932 Fax: +65 6352 6802
Mobile: +65 9673 0595 / +65 9788 9809
E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com
Company Registration No: 40156500M

*Consultants to Motor Industry, Automobile
Engineers, Claims Investigators, Accident
Reconstruction Specialists, Insurance Loss
Assessors / Adjusters, Valuers And
Licensed Appraisers.*

Our Ref : PP/ET/CT.8767.TP.1-18

30 January 2018

M/s Fuji Trading (Singapore) Pte Ltd
c/o Block 5 Pioneer Road North
01-35
Singapore 628458

WITHOUT PREJUDICE

Dear Sirs,

**Re : Third Party Claim
Vehicle Registration No. YM 8767 D**

We refer to your instruction to appraise the above-mentioned vehicle on 19 July 2017.

A static inspection was carried out and our report is enclosed for your perusal. The estimated repair costs submitted by Messrs **Rayspeed Automobil Works** for **\$4,142.00** as per our attached schedule has been rechecked thoroughly by us against the actual damages sustained on the vehicle, and we recommend the replacements and rectifications accordingly.

Our revised quotation for the repair is **\$1,496.50**. In our opinion, we consider it to be excessive. We, therefore, recommend a contract lump sum repair cost. This is more economical than to have the vehicle repaired on a parts by/for parts basis. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

We have negotiated with the repairer and they have agreed to repair this vehicle for **\$1,200.00 NETT** which, in our opinion is fair and reasonable.

The repairer has agreed to undertake the repairs to your requirements at the recommended contract lump sum. However, we have not given authorisation and instruction to the repairer to proceed with the repairs.

The entire repair of the damaged vehicle should be completed within a reasonable period of **3 (three) days**, excluding weekends and public holidays.

We are reverting the matter to you for a decision, and enclosed is our invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.

Very truly yours,
PRO PLUS AUTOMOBILE ENGINEERS

Errol Tan
Licensed Appraiser & Automobile Engineer

Encls:

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error please contact us immediately by telephone so that we can arrange for its return.



**PRO
PLUS
AUTOMOBILE
ENGINEERS**

221 Balestier Road #10-01, Rocca Balestier, Singapore 329928
Tel: +65 6707 8932 Fax: +65 6352 6802
Mobile: +65 9673 0595 / +65 9788 9809
E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com
Company Registration No: 40156500M

*Consultants to Motor Industry, Automobile
Engineers, Claims Investigators, Accident
Reconstruction Specialists, Insurance Loss
Assessors / Adjusters, Valuers And
Licensed Appraisers.*

VEHICLE INSPECTION REPORT

To : M/s Fuji Trading [Singapore] Pte Ltd
c/o Block 5 Pioneer Road North
#01-35
Singapore 628458

Insured :
Policy Number :
Claim Number :
Our Reference : PP/ET/CT.8767.TP.1-18
Own Damage/Sum Insured :
Excess :
Third Party/Insce Company :
Date : 30 January 2018

Instructed By : Madam May Pang
Date of Assignment : 19 July 2017
Date of Accident : 15 July 2017
Date of Inspection : 20 July 2017
Name of Workshop : Rayspeed Automobil Works
Place of Inspection : Block 5 Pioneer Road North
#01-35
Singapore 628458

PARTICULARS OF DAMAGED VEHICLE

Registration Number	: YM 8767 D	Odometer Reading	: 131 289 Km
Make/Model	: Isuzu FTR34P	Radio/Cassette/CD	: Fitted
Year of Manuf/Reg	: 2001	Air Conditioner	: Fitted
Engine Number	: Hidden from view	View Mirrors	: Fitted -O/s & n/s
Chassis Frame Number	: JALFTR34P87000044	Seat Belts	: Fitted -Front only
Class/Type	: Lorry (Wooden Deck)	Other Assessories (Specify)	:
Colour	: Blue		

PRE-ACCIDENT CONDITION OF VEHICLE

General Condition	: Good	Any Apparent Engine Modification/s	:
Paintwork	: Good	Market Value	: -
Footbrakes	: Serviceable	Scrap Value (PARF/OMV)	: -
Steering	: Serviceable		
Undercarriage (Front)	: Serviceable		
Undercarriage (Rear)	: Serviceable		

TYRE CONDITIONS ON VEHICLE

Front (Size)	: 275/70R22.5	NEAR SIDE	60%	OFF SIDE	60%
MAKE	: Yokohama				
Rear (Size)	: 275/70R22.5 X 2		60% X 60%		60% X 60%
MAKE	: Yokohama				
SPARE (Size)	: -				
MAKE	: -				
Type of Road Wheels	: Standard				

NOTE: The above percentages represent the estimated remaining life of the tyre threads
* Denotes damaged component/s


IMPACT OF VI
Direction of Impact (-
Damages sustained
subject vehicle

PRO PLUS AUTOMOBILE ENGINEERS


IMPACT OF VEHICLE

Direction of Impact (←→)

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered onto the o/s rear portion of the vehicle.



SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT



■ Damage Area/s

Damages sustained were the rear wooden carriage assembly- tilted, wooden tailgate iron mongery/lock & latch o/s- bent/twisted, wooden dropside iron mongery/hinge/latch o/s- twisted etc.

Note : Follow-up reinspection of vehicle on 27 December 2017 after spray painting & noted that the listed components as per our recommendations were replaced and repaired accordingly.

ESTIMATE

The estimate submitted by **M/s Rayspeed Automobil Works** as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. As instructed, we have/have not authorised the repairs.

	Repairer's Estimate	Our Recommendation	
Spare Parts	2252.00	576.50	Estimated number of days for repairs: 3
Labour Charges	1050.00	500.00	
Paint Work	800.00	400.00	Number of photographs taken at time of static inspection: 17
Towing Charges	40.00	20.00	
Others	4142.00	1496.50	
TOTAL			

Remarks: The repairer has agreed to undertake the repairs on a contract lump sum of \$1,200.00 NETT corresponding to supply of parts, labour and spray painting charges. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

NOTE: The revised estimate was made from a visual inspection. Any discrepancies or unseen damage/s should be notified with the company within 7 (seven) days from the date thereof. Otherwise, the revised amount should deem to be valid.

APPRAISEMENT SCHEDULE

Registration No: YM 8767 D

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$ ¢	Revised Amount \$ ¢
<u>PARTS REPLACEMENT- LIST ITEMS</u>					
1	1 pc	Taillamp assembly o/s	Cracked	302.00	302.00
		<u>Less</u> : 25% by Pro Plus Automobile Engineers		302.00	302.00
					75.50
				302.00	226.50
<u>PARTS REPLACEMENT- SPECIAL NETT ITEMS</u>					
1	1 pc	Wooden tailgate [including iron mongeries]	Replaced iron mongeries	650.00	50.00
2	1 pc	Wooden dropside [including iron mongeries]	Replaced iron mongeries	1050.00	50.00
3	1 pc	Wooden tailgate lower member	Cracked	250.00	150 250.00
					200
			Sub - Total	2252.00	576.50

Eng. No. 1 ENGINEERS


APPRAISEMENT SCHEDULE

Registration No: YM 8767 D

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate		Revised Amount	
				\$	¢	\$	¢
			B/F	2252.00		576.50	
		<u>LABOUR & MISC. CHARGES</u>					
1		To disconnect rear wire harness of electrical components to facilitate repairs, reconnect & check functions.			40.00		20.00
2		To dismantle/renew the rear accident damaged portion. To heat, cut/weld damaged body panels & components including to heat, knock-out, reshape, straighten, orientate, restore & align repairable constituents to symmetrical dimensions.			1050.00		400 500.00
3		To putty/primer application and spray painting including touch-up affected areas with polyurethane paint.)))))		800.00		350 400.00
4		To rustproofing & cavities preservation to the replaced and repaired panels.))				770
Grand Total					4142.00		1496.50

Note: The repairer has agreed to undertake the repairs at a contract lump sum of \$1,200.00 NETT, corresponding to supply of parts, labour and spray painting charges. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

Pro Plus Automobile Engineers

ERROL TAN
 B.A.Econ (Hons).UK
 Dip. Auto Engr. & Motor Trade Management .UK
 Automobile Engineer & Licensed Appraiser
 1196.50
 1/5 8950

SURIAKALA VALLI PARAM
GURDEEP SINGH SEKHON
CHIA KOK SENG
REY FOO JONG HAN
GOH LAM CHUAN
NAVINDER SINGH
P PADMAN
KWEH SOON HAN
PRADEEP KUMAR GOBIND
RAJIV NAIR
WEE CHENG IMM HOPE
HUE JIA PEI
WONG TECK MING



MAIN OFFICE:
10 Hoe Chiang Road, #13-03A
Keppel Towers,
Singapore 089315
Tel: 6538 3611
Fax: 6538 3708

Website :www.kscgp.com

(Fax/Email not for service of court documents)

Registered in Singapore with limited liability
as a Limited Liability Partnership
Registration Number T10LL1855L

DID: 3152 0985

Email: jiapei@kscgp.com

Your Ref : YP 3087A
Our Ref : YM 8767D
Date : 19 July 2016

Lonpac Insurance Berhad

BY FAX 6296 2706

DATE OF ACCIDENT: 15 JULY 2016
NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We are instructed by the owner of YM 8767D to notify you of a road traffic accident on 15 July 2016 at about 4.10pm at Penjuru Road, involving our client's vehicle registration number YM 8767D and vehicle registration number YP 3087A which was insured by you at the material time. A copy of the Singapore accident statement is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

NB. Any settlement or offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude client's driver/passenger from claiming injury-related damages arising from this accident.

Yours faithfully,

(Main Office)
Cc client

BRANCH: [PRIVATE PROPERTY CONVEYANCING]

490 Lorong 6 Toa Payoh, Biz 3 Lobby 2
#09-18 HDB Hub, Singapore 310490
Tel: 6591 7696 Fax: 6258 1625

BRANCH: [HDB CONVEYANCING]

490 Lorong 6 Toa Payoh Biz 3 Lobby 2
#09-18 HDB Hub, Singapore 310490
Tel: 6591 7696 Fax: 6258 1409

BRANCH: [SHIPPING, ADMIRALTY & COMMERCIAL]

36 Armenian Street #05-10
Singapore 179534
Tel: 6034 1346 Fax: 6034 1358

The information contained in this letter / facsimile message is CONFIDENTIAL and may also be LEGALLY PRIVILEGED, intended only for the individual or entity named above. If you are not the intended recipient, you are hereby notified that any use, revelation, dissemination, distribution or copying of this document is strictly prohibited. If you have received this document in error, please notify us immediately by telephone (call the number above) and destroy the original message.

Kindly acknowledge upon inspection in the acknowledgement box below.

Acknowledgement	
This is to confirm that I _____ [Full Name of Surveyor] of _____ [Surveyor's Company] have completed as follows:-	
(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].	
Signature of Appointed Surveyor Company Stamp	Witnessed by: Date
(b) Post - Repair Survey/Inspection on _____ [Date] at _____ [Time].	
Signature of Appointed Surveyor Company Stamp	Witnessed by: Date

Yours faithfully,

(Main Office)
Cc client



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

 6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

TAX INVOICE

 Our Ref No: GR-18-038680
 Date of Request: 13/03/2018

Your Ref No: GS/16/3463/RA/JP/CL

 KSCGP JURIS LLP
 10 Hoe Chiang Road #13-03A
 Keppel Tower
 Singapore 089315

Dear Sir/Madam,

Your Search Criteria:
 Date of Accident: 15/07/2016
 Place of Accident: AT PENJURU ROAD
 Client Vehicle No: YM8767D

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

 GIRO Cash Cheque



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC16013418/T1vbs2-1

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 02-04-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 3087A	Veh. Inspected	YM 8767D
Policy No.	Z/16/VC00/098795	Coverage (\$)	0.00
Claim No.	16/16/16/VC00/019032	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	21/03/2018

2. Vehicle Particulars & Condition

Make & Model	ISUZU FTR34P	c.c	7790
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JALFTR34PS7000044	Colour	BLUE
Odometer	128959	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	YOKOHAMA	6 mm
L/H Front Tyre	275/70 R22.5	YOKOHAMA	6 mm
R/H Rear Tyre	275/70 R22.5 (D)	YOKOHAMA	6/6 mm
L/H Rear Tyre	275/70 R22.5 (D)	YOKOHAMA	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/07/2016	Inspection Date	20/07/2016
Survey held at	RAYSPED AUTOMOBIL WORKSHOP BLK 5 PIONNER ROAD NORTH #01-35 SINGAPORE 628458		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YM 8767D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILLAMP ASSEMBLY O/S LESS 25% DISCOUNT	CRACKED	302.00 -	302.00 -75.50
			302.00	226.50
SPECIAL NETT ITEMS				
1	WODDEN TAILGATE (INCLUDING IRON MONGERIES) (SN)	REPLACE IRON MOGERIES	650.00	50.00
1	WODDEN DROPSIDE (INCLUDING IRON MOGERIES) (SN)	REPLACE IRON MOGERIES	1,050.00	50.00
1	WOODEN TAILGATE LOWER MEMBER (SN)	CRACKED	250.00	150.00
			1,950.00	250.00
LABOUR				
	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT & CHECK FUNCTIONS.		40.00	20.00
	TO DSIMANTLE / RENEW THE REAR ACCIDENT DAMAGED PORTION. TO HEAT, CUT / WELD DAMAGED BODY PANELS & COMPONENTS INCLUDING TO HEAT, KNOCK-OUT, RESHAPE, STRAIGHTEN, ORIENTATE, RESTORE & ALIGN REPAIRABLE CONSTITUENTS TO SYMMETRICAL DISMENSIONS.		1,050.00	400.00
	TO PUTTY / PRIMER APPLICATION AND SPRAY PAINTING INCLUDING TOUCH-UP AFFECTED AREAS WITH POLYURETHANE PAINT. }		800.00	350.00
	TO RUSTPROOFING & CAVITIES PRESERVATION TO THE REPLACED AND REPAIRED PANELS. }		-	-
			1,890.00	770.00
GRAND TOTAL			4,142.00	1,246.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				950.00

Report Ref No. CS3/LPC16013418/T1vbs2-1

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.