

INS. CASE OWNER:

Bennie unit CC 4 /AIG1800 5435, Kph39

LKK:
IDAC:

Surveyor:

Fenneth

DOI:

ASSIGNMENT

27/3/18

Date / Time:

27/3/18

Registered in Merimen:

27/3/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLB 760A

Name of Insured:

FOH 500 M40R.

Insured Tel No.:

HP:

97383422

Excess Sec II :SS

D.O.A.:

27/3/18

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

LEE 719 WFN

Driver Tel No.:

(V/L: ☒ YES / NO)

Claim No.:

079271696561

Policy No.:

70046287-01000

Make / Model:

MAZDA

Place of Accident:

BLK 505 HDB BISHAN ST 11

OI GIA REPORT: ☒ YES / NO; TP GIA REPORT: ☒ YES / NO

Insured Liability: %

Final ? Yes / No

SLF 9794X



INSRS:

WSP:

Tel:

Liability:

RMKS:

Pang
MTC.

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

27/3/18 3/4/18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

29/3/18

OI video uploaded in Merimen by Bennie.

2/4/18 @ 4.26pm
@ 5.30pmCalled OI, Ms Lee. No response.
Called OI, Mr Khur. Not pick up.- OI failed to rep at stop line & collided with
tr who has the right of way.

17/4/18

File pass to type mandate

RECEIVED 18 APR 2018

4/5/18

PV sent
File pass to shu per to close.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA SA No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS

7612.06

Loss of Rental (LOR):

SS

6w.00

Loss of Use (LOU):

SS

(\$ - x - days)

Loss of Income (LOI):

SS

(\$ - x - days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

GIA/LTA Search

SS

7.45

Medical:

SS

Disbursement:

SS

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

#220-e#20

Total:

SS

8219.51

Global Sum SS: 8000.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

8000.00

Payee 2: (Strike if N.A.)

SS

Payee 3: (Strike if N.A.)

SS

Name 1:

Kang Auto Engineering Pte Ltd.

Name 2:

Name 3:

RECEIVED 07 MAY 2018

REF: AIG

ASSIGNMENT

From: Date: 23/3/18

Estimated Cost:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLF 9799X

at Workshop/mis: Kang Auto

of 160 Sin Ming Drive # 02-16

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 05 days Res: Yes or No

Lum Sum: 1.3% 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLF 9799X Yr Regn: 09 16

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Jetta ^{A1} 230TS, 1390

Colour: White A/C: Insured / Std / NI / NA

Sp Reading: 24057 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVVW ZZZ16 ZG M840922

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD R/Rim or

Tyre Size: F: 235/35R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 8 mm

L/Bal: 8 mm

D.O.A: 21/3/18

Rear

R/Bal: 8 mm

L/Bal: 8 mm

D.O.I: 23/3/18

Survey held at: ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/3 File pass to Customer

111 # 761206 (Reel # 227.40) 23/1.

Date/Time: File Pass to?

☐

: Preli. Report

☐

: Final Report

Date/Time: File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1. 3-4 RS, 51

2. Phone

3. Other

Report Format:

Lump Sum / I.B. / 15

Add Fee: ☐ Site Insp: 15☐ Interview: 15☐ Tech. Insp: 15☐ Weekend: 15

TOTAL:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18005435/Kpb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 23-03-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLB 2260A	Veh. Inspected	SLF 9799X	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	23/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/03/2018	Inspection Date	23/03/2018	
Survey held at	KANG AUTO ENGINEERING PTE LTD 160 SIN MING DRIVE #02-16 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

KANG

AUTO ENGINEERING PTE LTD



Sin Ming Auto City

160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015
Email: kangauto@singnet.com.sg

M/S LEONG WAI MENG, KEVIN
BLK124 BUKIT BATOK
CENTRAL, #03-369
SINGAPORE 650124

POLICY NO : THIRD PARTY CLAIMS
OUR REF : TP18/03/1096
VEHICLE NO : SLF9799X
MAKE/MODEL : Volkswagen Jetta 1.4
DATE OF ACCIDENT : 21.03.2018

- 1 PC FRONT R/H FENDER
- 1 PC FRONT R/H DOOR
- 1 PC FRONT R/H DOOR RUBBER
- 1 PC FRONT R/H HINGES
- 1 PC REAR R/H DOOR
- 1 PC REAR R/H DOOR RUBBER
- 1 PC REAR R/H DOOR HINGES
- 1 PC R/H SIDE SKIRT


Bt/war	\$	435.00	✓
Bt	\$	2,328.53	✓
m	\$	155.00	✓
n	\$	236.20	X
Bt	\$	2,328.53	✓
m	\$	155.00	✓
n	\$	236.20	X
n	\$	775.00	X
	\$	6,649.46	

- TO CHECK WIRING, AUDIO SYSTEM AND SYSTEM RESETTING
- TO RE-SET WHEEL ALIGNMENT
- TO TRANSFER DOOR TO NEW DOOR
- TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL
- TO PUTTY AND SPRAY PAINT CHARGES
- LABOUR CHARGES

	\$	250.00	201
	\$	120.00	601
	\$	250.00	1201
	\$	200.00	901
	\$	1,600.00	8801
	\$	1,200.00	6001
	\$	10,269.46	

SGD TEN THOUSAND TWO HUNDRED SIXTY-NINE AND CENTS FORTY-SIX ONLY.

YOURS FAITHFULLY,


KANG AUTO ENGINEERING PTE LTD

87612-06

Not Authorised
1-B.1
Recovery B4 pain
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

KANG

AUTO ENGINEERING PTE LTD

Sin Ming Auto City



160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015
Email: kangauto@singnet.com.sg

M/S LEONG WAI MENG, KEVIN
BLK124 BUKIT BATOK
CENTRAL, #03-369
SINGAPORE 650124

POLICY NO : THIRD PARTY CLAIMS
OUR REF : TP18/03/1096
VEHICLE NO : SLF9799X
MAKE/MODEL : Volkswagen Jetta 1.4
DATE OF ACCIDENT : 21.03.2018

SUPPLEMENTARY

1 PC FRONT RH DOOR REGULATOR GEAR
1 PC FRONT RH DOOR MOTOR

S\$	<i>Di</i>	260.00	—
	<i>Ja</i>	180.00	—
		<u>440.00</u>	

SGD FOUR HUNDRED AND FORTY ONLY.

YOURS FAITHFULLY,


KANG AUTO ENGINEERING PTE LTD

9829.46

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium



AUTO ENGINEERING PTE LTD

Sin Ming Auto City

160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015

Email: kangauto@singnet.com.sg



M/S LEONG WAI MENG, KEVIN
BLK124 BUKIT BATOK
CENTRAL, #03-369
SINGAPORE 650124

POLICY NO : THIRD PARTY CLAIMS
OUR REF : TP18/03/1096
VEHICLE NO : SLF9799X
MAKE/MODEL : Volkswagen Jetta 1.4
DATE OF ACCIDENT : 21.03.2018

1 PC FRONT R/H FENDER	\$ <i>Bt/war</i> 435.00 ✓
1 PC FRONT R/H DOOR	\$ <i>Bt</i> 2,328.53 ✓
1 PC FRONT R/H DOOR RUBBER	\$ <i>m</i> 155.00 ✓
1 PC FRONT R/H HINGES	\$ <i>R</i> 236.20 X
1 PC REAR R/H DOOR	\$ <i>Bt</i> 2,328.53 ✓
1 PC REAR R/H DOOR RUBBER	\$ <i>m</i> 155.00 ✓
1 PC REAR R/H DOOR HINGES	\$ <i>R</i> 236.20 X
1 PC R/H SIDE SKIRT	\$ <i>R</i> 775.00 X
	<hr/>
	\$ 6,649.46
TO CHECK WIRING, AUDIO SYSTEM AND SYSTEM RESETTNG	\$ 250.00 <i>7</i>
TO RE-SET WHEEL ALIGNMENT	\$ 120.00 <i>601</i>
TO TRANSFER DOOR TO NEW DOOR	\$ 250.00 <i>1201</i>
TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL	\$ 200.00 <i>901</i>
TO PUTTY AND SPRAY PAINT CHARGES	\$ 1,600.00 <i>8801</i>
LABOUR CHARGES	\$ 1,200.00 <i>6001</i>
	<hr/>
	\$ 10,269.46

SGD TEN THOUSAND TWO HUNDRED SIXTY-NINE AND CENTS FORTY-SIX ONLY.

YOURS FAITHFULLY,

KANG AUTO ENGINEERING PTE LTD

*Not Withheld
1-B,1
Resurvey B4 paint
5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9412I
Vehicle Details	
Vehicle No.:	SLF9799X
Vehicle to be Exported:	No
Intended De-registration Date:	29 Mar 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA GP 1.4 TSI 90 A/T TL 1632G5
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	CAXF85741
Chassis No.:	WVWZZZ16ZGM040922
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$16,660.00
Original Registration Date:	16 Sep 2016
First Registration Date:	16 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$16,660.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Sep 2026
PARF Rebate Amount:	\$12,495.00
Intended COE Rebate Details	
COE Expiry Date:	15 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,506.00
COE Rebate Amount:	\$43,593.00
Total Rebate Amount:	\$56,088.00

The information contained herein is correct as at 22 Mar 2018

OK

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 29 March 2018 12:58 PM
To: Tan, Bennie-WZ (Bennie-WZ.Tan@aig.com)
Subject: <Request for OI Video> Your Ref: 0792716967SG *Our Ref: CC4/AIG18005435/Kpb3 [ACCIDENT INVOLVING SLB 2260A(AIG) & SLF 9799X ON 21/03/2018]

Your Ref: **0792716967SG**
Our Ref: CC4/AIG18005435/Kpb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLB 2260A(AIG) & SLF 9799X ON 21/03/2018

We refer to the above matter.

Kindly assist to upload OI's video in Merimen for our viewing.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Sent: Thursday, 29 March 2018 2:21 PM
To: Hsiao Tong (LKKAUTO)
Subject: RE: <Request for OI Video> Your Ref: 0792716967SG-003 *Our Ref: CC4/AIG18005435/Kpb3 [ACCIDENT INVOLVING SLB 2260A(AIG) & SLF 9799X ON 21/03/2018]

Hi Hsiao Tong

OI video been uploaded in merimem.

For your necessary follow up pls.

Best Regards

Bennie Tan
AIG
Senior Complex Claims Examiner
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1718 | Fax +(65) 6835 7416

Bennie-WZ.Tan@aig.com | www.aig.com.sg

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Thursday, March 29, 2018 12:58 PM
To: Tan, Bennie-WZ
Subject: <Request for OI Video> Your Ref: 0792716967SG *Our Ref: CC4/AIG18005435/Kpb3 [ACCIDENT INVOLVING SLB 2260A(AIG) & SLF 9799X ON 21/03/2018]

Your Ref: **0792716967SG**
Our Ref: CC4/AIG18005435/Kpb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLB 2260A(AIG) & SLF 9799X ON 21/03/2018

We refer to the above matter.

Kindly assist to upload OI's video in Merimen for our viewing.

Thank you.

KANG

AUTO ENGINEERING PTE LTD

Sin Ming Auto City



160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015
Email: kangauto@singnet.com.sg

M/S **AIG Asia Pacific Insurance Pte Ltd**
AIG Building
78 Shenton Way, #07-16
Singapore 079120
Attn: Motor Claims Dept

Date : 05/04/2018

DIRECT SETTLEMENT
Your Insured: SLB3360A
Our Ref: TP18/03/1096

LETTER OF DEMAND

RE: ACCIDENT INVOLVING VEHICLE SLF9799X & SLB2260A ON 21.03.18
ALONG MSCP OF BLK 505 BISHAN.

Details as follows :-

Cost of Repair	\$ 7,612.06
Loss of Rental (6Days x S\$120)	\$ 720.00
LTA Search Fees	\$ 7.45

\$ 8,339.51

SGD EIGHT THOUSAND THREE HUNDRED THIRTY-NINE AND CENTS FIFTY-ONE ONLY.

YOURS FAITHFULLY,


KANG AUTO ENGINEERING PTE LTD

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 4 May 2018 12:41 PM
To: 'kangauto@singnet.com.sg'
Subject: RE: LOD - ACCIDENT INVOLVING OUR INSURED VEHICLE SLB2260A AND SLF9799X ON 21/03/2018
Attachments: DV_SLF 9799X.pdf

Without Prejudice

Hi May,

We refer to the above matter.

As per our tele-conversation earlier, we confirm settlement at a global sum of **\$8,000.00(all-in)**.

Please duly sign the DV enclosed and return to us (LKK) for our necessary action.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: kangauto [mailto:kangauto@singnet.com.sg]

Sent: Thursday, 5 April 2018 12:37 PM

To: Imran.Ishak@aig.com

Cc: yokeshi.chan@aig.com; Zayyer (LKKAuto) <zayyer@lkkauto.com>; Lee-Ying.Chin@aig.com;

kangauto@singnet.com; Lily.Tan@aig.com; ShengYang.Lim@aig.com; Baljit.Kaur@aig.com;

Darshene.Supramaniam@aig.com; NoorMariesa.AbuKassim@aig.com; Andy-SY.Fong@aig.com

Subject: LOD - ACCIDENT INVOLVING OUR INSURED VEHICLE SLB2260A AND SLF9799X ON 21/03/2018

AIG Claims Dept

We had completed the repair of SLF9799X & had finalized with your appointed surveyor Mr kenneth Kong of LKK Auto Consultant.

Please find attached Letter of Demand and relevant documents for your acceptance to our offer.

Your soonest reply is highly appreciated.

Yours Sincerely,

May Ang

-----Original Message-----

From : Imran.Ishak@aig.com

Date : 22/03/2018 - 16:15 GMT+8

To : kangauto@singnet.com.sg

Cc : NoorMariesa.AbuKassim@aig.com, Baljit.Kaur@aig.com, Lily.Tan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Darshene.Supramaniam@aig.com, Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com
Subject : PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLB2260A AND SLF9799X ON 21/03/2018

WITHOUT PREJUDICE

Your Reference : SLF9799X

Our Reference : SLB2260A

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you

Sincerely,

Imran

Mohd Imran Md Ishak

AIG

Express Claims Adjuster II, FNOL SG Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 14, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 ext:1012661 | Fax +6 03 2685 5898

imran.ishak@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Our Ref: CC4/AIG18005435/Kpb3

04 APRIL 2018

KOH SOO NGOR
BLK 242 BISHAN ST 22
#10-256
SINGAPORE 570242

Dear Sir/Madam,

ACCIDENT INVOLVING SLB 2260A & SLF 9799X ON 21/03/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SLF 9799X against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
Email: chewht@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

Your Insured **SLB2260A**

AIG Asia Pacific Insurance Pte Ltd
AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attn: Motor Claims Dept

Dear Sirs/Mdm

LETTER OF AUTHORITY

RE: ACCIDENT INVOLVING VEHICLE SLF9799X AND SLB2260A ON 21.03.2018

I, Leong Wai Meng, Kevin owner of Motor Vehicle No. SLF9799X at all material times of the above accident, hereby irrevocably authorise you to pay my workshop, **Kang Auto Engineering Pte Ltd**, the compensation sum for my loss and damage suffered in the above accident involving your insured motor vehicle no. SLB2260A.

Yours Sincerely,



RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **KANG AUTO ENGINEERING PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$8,000.00** (Global Sum) for vehicle no. **SLF 9799X** that was damaged pursuant to the accident which occurred on **21/03/2018** (date) along **MSCP OF BLK 505 BISHAN STREET 11** involving vehicle no/s **SLB 2260A**.

This is pursuant to the inspection conducted on **23/03/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **LEONG WAI MENG, KEVIN** ("the third party claimant") of vehicle no. **SLF 9799X** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLF 9799X** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 04 (day) of May (month) 2018 (year)



Signed by appointed surveyor

Kang Auto Engineering Pte Ltd
Sin Ming Auto City, Sin Ming Drive
#02-16 Singapore 575722
Tel: 6556 0103 (3 Lines) Fax: 6556 1015
kangauto@singnet.com.sg

Signed by "the workshop" (with chop)

**INVOICE : 00002233****Bill To :**

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
AIG Building
Singapore 079120

Our Ref: : TP18/03/1096

Date : 4/5/2018

Vehicle No : SLF9799X

Make/Model No : Volkswagen Jetta

Date of Accident : 21.03.2018

Date Discharge : 30.03.2018

Attn: Motor Claims Dept

Tel : 64191891 Fax : 683574716

Description	Quantity	Unit Price	Amount
Cost of Repair (All-in) Your Insured : SLB2260A	1 1	\$8,000.00	\$8,000.00
Total Payable			\$8,000.00

Goods sold are not returnable.

Specialised in Motor Insurance Claims. Repairs all Types of Motor Cars.
All Vicom Inspection Service, Sourcing "Cheaper Premium" for your vehicle.

Received the above in good order and condition

YOURS FAITHFULLY

KANG AUTO ENGINEERING PTE LTD

Kang Auto Engineering Pte Ltd

Sin Ming Auto City 160 Sin Ming Drive #02-16 Singapore 575722 Tel: 65560103 (3Lines) Fax: 6556 1015

Email: kangauto@singnet.com.sg

Co. Reg. No: 200617880K



RICA LEASING PTE LTD

126 Joo Seng Road #05-12 Gold Pine Industrial Building
Singapore 368355 Tel: 6552 8003 Fax: 6453 1409
Co Reg No. 200510430K

OFFICIAL RECEIPT

No. 20534

Date 28-03-18

Received from Leong Wai Meng, Kevin

the sum of Dollars Seven Hundred Twenty Only

Being payment for SGM 8557G 22/3/18 - 28/3/18 STA # 25881

- ☐ Cash
☐ Nets
☐ Cheque / Visa / Master

\$

720/100

for RICA LEASING PTE LTD



RICA LEASING PTE LTD

Co Reg No. 200510430K

57P 7444X
 Registered Address:
 126 Joo Seng Road #05-12 Gold Pine Industrial Building
 Singapore 368355
 Operation Address:
 160 Sin Ming Drive, #08-05 Sin Ming AutoCity
 Singapore 575722 Tel: 6266 2307 Fax: 6266 2306

VEHICLE RENTAL AGREEMENT

STA No. 25881

HIRER'S PARTICULAR		Veh No : SCM957G		Replace Veh No :	
Name : (as in I/C) <u>LEONG HAI MENG, KEVIN</u>		Mileage Out : <u>172673</u>		Mileage Out :	
NRIC / PASSPORT No : _____		Make & Model <u>Tyota</u>		Make & Model	
Address (Res) : _____		Auto / Manual <u>Auto</u>		Auto / Manual	
Name & Address of Employer : _____		OUT : Date <u>27-3-18</u>		OUT : Date	
Occupation : _____ Driving Exp : _____		OUT : Time <u>12-45p</u>		OUT : Time	
D/L No : _____ D/L Type : Local/International		RENTAL CHARGES			
Pass Date : _____ Date of Birth : _____		Daily <u>6</u> @ \$120/- = <u>\$720 00</u>			
Tel : (O) _____ (R) _____ HP/PG : _____		Weekly @ \$ _____			
ADDITIONAL DRIVER'S PARTICULARS		Monthly @ \$ _____			
Name : (as in I/C) <u>LIM YAN KUN</u>		Hours @ \$ _____			
NRIC / PASSPORT No : <u>S84004001</u>		Others @ \$ _____			
Pass Date : <u>19-12-2001</u> Date of Birth : <u>13-01-1984</u>		CDW @ \$ _____			
Address (Res) : <u>Blk 460 Clementi Ave 3</u>		PAI @ \$ _____			
<u>#16-604 (120460)</u> Tel/Hp : _____		Delivery Service			
Refundable Deposit : _____		SUB-TOTAL \$ <u>720 00</u>			
Cash/Nets/Cheque/VISA/MC Cards No : _____					
(A) - ACCIDENTS (D) - DENTS (S) - SCRATCHES		EXTENSION			
		Collection Service			
ACCESSORIES CHECK <input type="checkbox"/> Ashtray <input type="checkbox"/> Cig Lighter <input type="checkbox"/> S / Tyre <input type="checkbox"/> STD Tools <input type="checkbox"/> Jack <input type="checkbox"/> Hub Caps <input type="checkbox"/> Radio / Cass <input type="checkbox"/> CD/Cartridges <input type="checkbox"/> S / RIM		Misc.			
		ESTIMATED TOTAL RENTAL \$			
		Sales Person Code :			
		Hirer is responsible for the first \$1,500.00 excess for collision / damage to first party, (i.e.) RICA LEASING PTE LTD Vehicle (including windscreen) and also first \$1,500.00 excess for collision / damage to third party's vehicle for each and every accident / damage.			
		Hirer's Signature			
		Addition Driver's Signature			

I/We agreed to the terms and conditions above, overleaf and that all information given are true & correct in all respect. My/Our driving licence(s) is/are current and not disqualified from driving. You may charge all amount due on the rental to my/our credit card.

* IMPORTANT

- ONLY PERSONS ABOVE 25 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY RICA LEASING PTE LTD.
- IN THE EVENT OF AN ACCIDENT, THE HIRER OR AUTHORIZED DRIVER :
 - shall report all accidents involving the said vehicle to the Owner immediately
 - shall take immediate steps to complete and sign Form MAR 1 (Motor Accident Report Form) and do all other acts required in compliance with the "NON-INJURY MOTOR ACCIDENT REPORT SCHEME" (the form will be made available when the accident is report to the Owner).
 - shall report to the police within 24 hours from the occurrence, the following types of accidents :
 - injury case;
 - non-injury case involving a Government vehicle, or damage to Government property;
 - non-injury case involving a foreign vehicle (to obtain their motor insurance policy, Passport No./Name of the driver, Vehicle number, Log card and Vehicle road tax information);
 - non-injury case involving a pedestrian or cyclist.

RETURN OF VEHICLE-THE HIRER/DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER/DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO RICA LEASING PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	DEPOSIT REFUND	SIGNATURE OF HIRER/DRIVER
<u>28/3</u>	<u>1130 am</u>	<u>173147</u>				

Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 22 Mar 2018 / 14:17:43

Receipt Date/Time : 22 Mar 2018 / 14:17:43

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180322-001143

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	--	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SLB2260A

As at 21 Mar 2018/20:00:00

Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.

1 Insurance Enquiry - SLB2260A

Enquiry Fee

20180322141640137804

7.00 0.49 7.49

Sub-Total 7.00 0.49 7.49

Total Before Rounding 7.00 0.49 7.49

Rounding Difference 0.04

Total Amount Payable 7.45

Paid By

xxxxxxxxxxxx0459 Credit Card:
Visa/MasterCard 7.45

Total 7.45

Cash Change 0.00

Tendered Amount 7.45

Excess Refundable Amount 0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Mar 2018 Edit Reg		22 Mar 2018 00:00 Edit Adj Rpt	S\$7,612.06 Edit Estimates	S\$7,612.06 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Koh Soo Ngor , ID: S6805823F								
Main Claimant:	LEONG WAI MENG KEVIN , ID: S84094121								
Vehicle Reg. No.:	SLF9799X	Date of Loss:	21/03/2018 00:00 - :59 [18 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0792716967SG	Policy/Cover Note No.:	2100462287						
Vehicle Reg. No. (Insured):	SLB2260A	Policy No. (Claimant):	A28826103AVW						
		Excess:							
Repairer:	Kang Auto Engineering Pte Ltd () 160 Sin Ming Drive, #02-16, Sin Ming AutoCity, 575722 Sin Ming - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 04/04/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (26/03/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLF9799X (0792716967SG)

[SLB2260A]

TP

LEONG WAI MENG KEVIN

Mar 21 2018 12:00AM

[Koh Soo Ngor]

Kang Auto Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	29/03/18 14:12	01 Video - Accident	Load MP4	
Letters/Correspondences				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	
Assessment Reports				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	26/03/18 09:28	Accident Statement <small>From: SC - Reg. No: SLB2260A, Claimant: KOH SOO NGOR</small>	Load HTM	
Photos/Images				
			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/03/18 12:55	General View	Load JPG	<input checked="" type="checkbox"/>
2	29/03/18 12:55	General View	Load JPG	<input checked="" type="checkbox"/>
3	29/03/18 12:55	General View	Load JPG	<input checked="" type="checkbox"/>
4	29/03/18 12:55	General View	Load JPG	<input checked="" type="checkbox"/>
5	29/03/18 12:55	General View	Load JPG	<input checked="" type="checkbox"/>
6	29/03/18 12:55	General View	Load JPG	<input checked="" type="checkbox"/>
7	29/03/18 12:55	General View	Load JPG	<input checked="" type="checkbox"/>
8	29/03/18 12:55	General View	Load JPG	<input checked="" type="checkbox"/>
9	29/03/18 12:55	General View	Load JPG	<input checked="" type="checkbox"/>
10	29/03/18 12:55	General View	Load JPG	<input checked="" type="checkbox"/>
11	29/03/18 12:55	General View	Load JPG	<input checked="" type="checkbox"/>
12	29/03/18 12:55	General View	Load JPG	<input checked="" type="checkbox"/>
13	29/03/18 12:55	General View	Load JPG	<input checked="" type="checkbox"/>
14	29/03/18 12:55	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
15	29/03/18 12:55	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
16	29/03/18 12:55	General View	Load JPG	<input checked="" type="checkbox"/>
17	29/03/18 12:55	General View	Load JPG	<input checked="" type="checkbox"/>
18	04/05/18 12:33	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
19	04/05/18 12:33	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
20	04/05/18 12:33	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
21	04/05/18 12:33	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation				
			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/03/18 14:01	EMAIL FROM AIG DD 22032018	Load PDF	
2	26/03/18 19:35	TP ESTIMATE- MARKED	Load PDF	
3	26/03/18 19:35	TP GIA REPORT	Load PDF	
4	17/04/18 15:02	TP ESTIMATE.	Load PDF	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
5	09/05/18 07:34	WORKSHOP INVOICE	Load PDF	
6	09/05/18 07:34	AUTHORISATION TO ACT FORM	Load PDF	
7	09/05/18 07:34	Release Voucher	Load PDF	
8	09/05/18 07:34	RENTAL RECEIPT	Load PDF	
9	09/05/18 07:34	LTA SEARCH	Load PDF	
10	09/05/18 07:34	LETTER TO OI	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	05/04/18 16:44	TP LOD	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLB2260A (Insd veh)	Model:	VOLKSWAGEN JETTA TSI
	SLF9799X (TP veh)		1.4 (A)
Date of Accident:	21/03/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [X] Yes	<input type="checkbox"/> [] No
Repair Estimate	:	\$	10,709.46
Final Repair Cost	:	\$	8,000.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	6 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	8,000.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> [] YES <input checked="" type="checkbox"/> [X] NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ____ 100 ____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Kang Auto Engineering Pte Ltd	:	\$ 8,000.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

09 May
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18005435/KPB3Q2

Date: 09/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100462287
 Claimant Vehicle No: SLF9799X Insured Vehicle No: SLB2260A
 Date of Loss: 21/03/2018 Nature of Claim: TP Claim No: 0792716967SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLF9799X
 Make & Model: VOLKSWAGEN JETTA TSI, 1.4 (A) Engine No: CAXF85741
 Reg. Date: 16/09/2016 (Man. Year: 2016) Chassis No: WWWZZZ16ZGM040922
 Colour: White Odometer: 24057 km
 Engine Capacity: 1390 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/35 R19 Rear Tyre Size: 235/35 R19
 Front Left Side: Goodyear 8 mm Rear Left Side: Goodyear 8 mm
 Front Right Side: Goodyear 8 mm Rear Right Side: Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,089.46	5,842.06	1,247.40	17.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,620.00	1,770.00	1,850.00	51.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	10,709.46	7,612.06	3,097.40	28.92
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,219.51		
Global Sum Settlement (S\$)		8,000.00		

INSPECTION

Date of Assignment: 22/03/2018
 Date Inspected: 23/03/2018 Inspected At: Kang Auto Engineering Pte Ltd
 160 Sin Ming Drive, #02-16, Sin Ming
 AutoCity
 Singapore 575722
 Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT R/H FENDER	Bent / Warped	435.00 F	*435.00 F
2	1		*FRONT R/H DOOR	Bent	2,328.53 F	*2,328.53 F
3	1		*FRONT R/H DOOR RUBBER	Necessary	155.00 F	*155.00 F
4	1		*FRONT R/H HINGES	Repair	236.20 F	*- F
5	1		*REAR R/H DOOR	Bent	2,328.53 F	*2,328.53 F
6	1		*REAR R/H DOOR RUBBER	Necessary	155.00 F	*155.00 F
7	1		*REAR R/H DOOR HINGES	Repair	236.20 F	*- F
8	1		*R/H SIDE SKIRT	Repair	775.00 F	*- F
9	1		*FRONT RH DOOR REGULATOR GEAR	Distorted	260.00 F	*260.00 F
10	1		*FRONT RH DOOR MOTOR	Jammed	180.00 F	*180.00 F

F=Franchise part.

Total Parts (S\$)	7,089.46	5,842.06
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING ,AUDIO SYSTEM AND SYSTEM RESETING	New	250.00	20.00
2	TO RE-SET WHEEL ALIGNMENT	New	120.00	60.00
3	TO TRANSFER DOOR TO NEW DOOR	New	250.00	120.00
4	TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL	New	200.00	90.00
5	TO PUTTY AND SPRAY PAINT CHARGES	New	1,600.00	880.00
6	LABOUR CHARGES	New	1,200.00	600.00
Gross Labour Cost (S\$)			3,620.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >