

ASS. REC. BY:

REF: CS/MSG18005460/ RI rd3et

Special Instruction

Survivor
Merimen

Reason

ASSIGNMENT (Office)

Date/Time: 22/3/18 @ 2:07pm

From (Person):

Lionel Tan

of

MSG

Bill to:

Estimated Cost:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

Insured: SJJ 65312

To Inspect Vehicle No:

SJG 3745J

Tel: 66311857

at Workshop m/s

Borneo Motors

2 Pandan Crescent

of

Policy No: 29067495 MCY

Claim No: 551062

Sum Insured:

Excess:

D.O.A. 15/02/2018

Make of Veh:
(Client's Record)

04-04-2018 @ 10am - 12pm

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS / wp

Date/Time: 10:08am @ 23/3/18 Person Contacted:

Reymond

Vehicle IN / OUT

Date/Time Action/Instruction (✓) Estimate

SJG 3745J -X

SJJ 65312 -X

05/04/18 @ 14:15 p.m revised to Lionel Tan Tian Pei via merimen.

9/4/18 Final fig \$ 1617.19 confirmed by email (Ref 3287.63, 679)

Signature *Rane*

REF: MSU1

0233B

04 XPiky, 2018/84N

ASSIGNMENT

From: Date: 04042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJG 3745J

at Workshop m/s: Borneo Motor
of 2 Pandan Crescent

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Raymond

10am - 12pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 8K 8.5K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJG 3745J Yr Regn: 2008 / July

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA COROLLA VIOS EA c.c 1497

Colour: GREY A/C: Insured / Std / NI / NA

Sp.Reading: 111185 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MK053H49305069830

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 5 mm

L/Bal: 5 mm

D.O.A: 15/02/18

Survey held at: Borneo Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 09 APR 2018

Date/Time: File Pass to?

☐ : Preli. Report

☐ : Final Report

Date/Time: File Return to?

2) 914- typist

Report Format: merimen

Lump Sum / I.B.I: (\$) 1617.19

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18005460/R1vd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 23-03-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJJ 6531Z	Veh. Inspected	SJG 3745J
Policy No.	29067495MCY	Coverage (\$)	0.00
Claim No.	551062	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	23/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/02/2018	Inspection Date
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Mar 2018		22 Mar 2018 14:07 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HANWELL HOLDINGS LIMITED, Co. Reg. No.: 197400888M		
Main Claimant:	LEE YEN SIN, ID: S7520833B		
Vehicle Reg. No.:	SJG3745J	Date of Loss:	15/02/2018 16:00 - :59
Claim Type:	TP / 551062	Policy/Cover Note No.:	29067495MCY (Comprehensive) Coverage: 01/01/2018 - 31/12/2018
Vehicle Reg. No. (Insured):	SJJ6531Z	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/03/2018]		
Driver/Custodian (Insured):	YEO KUAN WEI(YANG GUANGWEI) (41 / Male), NRIC: S7637810Z		
Adj Asg. Remarks:	ON WP		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0833B
Vehicle Details	
Vehicle No.:	SJG3745J
Vehicle to be Exported:	No
Intended De-registration Date:	05 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1NZX774026
Chassis No.:	MR053HY9305069830
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,344.00
Original Registration Date:	27 Jun 2008 ✓
First Registration Date:	27 Jun 2008
Transfer Count:	1
Actual ARF Paid:	\$12,344.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jun 2018
PARF Rebate Amount:	\$6,172.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jun 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,590.00
COE Rebate Amount:	\$328.00
Total Rebate Amount:	\$6,500.00

The information contained herein is correct as at 05 Apr 2018

OK

85w
~~8000~~
 6,15w
 1500 2000

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
Tel: 6461 6555 | Fax: 6221 3302 | Website: www.sompo.com.sg
Co. Reg. No.: 198905490E | GST Reg. No.: M200903196

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No. : D17MTPV01017017
Insured : LEE YEN SIN
Motor Car (Registration No.) : SJG3745J
Cover : Comprehensive - ExcelDrive FOCUS
Policy Commencement Date : 27 DECEMBER 2017 00:00
Policy Expiry Date : 26 DECEMBER 2018 23:59
Maximum Liability (Section I) : Market value at time of loss
Excess* : \$500 - Section I
(Waived up to 50% or maximum S\$600 whichever is lower if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess* : Buy Up : \$600 - Section I
Windscreen Excess* : S\$100.00 - Waived if Repair at ExcelDrive Workshop
Loss of Use : N.A.
* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the insured,
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

WE HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP.27

Sompo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue : 20 NOVEMBER 2017 16:43

IMPORTANT NOTICE

- o Keep the Certificate in your Motor Car.
- o Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
- o On the sale of the Motor Car or if for any reason the Insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).
- o This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name : 11P02009 & PANA HARRISON (ASIA) PTE LTD CI Code: 22A L4KDHSB2202YM6EA

SOMPO**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
 Tel: 6461 6555 | Fax: 6221 3302 | Website: www.sompo.com.sg
 Co. Reg. No.: 198905490E | GST Reg. No.: M200903196

PRIVATE CAR POLICY SCHEDULE

Policy No. : D17MTPV01017017

Intermediary Code : 11P02009

This Schedule is issued in accordance and should be read in conjunction with the terms, conditions and exceptions of the
 PRIVATE CAR Policy wordings, ref. MTP.27

Insured : LEE YEN SIN
 Address : 52 DUCHESS AVENUE
 #04-05
 SINGAPORE 269197

Business/Profession : BUSINESS CENTER HEAD

INSURED DETAILS

Date of Birth & Age : 15 JUL 1975 & 42 years old
 Driving Experience in Singapore : 20 years

Marital Status : MARRIED
 Gender : Female

Identification Type : NRIC(Singaporean)

Identification No. : S7520833B

Period of Insurance : 27 DECEMBER 2017 00:00 TO 26 DECEMBER 2018 23:59

Persons or Classes of Persons entitled to drive : Refer to Certificate of Insurance

Limitations as to use : Refer to Certificate of Insurance

VEHICLE DETAILS

Vehicle Registration No. : SJG3745J
 Chassis No. : MR053HY9305069830
 Engine No. : 1NZX774026
 Vehicle Make & Model : TOYOTA VIOS 1.5E A
 Cc : 1497
 Type of Body : SALOON
 Year of Registration : 2008
 Seating Capacity : 5
 (including driver)
 Estimated value of Vehicle : Market value at time of loss
 Hire Purchase Owner : NIL

PREMIUM DETAILS

Premium	1,479.00
Less No Claim Discount (30%)	(443.70)
Less Offence free Discount (5%)	(51.77)
Less EDF Discount (20%)	(196.71)
Add others :	
Less Buy Up Excess	(90.00)
Total	S\$ 696.82
GST	S\$ 48.78
Premium (incl. GST)	S\$ 745.60

Coverage : Comprehensive - ExcelDrive FOCUS

Excess : \$ 500 - Section I
 (Waived up to 50% or maximum S\$600 whichever is lower if accident repair is done at ExcelDrive Workshops for the first claim per policy year)

Voluntary Excess : Buy Up : \$ 600 - Section I
 In consideration of the premium discount granted, the Insured shall bear the additional Voluntary Excess specified above. The additional Voluntary Excess will not be waived for repairs at ExcelDrive Workshops.

Additional Excess : Named Young and/or Inexperienced Drivers or Elderly Drivers - \$1,500
 Un-named Young and/or Inexperienced Drivers or Elderly Drivers - \$3,000
 Un-named All Other Drivers - \$500

The terms shall be defined as follows:

'Young Drivers' shall be defined as drivers (including the Insured) who are below 25 years old.

'Inexperienced Drivers' shall be defined as drivers (including the Insured) who have less than 2 years of driving experience in Singapore

'Elderly Drivers' shall be defined as drivers (including the Insured) who are above 70 years old.

Paragraph 2 of Endorsement E in the policy will not apply to insured's spouse provided he/she is 25 years old & above but less than 70 years old &/or has 2 or more years driving experience.

Windscreen Excess : S\$100.00 - Waived if Repair at ExcelDrive Workshop

Endorsements Applicable : Endorsement D - Young and/or Inexperienced or Elderly Drivers Excess
 Endorsement E - Excess Clause
 Endorsement H - Total Loss
 Endorsement M - Inclusion Of Special Perils
 Endorsement P6 - Riot And Strike Endorsement

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7520833B



Name
LEE YEN SIN
(LI YANXIN)
李燕心
Race
CHINESE
Date of birth
15-07-1975 Sex
F
Country of birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S7520833B**
Name:
LEE YEN SIN
(LI YANXIN)
Birth Date: **15 Jul 1975**
Issue Date: **23 Jun 2005**



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7274138B



Name
GOH MONG CHIN
吴梦炯
Race
CHINESE
Date of Birth
21-12-1972 Sex
M
Country of Birth
MALAYSIA

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S7274138B**
Name:
GOH MONG CHIN
Birth Date: **21 Dec 1972**
Issue Date: **04 Apr 2007**



NRIC No. **S7520833B**



Date of issue
14-03-2005
52 DUCHESS AVENUE #04-05
SINGAPORE 269197
NRIC No: **S7520833B** Date: **08/09/2014**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor cars =< 3000 kg with =< 7 passengers, exclusive of the driver; and motor tractors / vehicles =< 2500 kg

PASS DATE
17 Oct 1994

NP 428A



NRIC No. **S7274138B**



Nationality
MALAYSIAN
Blood Group Date of issue
O+ **03-02-1996**
52 DUCH **3 AVENUE #04-05**
SINGAPO **269197**
S7274138B **08/09/2014**


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver, and other motor vehicles =< 2500kg

PASS DATE

04 Apr 2007

NP 428A



COLLECTION SLIP FOR NEW SINGAPORE CITIZEN



SIC NO: S7274138B (PINK IC)

FEES: \$10.00

NAME: GOH MONG CHIN

DATE OF ISSUE: 05/03/2018

REGISTRATION OFFICER: SAUYAH BINTE PARJAN



DOCUMENTS ARE TO BE PRESENTED AT GRC CITIZENSHIP CEREMONY.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/02/2018 23:36
Date Of Accident	15/02/2018 16:45
Exact Location Of Accident	WOODLANDS CHECKPOINT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJG3745J
Insured/Policyholder	
Name Of Registered Owner	LEE YEN SIN
NRIC No	S7520833B
Email Address	GMCYS@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-97362887
Alternative Phone No	OFFICE-97362887

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS E AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01017017
Cover Note Number	N.A.

Driver

Name of Driver	GOH MONG CHIN
NRIC No	S7274138B
Date Of Birth	21/12/1972
Occupation	INDOOR
Date Of Driving Pass	04/04/2007
Driving Experience	10 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97362887
Fax Number	
Contact Number	OFFICE-97362887
Email Address	GMCYS@SINGNET.COM.SG

Address	52 DUCHESS AVENUE #04-05
Postcode	269197
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : LEE YEN SIN GENDER: : FEMALE
Passenger 2	NAME: : GOH TZU KYE GENDER: : MALE
Passenger 3	NAME: : ATUN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

My vehicle was in stationary position due to heavy traffic at the woodlands checkpoint. While waiting, suddenly I felt an impact from the right and saw a vehicle just inched out from the custom booth. As a result the vehicle bumped onto my vehicle right side rear bumper. We both already agreed about private settlement. I waited for him and ended he had file the accident report and told me to claim his insurance.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJJ6531Z
Vehicle Make/Model/Colour	HONDA/FREED 1.5G A/RED
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MR YEO KUAN WEI

NRIC/Passport Number	S7637810Z
Contact Number	86861130
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of an incident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as correct and accurate as possible. Any willful misrepresentation or withholding of material facts may affect insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) I understand, acknowledge, agree and consent that:
 - (i) my insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured my vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER


AIZAM BIN ATAN

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



Common Statement

ACCIDENT STATEMENT (2000 characters)

My vehicle was in stationary position due to heavy traffic at the woodlands checkpoint. While waiting, suddenly I felt an impact from the right and saw a vehicle just inched out from the custom booth. As a result the vehicle bumped onto my vehicle right side rear bumper. We both already agreed about private settlement. I waited for him and ended he had file the accident report and told me to claim his insurance.

Taxi Voucher No.:

Are you claiming your own insurance policy for the repair of your vehicle?

No. Claim 3rd party

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect.

VERIFIED BY AJAX MARS REPORTING OFFICER -
AIZAM BIN ATAN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

28 February, 2018 8:30 pm

Date/Time:

28 February, 2018 8:30 pm



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188
Customer Detail

Mdm Chong Yok Tiong
629 Woodlands Ring Road
#06-242
Singapore 730629
Mobile: 98582060

Account Detail		Account No	Mdm Chong Yok Tiong 629 Woodlands Ring Road #06-242 Singapore 730629 Mobile: 98582060
THIRD PARTY CLAIM <i>MSG</i>	S1000020 / TPCLAIM		
	Document No	0	
		Document Date	21/03/2018

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
08	BEPRKT	NCP93R	27/06/2008	SJG3745J	0	30089	9DS/SJG3745J-15021
Chassis No		Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On

MR053HY9305069830	1NZX774026	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00
-------------------	------------	----	------------------	------------	------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	2	BP-SUNDRY TP/DS CLAIM TP VEH: SJJ6531Z ACC DATE: 15/02/2018 TP INS: <i>MSG</i> NO OF REPAIR DAYS: DATE-IN: DATE SURVEY: BY: LKK AUTHORIZED ON:				30.00
2	B	BP-LAB TO CHECK WIRING & LIGHTING. TO WATER TEST FOR LEAK.				X 91.12
3	B	BP-LAB TO DRILL HOLES & INSTALL REVERSE SENSOR ON NEW BUMPER.				X 154.00
4	B	BP-LAB TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.				✓ 616 1848.00
5	B	BP-RES TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.				✓ 506 1518.00
6	1	S81550-OD220 R/R COMBINATION LAMP,	1.00	413.80		WAX 413.80
7	2	S81910-OD010 R/R BUMPER REFLECTOR,	1.00	88.60		WAX 88.60
8	3	S52159-OD983 REAR BUMPER COVER, <i>40791</i>	1.00	479.90		DE-R 479.90 ✓
9	4	S52161-OK040 PIECE, RR BUMPER	4.00	3.90		WAX 15.60
10	5	S52575-OD070 R/RR BUMPER RETAINER,	1.00	99.20		SVC X 99.20
11	6	S52576-OD070 L/RR BUMPER RETAINER,	1.00	99.20		WAX 99.20
12	7	S52155-OD030 R/R SIDE BPR SUPPORT, <i>38.64</i>	1.00	33.70		new X 33.70 ✓

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	Amount Due
		Others	

PLEASE TEAR ALONG PERFORATED LINE

3624028

TO SECURITY GUARD

3624028

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE
TIME 21/03/2018
12:49

VEHICLE NO

SJG3745J

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188
Customer Detail

ESTIMATE

Account Detail	Account No	Mdm Chong Yok Tiong 629 Woodlands Ring Road #06-242 Singapore 730629 Mobile: 98582060
THIRD PARTY CLAIM	S1000020 / TPCLAIM Document No	
	0 Document Date 21/03/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
08	BEPRKT	NCP93R	27/06/2008	SJG3745J	0	30089	9DS/SJG3745J-15021
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

MR053HY9305069830 1NZX774026 60 Raymond Seah L M --/--/---- 0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	8	S52156-0D030 L/R SIDE BPR SUPPORT, 38.64 nrc	1.00	33.70		X 33.70 ✓
<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div> <div style="margin-top: 10px;"> <p>Rasul Hy 90010068 3 days 04/04/18 @ 1245 Reg after repair</p> <p><i>[Signature]</i> 5/4/18</p> </div>						
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
<i>[Signature]</i>	Please acknowledge receipt of vehicle	Parts	4,904.82
		Labour	1,263.70
		Materials	3,641.12
		Lubrication/Fluid	0.00
		Others	0.00
			GST 7.00%
			Less
			0.00
			Amount Due
			5,248.16

PLEASE TEAR ALONG PERFORATED LINE

3624029

3624029

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE
TIME 21/03/2018
12:49

VEHICLE NO

SJG3745J

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

4/5/2018

Adjuster Immediate Advice

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 05 Apr 2018

Preliminary Advice

Insured Vehicle No	: SJJ6531Z	Accident Date	: 15/02/2018
TP Vehicle No	: SJG3745J	Assignment Date	: 22/03/2018
Make	: TOYOTA VIOS	Est. Duration of Repair	: 3.00
Date of Inspection	: 04/04/2018		
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,904.82
Revised Amount	:S\$	1,152.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,152.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

LIST ITEMS

<u>PAY</u>	<u>UNPAID</u>
	413.80
	88.60
	479.90
	15.60
	99.20
	99.20
	33.70
	33.70

NETT ITEMS

<u>PAY</u>	<u>UNPAID</u>
------------	---------------

LABOUR

<u>PAY</u>	<u>UNPAID</u>
30.00	91.12
616.00	154.00
506.00	1232.00
	1012.00

0.00

0.00

0.00

1263.70

1152.00

2489.12

0.00

4904.82

3641.12

0.00

3641.12

1152.00

0.00

1263.70

2489.12

0.00

0.00

0.00 LIST ITEM (PAY)

0.00 NETT ITEM (PAY)

1152.00 LABOUR (PAY)

1152.00

}

CHECK ITEM

0.00

0.00 (20% DISC)

0.00 LIST ITEM AFTER DISC (CHECK ITEM)

0.00 LABOUR (CHECK ITEM)

0.00

TOTAL = 1152.00 (PAY ITEM)



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6531 1188

Account Detail		Account No	Customer Detail				
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUA1	LEE YEN SIN 52 DUCHESS AVENUE #04-05 Singapore 269197 269197 Mobile: 97362887				
Document No		0					
Document Date		06/04/2018					
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
08	BEPRKT	NCP93R	27/06/2008	SJG3745J	136767	30089	9DS/SJG3745J-15021:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053HY9305069830	1NZX774026	60	Raymond Seah L M	04/04/2018 12.50	06/04/2018 18.00		
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY TP/DS CLAIM TP VEH: SJJ6531Z ACC DATE: 15/02/2018 TP INS: MSIG NO OF REPAIR DAYS: 03 DATE-IN: 04/04/2018 DATE SURVEY: 04/04/2018 BY: LKK-RASUL AUTHORISED ON: 29/03/2018				30.00	
2	B	BP-LAB TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.	36			616.00	
3	B	BP-RES TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.	*			506.00	
4	1	S52159-OD983 COVER, RR BUMPER	1.00	479.90	15.00	407.91	
5	2	S52155-OD030 SUPPORT, BUMPER RH	1.00	33.70	15.00	28.64	
6	3	S52156-OD030 SUPPORT, BUMPER LH	1.00	33.70	15.00	28.64	
<p>P.S. REAR BUMPER CRACK & DEFORM SEE PHOTOS.</p> <p>Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.</p>							
For & on behalf of Borneo Motors		Customer's Signature	Change Summary		Total		1,617.19
		Please acknowledge receipt of vehicle	Parts	465.19	GST 7.00%	113.20	
			Labour	1,152.00	Less	0.00	
			Materials	0.00			
			Lubrication/Fluid	0.00			
			Others	0.00			
Amount Due						1,730.39	

PLEASE TEAR ALONG PERFORATED LINE

3623440

3623440

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 06/04/2018
TIME 10:53

VEHICLE NO SJG3745J

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 9 April 2018 10:47 AM
To: 'Raymond Seah PTCBC'; Rasul (LKKAUTO)
Cc: SUR
Subject: RE: FINALISE FOR SJG3745J

Dear Raymond,

Confirmed final figure \$1,617.19 before GST

No of days: 3 days

Final invoice and all supporting documents sent over to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Raymond Seah PTCBC [mailto:Raymond.Seah@borneomotors.com.sg]
Sent: Friday, 6 April 2018 10:58 AM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: FINALISE FOR SJG3745J

Dear Rasul,

Attach are photos & estimate of SJG3745J to finalize.

Thanks

Raymond Seah

9221 3150

From: Raymond.Seah@borneomotors.com.sg <Raymond.Seah@borneomotors.com.sg>
Sent: Friday, April 6, 2018 10:56 AM
To: Raymond Seah PTCBC
Subject: Scan Data from FX-0DBC96

Sent by: B051779 [Raymond.Seah@borneomotors.com.sg]
Number of Images: 1
Attachment File Type: PDF

Device Name: ApeosPort-V C2276
Device Location:

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Mar 2018		22 Mar 2018 14:07 Edit Adj Rpt	S\$1,617.19 Edit Estimates	S\$1,617.19 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: HANWELL HOLDINGS LIMITED , Co. Reg. No.: 197400888M									
Main Claimant: LEE YEN SIN , ID: S7520833B									
Vehicle Reg. No.: SJG3745J		Date of Loss: 15/02/2018 16:00 - :59 [115 Months and 19 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 551062		Policy/Cover Note No.: 29067495MCY (Comprehensive) Coverage: 01/01/2018 - 31/12/2018							
Vehicle Reg. No. (Insured): SJJ6531Z		Policy No. (Claimant):							
		Excess: S\$500.00							
Repairer: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 21/04/2018]									
Driver/Custodian (Insured): YEO KUAN WEI(YANG GUANGWEI) (41 / Male), NRIC: S7637810Z									
Adj Asg. Remarks: ON WP									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJG3745J (551062)
[SJJ6531Z]
TP
LEE YEN SIN
Feb 15 2018 4:00PM
[HANWELL HOLDINGS LIMITED]
Borneo Motors (S) Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

1 per page ☐

☒

Assessment Reports			Thumbnail	Print
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Load HTM
1	05/04/18 14:15	Adjuster Immediate Advice		

3 per page ☐


☒

Photos/Images			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Load JPG <input checked="" type="checkbox"/>
1	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
2	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
3	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
4	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
5	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
6	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
7	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
8	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
9	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
10	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
11	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
12	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
13	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
14	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
15	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
16	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
17	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
18	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
19	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
20	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
21	05/04/18 12:32	General View		Load JPG <input checked="" type="checkbox"/>
22	06/04/18 14:31	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
23	06/04/18 14:31	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
24	06/04/18 14:31	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
25	06/04/18 14:31	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
26	06/04/18 14:31	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
27	06/04/18 14:31	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
28	06/04/18 14:31	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
29	06/04/18 14:31	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

1 per page ☐

☒

Documentation			Thumbnail	Print
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Load PDF
1	21/03/18 16:57	TPD SJG3745J GIA REPORT		Load PDF
2	21/03/18 16:57	TPD SJG3745J EST.		Load PDF
3	21/03/18 16:57	OI SJJ6531Z GIA REPORT		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005460/R1VD3E2

Date: 12/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29067495MCY

Claimant Vehicle No: SJG3745J

Insured Vehicle No: SJJ6531Z

Date of Loss: 15/02/2018

Nature of Claim: TP

Claim No: 551062

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJG3745J

Make & Model: TOYOTA VIOS, 1.5 E (A)

Engine No: 1NZX774026

Reg. Date: 27/06/2008 (Man. Year: 2008)

Chassis No: MR053HY9305069830

Colour: Grey

Odometer: 111185 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,293.70	495.19	798.51	61.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,611.12	1,122.00	2,489.12	68.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,904.82	1,617.19	3,287.63	67.03
+ GST 7.00/7.00% (S\$)	343.34	113.20	230.14	67.03
Nett Amount (S\$)	5,248.16	1,730.39	3,517.77	67.03

INSPECTION

Date of Assignment: 22/03/2018

Date Inspected: 04/04/2018 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Apr 2018)
Parts: 143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJG3745J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	30.00 FS	*30.00 FS
2	1		*R/R COMBINATION LAMP	Not Necessary	413.80 FS	*- FS
3	1		*R/R BUMPER REFLECTOR	Not Necessary	88.60 FS	*- FS
4	1		*REAR BUMPER COVER	Deformed	479.90 FS	*407.91 FS
5	4		*PIECE, RR BUMPER	Not Necessary	15.60 FS	*- FS
6	1		*R/RR BUMPER RETAINER	Serviceable	99.20 FS	*- FS
7	1		*L/RR BUMPER RETAINER	Not Necessary	99.20 FS	*- FS
8	1		*R/R SIDE BPR SUPPORT	Necessary	33.70 FS	*28.64 FS
9	1		*L/R SIDE BPR SUPPORT	Necessary	33.70 FS	*28.64 FS
Total Parts (S\$)					1,293.70	495.19

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING & LIGHTING. TO WATER TEST FOR LEAK	New	91.12	0.00
2	TO DRILL HOLES & INSTALL REVERSE SENSOR ON NEW BUMPER	New	154.00	0.00
3	TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN / REALIGN ALL OTHER AFFECTED AREAS	New	1,848.00	616.00
4	TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS	New	1,518.00	506.00
Gross Labour Cost (S\$)			3,611.12	1,122.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >