

22/03/2007

Range & days

ASS. REC. BY:

REF:

CS3/CTI18005462/M1d30

Special Instruction:

Surveyor:

Meimen

MA

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

23/3/18 @ 9:22am

Estimated Cost:

Bill to:

OD / ☒ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

WYW 731

Insured:

GBF 5288Z

at Workshop m/s

Kuo Li Auto Workshop

Tel:

9694 3328

of

Blk 5035, AMK Ind Park 2 # 01-363

Policy No:

DMCVSN3015961801

Claim No:

SNM18D01419C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/03/2018

CA / REV / REP. / REV 24 HRS

/wp

H.O.D. Endorsement:

Date/Time:

9:19am @ 23/3/18

Person Contacted:

Alvin

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(X)

Estimate

WYW 731 - X

GBF 5288Z - X

Dismantle: 23/3/2018

After repair: 10/4/2018

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: WYW 731Yr Regn: 08 / 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDAC.C. 249Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: NO READING

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM4M357C 201101100Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/70R17R: 150/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 16/3/2018D.O.I. 23/03/2018

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

NEC BODY PRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>PRI. [No Estimate upon Survey]</u>
	<u>Estimated repair range = \$4,000 - \$5,500</u>
	<u>5 days</u>
	<u>RECEIVED 12 JUN 2018</u>
	<u>7/6/2018</u>

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 5

1)

☐ : Final ReportResurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee: 150

2)

Add Fee: ☐ : Site Insp (\$)

Transportation

☐ : Interview (\$)

) S + RS. SI

☐ : Tech. Invs (\$)

) Photos

☐ : Weekend (\$)

) Others

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Mar 2018		23 Mar 2018 09:22 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	EVERLASTING FURNITURES , Co. Reg. No.: 53132944E		[Created by insurer]
Main Claimant:	LAU HOCK WEI , ID: G2838386Q		
Vehicle Reg. No.:	WYW731	Date of Loss:	16/03/2018 13:00 - :59
Claim Type:	TP / SNM18D01419C02	Policy/Cover Note No.:	DMCVSN3015961801 (Comprehensive)
Vehicle Reg. No. (Insured):	GBF5288Z	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Kuo Li Auto Workshop (HQ) Blk 5035 Ang Mo Kio Ind Park 2, #01-363, 569538 Ang Mo Kio - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/04/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Thursday, 22 March 2018 6:02 PM
To: Jennifer Guay; Lucas Lee
Cc: assignments@lkkauto.com
Subject: RE: OUR REF: AW-INS-K24-WYW731-18.jgv & YR REF: GBF 5288Z

Dear Catherine,

As spoken, please get your survey to conduct a PRS

Regards,

Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Jennifer Guay [mailto:jenniferguay@visionlawllc.com]
Sent: Thursday, 22 March, 2018 6:00 PM
To: Sharon Han <sharon.han@sg.cntaiping.com>; Lucas Lee <lucas.lee@sg.cntaiping.com>
Cc: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: RE: OUR REF: AW-INS-K24-WYW731-18.jgv & YR REF: GBF 5288Z
Importance: High

PRE - REPAIR SURVEY

CLAIMANT: LAU HOCK WEI

ACCIDENT INVOLVING WYW 731 & GBF 5288 Z ON 16 MARCH 2018 ALONG DEFU LANE 10

Dear Irene

As spoken, our repairers reject LKK to conduct a pre-repair survey and to your List of Surveyors.

TAKE NOTICE that we object to all your surveyors stated in your said List, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following surveyor for your consideration:-

1. Lee Kok Weng

Our client's vehicle is available for Pre-repair survey as follows :

Name of Workshop **KUO LI AUTO WORKSHOP**

Address Blk 5035 Ang Mo Kio Industrial Park 2 # 01-363
Singapore 569536

Contact Person 9694 3328 – Alvin

Thank you.

Regards

Jennifer Guay

(Secretary)

VISION LAW LLC

133 New Bridge Road #18-01

Chinatown Point

Singapore 059413

Tel : 6534 2811 (Ext 116)

Fax : 6535 6802

From: Jennifer Guay [<mailto:jenniferguay@visionlawllc.com>]

Sent: Thursday, 22 March, 2018 5:54 PM

To: 'Sharon Han'; 'Lucas Lee'

Cc: 'Irene Tay'

Subject: RE: OUR REF: AW-INS-K24-WYW731-18.jgv & YR REF: GBF 5288Z

PRE - REPAIR SURVEY

CLAIMANT: LAU HOCK WEI

ACCIDENT INVOLVING WYW 731 & GBF 5288 Z ON 16 MARCH 2018 ALONG DEFU LANE 10

Dear Sharon

Thank you for your email.

Todate your office has not responded to the PRI repair .

Please expedite. Thank you.

Regards

Jennifer Guay

(Secretary)

VISION LAW LLC

133 New Bridge Road #18-01

Chinatown Point

Singapore 059413

Tel : 6534 2811 (Ext 116)

Fax : 6535 6802

From: Sharon Han [<mailto:sharon.han@sg.cntaiping.com>]
Sent: Thursday, 22 March, 2018 2:33 PM
To: Lucas Lee
Cc: Irene Tay; Jennifer Guay
Subject: FW: OUR REF: AW-INS-K24-WYW731-18.jgv & YR REF: GBF 5288Z

Lucas – pls assist with the PRS arrangement.

Thank you & regards

Sharon Han
Motor Division
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-02
Springleaf Tower Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6193
Fax: 6224 7175 / 6224 7478
Email: claimsdept@sg.cntaiping.com
sharon.han@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer : This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Jennifer Guay [<mailto:jenniferguay@visionlawllc.com>]
Sent: Thursday, 22 March, 2018 12:27 PM
To: Sharon Han <sharon.han@sg.cntaiping.com>
Subject: FW: OUR REF: AW-INS-K24-WYW731-18.jgv & YR REF: GBF 5288Z

PRE - REPAIR SURVEY
CLAIMANT: LAU HOCK WEI
ACCIDENT INVOLVING WYW 731 & GBF 5288 Z ON 16 MARCH 2018 ALONG DEFU LANE 10

Dear Sharon

Please assist. Thanks

Regards

Jennifer Guay
(Secretary)

VISION LAW LLC

133 New Bridge Road #18-01
Chinatown Point
Singapore 059413
Tel : 6534 2811 (Ext 116)

Fax : 6535 6802

From: Jennifer Guay [<mailto:jenniferguay@visionlawllc.com>]
Sent: Wednesday, 21 March, 2018 4:22 PM
To: Claims Dept of CTI
Cc: 'Alvin Tan'
Subject: RE: OUR REF: AW-INS-K24-WYW731-18.jgv & YR REF: GBF 5288Z

PRE - REPAIR SURVEY
CLAIMANT: LAU HOCK WEI
ACCIDENT INVOLVING WYW 731 & GBF 5288 Z ON 16 MARCH 2018 ALONG DEFU LANE 10

Dear Sirs

Refer to our email of 20 March 2018 of which we have not hear from you.

Please let us hear from by close of business today. Thank you.

Regards

Jennifer Guay
(Secretary)

VISION LAW LLC

133 New Bridge Road #18-01
Chinatown Point
Singapore 059413
Tel : 6534 2811 (Ext 116)
Fax : 6535 6802

From: Jennifer Guay [<mailto:jenniferguay@visionlawllc.com>]
Sent: Tuesday, 20 March, 2018 2:21 PM
To: Claims Dept of CTI
Cc: 'Alvin Tan'
Subject: OUR REF: AW-INS-K24-WYW731-18.jgv & YR REF: GBF 5288Z
Importance: High

PRE - REPAIR SURVEY
CLAIMANT: LAU HOCK WEI
ACCIDENT INVOLVING WYW 731 & GBF 5288 Z ON 16 MARCH 2018 ALONG DEFU LANE 10

Dear Sirs

We are instructed by **LAU HOCK WEI** to notify you of a road accident on **16 MARCH 2018** at about 13.30hr **ALONG DEFU LANE 10** involving our client's **WYW 731 & GBF 5288 Z** driven by your driver at the material time.

As a result of the accident, our client's vehicle has been damage. Before our client proceed to repair the damage vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct

a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Jennifer Guay
(Secretary)
VISION LAW LLC
133 New Bridge Road #18-01
Chinatown Point
Singapore 059413
Tel : 6534 2811 (Ext 116)
Fax : 6535 6802

For Surveyor

Please initial here after completion of pre-repair survey.
Thank you.

Appointed Surveyor: _____

Name & Signature

Contact: _____

Date & Time _____

Surveyor during repair: _____

Date & Time: _____

Surveyor after repair: _____

Date & Time: _____

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

JABATAN PENGANGKUTAN JALAN MALAYSIA

PERAKUAN PENDAFTARAN KENDERAAN

No. Siri B 5313698

NO. PENDAFTARAN: WYW731

950707065713
[MAL]

Nama Pemunya
Berdaftar

WONG KA POH

Alamat

NO 1 TAMAN SRI MAKMUR
27000 JERANTUT PAHANG D.M.

No. Enjin

GT250-158437

No. Casis

KN4MJ57C2D1101100

Buatan

NAZA

Nama Model

NBF 250Ri

Keupayaan Enjin

249 S.P

Bahan Bakar

PETROL

Warna

HITAM

Kelas Kegunaan

MOTOSIKAL

Jenis Badan

MOTOSIKAL

Tahun Dibuat

2013

Tarikh Pendaftaran

28/08/2013

Status Pemunya

PERSENDIRIAN

Muatan Tempat

Duduk

2

Kadar Lesen

Kenderaan Motor

6 bulan

12 bulan

RM25.00

RM50.00

B.D.M/B.G.K

B.T.T.

Berat Kerb

B.T.M.

B.G.1

B.G.2

B.G.3

B.G.4

B.G.5

B.G.6

B.G.7

B.G.8

B.G.9

B.G.10

B.G.11

B.G.12

Tandatangan Pemunya Berdaftar

Perakuan Pendaftaran ini dikeluarkan

oleh Pengarah JPJ Negeri JPJ CAV. BDR. SRI PERMAISURI 1

PENASANGAN TEMPATAN

UNTUK KEGUNAAN PEJABAT

HAKSILIA DITUNTUT OLEH IK P BIAH MOTOR NO SIRI SURAT (J017)

NOTA PENTING

1. Simpan perakuan ini di tempat yang selamat. Jika perakuan ini hilang, anda dikehendaki melaporkan kepada balai polis dengan segera dan memohon salinan perakuan pendaftaran daripada Pengarah Jabatan Pengangkutan Jalan (JPJ).
2. Semak butir-butir kenderaan di muka ini dan laporkan dengan segera kepada Pengarah JPJ jika terdapat sebarang perubahan.
3. Lesen kenderaan motor yang sah hendaklah sentiasa dipamerkan. Anda boleh membatalkan lesen 60 hari sebelum tempohnya tamat.
4. Anda dikehendaki melaporkan secara bertulis dengan segera kepada Pengarah JPJ sekiranya kenderaan anda tidak berlesen.
5. Jika anda menjual kenderaan, serahkan perakuan pendaftaran ini kepada pembeli. Anda dan pembeli dikehendaki mengisi dan mengemukakan borang JPJK3/JPJK3A kepada Pengarah JPJ dalam tempoh tujuh hari dari tarikh penjualan itu.
6. Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran milikan telah disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik baru.
7. Jika selamat anda bertukar, kemukakan perakuan pendaftaran ini kepada Pengarah JPJ dalam tempoh tujuh hari dari tarikh pertukaran itu.



Police Station Of Origin:
Hougang NPP
357 Hougang Avenue 7 #01-805
SINGAPORE 530357
Tel No: 1800-2869999

Report No. T/20180316/2148

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/03/2018 18:46	Vide Report No.:	Station Diary No.: 29
--	------------------	--------------------------

Informant's Particulars

Name of Informant: LAU HOCK WEI			Address: APT BLK 103 YISHUN RING ROAD #01-95 SINGAPORE 760103	
ID Type / ID No.: FIN NO / G2838386Q			Contact No.: Home/Office: Mobile: 91315598	
Nationality: MALAYSIAN			Email:	
Sex: Male	Age: 25	Date of Birth: 02/09/1992	Type of Informant: Rider	
Race: Chinese			Language: Malay	Institution / School Name:
Occupation: STOREKEEPER			Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 16/03/2018 13:30	Type of Location: BETWEEN ROADS
Location: Along Road 1 DEFU LANE 10 ALONG DEFU LANE 10, BLK 31				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF5288Z	Lorry	TOYOTA		Grey	Slightly Damaged	0
WYW731	Motorcycle	NAZA		Black	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Hougang NPP
357 Hougang Avenue 7 #01-805
SINGAPORE 530357
Tel No: 1800-2869999

Report No. T/20180316/2148

CONTINUATION OF REPORT

Date

Name	SIEW GEK		ID No.	S6925017C
Related Vehicle	GBF5288Z (Lorry)		Contact No.	96756310
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Rider				
Name	LAU HOCK WEI		ID No.	G2838386Q
Related Vehicle	WYW731 (Motorcycle)		Contact No.	91315598
Hospital/Clinic	RAFFLES HOSPITAL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	16/03/2018		Date Discharge	16/03/2018
No. of Days granted Medical Leave	05		Degree of Injury	Slight

Brief Details.

On 16/03/2018 at about 1328hrs, I was riding my Black Naza Malaysian motorcycle bearing the plate number WYW731 along Defu Lane 10. I was along the vicinity of Blk 31 Defu Lane 10. I noticed that there was a lorry was about to make a right turn into my road. The lorry then made a quick right turn into my road and I engaged my motorcycle's brake however both vehicles got into a Traffic Accident. The lorry is a Gray Toyota GBF5288Z.

On the same day, my motorcycle collided head on into the lorry's driver side front door. I fell onto the road. Shortly, Police and Ambulance came to the scene. I was immediately conveyed to Raffles Hospital to get Medical treatment. I suffered a fracture at my left elbow and multiple abrasions on my left arm. I was awarded 5 days of medical leave. I was informed that my company colleague helped me push and park my motorcycle aside during the Accident.

I do not have recording of the accident. That is all.



SINGAPORE
POLICE FORCE



T/20180316/2148

3 of 3

Police Station Of Origin:
Hougang NPP
357 Hougang Avenue 7 #01-805
SINGAPORE 530357
Tel No: 1800-2869999

Report No. T/20180316/2148

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Staff Sgt MUHAMMAD SALAMUN BIN AHMAD

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt MUHAMMAD KHAIRIL BIN KAMAL

Contact No.: 65476131

Signature Of Informant:

Date/Time:

16/03/2018 18:46

Classification Of Case:

Authentication Stamp

NP168

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Mar 2018		23 Mar 2018 09:22 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: EVERLASTING FURNITURES , Co. Reg. No.: 53132944E									
Main Claimant: LAU HOCK WEI , ID: G2838386Q									
Vehicle Reg. No.: WYW731		Date of Loss: 16/03/2018 13:00 - :59 [54 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D01419C02		Policy/Cover Note No.: DMCVSN3015961801 (Comprehensive)							
Vehicle Reg. No. (Insured): GBF5288Z		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Kuo Li Auto Workshop (HQ) Blk 5035 Ang Mo Kio Ind Park 2, #01-363, 569538 Ang Mo Kio - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 04/04/2018]									
Adj Asg. Remarks: NO EST, CASE W/O SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***WYW731 (SNM18D01419C02)**
[GBF5288Z]
TP
LAU HOCK WEI
Mar 16 2018 1:00PM
[EVERLASTING FURNITURES]
Kuo Li Auto Workshop

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	17/03/18 11:19	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	17/03/18 11:16	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	17/03/18 11:16	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	17/03/18 11:16	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	17/03/18 11:16	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	17/03/18 11:16	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	17/03/18 11:16	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	17/03/18 11:16	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	17/03/18 11:16	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	17/03/18 11:16	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	17/03/18 11:16	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	17/03/18 11:16	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	17/03/18 11:16	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
13	17/03/18 11:16	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/05/18 11:38	General View	Load PDF	
2	02/05/18 11:40	Photographs of Damaged Parts	Load PDF	
3	12/06/18 15:45	Photo After Spray	Load PDF	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/03/18 09:22	PRS	Load PDF	
2	23/03/18 09:22	OI GIA REPORT	Load PDF	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	17/03/18 11:14	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	17/03/18 11:14	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	17/03/18 11:14	Police Report [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	17/03/18 11:14	Police Report [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	17/03/18 11:14	Police Report [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	17/03/18 11:14	Identification Card [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
7	17/03/18 11:14	Driving Licence [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	17/03/18 11:19	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	17/03/18 11:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	17/03/18 11:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	17/03/18 11:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	17/03/18 11:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	17/03/18 11:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	17/03/18 11:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	17/03/18 11:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	17/03/18 11:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	17/03/18 11:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	17/03/18 11:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	17/03/18 11:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	17/03/18 11:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	17/03/18 11:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	17/03/18 11:14	Accident Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	17/03/18 11:14	Accident Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
3	17/03/18 11:14	Police Report	Load JPG	<input checked="" type="checkbox"/>
4	17/03/18 11:14	Police Report	Load JPG	<input checked="" type="checkbox"/>
5	17/03/18 11:14	Police Report	Load JPG	<input checked="" type="checkbox"/>
6	17/03/18 11:14	Identification Card	Load JPG	<input checked="" type="checkbox"/>
7	17/03/18 11:14	Driving Licence	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118005462/M1D3E2

Date: 18/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3015961801

Claimant Vehicle
No : WYW731Insured Vehicle
No : GBF5288Z

Date of Loss: 16/03/2018

Nature of Claim: TP

Claim
No: SNM18D01419C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: WYW731

Make & Model: NAZA NBF250RI, 249cc

Reg. Date: 28/08/2013 (Man. Year: 2013)

Colour: Black

Engine Capacity: 249 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: GT250158437

Chassis No: KM4MJ57C201101100

Odometer: 0 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70 R17

Front Left Side: Bridgestone 7 mm

Front Right Side: 0 mm

Rear Tyre Size: 150/60 R17

Rear Left Side: Bridgestone 7 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/03/2018

Date Inspected: 23/03/2018 Inspected At:

Kuo Li Auto Workshop (HQ)
Blk 5035 Ang Mo Kio Ind Park 2, #01-363
Singapore 569538

Estimated Period of Repair: 5.0 days

Adjuster: MA CHIN FOOK

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,500.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 14 Jun 2018)

Parts: N/A NAZA NBF250RI 249cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for WYW731)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >