



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18005470/T1ga3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 12-06-2019



ATTN: VALE OH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDF 56K	Veh. Inspected	SKW 153R
Policy No.	P1261781	Coverage (\$)	0.00
Claim No.	S8M00BF1	Excess (\$)	0.00
Assign From	VALE OH	Assign Date	22/03/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VELLFIRE	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTNGF3DH708002727	Colour	BLACK
Odometer	130823	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50R18	HANKOOK	6 mm
L/H Front Tyre	235/50R18	HANKOOK	6 mm
R/H Rear Tyre	235/50R18	HANKOOK	6 mm
L/H Rear Tyre	235/50R18	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/03/2018	Inspection Date	23/03/2018
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	-----------------------