

ASS. REC. BY:

REF:

CS/ASM18005475/T1td3eb

Special Instruction:

Surveyor

Taufik

ASSIGNMENT (Office)

From (Person):

Yvonne Ang

of

ASM

Date/Time:

22/3/2018

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8JY 2240K

Insured:

at Workshop m/s

8ng Ah Tee

Tel:

62686183

of

Blk 3 pioneer Rd North #01-18

Policy No:

Claim No:

S8M00BMY

Sum Insured:

Excess:

78A 0

Make of Veh:

D.O.A.

22/03/2018

(Client's Record)

CA / ☒ REV /

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:52am @ 23/3/18

Person Contacted:

Joyce

Vehicle

☒ IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

26/3-

Revert via smart claims (not authorise)

28/3-

Revert with parts price

29/3-

Revert parts price pending DL

31/4

2:45pm authorise repair by Yvonne

3/4

inform Joyce authorise repair excess \$0

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: 169  
 (Client's Record) \_\_\_\_\_  
 Make of Veh: \_\_\_\_\_

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 426K-  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: 8JY2240K Yr Regn: 2010 Ag  
 Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Ford Fiesta Trend. C.C. 1388  
 Colour: Red A/C: \_\_\_\_\_ Insured / Std / NI / NA  
 Sp. Reading: 166266 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WF0JXXG7H3JH482284  
 Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt  
 Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or  
 Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 195/50 R15  
 R: 2 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
☒ TOYO / ☐ YOKO or \_\_\_\_\_

Front 6 mm Rear 6 mm  
 R/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 25/3/18 @ 6pm

Survey held at Sig Lm Pte

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Ft of s/w/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

lump sum \$3250/- (Red: 3092 :48%)

RECEIVED 14 AUG 2018

Date/Time File Pass to?

14/8 Typist

Date/Time File Return to?

2)

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Insp (\$)

☐ Weekend (\$)

Photos

Others

Report Format: OD

Lump Sum / (B.) (\$ 3250/-)

TOTAL

200

200



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18005475/T1td3

8 SHENTON WAY #24-01  
AXA TOWERS SINGAPORE 068811

Date : 23-03-2018



Code : ASM

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SJY 2240K
Policy No.	Coverage (\$)	0.00
Claim No. S8M00BMY	Excess (\$)	0.00
Assign From SMARTCLAIM (YVONNE ANG)	Assign Date	23/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date 22/03/2018	Inspection Date 23/03/2018
Survey held at SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.	

## 5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.



## Service Request Details

Claim

S8M00BMY

Reference

None 

Loss Date

March 22, 2018

Request Date

March 22, 2018

Due Date

June 23, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

### Actions

Next Step

Finish the work

Complete Work

More ▾

### Vehicle Information

Incident Vehicle Registration #

SJY2240K

Make

FORD

---

Service Address

---

Blk 3 Pioneer Road North, , , 628457

---

Primary Contact/Insured

---

GUO JIANHAO

05-723, 305B Punggol Road, 822305, Singapore

anthonyguojianhao@gmail.com

---

Claim Handler

---

ANG Yvonne

6568804461

yvonne.ang@axa.com.sg

Additional Instructions

EXCESS 0 PENDING EST & DL WORKSHOP : SNG AH TEE

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE



SENT

3/22/18 5:05 PM

FROM

ANG Yvonne

SUBJECT

PENDING INVESTIGATION

BODY

We are conducting investigation, fyi



## Denise Tay (LKKAUTO)

**From:** ANG Yvonne <yvonne.ang@axa.com.sg>  
**Sent:** Friday, 6 April 2018 7:03 PM  
**To:** Denise Tay (LKKAUTO)  
**Subject:** SJY2240K S8M00BMY GUO JIANHAO  
**Attachments:** 2240.pdf

Hi Denise

Can you assist to comment any mechanical issue when upon survey the vehicle ?

Regards

Yvonne Ang  
Assistant Manager  
Motor (Property) Claims

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | [www.axa.com.sg](http://www.axa.com.sg)  
Email: yvonne.ang@axa.com.sg  
DID: 1800 880 4888



**redefining / insurance**

### AXA's Values at Work:



**Customer  
First**



**Integrity**



**Courage**



**ONE  
AXA**

Please consider the environment before printing this email

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

### -----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

## Denise Tay (LKKAUTO)

---

**To:** ANG Yvonne  
**Subject:** RE: SJY2240K S8M00BMY GUO JIANHAO

Dear Yvonne,

According to our surveyor, there was no mechanical issue upon the survey

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** ANG Yvonne [<mailto:yvonne.ang@axa.com.sg>]

**Sent:** Wednesday, 11 April 2018 9:49 AM

**To:** Denise Tay (LKKAUTO) <[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)>

**Subject:** RE: SJY2240K S8M00BMY GUO JIANHAO

Hi Denise

Any update ?

Thanks

Yvonne Ang  
Assistant Manager  
Motor (Property) Claims

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | [www.axa.com.sg](http://www.axa.com.sg)  
Email: [yvonne.ang@axa.com.sg](mailto:yvonne.ang@axa.com.sg)  
DID: 1800 880 4888



**redefining / insurance**

**AXA's Values at Work:**



**Customer  
First**



**Integrity**



**Courage**



**ONE  
AXA**

Please consider the environment before printing this email

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited.  
If you are not the intended recipient of the message, please notify the sender immediately.

## Service Address

Blk 3 Pioneer Road North, , 628457

## Primary Contact/Insured

GUO JIANHAO

05-723, 305B Punggol Road, 822305, Singapore

anthonyguojianhao@gmail.com

## Claim Handler

ANG Yvonne

6568804461

yvonne.ang@axa.com.sg

Additional Instructions

EXCESS 0 PENDING EST & DL WORKSHOP : SNG AH TEE

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE



SENT

4/3/18 2:45 PM

FROM

ANG Yvonne

SUBJECT

Authorized

BODY

Please proceed to authorize repair



TYPE



SENT

3/27/18 11:00 AM

FROM

LKK AUTO CONSULTANTS PTE LTD (OD)





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S8M00BMY

Our Ref: CS/ASM18005475/T1td3

Date: 27/3/2018

The Motor Claims Department  
M/s AXA Insurance Singapore Pte Ltd

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO SJY 2240K**


We thank you for the instruction on 22/3/2018

Please be informed that we had conducted the inspection of the abovementioned vehicle on 23/3/2018 at the premises of M/s Sng Ah Tee and have the following to report: -

Workshop Estimate Amount	: S\$ <u>6,342.00</u>
Revised Estimate Amount	: S\$ <u>3,551.00</u>
"Check" Items Amount	: S\$ <u>2,391.00</u>
Total	: S\$ <u>5,942.00</u>
Market Value	: S\$ <u>26,000.00</u>
LTA Reimbursement Value	: S\$ <u>14,551.00</u>
Nett Value	: S\$ <u>11,449.00</u>

Description of Damage:

The vehicle sustained damages at the Front O/S, uncarriage portion.



Comments/ Present Status:  
Damages Consistent  
Repair cost economical  
We have not authorize repair

Repair Days: 3

Yours Faithfully,  
Taufikh  
Automotive Assessor



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S8M00BMY

Our Ref: CS/ASM18005475/T1td3

Date: 26/3/2018

The Motor Claims Department  
M/s AXA Insurance Singapore Pte Ltd

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO SJY 2240K**


We thank you for the instruction on 22/3/2018

Please be informed that we had conducted the inspection of the abovementioned vehicle on 23/03/2018 at the premises of M/s Sng Ah Tee and have the following to report: -

Workshop Estimate Amount	: S\$ <u>1,796.00(Labour only)</u>
Revised Estimate Amount	: S\$ <u>1,096.00</u>
"Check" Items Amount	: S\$ <u>300.00</u>
Total	: S\$ <u>1,396.00</u>
Market Value	: S\$ <u>26,000.00</u>
LTA Reimbursement Value	: S\$ <u>14,551.00</u>
Nett Value	: S\$ <u>11,449.00</u>

Description of Damage:

The vehicle sustained damages at the Front portion.



Comments/ Present Status:  
Damages Consistent  
Pending part price

Repair Days: 6

Yours Faithfully,  
Taufikh  
Automotive Assessor

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	6408Z
<b>Vehicle Details</b>	
Vehicle No.:	SJY2240K
Vehicle to be Exported:	No
Intended De-registration Date:	31 Mar 2018
Vehicle Make:	FORD
Vehicle Model:	FIESTA TREND 1.4L (A) 5-DOOR
Primary Colour:	Red
Manufacturing Year:	2010
Engine No.:	AU82284
Chassis No.:	WF0JXXGAJJAU82284
Maximum Power Output:	71.0 kW (95 bhp)
Open Market Value:	\$12,635.00
Original Registration Date:	12 Aug 2010
First Registration Date:	12 Aug 2010
Transfer Count:	0
Actual ARF Paid:	\$12,635.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Aug 2020
PARF Rebate Amount:	\$7,581.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	11 Aug 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$29,501.00
COE Rebate Amount:	\$6,970.00
<b>Total Rebate Amount:</b>	<b>\$14,551.00</b>

The information contained herein is correct as at 22 Mar 2018

OK



redefining / insurance

**LETTER OF UNDERTAKING/ AUTHORIZATION FOR LUMP SUM REPAIR**

1. I, [Name] [NRIC] Guo Jian Hao, the owner/ authorized driver of vehicle [Registration No.] S83264082 ("Vehicle") do hereby authorize the [Workshop/Insurer] to repair the Vehicle on a lump sum basis instead of part by part.
2. The [Workshop/Insurer] has explained to me the difference between lump sum repair and part by part repair and the consequences of my authorization for lump sum repair for the Vehicle.
3. I understand that with lump sum repair, the Workshop may use a mixture of genuine parts, original equipment manufacturer (OEM) parts, reconditioned and second hand parts to carry out the repair and I note that the [Workshop/Insurer] will not be furnishing a detailed breakdown of parts or price for such lump sum repair.
4. I am aware that AXA Insurance Pte Ltd ("AXA Insurance") does not encourage lump sum repair as AXA Insurance strongly recommends repairs for vehicles on a part by part basis for transparency reasons. I confirm that I will hold AXA Insurance harmless from any claims arising from the lump sum repair of the Vehicle which I have authorized.
5. \* *To be applicable where person authorizing is the authorized driver.*  
I confirm that I have the authority from the owner of the Vehicle to authorize the lump sum repairs and that I have duly notified the owner of the Vehicle of the contents of this Letter of Authorization.

Signed and acknowledged by:

Signature of policyholder/ authorized driver\* and company stamp (where applicable)  
Date:

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD  
BLK 3 PIONEER ROAD NORTH #01-18  
SINGAPORE 628457

Name and signature of workshop personnel including workshop stamp  
Date: 25/03/2014

\*authorized driver to either the named drivers as per motor insurance policy or in the case of commercial vehicles, permitted drivers who are permitted to drive the insured Vehicle.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/03/2018 14:11
Date Of Accident	22/03/2018 08:00
Exact Location Of Accident	ALONG PENG KANG AVE SAFTI MILITARY INSTITUTE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJY2240K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GUO JIANHAO
NRIC No	S8326408Z
Email Address	ANTHONYGUOJIANHAO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98302788
Alternative Phone No	OFFICE-NOPHONE

### Vehicle Particulars

Manufacturer	FORD
Model	FIESTA-1.4

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA117510
Cover Note Number	

### Driver

Name of Driver	GUO JIANHAO
NRIC No	S8326408Z
Date Of Birth	27/08/1983
Occupation	OUTDOOR
Date Of Driving Pass	07/05/2007
Driving Experience	10 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98302788
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	ANTHONYGUOJIANHAO@GMAIL.COM

Address	BLK 305B PUNGGOL RD #05-723
Postcode	822305
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PEDESTRIAN
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG WEST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2689999 - FAX NO: 62672438
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT J/20180322/7014

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF INJURED PERSON 1

Name	CHOO PING CHERN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

I AM AWARED THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.



**SINGAPORE  
POLICE FORCE**



J/20180322/7014

1 of 2

**POLICE REPORT (NP299)**

Report No. J/20180322/7014

Police Station Of Origin  
Jurong Police Divisional HQ  
2 Jurong West Avenue 5 SINGAPORE  
649482  
Tel No: 1800-7910000

Date/Time Report Made 22/03/2018 13:36	Vide Report No.	Station Diary No.
Name Of Informant GUO JIANHAO	Address APT BLK 305B PUNGGOL ROAD #05-723 SINGAPORE 822305	
ID Type / ID No. NRIC NO / S8326408Z	Contact No. Home/Office:	Mobile: 98302788
Nationality SINGAPORE CITIZEN	Email Address anthonyguojianhao@gmail.com	
Occupation OFFICER	Sex Male	Age 34
Institution/School Name	Date of Birth 27/08/1983	Race Chinese
Date/Time Of Incident 22/03/2018 08:00	Location Of Incident 500 PENG KANG AVENUE SAFTI MILITARY INSTITUTE SINGAPORE 638364	

**Brief details.**

While driving along Peng Kang Ave towards GKSCSC near Brani Ave section, I dropped my camp pass in the car and while trying to retrieve it, knocked onto the victim (MR Choo Ping Chern, S7933727G) who was walking along the side of the road.

I got out of my vehicle and checked on the status of the victim. The victim was conscious and there was some laceration on the back of his head at the point of time. Passerbys also called for ambulance and

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 22/03/2018 13:36
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp



# 孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

Our Ref: S8M00BMY

Date : 23/3/2018

## ATTN:THE MOTOR CLAIMS DEPT

AXA INSURANCE PTE LTD

8 SHENTON WAY

AXA TOWER #B1-01

SINGAPORE 068811

## ESTIMATE COST OF REPAIR

Vehicle Reg No.	SJY2240K	Model / Year	FORD FIESTA 2010
Date of Accident	22-Mar-18	Policy No.	GA117510
Type of Claim	OD AXA	Prepared By	JOYCE
Survey By		Chassis No.	WF0JXXGAJJAU82284

S/NO	Description	Qty	Cost Price	Amount	
1	FRT BUMPER <i>de</i>	1		\$ -	
2	FRT BUMPER SIDE RETAINER LH ?	1		\$ -	
3	FRT BUMPER CLIP <i>net</i>	10		\$ -	
4	FRT HEADLAMP(LH) <i>cut</i>	1		\$ -	
5	FRT BONNET <i>h1</i>	1		\$ -	
6	FRT BONNET INSULATOR ?	1		\$ -	
7	FRT BONNET INSULATOR CLIP ?	1		\$ -	
8	FRT BONNET RUBBER SEAL ?	2		\$ -	
9	FRT WIPER GARNISH ?	1		\$ -	
10	FRT WINDSCREEN <i>cut</i>	1		\$ -	
11	FRT WINDSCREEN MOULDING SET <i>cut</i>	1		\$ -	
12	FRT WIPER BLADE(LH) <i>cut</i>	1		\$ -	
13	FRT WINDSCREEN SIDE GARNISH(LH) <i>cut</i>	1		\$ -	
14	FRT TYRE (LH)(196/50R15) <i>putted</i>	1		\$ -	
15	FRT RIM(LH) <i>cut</i>	1		\$ -	
16	FRT SHOCKABSORBER(LH)	1		\$ -	
17	FRT KNUCKLE ARM(LH)	1		\$ -	
18	FRT LOWER ARM(LH)	1		\$ -	
19	FRT WHEEL HUB(LH)	1		\$ -	
20	FRT WHEEL BEARING(LH)	1		\$ -	
	<i>Frt windscreen pillar (LH) RY</i>				
21	FRT WINDSCREEN SEALANT <i>net</i>	1	\$ 40.00	\$ 40.00	S/N
22	ERP BRACKET <i>net</i>	1	\$ 26.00	\$ 26.00	S/N
	TO REPAIR & REPLACE UNDERCARRIAGE			\$ 300.00	150? plants
	TO CHECK WIRING			\$ 30.00	
	TO KNOCK,WELD,REMOVE & FIX ABOVE PARTS			\$ 700.00	500
	TO PUTTY & RESPRAY PAINTING ON FRT BUMPER			\$ 700.00	500.
	FRT BONNET,FRT FENDER(LH)				

TOTAL

\$ 1,796.00

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749  
Revert

Ex: to be advise.  
Resurvey before paint.

6 days

sw @ lkkauto.com

# 孫亞弟汽車燒焊私人有限公司

## SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

Our Ref: S8M00BMY

Date : 23/3/2018

### ATTN:THE MOTOR CLAIMS DEPT

AXA INSURANCE PTE LTD

8 SHENTON WAY

AXA TOWER #B1-01

SINGAPORE 068811

### ESTIMATE COST OF REPAIR

Vehicle Reg No.	SJY2240K	Model / Year	FORD FIESTA 2010
Date of Accident	22-Mar-18	Policy No.	GA117510
Type of Claim	OD AXA	Prepared By	JOYCE
Survey By		Chassis No.	WF0JXXGAJJAU82284

S/NO	Description	Qty	Cost	Price	Amount	
1	FRT BUMPER ✓	1	\$	500.00	\$ 500.00	✓ de
2	FRT BUMPER SIDE RETAINER LH ?	1			\$ -	nn
3	FRT BUMPER CLIP ✓	10	\$	6.50	\$ 65.00	✓ nec
4	FRT HEADLAMP(LH) ✓	1	\$	320.00	\$ 320.00	✓ cut
5	FRT BONNET	1	\$	450.00	\$ 450.00	✓ Bent
6	FRT BONNET INSULATOR ?	1	\$	105.00	\$ 105.00	X 24
7	FRT BONNET INSULATOR CLIP ?	10	\$	2.50	\$ 25.00	X 24
8	FRT BONNET RUBBER SEAL ?	2	\$	38.00	\$ 76.00	X 24
9	FRT WIPER GARNISH ?	1	\$	240.00	\$ 240.00	X 24
10	FRT WINDSCREEN ✓	1	\$	950.00	\$ 950.00	✓ ant }
11	FRT WINDSCREEN MOULDING SET ✓	1			\$ -	✓ ant }
12	FRT WIPER BLADE(LH) ✓	1	\$	50.00	\$ 50.00	✓ ant
13	FRT WINDSCREEN SIDE GARNISH(LH) ✓ (OUTER MOULDING) ✓	1	\$	120.00	\$ 120.00	✓ ant
14	FRT TYRE (LH)(196/50R15) ?	1	\$	200.00	\$ 200.00	S/N ✓ purchased ✓
15	FRT RIM(LH) ?	1	\$	280.00	\$ 280.00	S/N ✓ cut ✓
16	FRT SHOCKABSORBER(LH) ?	1	\$	250.00	\$ 250.00	} X un
17	FRT KNUCKLE ARM(LH) ?	1	\$	400.00	\$ 400.00	
18	FRT LOWER ARM(LH) ?	1	\$	220.00	\$ 220.00	
19	FRT WHEEL HUB(LH) ?	1	\$	165.00	\$ 165.00	
20	FRT WHEEL BEARING(LH) ?	1	\$	130.00	\$ 130.00	
					\$ 4,546.00	
21	FRT WINDSCREEN SEALANT ✓	1	\$	40.00	\$ 40.00	S/N ✓ nec
22	ERP BRACKET ✓	1	\$	26.00	\$ 26.00	S/N ✓ nec
TO REPAIR & REPLACE UNDERCARRIAGE					\$ 300.00	150 ? X un.
TO CHECK WIRING					\$ 30.00	✓
TO KNOCK,WELD,REMOVE & FIX ABOVE PARTS					\$ 700.00	500 ✓
TO PUTTY & RESPRAY PAINTING ON FRT BUMPER					\$ 700.00	500 ✓
FRT BONNET,FRT FENDER(LH)						
<b>TOTAL</b>					<b>\$ 6,342.00</b>	

# 孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

Our Ref: S8M00BMY

Date : 23/3/2018

**ATTN:THE MOTOR CLAIMS DEPT**

AXA INSURANCE PTE LTD

8 SHENTON WAY

AXA TOWER #B1-01

SINGAPORE 068811

## ESTIMATE COST OF REPAIR

Vehicle Reg No.	SJY2240K	Model / Year	FORD FIESTA 2010
Date of Accident	22-Mar-18	Policy No.	GA117510
Type of Claim	OD AXA	Prepared By	JOYCE
Survey By		Chassis No.	WF0JXXGAJJAU82284

S/NO	Description	Qty	Cost	Price	Amount
1	FRT BUMPER	1	\$	500.00	\$ 500.00 ✓ de
2	FRT BUMPER SIDE RETAINER LH	1			\$ - nn
3	FRT BUMPER CLIP	10	\$	6.50	\$ 65.00 ✓ nel
4	FRT HEADLAMP(LH)	1	\$	320.00	\$ 320.00 ✓ cut
5	FRT BONNET	1	\$	450.00	\$ 450.00 ✓ bt
6	FRT BONNET INSULATOR	1	\$	105.00	\$ 105.00 X nn
7	FRT BONNET INSULATOR CLIP	10	\$	2.50	\$ 25.00 X nn
8	FRT BONNET RUBBER SEAL	2	\$	38.00	\$ 76.00 X nn
9	FRT WIPER GARNISH	1	\$	240.00	\$ 240.00 X nn
10	FRT WINDSCREEN	1	\$	950.00	\$ 950.00 ✓ cut
11	FRT WINDSCREEN MOULDING SET	1			\$ - ✓ comes w/ windscreen cut
12	FRT WIPER BLADE(LH)	1	\$	50.00	\$ 50.00 ✓ cut
13	FRT WINDSCREEN SIDE GARNISH(LH) (OUTER MOULDING)	1	\$	120.00	\$ 120.00 ✓ (outer) cut
14	FRT TYRE (LH)(196/50R15)	1	\$	200.00	\$ 200.00 S/N ✓ put new
15	FRT RIM(LH)	1	\$	280.00	\$ 280.00 S/N ✓ cut
16	FRT SHOCKABSORBER(LH)	1	\$	250.00	\$ 250.00 X
17	FRT KNUCKLE ARM(LH)	1	\$	400.00	\$ 400.00 X
18	FRT LOWER ARM(LH)	1	\$	220.00	\$ 220.00 X
19	FRT WHEEL HUB(LH)	1	\$	165.00	\$ 165.00 X
20	FRT WHEEL BEARING(LH)	1	\$	130.00	\$ 130.00 X
					\$ 4,546.00 parts \$7456 cut \$546
21	FRT WINDSCREEN SEALANT	1	\$	40.00	\$ 40.00 S/N ✓ nel
22	ERP BRACKET	1	\$	26.00	\$ 26.00 S/N ✓ nel
	TO REPAIR & REPLACE UNDERCARRIAGE				\$ 300.00 \$150? nn
	TO CHECK WIRING				\$ 30.00 ✓
	TO KNOCK, WELD, REMOVE & FIX ABOVE PARTS				\$ 700.00 \$500
	TO PUTTY & RESPRAY PAINTING ON FRT BUMPER				\$ 700.00 \$500
	FRT BONNET, FRT FENDER(LH)				
<b>TOTAL</b>			<b>\$</b>	<b>6,342.00</b>	labour \$1100

*Supplementary Labour*

① Wheel Alignment \$80- CPD rec

total \$4111

15% 70% = \$3288.80

≈ \$3250 Lump Sum

OK? pls Revise

Shawn 7/27/2018

# 孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457  
Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg  
Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

Our Ref: S8M00BMY  
Date : 23/3/2018

ATTN: THE MOTOR CLAIMS DEPT  
AXA INSURANCE PTE LTD  
8 SHENTON WAY  
AXA TOWER #B1-01  
SINGAPORE 068811

## ESTIMATE COST OF REPAIR

Vehicle Reg No.  
Date of Accident  
Type of Claim  
Survey By

SJY2240K

22-Mar-18

OD AXA

Model / Year

FORD FIESTA 2010

Policy No.

GA117510

Prepared By

JOYCE

Chassis No.

WF0JXXGAJJAU82284

### S/NO Description

### Qty Cost Price Amount

1	FRT BUMPER <i>de</i>	1		\$	-	
2	FRT BUMPER SIDE RETAINER LH ?	1		\$	-	
3	FRT BUMPER CLIP <i>net</i>	10		\$	-	
4	FRT HEADLAMP(LH) <i>cut</i>	1		\$	-	
5	FRT BONNET <i>h</i>	1		\$	-	
6	FRT BONNET INSULATOR ?	1		\$	-	
7	FRT BONNET INSULATOR CLIP ?	1		\$	-	
8	FRT BONNET RUBBER SEAL ?	1		\$	-	
9	FRT WIPER GARNISH ?	2		\$	-	
10	FRT WINDSCREEN <i>cut</i>	1		\$	-	
11	FRT WINDSCREEN MOULDING SET <i>cut</i>	1		\$	-	
12	FRT WIPER BLADE(LH) <i>cut</i>	1		\$	-	
13	FRT WINDSCREEN SIDE GARNISH(LH) <i>cut</i>	1		\$	-	
14	FRT TYRE (LH)(196/50R15) <i>putted</i>	1		\$	-	
15	FRT RIM(LH) <i>cut</i>	1		\$	-	
16	FRT SHOCKABSORBER(LH) ?	1		\$	-	
17	FRT KNUCKLE ARM(LH) ?	1		\$	-	
18	FRT LOWER ARM(LH) ?	1		\$	-	
19	FRT WHEEL HUB(LH) ?	1		\$	-	
20	FRT WHEEL BEARING(LH) ?	1		\$	-	
21	FRT WINDSCREEN SEALANT <i>net</i>	1	\$	40.00	\$	40.00 S/N
22	ERP BRACKET <i>net</i>	1	\$	26.00	\$	26.00 S/N
	TO REPAIR & REPLACE UNDERCARRIAGE				\$	300.00 150? <i>pluto</i>
	TO CHECK WIRING				\$	30.00
	TO KNOCK, WELD, REMOVE & FIX ABOVE PARTS				\$	700.00 500
	TO PUTTY & RESPRAY PAINTING ON FRT BUMPER				\$	700.00 500
	FRT BONNET, FRT FENDER(LH)				\$	

TOTAL

\$ 1,796.00

LKK  
denice

← Authorize  
repair

Excess waive

03/04-1500

Tarfon 97495749  
Revent

Ex: to be advise.

Resumy before paint.

6 days

sur @ 16 hours on m.