

ASS. REC. BY:

REF: CS/FCI18005494/47d3<sup>12</sup> Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

aws

Joanne Yong

of

FCI

Date/Time:

23/3/18 @ 3:34pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 3510L

Insured:

SHA 3847D

at Workshop in/s:

Pegasus @ SME Motor

Tel:

8338 8418

of

1 Keiki Bkt Ave 6 # 02-15

Policy No:

Claim No:

D18002369MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

2/103/18

CA / REV / REP. / REV 24 HRS

1DS

H.O.D. Endorsement:

Date/Time:

5:19pm @ 23/3/18

Person Contacted:

Gary

Vehicle IN /

OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|---------------------------------|
|           | SLW 3510L-X                     |
|           | SHA 3847D-X                     |
|           |                                 |
|           |                                 |
|           |                                 |
|           |                                 |
|           |                                 |

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 3510Lat Workshop m/s Pyosun

of

Insured: SH/A3847D

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

CIA / PR Seen: 2

Consistent? : Yes or No

Est. Repairs: 3

days

Res.: Yes or No

Lum Sum: 1.34

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLW 3510LYr Regn: 218Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAIMake: Hondaverel Hybrid 1496Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 15-065

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RU 31222447Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / DS/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal. 2

mm

R/Bal. 2

mm

L/Bal. 2

mm

L/Bal. 2

mm

D.O.A. 21/3/18D.O.I. 2/4/18Survey held at Kokor buher

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                                       |
|-------------|------------------------------------------------------------|
| 10/4/18     | Confirmed final by \$1833.76 w.l. AH yoy. (Ched: 826:3176) |

RECEIVED 12 APR 2018

Date/Time, File Pass to?

☐

: Prel. Report

1) 11/4 Typist☒

: Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 3Resurvey No. of Trip: 3

Add Fee:

☐

: Site Insp (\$ \_\_\_\_\_)

☐

: Interview (\$ \_\_\_\_\_)

☐

: Tech. Invs (\$ \_\_\_\_\_)

☐

: Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

110

50

50

30

240

Report Format: TPLump Sum / I.B.I. (\$) 1833.76

**MOTOR SURVEY ASSIGNMENT**

|                    |                                                      |                               |
|--------------------|------------------------------------------------------|-------------------------------|
| Date               | 23-03-2018                                           | Our Ref No. D18002369MFSH     |
| Accident Date      | 21-03-2018                                           | Claim Type. Third Party       |
| Insured Vehicle    | SHA3847D                                             | Third Party Vehicle. SLW3510L |
| Survey Location    | NO. 1 KAKI BUKIT AVENUE 6 #02-15AUTOBAY @ KAKI BUKIT |                               |
| Contact Person.    | GARY SEAH                                            |                               |
| Contact No.        | 0/ 83388418                                          | Fax No. 0                     |
| Survey Type        | DIRECT SETTLEMENT:                                   |                               |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD                         |                               |
| Contact Person     | NA                                                   | Fax No. 68416315              |
| Contact Number.    | NA                                                   |                               |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                   |               |                         |
|-------------------|---------------|-------------------------|
| Cc : Workshop     | PEGASUS @ SME | Attention. NIL          |
|                   | MOTOR         |                         |
| Cc : TP Solicitor | NA            | TP Solicitor Fax No. NA |
| Officer Incharge  | JOANNEY       |                         |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236268)



PRI Documents



Close



## PRI Header Details

|                   |                                                     |                                   |                                                                                                                                  |                      |              |
|-------------------|-----------------------------------------------------|-----------------------------------|----------------------------------------------------------------------------------------------------------------------------------|----------------------|--------------|
| Claim No          | D18002369MFSH                                       | Policy No                         | D-18088936MFSH                                                                                                                   | Claimant S.No & Name | 1 & PEGASUS  |
| Workshop Name     | PEGASUS @ SME MOTOR<br>(Contact Person : GARY SEAH) | Survey Location & Contact Details | NO. 1 KAKI BUKIT AVENUE 6 #02-15AUTOBAY @ KAKI I<br>Mobile: 83388418 , Phone: 0 , Fax: 0<br>EmailId: CLAIMS2@PEGASUSENGRG.COM.SG |                      |              |
| Our Surveyor      | LKK AUTO CONSULTANTS PTE LTD                        | Instructions To Surveyor          | DIRECT SETTLEMENT:                                                                                                               |                      |              |
| Insured Name      | COMFORT TRANSPORTATION PTE LTD                      | Insured Vehicle No                | SHA3847D                                                                                                                         | TP Vehicle No        | SLW3510L     |
| PRI Recieved Date | 23-03-2018 03:47:28 PM                              | Surveyor Appointed Date           | 23-03-2018 03:33:06 PM                                                                                                           | Surveyor Accept Date | 23-03-2018 0 |

## Survey Report Upload

|                             |  |                      |            |                         |                                            |
|-----------------------------|--|----------------------|------------|-------------------------|--------------------------------------------|
| Surveyor Inspection Date *: |  | Surveyor Report Date | 23-03-2018 | Upload Survey Report *: | <input type="button" value="Choose File"/> |
|-----------------------------|--|----------------------|------------|-------------------------|--------------------------------------------|

## Vehicle Particulars

|           |                                                 |                |                                                  |         |                                          |
|-----------|-------------------------------------------------|----------------|--------------------------------------------------|---------|------------------------------------------|
| Make      | <input type="text" value="Please Select Make"/> | Model          | <input type="text" value="Please Select Model"/> | Year    | <input type="text" value="Select Year"/> |
| Chasis No | <input type="text"/>                            | Engine No      | <input type="text"/>                             | Mileage | <input type="text"/>                     |
| Color     | <input type="text"/>                            | Cubic Capacity | <input type="text"/>                             |         |                                          |

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18005494/Utd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 23-03-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                   |                |            |
|--------------|-------------------|----------------|------------|
| Insured Veh. | SHA 3847D         | Veh. Inspected | SLW 3510L  |
| Policy No.   |                   | Coverage (\$)  | 0.00       |
| Claim No.    | D18002369MFSH     | Excess (\$)    | 0.00       |
| Assign From  | CWS (JOANNE YONG) | Assign Date    | 23/03/2018 |

## 2. Vehicle Particulars & Condition

|              |        |              |
|--------------|--------|--------------|
| Make & Model | c.c    | 0            |
| Engine No.   | HIDDEN | Year of Reg. |
| Chassis No.  |        | Colour       |
| Odometer     | -      | Steering     |
| Brakes       |        | Modification |
| General      |        |              |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |
|--|
|  |
|--|

## 5. General Information

|                |                                       |                 |
|----------------|---------------------------------------|-----------------|
| Accident Date  | 21/03/2018                            | Inspection Date |
| Survey held at | SME MOTOR                             |                 |
| Repairer       | PEGASUS ENGINEERING & TRADING PTE LTD |                 |

## 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

|                |         |
|----------------|---------|
| Owner ID Type: | Company |
| Owner ID:      | 7200G   |

**Vehicle Details**

|                                |                       |
|--------------------------------|-----------------------|
| Vehicle No.:                   | SLW3510L              |
| Vehicle to be Exported:        | No                    |
| Intended De-registration Date: | 02 Apr 2018           |
| Vehicle Make:                  | HONDA                 |
| Vehicle Model:                 | VEZEL HYBRID 1.5 AUTO |
| Primary Colour:                | Silver                |
| Manufacturing Year:            | 2016                  |
| Engine No.:                    | LEB5922457            |
| Chassis No.:                   | RU31222447            |
| Maximum Power Output:          | 112.0 kW (150 bhp)    |
| Open Market Value:             | \$22,540.00           |
| Original Registration Date:    | 07 Feb 2018           |
| First Registration Date:       | 07 Feb 2018           |
| Transfer Count:                | 0                     |
| Actual ARF Paid:               | \$13,556.00           |

**Intended PARF Rebate Details**

|                               |             |
|-------------------------------|-------------|
| PARF Eligibility:             | Yes         |
| PARF Eligibility Expiry Date: | 06 Feb 2028 |
| PARF Rebate Amount:           | \$10,167.00 |

**Intended COE Rebate Details**

|                             |                                       |
|-----------------------------|---------------------------------------|
| COE Expiry Date:            | 06 Feb 2028                           |
| COE Category:               | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years):          | 10                                    |
| QP Paid:                    | \$45,289.00                           |
| COE Rebate Amount:          | \$44,586.00                           |
| <b>Total Rebate Amount:</b> | <b>\$54,753.00</b>                    |

The information contained herein is correct as at 02 Apr 2018

OK



GST / ROC Company No : 201101753C

Third Party Insurer : FIRST CAPITAL  
Insured's Veh No : SHA3847D  
Date of accident : 21/03/2018

Grab Rentals Pte Ltd  
18 Sin Ming Lane  
#01-08 Midview City  
Singapore 573960

Quotation No : AR/QO18/03-1036  
Quotation Date : 23/03/2018

*Not Adherent  
Lack  
Take photo before  
painting.  
3dy.*

Estimate To Repair HONDA VEZEL HYBRID 1.5X AUTO  
Vehicle No : SLW3510L  
Chassis No : RU3-1222447

Pages : 1 of 1

| S/NO                              | QUANTITY | DESCRIPTION               | AMOUNT            |
|-----------------------------------|----------|---------------------------|-------------------|
| <b>SPARE PARTS</b>                |          |                           |                   |
| 1                                 | 1PC      | REAR BUMPER LH            | DO/DE \$185.00 ✓  |
| 2                                 | 1SET     | REAR BUMPER RETAINER LH   | Sub \$70.00 ✓     |
| 3                                 | 10PC     | REAR BUMPER CLIPS @\$5.50 | ren \$55.00 ✓     |
| 4                                 | 1PC      | REAR BUMPER (CENTRE)      | DO/DE \$810.00 ✓  |
| 5                                 | 1PC      | REAR BUMPER REFLECTOR LH  | 11 \$165.00 ✓     |
| 6                                 | 1PC      | REAR FENDER PROTECTOR LH  | ren \$225.00 ✓    |
| 7                                 | 8PC      | PROTECTOR CLIPS @\$5.90   | ren \$47.20 ✓     |
| 8                                 | 1PC      | REAR GATE "VEZEL" PLATE   | 11 \$45.00 ✓      |
| 9                                 | 1PC      | REAR GATE "HYBRID" PLATE  | 11 \$60.00 ✓      |
|                                   |          |                           | \$1,662.20        |
| LESS 20%                          |          |                           | \$332.44          |
|                                   |          |                           | \$1,329.76        |
| <b>MISC ITEMS</b>                 |          |                           |                   |
| 1                                 | 1PC      | REVERSE SENSOR            | 11 \$250.00 ✓     |
| Total                             |          |                           | \$250.00          |
| <b>LABOUR &amp; MISC. CHARGES</b> |          |                           |                   |
| 1                                 |          | WIRE CHECKING             | \$30.00           |
| 2                                 |          | LABOUR CHARGE             | \$500.00          |
| 3                                 |          | SPRAY PAINTING            | \$550.00          |
| Total                             |          |                           | \$1,080.00        |
| <b>Sub Total</b>                  |          |                           | <b>\$2,659.76</b> |
| <b>GST (7.00%)</b>                |          |                           | <b>\$186.18</b>   |
| <b>Total</b>                      |          |                           | <b>\$2,845.94</b> |

*1392.2  
1113.76  
20  
300  
400  
1837.76  
1467*

As a condition of payment, you must hence notify the Insurer of the following:  
- Repair work is after spray painting  
- Do not open door/wind/part(s) during resurvey  
- Materials provided are subject to confirmation  
• This survey is carried out on a "Without Prejudice" basis  
• No repair modification(s) is allowed.  
• If a repair is made, it must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883  
GARY 8338 8418



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                           |                 |                             |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------|-----------------|-----------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                           |                 | Ref : CS/FCI18005494/Utd3n2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                           |                 | Date : 16-04-2018           |  |
|                                                                                                                                                                                        |                                           |                 | Code : FCI2                 |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                           |                 |                             |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SHA 3847D                                 | Veh. Inspected  | SLW 3510L                   |                                                                                     |
| Policy No.                                                                                                                                                                             | D-18088936MFSH                            | Coverage (\$)   | 0.00                        |                                                                                     |
| Claim No.                                                                                                                                                                              | D18002369MFSH                             | Excess (\$)     | 0.00                        |                                                                                     |
| Assign From                                                                                                                                                                            | JOANNE YONG                               | Assign Date     | 23/03/2018                  |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                           |                 |                             |                                                                                     |
| Make & Model                                                                                                                                                                           | HONDA VEZEL HYBRID (A)                    | c.c             | 1496                        |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                    | Year of Reg.    | 2018                        |                                                                                     |
| Chassis No.                                                                                                                                                                            | RU31222447                                | Colour          | SILVER                      |                                                                                     |
| Odometer                                                                                                                                                                               | 15065                                     | Steering        | IN ORDER                    |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                  | Modification    | NIL                         |                                                                                     |
| General                                                                                                                                                                                | GOOD                                      |                 |                             |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                           |                 |                             |                                                                                     |
|                                                                                                                                                                                        | Size                                      | Make            | Balance                     |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 215/60 R16                                | MICHELIN        | 8 mm                        |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 215/60 R16                                | MICHELIN        | 8 mm                        |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 215/60 R16                                | MICHELIN        | 8 mm                        |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 215/60 R16                                | MICHELIN        | 8 mm                        |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                           |                 |                             |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.<br>DAMAGES SEE DETAILS.                                                                                                         |                                           |                 |                             |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                           |                 |                             |                                                                                     |
| Accident Date                                                                                                                                                                          | 21/03/2018                                | Inspection Date | 02/04/2018                  |                                                                                     |
| Survey held at                                                                                                                                                                         | SME MOTOR - BLK 1 KAKI BUKIT AVE 6 #02-15 |                 |                             |                                                                                     |
| Repairer                                                                                                                                                                               | PEGASUS ENGINEERING & TRADING PTE LTD     |                 |                             |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                           |                 |                             |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                           |                 |                             |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                           |                 |                             |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                           | 3 Working Days  |                             |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 3510L

| Qty                                | Description of Parts        | Condition         | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|-----------------------------|-------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b>        |                             |                   |                           |                   |
| 1                                  | REAR BUMPER LH              | DENTED / DEFORMED | 185.00                    | 185.00            |
| 1                                  | SET REAR BUMPER RETAINER LH | BENT              | 70.00                     | 70.00             |
| 10                                 | REAR BUMPER CLIPS @\$5.50   | NECESSARY         | 55.00                     | 55.00             |
| 1                                  | REAR BUMPER (CENTRE)        | DENTED / DEFORMED | 810.00                    | 810.00            |
| 1                                  | REAR BUMPER REFLECTOR LH    | NOT NECESSARY     | 165.00                    | -                 |
| 1                                  | REAR FENDER PROTECTOR LH    | TORN              | 225.00                    | 225.00            |
| 8                                  | PROTECTOR CLIPS @\$5.90     | NECESSARY         | 47.20                     | 47.20             |
| 1                                  | REAR GATE "VEZEL" PLATE     | NOT NECESSARY     | 45.00                     | -                 |
| 1                                  | REAR GATE "HYBRID" PLATE    | NOT NECESSARY     | 60.00                     | -                 |
|                                    | LESS 20% DISCOUNT           |                   | -332.44                   | -278.44           |
|                                    |                             |                   | 1,329.76                  | 1,113.76          |
| <b>SPECIAL NETT ITEMS</b>          |                             |                   |                           |                   |
| 1                                  | REVERSE SENSOR (SN)         | NOT NECESSARY     | 250.00                    | -                 |
|                                    |                             |                   | 250.00                    | -                 |
| <b>LABOUR</b>                      |                             |                   |                           |                   |
|                                    | WIRE CHECKING.              |                   | 30.00                     | 20.00             |
|                                    | LABOUR CHARGE.              |                   | 500.00                    | 300.00            |
|                                    | SPRAY PAINTING.             |                   | 550.00                    | 400.00            |
|                                    |                             |                   | 1,080.00                  | 720.00            |
| <b>GRAND TOTAL</b>                 |                             |                   | <b>2,659.76</b>           | <b>1,833.76</b>   |
| <b>RECOMMENDED COST OF REPAIRS</b> |                             |                   |                           | <b>1,833.76</b>   |

Report Ref No. CS/FC118005494/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.