

ASS. REC. BY:

REF: CS3/CTI18005548 | A d3ok

large & way 0

Special Instruction:

Subv of Member

Adrian

ASSIGNMENT (Office)

From (Person): Irene Tay

of CTI

Date/Time: 22/3/18 @ 5:31pm

Estimated Cost:

Bill to:

OD (T) / WS / TP RES / OD RES / EVA / INV / MV 7 CS

To Inspect Vehicle No: SLU 9Z

Insured: SLD 976X

at Workshop m/s: H.S Motor Engineering

Tel: 6747 2755

of BIK 2, kaki BK + Ave 2 # 01-15

Policy No: DMPCSN 30588 11701

Claim No: SNM18D01508C02

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A 20/03/2018

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time: 9:30am @ 26/3/18

Person Contacted: Connie

Vehicle (IN) / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SLU 9Z - X
	SLD 976X - X



## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Mar 2018		22 Mar 2018 17:31 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MOHAMED ALI MARAICAR BATHURUL JAMAN, ID: S7275616I		
Main Claimant:	NG YUAN GE, BENJAMIN (HUANG YUANGE), ID: S8836966A		
Vehicle Reg. No.:	SLU9Z	Date of Loss:	20/03/2018 20:00 - :59
Claim Type:	TP / SNM18D01508C02	Policy/Cover Note No.:	DMPCSN3058841701 (Comprehensive)
Vehicle Reg. No. (Insured):	SLD976X	Policy No. (Claimant):	D17MTPV01015162
		Excess:	S\$0.00
Repairer:	H C Motor Engineering (HQ) Blk 2 Kaki Bukit Avenue 2, #01-15 Kaki Bukit AutoHub, 417921 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/04/2018]		
Driver/Custodian (Insured):	MOHAMED ALI MARAICAR BATHURUL JAMAN (46 / Male), NRIC: S7275616I		
Adj Asg. Remarks:	KINDLY IGNORE THE SUBJECT ON THE EMAIL THE CORRECT FILE IS THIS.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	6966A
<b>Vehicle Details</b>	
Vehicle No.:	SLU9Z
Vehicle to be Exported:	No
Intended De-registration Date:	27 Apr 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C63 AMG A
Primary Colour:	Silver
Manufacturing Year:	2012
Engine No.:	15698560076069
Chassis No.:	WDD2040772A729370
Maximum Power Output:	358.0 kW (480 bhp)
Open Market Value:	\$101,244.00
Original Registration Date:	04 Dec 2012
First Registration Date:	04 Dec 2012
Transfer Count:	2
Actual ARF Paid:	\$101,244.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Dec 2022
PARF Rebate Amount:	\$70,870.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	03 Dec 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$80,001.00
COE Rebate Amount:	\$36,798.00
<b>Total Rebate Amount:</b>	<b>\$107,668.00</b>

The information contained herein is correct as at 27 Apr 2018

OK

MCR118038311 / ETHOZ Protect Pte Ltd - Bukit Batok  
 ENTRY DATE & TIME: 21/03/2018 11:22  
 SUBMITTED BY: Jonathan Lim Kok Siong

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/03/2018 11:22
Date Of Accident	20/03/2018 20:20
Exact Location Of Accident	ALONG ORCHARD ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU9Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG YUAN GE, BENJAMIN (HUANG YUANGE)
NRIC No	S8836966A
Email Address	TALONCERBERUS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96665550
Alternative Phone No	Office-96665550

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C63 AMG A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01015162
Cover Note Number	17/10/2017-16/10/2018

### Driver

Name of Driver	NG YUAN GE, BENJAMIN (HUANG YUANGE)
NRIC No	S8836966A
Date Of Birth	04/10/1988
Occupation	INDOOR
Date Of Driving Pass	05/09/2015
Driving Experience	2 YEARS AND 6 MONTHS

Gender	MALE
Mobile Number	(LOCAL) +65-96665550
Fax Number	
Contact Number	OFFICE-96665550
EMail Address	TALONCERBERUS@GMAIL.COM
Address	BLK 40 EASTWOOD RD
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	Name: : CHEN LIN Gender: : Female
Passenger 2	Name: : LIU TING Gender: : Female
Passenger 3	Name: : WANG XIA Gender: : Male

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

REFER TO ATTACHMENT

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

## DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD976X
Vehicle Make/Model/Colour	BMW (B)
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	S7275616I
Contact Number	91837865
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLF6861T
Vehicle Make/Model/Colour	HONDA VEZEL (C)
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**Sketch Plan**

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Mar 2018		22 Mar 2018 17:31 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	MOHAMED ALI MARAICAR BATHURUL JAMAN, ID: S72756161		
Main Claimant:	NG YUAN GE, BENJAMIN (HUANG YUANGE), ID: S8836966A		
Vehicle Reg. No.:	SLU9Z	Date of Loss:	20/03/2018 20:00 - :59 [63 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D01508C02	Policy/Cover Note No.:	DMPCSN3058841701 (Comprehensive)
Vehicle Reg. No. (Insured):	SLD976X	Policy No. (Claimant):	D17MTPV01015162
		Excess:	S\$0.00
Repairer:	H C Motor Engineering (HQ) Blk 2 Kaki Bukit Avenue 2, #01-15 Kaki Bukit AutoHub, 417921 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 03/04/2018]		
Driver/Custodian (Insured):	MOHAMED ALI MARAICAR BATHURUL JAMAN (46 / Male), NRIC: S72756161		
Adj Asg. Remarks:	KINDLY IGNORE THE SUBJECT ON THE EMAIL THE CORRECT FILE IS THIS.		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.			
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>
			<b>Subject</b>
			<b>Handler</b>
			<b>Assigned By</b>
			<b>Completed On</b>
			<b>Created On</b>
			<b>Done?</b>
No results.			

## Claim Documents

\*SLU9Z (SNM18D01508C02)  
[SLD976X]

TP

NG YUAN GE, BENJAMIN (HUANG YUANGE)

Mar 20 2018 8:00PM

[MOHAMED ALI MARAICAR BATHURUL JAMAN]

H C Motor Engineering

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
<b>Video</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)					Thumbnail		Print		
1	21/03/18 11:48	<b>Video - Accident</b> [Linked Accident Report Documents]						Load MP4			
2	21/03/18 11:48	<b>Video - Accident</b> [Linked Accident Report Documents]						Load MP4			
<b>Assessment Reports</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)					Thumbnail		Print		
1	21/03/18 11:49	<b>Accident Statement</b>						Load HTM			
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)					Thumbnail		Print		
1	21/03/18 11:41	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
2	21/03/18 11:41	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
3	21/03/18 11:41	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
4	21/03/18 11:41	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
5	21/03/18 11:41	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
6	21/03/18 11:41	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
7	21/03/18 11:41	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
8	21/03/18 11:41	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
9	21/03/18 11:41	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
10	21/03/18 11:41	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
11	21/03/18 11:41	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
12	21/03/18 11:49	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
13	21/03/18 11:49	<b>Accident Photo</b> [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print		
1	21/06/18 14:24	<b>General View</b>						Load PDF			
2	21/06/18 14:25	<b>Photographs of Damaged Parts</b>						Load PDF			
3	21/06/18 14:25	<b>Photo After Spray</b>						Load PDF			
<b>Documentation</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)					Thumbnail		Print		
1	21/03/18 11:46	<b>Sketch Plan</b> [Linked Accident Report Documents]						Load TIF			
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail		Print		
1	22/03/18 17:30	<b>PRS</b>						Load PDF			
2	22/03/18 17:30	<b>OI GIA REPORT</b>						Load PDF			

### Linked Accident Report Documents

View

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	21/03/18 11:48	Video - Accident	Load MP4	<input checked="" type="checkbox"/>
2	21/03/18 11:48	Video - Accident	Load MP4	<input checked="" type="checkbox"/>

  

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	21/03/18 11:49	Accident Statement	Load HTM	<input checked="" type="checkbox"/>

  

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	21/03/18 11:41	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	21/03/18 11:41	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	21/03/18 11:41	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	21/03/18 11:41	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	21/03/18 11:41	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	21/03/18 11:41	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	21/03/18 11:41	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	21/03/18 11:41	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	21/03/18 11:41	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	21/03/18 11:41	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	21/03/18 11:41	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	21/03/18 11:49	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	21/03/18 11:49	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

  

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	21/03/18 11:46	Sketch Plan	Load TIF	<input checked="" type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p><b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b></p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<p><b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18005548/AD3E2

Date: 27/06/2018

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3058841701	
Claimant Vehicle No :	SLU9Z	Insured Vehicle No :	SLD976X	
Date of Loss:	20/03/2018	Nature of Claim:	TP	Claim No: SNM18D01508C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>SLU9Z</b>		Engine No:	15698560076069
Make & Model:	MERCEDES-BENZ C63, 6.2 AMG (A)		Chassis No:	WDD2040772A729370
Reg. Date:	04/12/2012 (Man. Year: 2012)		Odometer:	68577 km
Colour:	Silver			
Engine Capacity:	6208 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	265/30 R19	Rear Tyre Size:	265/30 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	22/03/2018	
Date Inspected:	26/03/2018 Inspected At:	H S Motor Engineering (HQ) Blk 2 Kaki Bukit Avenue 2, #01-15 Kaki Bukit AutoHub Singapore 417921
Estimated Period of Repair:	10.0 days	

Adjuster: ADRIAN LING

Manager: Nivitha Govindasamy

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000.00 - \$19,000.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 27 Jun 2018)

**Parts:** 143      MERCEDES-BENZ C63 6.2 AMG (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLU9Z)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.