

ASS. REC. BY:

REF: CS/CTI18005559/KD302

Date of Instruction:

Survey of
Meinmen

Kenneth

ASSIGNMENT (Office)

From (Person): Jowyn Tay

of CTI

Date/Time: 26/3/18 @ 10:03am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No: SDW 9595Y

Insured: YN 9995A

at Workshop m/s: Lei Huet (Meng Kee)

Tel: 64538110

of 160 Sin Ming Drive #04-01

Policy No: DMcvSN1674971701

Claim No: 8NM18D01555C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 16/03/18

(Client's Record)

veh will be in after 2pm.

CA / REV / REP. / REV 24 HRS /wp

H.O.D. Endorsement:

Date/Time: 11:10am 26/3/18

Person Contacted:

jenny

Vehicle: IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SDW 9595Y - X

YN9995A - X

11/5/18

Final fig \$1769 confirmed by email (Recd 15, 8/5)

~~check with joint photo.~~

CRB SW

[Signature]
14/05/18

ASS. REC. BY:

REF: 0721

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s 611 m/c

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: POW 95954 Yr Regn: 10, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Camry c.c. 2494

Colour: Wh. Silver A/C: Insured / Std / Nil / NA

Sp. Reading: 34434 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: NR053AK 500 & 011575

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / RIM or

Tyre Size: F: 215/65R17

R: _____

BS: BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 16/3/18

D.O.I. 26/3/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or O/S R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/3 File sent to Catherine

RECEIVED 14 MAY 2018

Date/Time, File Pass to?

: Prell. Report

1)

: Final Report

Date/Time, File Return to?

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

220

Transportation:

S + RS \$

Photos

Others

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format:

merimen

Lump Sum / I.B.I. (\$) 1769/2

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18005559/Kvd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 26-03-2018



Code : CTI

1. Policy Particulars - THIRD PARTY CLAIM

Insured Veh.	YN 9995A	Veh. Inspected	SDW 9595Y
Policy No.	DMCVSN1674971701	Coverage (\$)	0.00
Claim No.	SNM18D01555C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	26/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	16/03/2018	Inspection Date	26/03/2018
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Mar 2018 Sendback Est	23 Mar 2018 14:04 S\$1,919.00	26 Mar 2018 10:03 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	--, ID: --								
Main Claimant:	LAU ENG HWA, ID: S1299555E								
Vehicle Reg. No.:	SDW9595Y	Date of Loss:	16/03/2018 17:00 - :59						
Claim Type:	TP / SNM18D01555C02	Policy/Cover Note No.:	DMCVSN1674971701						
Vehicle Reg. No. (Insured):	YN9995A	Policy No. (Claimant):	17-MH001436-R01						
		Excess:	S\$0.00						
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/04/2018]								
Adj Asg. Remarks:	EST - \$2053.33 , CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 9555E

Vehicle Details

Vehicle No.: SDW9595Y
Vehicle to be Exported: Yes
Intended De-registration Date: 19 Mar 2018
Vehicle Make: TOYOTA
Vehicle Model: CAMRY 2.5 AUTO
Primary Colour: Silver
Manufacturing Year: 2016
Engine No.: 2ARU343399
Chassis No.: MR053AK5004011579
Maximum Power Output: 133.0 kW (178 bhp)
Open Market Value: \$29,570.00
Original Registration Date: 17 Oct 2016
First Registration Date: 17 Oct 2016
Transfer Count: 0
Actual ARF Paid: \$33,398.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 16 Oct 2026
PARF Rebate Amount: \$25,048.00

Intended COE Rebate Details

COE Expiry Date: 16 Oct 2026
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$56,889.00
COE Rebate Amount: \$45,511.00
Total Rebate Amount: \$70,559.00

The information contained herein is correct as at 19 Mar 2018



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

 6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

TAX INVOICE

 Our Ref No: GR-18-041216
 Date of Request: 19/03/2018

Your Ref No: Online Purchase

 Lai Huat (Meng Kee) Motor Pte Ltd
 160 Sin Ming Drive #04-01
 Sin Ming AutoCity
 Singapore 575722

Dear Sir/Madam,

 Enquiry Date 19/03/2018
 Enquiry By Jenny Lim Lai Foong
 TP Vehicle No. YN9995A
 Accident Date 16/03/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00



Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:



 GIRO Cash Cheque



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	29 Dec 1980

NP 428A



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/03/2018 13:52
Date Of Accident	16/03/2018 17:30
Exact Location Of Accident	YU LI INDUSTRIAL BUILDING CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDW9595Y
Insured/Policyholder	
Name Of Registered Owner	LAU ENG HWA
NRIC No	S1299555E
Email Address	DAVIDLAU@EHB.COM.SG
Mobile Phone No	(LOCAL) +65-97880865
Alternative Phone No	OTHERS-97880865
Vehicle Particulars	
Manufacturer	TOYOTA
Model	CAMRY-2.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MH001436-R01
Cover Note Number	
Driver	
Name of Driver	LAU ENG HWA
NRIC No	S1299555E
Date Of Birth	20/12/1958
Occupation	INDOOR
Date Of Driving Pass	29/12/1980
Driving Experience	37 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	+65-97880865
Fax Number	
Contact Number	OTHERS-97880865
EEmail Address	DAVIDLAU@EHB.COM.SG

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: **19 MAR 2018**

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: **Jenny Lim**
NRIC/FIN No.: **S6927273H**



**SINGAPORE
POLICE FORCE**



T/20180322/2064

Police Station Of Origin:
Geylang Serai NPP
111 Aljunied Crescent #01-102 SINGAPORE
380111
Tel No: 1800-7459999

1 of 3

Report No. T/20180322/2064

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/03/2018 13:39	Vide Report No.:	Station Diary No.: 12
--	------------------	--------------------------

Informant's Particulars:			
Name of Informant: LAU ENG HWA		Address: APT BLK 766 YISHUN AVENUE 3 #09-287 SINGAPORE 760766	
ID Type / ID No.: NRIC NO / S1299555E		Contact No.: Home/Office: Mobile: 97880865	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 59	Date of Birth: 20/12/1958	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: MANAGER		Driving Licence Information: Class:	Date of Expiry:

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 16/03/2018 17:30	Type of Location: parking lot
Location: Along Road 1 LORONG 23 GEYLANG				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SDW9595Y	Car	TOYOTA	CAMRY 2.5 AUTO	Silver		0
YN9995A	Lorry					0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SDW9595Y	TOKIO MARINE INSURANCE SINGAPORE LTD.	MH001436	17/10/2016	16/10/2018



**SINGAPORE
POLICE FORCE**



T/20180322/2064

Police Station Of Origin:
Geylang Serai NPP
111 Aljunied Crescent #01-102 SINGAPORE
380111
Tel No: 1800-7459999

3 of 3



Report No. T/20180322/2064

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 HAIDER YAHYA	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 22/03/2018 13:39
Officer In Charge Of Case: TP / HRT / SI TAN LEE HWANG DAWN Const. No: 76215	Classification Of Case:
Authentication Stamp NP168  SIGNATURE	

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

Claimant Insurer: Tokio Marine Insurance Singapore Ltd

PARTICULARS OF CLAIM

Claim Type: Third Party	Ref. No: 69328
Policy No:	Date of Loss: 16/03/2018
Vehicle Reg. No.: SDW9595Y	Driveable?
Party At Fault: UNKNOWN	
Driver (TP): LAU ENG HWA	

Make/Model: TOYOTA CAMRY, 2.5 (A)	Vehicle Reg. Date: 17/10/2016
Vehicle Colour: Silver	
Engine No: 2ARU343399	Chassis No: MR053AK5004011579
Odometer: 0 KM	

*Not with claim
1. B1
Resurvey before painting*

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	7/3

Description of Accident/Loss: REFER TO SKETCH PLAN / REFER TO POLICE REPORT NO: T/20180322/2064

Present Location: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) / VICTOR FAN

COST OF CLAIMS

Parts
 Miscellaneous Items
 Labour
 Paintwork Labour
 Towing

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged parts during resurvey • Parts prices are subject to confirmation • Third party surveys on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary items must be resurveyed and is subject to final approval from Insurance Company 	Amount
<p>Acknowledged by: _____</p> <p>Gross Total (S\$)</p>	1,919.00
<p>+ GST 7.00% (S\$)</p>	134.33
Nett Amount (S\$)	2,053.33

This claim is handled by: VICTOR FAN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Mar 2018)
Parts: 143 TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SDW9595Y/23/03/2018 14:04
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper	<i>CRM</i> 0.00	0.00	*265.00 F
2	1		*Front bumper side holder RH	<i>CRM</i> 0.00	0.00	*38.00 F
3	1		*Front parking sensor RH	<i>SUR</i> 0.00	0.00	*180.00 F
4	1		*Front headlamp with chrome moulding RH	<i>CRM</i> 0.00	0.00	*420.00 F
5	1		*Front bumper air intake RH	<i>MII</i> 0.00	0.00	*45.00 F
6	1		*Front fender inner shield RH	<i>CRM</i> 0.00	0.00	*90.00 F
7	1		*Front bumper side clip RH	<i>NA</i> 0.00	0.00	*7.00 F
8	4		*Front bumper inner shield clips RH	<i>MIC</i> 0.00	0.00	*4.00 F
9	1		*Dual VVTi emblem RH	<i>NA</i> 0.00	0.00	*20.00 F
Total Parts (S\$)						1,069.00

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SDW9595Y/23/03/2018 14:04. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			<i>400</i>
1	To spray paint	New	500.00
<u>Labour Items</u>			<i>300</i>
2	To knock dents on front fender RH and renew of parts	New	350.00
Gross Labour Cost (S\$)			850.00

Lai Huat (Meng Kee) Motor Pte Ltd/SDW9595Y/23/03/2018 14:04. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 11 May 2018 12:07 PM
To: 'Jenny Lim'; SUR
Subject: RE: Finalisation - SDW 9595Y / Toyota Camry

Dear Jenny,

WITHOUT PREJUDICE

Confirmed \$1769 @ 4 days instead of 7 days.

Final invoice and all supporting documents sent over to CNTPI

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Lim [mailto:jenny.lim@laihuat.com.sg]
Sent: Thursday, 10 May 2018 4:30 PM
To: SUR <sur@lkkauto.com>
Subject: FW: Finalisation - SDW 9595Y / Toyota Camry

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

From: Jenny Lim [mailto:jenny.lim@laihuat.com.sg]
Sent: Monday, 7 May, 2018 4:39 PM
To: Kenneth Kong
Subject: Finalisation - SDW 9595Y / Toyota Camry

Dear Sir

For your confirmation, please:

- Parts: \$1,069.00
- Labour: \$ 300.00
- Paint: \$ 400.00
- Total: \$1,769.00 / 7 days**

Supporting document and photographs are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Mar 2018)
Parts: 143 TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SDW9595Y/23/03/2018 14:04
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper	<i>CMA</i> 0.00	0.00	*265.00 F
2	1		*Front bumper side holder RH	<i>CMA</i> 0.00	0.00	*38.00 F
3	1		*Front parking sensor RH	<i>SCR</i> 0.00	0.00	*180.00 F
4	1		*Front headlamp with chrome moulding RH	<i>CMA</i> 0.00	0.00	*420.00 F
5	1		*Front bumper air intake RH	<i>M/I</i> 0.00	0.00	*45.00 F
6	1		*Front fender inner shield RH	<i>CMA</i> 0.00	0.00	*90.00 F
7	1		*Front bumper side clip RH	<i>NA</i> 0.00	0.00	*7.00 F
8	4		*Front bumper inner shield clips RH	<i>NA</i> 0.00	0.00	*4.00 F
9	1		*Dual VVTi emblem RH	<i>NA</i> 0.00	0.00	*20.00 F
Total Parts (\$\$)						1,069.00

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SDW9595Y/23/03/2018 14:04. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To spray paint	New	500.00
<u>Labour Items</u>			
2	To knock dents on front fender RH and renew of parts	New	350.00
Gross Labour Cost (S\$)			850.00

4000

3000

Lai Huat (Meng Kee) Motor Pte Ltd/SDW9595Y/23/03/2018 14:04. Not valid without Reference section.
Generated using Merlimen e-Claims IEAS

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Mar 2018 Sendback Est	23 Mar 2018 14:04 \$1,919.00	26 Mar 2018 10:03 Edit Adj Rpt	\$1,769.00 Edit Estimates	\$1,769.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS			
Insured:	--, ID: --		
Main Claimant:	LAU ENG HWA, ID: S1299555E		
Vehicle Reg. No.:	SDW9595Y	Date of Loss:	16/03/2018 17:00 - :59 [16 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D01555C02	Policy/Cover Note No.:	DMCVSN1674971701
Vehicle Reg. No. (Insured):	YN9995A	Policy No. (Claimant):	17-MH001436-R01
		Excess:	S\$0.00
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 05/04/2018]		
Adj Asg. Remarks:	EST - \$2053.33 , CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS <input type="checkbox"/>											View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?					
No results.														

Claim Documents

SDW9595Y (SNM18D01555C02)
 [YN9995A]
 TP
 LAU ENG HWA
 Mar 16 2018 5:00PM
 [--]
 Lai Huat (Meng Kee) Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser <input type="checkbox"/>	
Assessment Reports			1 per page <input type="checkbox"/>	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	19/03/18 16:56	Accident Statement	Load HTM	<input type="checkbox"/>
2	23/03/18 13:43	Addendum Sheet	Load TIF	<input type="checkbox"/>
3	23/03/18 13:44	Accident Statement Addm. #1	Load HTM	<input type="checkbox"/>
4	23/03/18 14:04	Repairer Estimates	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/>	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	19/03/18 16:55	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	19/03/18 16:55	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	19/03/18 16:55	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	19/03/18 16:55	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	19/03/18 16:55	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	23/03/18 14:02	Front View	Load JPG	<input checked="" type="checkbox"/>
7	23/03/18 14:02	Front View Left	Load JPG	<input checked="" type="checkbox"/>
8	23/03/18 14:02	Front View Right	Load JPG	<input checked="" type="checkbox"/>
9	23/03/18 14:02	Front View Right	Load JPG	<input checked="" type="checkbox"/>
10	23/03/18 14:02	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
Relabel/Reorder			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/05/18 11:59	General View	Load PDF	<input type="checkbox"/>
2	11/05/18 12:00	Reinspection Photo	Load PDF	<input type="checkbox"/>
Documentation			1 per page <input type="checkbox"/>	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	19/03/18 15:54	Sketch Plan [Linked Accident Report Documents]	Load TIF	<input type="checkbox"/>
2	19/03/18 15:54	Driver's NRIC + Driving License [Linked Accident Report Documents]	Load TIF	<input type="checkbox"/>
3	19/03/18 15:54	Certificate of Insurance [Linked Accident Report Documents]	Load TIF	<input type="checkbox"/>
4	23/03/18 14:04	E-filed GIA report	Load PDF	<input type="checkbox"/>
5	23/03/18 14:04	Driver's NRIC + Driving License	Load PDF	<input type="checkbox"/>
6	23/03/18 14:04	Certificate of Insurance	Load PDF	<input type="checkbox"/>
7	23/03/18 14:04	Enquire PARF / COE Rebate for Registered Vehicle	Load PDF	<input type="checkbox"/>
8	23/03/18 14:04	GIA Search	Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Repairer Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18005559/KVD3E2

Date: 18/05/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN1674971701	
Claimant Vehicle No: SDW9595Y	Insured Vehicle No: YN9995A	
Date of Loss: 16/03/2018	Nature of Claim: TP	Claim No: SNM18D01555C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDW9595Y		Engine No: 2ARU343399
Make & Model: TOYOTA CAMRY, 2.5 (A)		Chassis No: MR053AK5004011579
Reg. Date: 17/10/2016 (Man. Year: 2016)		Odometer: 34434 km
Colour: Metallic Silver		
Engine Capacity: 2494 cc		
Market Value/New Car Price: N/A		
Sum Insured (\$\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes	
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 215/65 R17	Rear Tyre Size: 215/65 R17
Front Left Side: Dunlop 7 mm	Rear Left Side: Dunlop 7 mm
Front Right Side: Dunlop 7 mm	Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,069.00	1,069.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	350.00	300.00	50.00	14.29
Paintwork Labour	500.00	400.00	100.00	20.00
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,919.00	1,769.00	150.00	7.82
+ GST 7.00/7.00% (\$\$)	134.33	123.83	10.50	7.82
Nett Amount (\$\$)	2,053.33	1,892.83	160.50	7.82

INSPECTION

Date of Assignment: 26/03/2018	Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	
Date Inspected: 26/03/2018	Inspected At: 160 Sin Ming Drive #04-01, Sin Ming AutoCity	
Estimated Period of Repair: 4.0 days	Singapore 575722	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 May 2018)
Parts: 143 TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SDW9595Y)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bumper	Cracked	265.00 F	*265.00 F
2	1		*Front bumper side holder RH	Cracked	38.00 F	*38.00 F
3	1		*Front parking sensor RH	Scratched	180.00 F	*180.00 F
4	1		*Front headlamp with chrome moulding RH	Cut	420.00 F	*420.00 F
5	1		*Front bumper air intake RH	Missing	45.00 F	*45.00 F
6	1		*Front fender inner shield RH	Cracked	90.00 F	*90.00 F
7	1		*Front bumper side clip RH	Necessary	7.00 F	*7.00 F
8	4		*Front bumper inner shield clips RH	Necessary	4.00 F	*4.00 F
9	1		*Dual VVTi emblem RH	Necessary	20.00 F	*20.00 F
Total Parts (S\$)					1,069.00	1,069.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To spray paint	New	500.00	400.00
<u>Labour Items</u>				
2	To knock dents on front fender RH and renew of parts	New	350.00	300.00
Gross Labour Cost (\$\$)			850.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >