

ASS. REC. BY:

REF: CS3 / MSG18005563 / T1d347

Range

Special Instruction:

Surveyor

Mennen

Taufikh

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSIG

Date/Time:

26/3/18 @ 9:37am

Estimated Cost:

Bill to:

OD ~~FP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 369D

Insured:

SJH 9093L

at Workshop m/s

Empire Image

Tel:

9742 5441

of

No. 4 pendan loop Blk K

Policy No:

A28896348 QMX

Claim No:

553345

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/03/2018

CA / REV / REP. / REV 24 HRS

wp?

Date/Time:

11:15am @ 26/3/18

Person Contacted:

Kenny

H.O.D. Endorsement:

Vehicle

IN / OUT

Date/Time

Action/Instruction

(X)

Estimate

SLC 369D-x

SJH 9093L-x.

Signature

Tang

REF:


MSLG

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No. \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record) \_\_\_\_\_  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAO Accident Report: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

WP' PRS'

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Kenny

Date / Time Action / Instruction

No GIA

\* Repair Estimate : S\$ 8400 - 9400

\* 3 days

7/5 Submit PRS report.

RECEIVED 07 MAY 2018

Date/Time: File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

Report Format: PRS-

Lump Sum / I.B.R. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Ins (\$)

☐

Weekend (\$)

Survey Fee

Transportation

S - PR \$

Photos

Other

TOTAL

120
50
10
180

Veh No: SIC369 D Yr Regn: 10Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz E250 cc: 1796Colour: white A/C: Insured / Std / NI / NASo Reading: 73624 T Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WDD2074472F052224Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 265/55 R 19.R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal: 6 mm R/Bal: 6 mmL/Bal: 6 mm L/Bal: 6 mmD.O.A. 26/3/18 @ 165Survey held at Empire ImageDes. of Damages: FR / Rear / O/S / MS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Mar 2018		26 Mar 2018 09:37 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN CHEONG BENG, ID: S1296158H, Tel: +6596264819, Email: tanjason98@gmail.com		
Main Claimant:	Leow Kok Meng, ID: S8217033B		
Vehicle Reg. No.:	SLC369D	Date of Loss:	22/03/2018 14:00 - :59
Claim Type:	TP / 553345	Policy/Cover Note No.:	A28896348QMX (Comprehensive) Coverage: 18/03/2017 - 27/08/2018
Vehicle Reg. No. (Insured):	SJH9093L	Policy No. (Claimant):	
		Excess:	
Repairer:	Empire Image (HQ) NO 4 PANDAN LOOP (BLK 1/ BLK K), 128222 West Coast - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/03/2018]		
Driver/Custodian (Insured):	TAN CHEONG BENG (59 / Male), NRIC: S1296158H, Tel: +6596264819		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Our Ref : CY(EI)SLC369D/hh  
Please email to: [helen@yoga-legal.com](mailto:helen@yoga-legal.com)  
Your Ref : Your insured vehicle SJH9093L

26th March 2018

The Motor Claims Department  
**MSIG Insurance (Singapore) Pte Ltd**  
4 Shenton Way #21-01 SGX Centre 2  
Singapore 068807

By Email: [Nabilah\\_rasol@sg.msig-asia.com](mailto:Nabilah_rasol@sg.msig-asia.com)

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION**  
**ACCIDENT INVOLVING SLC369D & SJH 9093L ON 22/03/2018 @ 15:30 HRS**  
**ALONG CENTRAL EXPRESSWAY TO BRADDELL ROAD**

We refer to your email of even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose Mr. Jimmy Lee of M/s. Priority Services to conduct a Pre-Repair inspection.

Please be informed that the said vehicle can be inspected at:

Name of workshop : M/s. Empire Image Pte Ltd  
Address : 4 PandanLoop (Blk 1/Blk 1K)  
Singapore 12822  
Contact person : Mr. Kenny Lim  
Telephone number : 97425441  
Fax number : 67778126

Please be informed that if we do not hear from you **within 2 working days** from the date hereof, we will assume, as per Protocol, that you have no objections to our abovenamed motor surveyor you will be deemed to have agreed as a "single joint expert".

**If you object to our motor surveyor, we will accordingly inform the claimant to instruct his choice of motor Surveyor to conduct the pre-repair survey.**

Yours faithfully,

**C. Yogarajah LLC**

c.c. client  
Mr. Leow Kok Meng  
c/o M/s. Empire Image  
(By Fax: 67778126)

**For Surveyor**

Please initial here after completion of pre-repair inspection.  
Thank you.

Name:  
Signature:

Date & Time of Pre-repair inspection: /

## Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLC369D		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	MERCEDES BENZ		
Vehicle Model :	E250 CGI A		
Chassis No. :	WDD2074472F052224		
Propellant :	Petrol		
Engine No. :	27186030071946		
Engine Capacity :	1796 cc		
Maximum Power Output :	150.0 kW ( 201 bhp )		
Maximum Laden Weight :	2165 kg		
Unladen Weight :	1695 kg		
Year Of Manufacture :	2010		
Original Registration Date :	30 Sep 2010		
Lifespan Expiry Date :	-		
COE Category :	B - Car (1601cc & above)		
Quota Premium :	\$42,501.00		
COE Expiry Date :	29 Sep 2020		
Road Tax Expiry Date :	29 Sep 2018		
PARF Eligibility Expiry Date :	29 Sep 2020		
Inspection Due Date :	29 Sep 2019		
Intended Transfer Date :	25 Apr 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	7033B
<b>Vehicle Details</b>	
Vehicle No.:	SLC369D
Vehicle to be Exported:	No
Intended De-registration Date:	25 Apr 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E250 CGI A
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	27186030071946
Chassis No.:	WDD2074472F052224
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$61,908.00
Original Registration Date:	30 Sep 2010
First Registration Date:	30 Sep 2010
Transfer Count:	3
Actual ARF Paid:	\$61,908.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2020
PARF Rebate Amount:	\$37,144.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Sep 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$42,501.00
COE Rebate Amount:	\$10,318.00
<b>Total Rebate Amount:</b>	<b>\$47,462.00</b>

The information contained herein is correct as at 25 Apr 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/03/2018 12:23
Date Of Accident	22/03/2018 15:30
Exact Location Of Accident	ALONG ROAD 1 CENTRAL EXPRESSWAY TO BRADDELL ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC369D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LEOW KOK MENG
NRIC No	S8217033B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97643699
Alternative Phone No	OFFICE-97643699

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250 CGI
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA102575
Cover Note Number	

### Driver

Name of Driver	HO WUN CHENG
NRIC No	S9442459C
Date Of Birth	15/11/1994
Occupation	INDOOR
Date Of Driving Pass	14/04/2016
Driving Experience	1 YEAR AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97643699
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 264 JURONG EAST STREET 24 #08-511 SINGAPORE
Postcode	600264
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HUSBAND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	SENGKANG N.P.C 2 SENGKANG SQUARE #01-02 SINGAPORE 545025
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHED POLICE REPORT NO T/20180322/2137

#### Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJH9093L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN CHEONG BENG
NRIC/Passport Number	
Contact Number	96264819
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

# Accident Sketch Plan Pg. 1

## SKETCH PLAN



A = SLC 369 D  
B = SJH 9093 L

← CTE (CITY) before braddell road exit.

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SLC 369 D	ACCIDENT DATE & TIME: 22/3/18 @ 1530 HRS
CONTACT NUMBER: 97643699	E-MAIL ADDRESS:
LOCATION: (CITY) CNY before braddell road exit	
<p>on 22/3/18 at around 1530 HRS, I was travelling on lane 1 of the CTE towards city near the braddell road exit, when I notice the cars in front of me slowing down and stopping. I immediately applied my brakes and slowed down to a stop behind the taxi in front of me avoiding any collision, when suddenly the car (SJH 9093 L) who was behind me suddenly crash into the rear of my vehicle (SLC 369 D) as he could not stop in time and damaged my rear of the vehicle. Upon impact, I felt my neck and back to be painful. I was advised by traffic police who arrive at the scene of the chain collision behind me, to make a police report and seek medical advise.</p> <p>Repair at Empire Image Pte LTD</p>	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
Please state:	
<input type="checkbox"/> Claim Own Policy <input type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only	

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 23/03/18

Driver's Signature

(If driver is not the policyholder)

Date & Time: 23/03/18 1130 AM

Reporting Centre Personnel's Signature

Name: OO: LEE KEOH

NRIC/FIN No.: S18821451

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Mar 2018		26 Mar 2018 09:37 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>TAN CHEONG BENG</b> , ID: S1296158H, Tel: +6596264819, Email: tanjason98@gmail.com								
Main Claimant:	<b>Leow Kok Meng</b> , ID: S8217033B								
Vehicle Reg. No.:	<b>SLC369D</b>	Date of Loss:	22/03/2018 14:00 - :59 [89 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 553345</b>	Policy/Cover Note No.:	A28896348QMX (Comprehensive) Coverage: 18/03/2017 - 27/08/2018						
Vehicle Reg. No. (Insured):	<b>SJH9093L</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Empire Image (HQ)</b> NO 4 PANDAN LOOP (BLK 1/ BLK K), 128222 West Coast - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Katherine Wong Chew Shong</b> - 6594 2544]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Imm.Advice due 27/03/2018]								
Driver/Custodian (Insured):	TAN CHEONG BENG (59 / Male), NRIC: S1296158H, Tel: +6596264819								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLC369D (553345)  
[SJH9093L]  
TP  
Leow Kok Meng  
Mar 22 2018 2:00PM  
[TAN CHEONG BENG]  
Empire Image

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Video						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print	
1	26/03/18 08:25	Video - Accident - Front Camera - SDK7808K From:SC - Reg. No: SJH9093L, Claimant: TAN CHEONG BENG					Load AVI		
2	26/03/18 08:25	Video - Accident - Front Camera - SDK7808K From:SC - Reg. No: SJH9093L, Claimant: TAN CHEONG BENG					Load AVI		
3	26/03/18 08:25	Video - Accident - Front Camera - SDK7808K From:SC - Reg. No: SJH9093L, Claimant: TAN CHEONG BENG					Load AVI		
4	26/03/18 08:25	Video - Accident - Back Camera - SDK7808K From:SC - Reg. No: SJH9093L, Claimant: TAN CHEONG BENG					Load AVI		
5	26/03/18 08:25	Video - Accident - Back Camera - SDK7808K From:SC - Reg. No: SJH9093L, Claimant: TAN CHEONG BENG					Load AVI		
6	26/03/18 08:25	Video - Accident - Back Camera - SDK7808K From:SC - Reg. No: SJH9093L, Claimant: TAN CHEONG BENG					Load AVI		
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print	
1	26/03/18 08:25	Accident Statement From:SC - Reg. No: SJH9093L, Claimant: TAN CHEONG BENG					Load HTM		
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
2	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
3	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
4	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
5	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
6	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
7	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
8	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
9	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
10	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
11	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
12	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
13	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
14	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
15	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
16	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
17	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
18	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
19	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
20	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
21	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
22	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	
23	07/05/18 10:33	General View					Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
24	07/05/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/03/18 08:25	(2/6) SLC369D E FILE REPORT From: SC - Reg. No: SJH9093L, Claimant: TAN CHEONG BENG	Load PDF	
2	26/03/18 09:37	PRI Details	Load PDF	
3	26/03/18 09:37	TP Disagree on SJE	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18005563/T1D3E2

Date: 08/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28896348QMX

Claimant Vehicle  
No : SLC369D

Insured Vehicle No : SJH9093L

Date of Loss: 22/03/2018

Nature of Claim: TP

Claim No: 553345

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLC369D

Make &amp; Model: MERCEDES-BENZ E250, 1.8 CGI (A)

Engine No: 27186030071946

Reg. Date: 30/09/2010 (Man. Year: 2010)

Chassis No: WDD2074472F052224

Colour: White

Odometer: 73624 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/35 R19

Rear Tyre Size: 265/35 R19

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment: 26/03/2018

Date Inspected: 26/03/2018 Inspected At:

Empire Image (HQ)  
NO 4 PANDAN LOOP (BLK 1/ BLK K)  
Singapore 128222

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,400.00 - \$9,400.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 08 May 2018)
<b>Parts:</b> M1-COUPE	MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLC369D)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >