

22/03/2002

ASS. REC. BY:

REF: CS/MSG18005564/Aqd302

Special Instruction:

Survivor:
Mehmen

Adnan

ASSIGNMENT (Office)

From (Person):

Elaine Ngu

of

MSIG

Date/Time:

26/3/18 @ 8:45am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKD 9846R

Insured:

FY 3960G

at Workshop m/s

Ho Beng Trading

Tel:

9271 2214

of

Blk 3020A # 01-33 Ubi Road 1

Policy No:

MSD/VMT/17-367771-CA

Claim No:

MSC/V/18-000434

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/03/2018

CA / REV / REP. / REV 24 HRS

lwp?

H.O.D. Endorsement:

Date/Time:

11:19am @ 26/3/18

Person Contacted:

Chris

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SKD 9846R-X

FY 3960G-X

27/3/18 @ 9:20pm informed Elaine Ngu, we are pending estimate from repairer.

06/6/18 @ 10:32am revised to Elaine Ngu via Mehmen.

US \$200, 7 days (Red \$ 1241.11, 63%)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18005317/Atd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 21-03-2018	
Code : CTI			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJB 5041U	Veh. Inspected	SLG 8610H
Policy No.	DMHCSN1743851700	Coverage (\$)	0.00
Claim No.	SNM18D01432C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	21/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/03/2018	Inspection Date	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Mar 2018		26 Mar 2018 08:45 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SOO CHING YAN , ID: S2677904I		
Main Claimant:	LEE YING YING (LI YING YING) , ID: S7534535F		
Vehicle Reg. No.:	SKD9846R	Date of Loss:	21/03/2018 07:00 - :59
Claim Type:	TP / MSC/V/18-000434	Policy/Cover Note No.:	MSD/VMT/17-367771-CA(TP) (Third Party Only) Coverage: 10/09/2017 - 09/09/2018
Vehicle Reg. No. (Insured):	FY3960G	Policy No. (Claimant):	
		Excess:	
Repairer:	Ho Beng Trading (HQ) Blk 3020A #01-33, Ubi Road 1, 408714 Ubi - Tel: 81862100		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/03/2018]		
Driver/Custodian (Insured):	SOO CHING YAN (), NRIC: S2677904I		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 06 Jun 2018

Preliminary Advice

Insured Vehicle No	: FY3960G	Accident Date	: 21/03/2018
TP Vehicle No	: SKD9846R	Assignment Date	: 26/03/2018
Make	: BMW X3 XDRIVE20I	Est. Duration of Repair	: 5.00
Date of Inspection	: 26/03/2018		
Inspection At	: HO BENG TRADING (HQ) BLK 3020A #01-33, UBI ROAD 1 SINGAPORE 408714		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,241.11
Revised Amount	:S\$	8,908.19
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,908.19
Lump Sum Repair	:S\$	7,100.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Tuesday, 27 March 2018 5:20 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SKD 9846R (YOUR REF: MSC/V/18-000434)

This mail is associated with :
***SKD9846R (MSC/V/18-000434)**
[FY3960G]
TP
LEE YING YING (LI YING YING)
Mar 21 2018 7:00AM
[SOO CHING YAN]
Ho Beng Trading

Dear Elaine,

Please be informed that we have inspected the vehicle SKD 9846R on 26/03/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561
Fax: 6256 4315

[This mail is sent from a mailer account - do not reply to this email address]

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	4535F

Vehicle Details

Vehicle No.:	SKD9846R
Vehicle to be Exported:	Yes
Intended De-registration Date:	27 Mar 2018
Vehicle Make:	B.M.W.
Vehicle Model:	X3 XDRIVE20I ABS 4WD SR HID DSC NAV
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	A3260058N20B20A
Chassis No.:	WBAWX32080LW42739
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$40,601.00
Original Registration Date:	27 Jan 2012
First Registration Date:	27 Jan 2012
Transfer Count:	0
Actual ARF Paid:	\$40,601.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jan 2022
PARF Rebate Amount:	\$26,390.00

Intended COE Rebate Details

COE Expiry Date:	26 Jan 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$67,889.00
COE Rebate Amount:	\$26,005.00
Total Rebate Amount:	\$52,395.00

The information contained herein is correct as at 27 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/03/2018 11:24
Date Of Accident	21/03/2018 07:30
Exact Location Of Accident	JALAN LAPANG / JALAN SENANG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD9846R
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	LEE YING YING (LI YING YING)
NRIC No	S7534535F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96895773
Alternative Phone No	OTHERS-96895773

Vehicle Particulars

Manufacturer	BMW
Model	X3 XDRIVE20I ABS 4WD SR HID DSC NAV

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN: 10117137 (COMP)
Cover Note Number	

Driver

Name of Driver	LEE YING YING (LI YING YING)
NRIC No	S7534535F
Date Of Birth	12/11/1975
Occupation	INDOOR
Date Of Driving Pass	25/11/1997
Driving Experience	20 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96895773
Fax Number	
Contact Number	OTHERS-96895773
Email Address	NOEMAIL

Address 23 JALAN LAPANG
 Postcode 418982
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WITH OWNER
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FY3960G
 Vehicle Make/Model/Colour YAMAHA T110Z
 Details Of Properties
 Vehicle Category MOTORCYCLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)


SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: **21 MAR 2018**

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: enquiry@idac.com.sg
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21st Mar 2018, about 745am, I, owner of SKD 9846R was travelling straight on Jalan Lapang.

The motorist, FY 3960G suddenly came out from Jln Senang and banged into my driver's side door all the way to the passenger ~~to~~ (behind) door. My car is badly dented by the collision. The motorist failed to stop at stop line before ~~making~~ going straight or perhaps making a right turn.

I have a ~~dash~~ dashcam and everything is recorded to be submitted for evidence.

Thank you.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

2 1 MAR 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

HO BENG TRADING

Block 3020A Ubi Road 1 # 01-33 Singapore 408714

Tel : (65) 69664526 HP: 92712214 Fax: (65) 69664526

Email : chris_chanbebe@hotmail.com

BLOCK 3020A UBI ROAD 1
01-33
Singapore 408714

TP MS16.
Xiao Chan.
WBAW X320804W42739.

27th MARCH 2018

Accident date: 21th March 2018

Estimated repair cost for vehicle no: SKD9846R BMW X3 '12

S/n	Qty	Items	U/price	Amount
1	1	Front fender-RH <i>Dented.</i>		\$1,523.20 ✓ 578.
2	1	Front fender Protector <i>1</i> -RH <i>ut</i>		\$221.58 ✓
3	1	Front R/H Tyre <i>the new</i>		\$950.00 ✓
4	1	Front R/H Rim <i>ut</i>		\$1,200.00 ✓ 750(SN).
5	1	Front R/H Knuckle Arm <i>2 x the new</i>		\$1,060.50 ✓
6	1	Front R/H Knuckle Arm Bearing		\$709.03 ✓
7	1	Front L/H wheel hup with bearing <i>Dented</i>		\$709.30 ✓
8	1	Front R/H door <i>Dented.</i>		\$1,850.00 ✓ 1425
9	1	Front R/H door side mirror assy <i>Dented.</i>		\$890.00 ✓
10	1	Front R/H door lower moulding <i>Deformed.</i>		\$188.00 ✓
11	1	Front L/H door outer handle <i>the new</i>		\$220.00 ✓
12	1	Front R/H door inner rubber <i>the new</i>		\$225.00 ✓
13	1	Front R/H door inner lock <i>the new</i>		\$420.00 ✓
14	1	Front R/H door inner trim board <i>the new</i>		\$890.00 ✓
15	1	front R/H door glass gear <i>Dented</i>		\$439.00 ✓
16	1	FRONT R/H door gear motor Assy <i>the new</i>		\$750.00 ✓
17	1	Front R/H lower skirt <i>2 x the new</i>		\$975.00 ✓
18	15	R/H lower skirt clips <i>the new</i>	\$3.50	\$52.50 ✓
19	1	Rear RH Door <i>Dented</i>	1387. ✓	
20	1	Rear RH Door Weathershipe <i>the new</i>	255 ✓	
21	1	Rear RH Fender Protector <i>ut</i>	268 ✓	
22	1	Rear RH Rim <i>the new</i>	1200 X	
23	1	Wiper Washer Tank. <i>Deformed</i>	158. ✓	
			Subtotal :-	\$13,273.11

6713-88

637818

S.N. 750

Labour charges

To Remove & refix cushion		\$120.00 60
To Remove & refix front RH undercarriage and rear.		\$250.00 100
To Remove & refix R/H front door glass, motor & reset wiring		\$350.00 160
To check wheel alignment computer		\$150.00 80
Tuff kote	1780	\$150.00 X
To Check Wiring System		\$80.00 30
Panel beating		\$800.00 650
Spray painting		\$800.00 700
Subtotal :-		<u>\$2,700.00</u>
Total:-		<u>\$15,973.11</u>

19/11-11

total 8908.18

H/S: 7.1K
05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Mar 2018		26 Mar 2018 08:45 Edit Adj Rpt	S\$7,100.00 Edit Estimates	S\$7,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	SOO CHING YAN, ID: S2677904I			
Main Claimant:	LEE YING YING (LI YING YING), ID: S7534535F			
Vehicle Reg. No.:	SKD9846R	Date of Loss:	21/03/2018 07:00 - :59 [73 Months and 22 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / MSC/V/18-000434	Policy/Cover Note No.:	MSD/VMT/17-367771-CA(TP) (Third Party Only) Coverage: 10/09/2017 - 09/09/2018	
Vehicle Reg. No. (Insured):	FY3960G	Policy No. (Claimant):		
		Excess:		
Repairer:	Ho Beng Trading (HQ) Blk 3020A #01-33, Ubi Road 1, 408714 Ubi - Tel: 81862100			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 25/04/2018]			
Driver/Custodian (Insured):	SOO CHING YAN (), NRIC: S2677904I			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SKD9846R (MSC/V/18-000434)
 [FY3960G]
 TP
 LEE YING YING (LI YING YING)
 Mar 21 2018 7:00AM
 [SOO CHING YAN]
 Ho Beng Trading

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/06/18 10:32	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
2	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
3	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
4	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
5	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
6	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
7	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
8	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
9	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
10	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
11	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
12	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
13	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
14	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
15	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
16	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
17	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
18	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
19	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
20	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
21	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
22	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
23	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
24	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
25	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
26	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
27	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
28	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
29	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
30	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
31	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
32	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
33	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>
34	05/06/18 19:14	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
36	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
37	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
38	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
39	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
40	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
41	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
42	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
43	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
44	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
45	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
46	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
47	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
48	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
49	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
50	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
51	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
52	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
53	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
54	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
55	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
56	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
57	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
58	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
59	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
60	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
61	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
62	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
63	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
64	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
65	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
66	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
67	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
68	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
69	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
70	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
71	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
72	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
73	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
74	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
75	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
76	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
77	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
78	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
79	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
80	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
81	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
82	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
83	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
85	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
86	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
87	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
88	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
89	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
90	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
91	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>
92	05/06/18 19:14	General View	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/03/18 12:54	FY3960G e-file report	 Load PDF	
2	26/03/18 08:47	TPD SKD9846R GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005564/AQD3E2

Date: 11/06/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/17-367771-CA (TP)
Claimant Vehicle No :	SKD9846R	Insured Vehicle No :	FY3960G
Date of Loss:	21/03/2018	Nature of Claim:	TP
		Claim No:	MSCN/18-000434

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD9846R		
Make & Model:	BMW X3 XDRIVE20I, 2.0 4WD SR HID DSC NAV (A)	Engine No:	A3260058N20B20A
Reg. Date:	27/01/2012 (Man. Year: 2011)	Chassis No:	WBAWX32080LW42739
Colour:	White	Odometer:	120598 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/50 R18	Rear Tyre Size:	245/50 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,541.11	7,128.19	9,412.92	56.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,780.00	920.00	34.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,241.11	8,908.19	10,332.92	53.70
Approved Total (Overridden) (S\$)		7,100.00		
Nett Amount (S\$)	19,241.11	7,100.00	12,141.11	63.10

INSPECTION

Date of Assignment:	26/03/2018	Inspected At:	Ho Beng Trading (HQ)
Date Inspected:	26/03/2018		Blk 3020A #01-33, Ubi Road 1
			Singapore 408714
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Jun 2018)	
Parts: M1-SUV	BMW X3 XDRIVE20I 2.0 4WD SR HID DSC NAV (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SKD9846R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER - RH	Dented	1,523.20 F	*548.00 FL
2	1		*FRONT FENDER PROTECTOR - RH	Cut	221.58 F	*221.58 FL
3	1		*FRONT R/H TYRE	Not Necessary	950.00 F	*- FL
4	1		*FRONT R/H RIM	Cut	1,200.00 FS	*750.00 FS
5	1		*FRONT R/H KNUCKLE ARM	Not Necessary	1,060.50 F	*- FL
6	1		*FRONT R/H KNUCKLE ARM BEARING	Not Necessary	709.03 F	*- FL
7	1		*FRONT L/H WHEEL HUP WITH BEARING	Damaged	709.30 F	*709.30 FL
8	1		*FRONT R/H DOOR	Dented	1,850.00 F	*1,425.00 FL
9	1		*FRONT R/H DOOR SIDE MIRROR ASSY	Damaged	890.00 F	*890.00 FL
10	1		*FRONT R/H DOOR LOWER MOULDING	Deformed	188.00 F	*188.00 FL
11	1		*FRONT L/H DOOR OUTER HANDLE	Not Necessary	220.00 F	*- FL
12	1		*FRONT R/H DOOR INNER RUBBER	Necessary	225.00 F	*225.00 FL
13	1		*FRONT R/H DOOR INNER LOCK	Not Necessary	420.00 F	*- FL
14	1		*FRONT R/H DOOR INNER TRIM BOARD	Not Necessary	890.00 F	*- FL
15	1		*FRONT R/H DOOR GLASS GEAR	Damaged	439.00 F	*439.00 FL
16	1		*FRONT R/H DOOR GEAR MOTOR ASSY	Not Necessary	750.00 F	*- FL
17	1		*FRONT R/H LOWER SKIRT	Not Necessary	975.00 F	*- FL
18	15		*R/H LOWER SKIRT CLIPS	Not Necessary	52.50 F	*- FL
19	1		*REAR RH DOOR	Dented	1,387.00 F	*1,387.00 FL
20	1		*REAR RH DOOR WEATHERSTRIPE	Necessary	255.00 F	*255.00 FL
21	1		*REAR RH FENDER PROTECTOR	Cut	268.00 F	*268.00 FL
22	1		*REAR RH RIM	Not Necessary	1,200.00 F	*- FL
23	1		*WIPER WASHER TANK	Deformed	158.00 F	*158.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,541.11	7,463.88
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	335.69
Total Parts (\$\$)	16,541.11	7,128.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX CUSHION	New	120.00	60.00
2	TO REMOVE & REFIX FRONT RH UNDERCARRIAGE	New	250.00	100.00
3	TO REMOVE & REFIX R/H FRONT AND REAR DOOR GLASS, MOTOR & RESET WIRING	New	350.00	160.00
4	TO CHECK WHEEL ALIGNMENT COMPUTER	New	150.00	80.00
5	TO CHECK WIRING SYSTEM	New	80.00	30.00
6	PANEL BEATING	New	800.00	650.00
7	SPRAY PAINTING	New	800.00	700.00
8	TUFF KOTE	New	150.00	0.00
Gross Labour Cost (\$\$)			2,700.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >