

REF:

Surveyor

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

PIP

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHD 6748X

Yr Regn:

2015 / April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make:

Hyundai I40

c.c

1685

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

199895

T/Radio: Insured / Std / NI / NA

Eng/No:

D4FDEU495794

C/No:

KMHLB41UMFU68135

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Mil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

- 11 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

23/03/2018

D.O.I.

23/03/2018

Survey held at

EDGE Loyang

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Body & N/S Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

China Taiping BJX8123G

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO305128022

JMER S COMFORT TRANSPORTATION PTE LTD JMER NO 7010045 ESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (O) (P)		REGN NO: SHD6748X MAKE: HYUNDAI MODEL I-40 23.03.2018 12:45 YR OF MANU 23.04.2015 CHASSIS CODE KMHLB41UMFU068135		MILEAGE FUEL E.....1/2.....F DATE/TIME IN TARGET DATE COMPLETION DATE/TIME:	
---	--	--	--	--	--

JOB DESCRIPTION

Accident Date: 23.03.2018

ATURE: 3P 23.03.18

'NO

LABOR CODE

DESCRIPTION

RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE _____

ledgement Slip

Exit Pass

No.: SHD6748X

JU CHINA LKK

Vehicle No.:

SHD6748X

f Service Advisor

Signature/Date

Name of Service Advisor

Date _____

turned to Service Reception upon collection

To be kept by Security Guard