

22/03/2002

ASS. REC. BY:

REF: CS/CTI18005573/Svd3<sup>n2</sup>

Special Instruction:

Surveyor:  
MemberSebastian  
Irene Tay

ASSIGNMENT (Office)

of CTI

Date/Time: 23/3/18 @ 3:07pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 9218B

Insured:

Gv 7237P

at Workshop m/s

World Auto

Tel:

6362 1776

of

No.1 Kranji Loop

Policy No:

DMCVSN 3030861700

Claim No:

SNM18D01525C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

11:27am @ 26/3/18

Person Contacted:

Daniel

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SLG 9218B-X

Gv 7237P-X

25/4/18

@ 1150am final fig \$ 864 confirmed with Sophia (Real 1620, 65%)

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days 25/4/18 Res. Sebastian Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLC 7218B Yr Regn: 18/10/2016Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle C.C. 1496Colour: Black A/C: Insured / Std / NI / NASp. Reading: 149709 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: GP 7 1041186Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60R15R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Rowlo

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 19/12/2017 D.O.I. 26/5/18Survey held at World AutoDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 25 APR 2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Others

TOTAL

Date/Time, File Return to?

25/4-19pmAdd Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Insp (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

meimen  
864

220



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18005573/Svd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 26-03-2018	
		Code : CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GV 7237P	Veh. Inspected	SLG 9218B
Policy No.	DMCVSN3030861700	Coverage (\$)	0.00
Claim No.	SNM18D01525C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	26/03/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	19/12/2017	Inspection Date	26/03/2018
Survey held at	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## Veron Chen (LKKAUTO)

---

**From:** tggtan@worldauto.com.sg  
**Sent:** Wednesday, 25 April 2018 2:38 PM  
**To:** Sebastian Yeang (LKK Auto)  
**Cc:** Veron Chen (LKKAUTO)  
**Subject:** FW: Finalization for SLG 9218B

Hi Sebastian

Confirmed COR @ \$864.00/3 days

Rdgs  
Sophia Tan  
World Auto Pte Ltd (Kranji)

---

**From:** tggtan@worldauto.com.sg <tggtan@worldauto.com.sg>  
**Sent:** Monday, 23 April 2018 3:18 PM  
**To:** 'Sebastian Yeang (LKK Auto)' <SebastianYeang@lkkauto.com>  
**Subject:** RE: Finalization for SLG 9218B

Hi Sebastian

Confirmed COR @ \$846.00. (\$864.00)

You have given 2 days for repairs.

Please confirm 3 days as stated in our estimate.

Rdgs  
Sophia Tan  
World Auto Pte Ltd (Kranji)

---

**From:** Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>  
**Sent:** Monday, 23 April 2018 1:44 PM  
**To:** tggtan@worldauto.com.sg  
**Cc:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Subject:** Finalization for SLG 9218B

Dear Sophia

Kindly refer to attachment t for the finalization.

Repair price subject to insurance approval.

Thank You

CS/CTI18005573/Svd3

Best Regards,

**Sebastian** | Automotive Assessor  
**LKK Auto Consultants**

phone: 6256-3561 email: [sebastianyeang@lkkauto.com](mailto:sebastianyeang@lkkauto.com) fax: 6256-4315



## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Mar 2018		23 Mar 2018 15:07 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	ROHAIZAD BIN SALAM		
Vehicle Reg. No.:	SLG9218B	Date of Loss:	19/12/2017 00:00 - :59
Claim Type:	TP / SNM18D01525C02	Policy/Cover Note No.:	DMCVSN3030861700
Vehicle Reg. No. (Insured):	GV7237P	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	World Auto (HQ) NO. 1 KRANJI LOOP, 739535 Kranji - Tel: 97422188		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/04/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN TO XING QUO QIANG AS SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date   Priority   Type   Task Group   Subject   Handler   Assigned By   Completed On   Created On   Done?

No results.

Lucas Lee

---

**From:** Ainee31 <aine31@worldauto.com.sg>  
**Sent:** Wednesday, 21 March, 2018 10:38 AM  
**To:** Claims Dept of CTI  
**Subject:** PRE- INSPECTION

**Dear Sir/Mdm,**

**We would like to request for a Third Party Motor Claim Survey, details as follow;**

**Our Vehicle: SLG9218B**

**Your Insured: GV7237P**

**DOA: 19/12/2017**

**Our vehicle is currently in the workshop, address as follow;**

**AINEE  
World Auto Pte Ltd  
No.1, Kranji Loop  
Singapore 739535**

Thanks and Rgds,

World Auto Pte Ltd

Tel HQ: 64513933

Kranji: 63621776

Fax: 64557576

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/12/2017 13:55
Date Of Accident	19/12/2017 12:15
Exact Location Of Accident	WOODLANDS AVENUE 3
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG9218B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201604597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992

### Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE HYBRID-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY  
Vehicle Category PRIVATE HIRE

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995174
Cover Note Number	

### Driver

Name of Driver	ROHAIZAD BIN SALAM
NRIC No	S8031406Z
Date Of Birth	08/10/1980
Occupation	OUTDOOR
Date Of Driving Pass	13/05/2003
Driving Experience	14 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL



Address	NOADDRESS
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : NONAME GENDER: : MALE
Passenger 2	NAME: : NONAME GENDER: : MALE

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

REFER TO SKETCH PLAN

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	NO VIDEO TO SHOW
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GV7237P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	



Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
  2. This Form must be completed by the Policyholder and/or the Authorised Driver.
  3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
  5. Any false reporting may be referred to the Police for investigation.
  6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
  8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

WOODLANDS  
CENTRE ROAD

Witnessed by Reporting Centre Personnel



WOODLANDS AVE 3

## Sketch Plan #2

### Describe Circumstances of the Accident


WH ON 19/12/2017, AT ABOUT 1215 PM, MY VEHICLE CAME TO  
AT A STOP AT THE JUNCTION OF WOODLANDS AVE 3 & WOODLANDS  
CENTRE ROAD. WHILE WAITING FOR THE LIGHT TO CHANGE TO  
TURN RIGHT INTO WOODLANDS CENTRE ROAD, MY VEHICLE WAS  
HIT FROM THE REAR BY VEHICLE GV7237P.

### Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &  
Time



20/12/17

Driver's Signature (if driver is not the policyholder) / Date  
& Time

Witnessed by Reporting Centre  
Personnel

# WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03  
Halcyon 2, S'pore 577200  
Tel No. : 6451 3933 Fax No. : 6455 7576  
E-Mail : worldaut@singnet.com.sg  
Website : www.worldauto.com.sg  
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

China Taiping Insurance (S) Pte Ltd

Attention : Motor Claim Department

Estimate : ES000012

Date : 21/03/2018  
Vehicle Num. : SLG 9218B (LCR)  
Make/Model : HONDA SHUTTLE HYBRID  
Chassis/Eng# :  
Accident Date : 19/12/2017  
Claim No. :  
Reference :  
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
<b>LIST ITEMS :</b>				
1.	1	REAR TAILGATE <i>R</i>		1,200.00
2.	1	REAR TAILGATE HYBRID EMBLEM (SHUTTLE) <i>VNEC</i>		90.00
3.	1	REAR TAILGATE SHUTTLE EMBLEM (SHUTTLE) <i>VNEC</i>		90.00
List TotalS\$ :				1,380.00
20.00% Discount S\$ :				276.00
				1,104.00
<b>LABOUR :</b>				
REMOVE & REFIT REAR WINDSCREEN GLASS				<i>120</i> 180.00
TO LABOUR FOR REMOVING & REPAIRS THE REAR TAILGATE				<i>300</i> 600.00
TO PUTTY & SPRAY PAINT THE REAR AFFECTED AREARS.				<i>300</i> 600.00
Labour Total S\$ :				1,380.00

E. & O.E.

Total S\$ : 2,484.00

for WORLD AUTO PTE LTD

*Sebastian*  
*29/3/18*  
*- Part by part repair*  
*- Photo After Paint*  
*90036121*  
*sebastianyeang@lkkauto.com*  
*3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

China Taiping Insurance (S) Pte Ltd

Attention : Motor Claim Department

Estimate : ES000012

Date : 21/03/2018

Vehicle Num. : SLG 9218B (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 19/12/2017

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	LIST ITEMS :		
2.	1	REAR TAILGATE		1,200.00
3.	1	REAR TAILGATE HYBRID EMBLEM (SHUTTLE)		90.00
		REAR TAILGATE SHUTTLE EMBLEM (SHUTTLE)		90.00
		List TotalS\$ :		1,380.00
		20.00% Discount S\$ :		276.00
				1,104.00

LABOUR :  
REMOVE & REFIT REAR WINDSCREEN GLASS

TO LABOUR FOR REMOVING & REPAIRS THE REAR TAILGATE

TO PUTTY & SPRAY PAINT THE REAR AFFECTED AREARS.

Labour Total S\$ :

1) Parts : \$ 144

2) Labour : \$ 720

\$ 864 @ 2 days.

E. & O.E.

Total S\$ :

2,484.00

for WORLD AUTO PTE LTD

Sebastian  
29/3/18  
- Part by part repair  
- Photo After Paint  
90036121  
sebastian.jong@tkauto.com  
3 days.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18005573/SVD3N2

Date: 30/04/2018

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3030861700
Claimant Vehicle No :	SLG9218B	Insured Vehicle No :	GV7237P
Date of Loss:	19/12/2017	Nature of Claim:	TP
		Claim No:	SNM18D01525C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLG9218B	Engine No:	LEB4260598
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GP71041186
Reg. Date:	18/10/2016 (Man. Year: 2016)	Odometer:	144904 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Rovelo 6 mm	Rear Left Side:	Rovelo 6 mm
Front Right Side:	Rovelo 6 mm	Rear Right Side:	Rovelo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,104.00	144.00	960.00	86.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	720.00	660.00	47.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>2,484.00</b>	<b>864.00</b>	<b>1,620.00</b>	<b>65.22</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>173.88</b>	<b>60.48</b>	<b>113.40</b>	<b>65.22</b>
<b>Nett Amount (\$\$)</b>	<b>2,657.88</b>	<b>924.48</b>	<b>1,733.40</b>	<b>65.22</b>

## INSPECTION

Date of Assignment:	23/03/2018	Inspected At:	World Auto (HQ)
Date Inspected:	26/03/2018		NO. 1 KRANJI LOOP
			Singapore 739535

Estimated Period of Repair: 3.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 30 Apr 2018)  
**Parts:** N/A HONDA SHUTTLE 1.5 (A) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SLG9218B)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	1,200.00 FL	*- FL
2	1		*REAR TAILGATE HYBRID EMBLEM (SHUTTLE)	Necessary	90.00 FL	*90.00 FL
3	1		*REAR TAILGATE SHUTTLE EMBLEM (SHUTTLE)	Necessary	90.00 FL	*90.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					1,380.00	180.00
- List Item Discount on L Items 20.00/20.00% (S\$)					276.00	36.00
Total Parts (S\$)					1,104.00	144.00

Report was unsubmitted during this print-out.



**Recommended Miscellaneous Items**

There are no new miscellaneous items selected.

**Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
2	TO LABOUR FOR REMOVING & REPAIRS THE REAR TAILGATE	New	600.00	300.00
3	TO PUTTY & SPRAY PAINT THE REAR AFFECTED AREARS	New	600.00	300.00
Gross Labour Cost (S\$)			1,380.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >