

ASS. REC. BY

REF: CS/FCI18005586/K1d3<sup>n2</sup> Object of Instruction:

Survivor

CWS

Kenneth

ASSIGNMENT (Office)

From (Person):

Lurene Jaw

of

FCI

Date/Time: 24/3/18 @ 11:46am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR14132

Insured:

SHC0530B

at Workshop n/:

Huiyang Motor

Tel:

64515752

of Blk 176 Sin Ming Drive # 04-02

Policy No:

D-18088437MFSH

Claim No:

D18002234MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

17/03/2018

CA / REV / REP. / REV 24 HRS

'ds'

H.O.D. Endorsement:

Date/Time: 9:24am @ 26/3/18

Person Contacted:

Marco

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLR14132-X

SHC530B-CS FCI17008910/Krbn2

D.O.A: 29/4/17

28/3/18 @ 4:21pm VMSLD to Lurene by email.

03/4/18 @ 3:50 PM 83416-08 email & confirmed with Bel  
(Fed \$1333.62, 28%)

ASS. REC. BY:

REF:

1021

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-B.1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SUR 14137 Yr Regn: 08, 17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496Colour: A. Black A/C: Insured / Std / NI / NASp. Reading: 45105 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RU 3 . 1254270Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / PUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal. 3 mmL/Bal. 3 mmD.O.A. 17/3/18

Survey held at

Rear

R/Bal. 2 mmL/Bal. 2 mmD.O.I. 27/3/18Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop orO/S Rm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/3 File pass to Catherine

RECEIVED 4 APR 2018

Date/Time, File Pass to?

1) 03/4 trp ☐ : Prel. ReportDate/Time, File Return to? ☐ : Final Report

2) \_\_\_\_\_

Report Format :

Lump Sum / I.B.I. (\$) 3416.08Days Of Repair: 4Resurvey No. of Trlp: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

252

|     |
|-----|
| 135 |
| 50  |
| 50  |
| 17  |
| 252 |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                    |                           |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------|---------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                            |                                                                                                    | Ref : CS/FC118005586/Kqd3 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                  |                                                                                                    | Date : 26-03-2018         |  |
|                                                                                                                                        |                                                                                                    | Code : FCI2               |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                    |                           |                                                                                     |
| Insured Veh.                                                                                                                           | SHC 530B                                                                                           | Veh. Inspected            | SLR 1413Z                                                                           |
| Policy No.                                                                                                                             |                                                                                                    | Coverage (\$)             | 0.00                                                                                |
| Claim No.                                                                                                                              | D18002234MFSH                                                                                      | Excess (\$)               | 0.00                                                                                |
| Assign From                                                                                                                            | CWS (LURENE JAW)                                                                                   | Assign Date               | 26/03/2018                                                                          |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                    |                           |                                                                                     |
| Make & Model                                                                                                                           |                                                                                                    | c.c                       | 0                                                                                   |
| Engine No.                                                                                                                             | HIDDEN                                                                                             | Year of Reg.              |                                                                                     |
| Chassis No.                                                                                                                            |                                                                                                    | Colour                    |                                                                                     |
| Odometer                                                                                                                               | -                                                                                                  | Steering                  |                                                                                     |
| Brakes                                                                                                                                 |                                                                                                    | Modification              |                                                                                     |
| General                                                                                                                                |                                                                                                    |                           |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                    |                           |                                                                                     |
|                                                                                                                                        | Size                                                                                               | Make                      | Balance                                                                             |
| R/H Front Tyre                                                                                                                         |                                                                                                    |                           | mm                                                                                  |
| L/H Front Tyre                                                                                                                         |                                                                                                    |                           | mm                                                                                  |
| R/H Rear Tyre                                                                                                                          |                                                                                                    |                           | mm                                                                                  |
| L/H Rear Tyre                                                                                                                          |                                                                                                    |                           | mm                                                                                  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                    |                           |                                                                                     |
|                                                                                                                                        |                                                                                                    |                           |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                                    |                           |                                                                                     |
| Accident Date                                                                                                                          | 17/03/2018                                                                                         | Inspection Date           |                                                                                     |
| Survey held at                                                                                                                         | HUI YANG MOTOR PTE LTD<br>BLOCK 176 SIN MING DRIVE<br>#04-02 SIN MING AUTOCARE<br>SINGAPORE 575721 |                           |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                    |                           |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                    |                           |                                                                                     |



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002234MFSH

Date: 28 March 2018

Our Ref: CS/FCI18005586/Kqd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SLR 1413Z .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/03/2018 at the premises of M/s HUI YANG, and have the following to report:-

|                          |                  |
|--------------------------|------------------|
| Workshop Estimate Amount | : S\$ 4,035.86 . |
| Revised Estimate Amount  | : S\$ 2,921.52 . |
| "Check" Items Amount     | : S\$ 248.34 .   |
| Market Value             | : S\$ - .        |
| LTA Reimbursement Value  | : S\$ - .        |
| Nett Value               | : S\$ - .        |

**Description of Damage:**

The vehicle sustained damages  
at the o/s front portion.



Yours faithfully

KONG SENG CHEONG  
Licensed Appraiser

**MOTOR SURVEY ASSIGNMENT**

|                           |                                                 |                                      |
|---------------------------|-------------------------------------------------|--------------------------------------|
| <b>Date</b>               | 19-03-2018                                      | <b>Our Ref No.</b> D18002234MFSH     |
| <b>Accident Date</b>      | 17-03-2018                                      | <b>Claim Type.</b> Third Party       |
| <b>Insured Vehicle</b>    | SHC0530B                                        | <b>Third Party Vehicle.</b> SLR1413Z |
| <b>Survey Location</b>    | BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE |                                      |
| <b>Contact Person.</b>    | BEL                                             |                                      |
| <b>Contact No.</b>        | 6451 5752/ 90573466                             | <b>Fax No.</b> 6451 4658             |
| <b>Survey Type</b>        | DIRECT SETTLEMENT:                              |                                      |
| <b>Appointed Surveyor</b> | LKK AUTO CONSULTANTS PTE LTD                    |                                      |
| <b>Contact Person</b>     | NA                                              | <b>Fax No.</b> 68416315              |
| <b>Contact Number.</b>    | NA                                              |                                      |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                          |                        |                                |
|--------------------------|------------------------|--------------------------------|
| <b>Cc : Workshop</b>     | HUI YANG MOTOR PTE LTD | <b>Attention.</b> NIL          |
| <b>Cc : TP Solicitor</b> | NA                     | <b>TP Solicitor Fax No.</b> NA |
| <b>Officer Incharge</b>  | LURENE                 |                                |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236090)



PRI Documents



Close



## PRI Header Details

|                   |                                                  |                                   |                                                                                                                                               |                      |              |
|-------------------|--------------------------------------------------|-----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------|----------------------|--------------|
| Claim No          | D18002234MFSH                                    | Policy No                         | D-18088937MFSH                                                                                                                                | Claimant S.No & Name | 1 & HUI YANG |
| Workshop Name     | HUI YANG MOTOR PTE LTD<br>(Contact Person : BEL) | Survey Location & Contact Details | BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE<br>Mobile: 90573466 , Phone: 6451 5752 , Fax: 6451 46.<br>EmailId: HUI_YANG_MOTOR@HOTMAIL.COM |                      |              |
| Our Surveyor      | LKK AUTO CONSULTANTS PTE LTD                     | Instructions To Surveyor          | DIRECT SETTLEMENT:                                                                                                                            |                      |              |
| Insured Name      | CITYCAB PTE LTD                                  | Insured Vehicle No                | SHC0530B                                                                                                                                      | TP Vehicle No        | SLR1413Z     |
| PRI Recieved Date | 23-03-2018 06:32:09 PM                           | Surveyor Appointed Date           | 24-03-2018 11:46:48 AM                                                                                                                        | Surveyor Accept Date | 26-03-2018 1 |

## Survey Report Upload

|                             |  |                      |            |                         |                                            |
|-----------------------------|--|----------------------|------------|-------------------------|--------------------------------------------|
| Surveyor Inspection Date *: |  | Surveyor Report Date | 26-03-2018 | Upload Survey Report *: | <input type="button" value="Choose File"/> |
|-----------------------------|--|----------------------|------------|-------------------------|--------------------------------------------|

## Vehicle Particulars

|           |                      |                |                       |         |                      |
|-----------|----------------------|----------------|-----------------------|---------|----------------------|
| Make      | Please Select Make ▼ | Model          | Please Select Model ▼ | Year    | Select Year ▼        |
| Chasis No | <input type="text"/> | Engine No      | <input type="text"/>  | Mileage | <input type="text"/> |
| Color     | <input type="text"/> | Cubic Capacity | <input type="text"/>  |         |                      |

## Multiple Documents Upload

|                                                          |        |
|----------------------------------------------------------|--------|
| <input type="button" value="Upload Multiple Documents"/> |        |
| File Name                                                | Action |

## Surveyor Job Remarks

|         |                      |                                     |
|---------|----------------------|-------------------------------------|
| Remarks | <input type="text"/> | <input type="button" value="Save"/> |
|---------|----------------------|-------------------------------------|

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Wednesday, 28 March 2018 4:21 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18002234MFSH/1  
**Attachments:** CSFCI18005586Kqd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SLR 1413Z.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Monday, 26 March 2018 9:29 AM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18002234MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Saturday, 24 March 2018 11:46 AM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [LURENEJAW@MSFIRSTCAPITAL.COM.SG](mailto:LURENEJAW@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18002234MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System

# 輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

17/03/2018

Owner: SKYWAY MOTOR PTE LTD

## ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SLR1413Z

|          |                                    |         |             |             |   |
|----------|------------------------------------|---------|-------------|-------------|---|
| 1pc      | front RH headlamp                  | 1485.30 | CMS         | \$ 1,759.40 | ✓ |
| 1pc      | front RH headlamp lower bracket    |         | 2           | \$ 35.00    | X |
| 1pc      | front RH headlamp top bracket      |         | 1           | \$ 28.85    | X |
| 1pc      | front RH fender                    |         | 1           | \$ 580.00   | ✓ |
| 1pc      | front RH fender protector          |         | 1           | \$ 195.00   | X |
| 1pc      | front wiper garnish                |         | 1           | \$ 281.58   | X |
| 1pc      | front wiper garnish RH side rubber |         | 1           | \$ 95.00    | X |
| 1pc      | front bonnet RH hinge              |         | 1           | \$ 45.00    | X |
|          |                                    |         | <hr/>       |             |   |
|          |                                    |         | \$ 3,019.83 |             |   |
| less 20% |                                    |         | <hr/>       |             |   |
|          |                                    |         | \$ 603.97   |             |   |
|          |                                    |         | <hr/>       |             |   |
|          |                                    |         | \$ 2,415.86 |             |   |

|                |             |      |
|----------------|-------------|------|
| wiring         | \$ 60.00    | 2cl  |
| tuffkote       | \$ 60.00    | 3cl  |
| spray painting | \$ 900.00   | 60cl |
| labour charges | \$ 600.00   | 40cl |
| Total          | <hr/>       |      |
|                | \$ 4,035.86 |      |



**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

4749 70

輝陽汽車有限公司  
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

17/03/2018

Owner: SKYWAY MOTOR PTE LTD

SUPPLEMENTRY TO REPAIR HONDA VEZEL HYBRID - SLR1413Z

1pc front bonnet

B7 \$ 892.30 ✓

less 20%

|    |        |
|----|--------|
| \$ | 892.30 |
| \$ | 178.46 |
| \$ | 713.84 |





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                                                    |                 |                             |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------|-----------------|-----------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                                                    |                 | Ref : CS/FCI18005586/Kqd3n2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                                                    |                 | Date : 04-04-2018           |  |
|                                                                                                                                                                                        |                                                                                                    |                 | Code : FCI2                 |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                                                    |                 |                             |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SHC 530B                                                                                           | Veh. Inspected  | SLR 1413Z                   |                                                                                     |
| Policy No.                                                                                                                                                                             | D-18088937MFSH                                                                                     | Coverage (\$)   | 0.00                        |                                                                                     |
| Claim No.                                                                                                                                                                              | D18002234MFSH                                                                                      | Excess (\$)     | 0.00                        |                                                                                     |
| Assign From                                                                                                                                                                            | LURENE                                                                                             | Assign Date     | 24/03/2018                  |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                                                    |                 |                             |                                                                                     |
| Make & Model                                                                                                                                                                           | HONDA VEZEL (A)                                                                                    | c.c             | 1496                        |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                                             | Year of Reg.    | 2017                        |                                                                                     |
| Chassis No.                                                                                                                                                                            | RU31254270                                                                                         | Colour          | METALLIC BLACK              |                                                                                     |
| Odometer                                                                                                                                                                               | 45105                                                                                              | Steering        | IN ORDER                    |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                                           | Modification    | STANDARD ALLOY RIM          |                                                                                     |
| General                                                                                                                                                                                | GOOD                                                                                               |                 |                             |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                                                    |                 |                             |                                                                                     |
|                                                                                                                                                                                        | Size                                                                                               | Make            | Balance                     |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 215/60 R16                                                                                         | DUNLOP          | 3 mm                        |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 215/60 R16                                                                                         | DUNLOP          | 3 mm                        |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 215/60 R16                                                                                         | DUNLOP          | 2 mm                        |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 215/60 R16                                                                                         | DUNLOP          | 2 mm                        |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                                                    |                 |                             |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.<br>DAMAGES SEE DETAILS.                                                                                                        |                                                                                                    |                 |                             |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                                                    |                 |                             |                                                                                     |
| Accident Date                                                                                                                                                                          | 17/03/2018                                                                                         | Inspection Date | 27/03/2018                  |                                                                                     |
| Survey held at                                                                                                                                                                         | HUI YANG MOTOR PTE LTD<br>BLOCK 176 SIN MING DRIVE<br>#04-02 SIN MING AUTOCARE<br>SINGAPORE 575721 |                 |                             |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                                                    |                 |                             |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                    |                 |                             |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                                                    |                 |                             |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                                                    | 4 Working Days  |                             |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 1413Z

| Qty                                | Description of Parts                                            | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|-----------------------------------------------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b>        |                                                                 |                      |                           |                   |
| 1                                  | FRONT RH HEADLAMP                                               | CRACKED              | 1,759.40                  | 1,485.30          |
| 1                                  | FRONT RH HEADLAMP LOWER BRACKET                                 | SERVICEABLE          | 35.00                     | -                 |
| 1                                  | FRONT RH HEADLAMP TOP BRACKET                                   | SERVICEABLE          | 28.85                     | -                 |
| 1                                  | FRONT RH FENDER                                                 | BENT                 | 580.00                    | 580.00            |
| 1                                  | FRONT RH FENDER PROTECTOR                                       | SERVICEABLE          | 195.00                    | -                 |
| 1                                  | FRONT WIPER GARNISH                                             | SERVICEABLE          | 281.58                    | -                 |
| 1                                  | FRONT WIPER GARNISH RH SIDE RUBBER                              | SERVICEABLE          | 95.00                     | -                 |
| 1                                  | FRONT BONNET RH HINGE                                           | TO REPAIR SEE LABOUR | 45.00                     | -                 |
| 1                                  | FRONT BONNET (ADDITIONAL)                                       | BENT                 | 892.30                    | 892.30            |
|                                    | LESS 20% DISCOUNT                                               |                      | -782.43                   | -591.52           |
|                                    |                                                                 |                      | 3,129.70                  | 2,366.08          |
| <b>LABOUR</b>                      |                                                                 |                      |                           |                   |
|                                    | WIRING.                                                         |                      | 60.00                     | 20.00             |
|                                    | TUFFKOTE.                                                       |                      | 60.00                     | 30.00             |
|                                    | SPRAY PAINTING.                                                 |                      | 900.00                    | 600.00            |
|                                    | LABOUR CHARGE INCLUSIVE OF THE REPAIR OF FRONT BONNET RH HINGE. |                      | 600.00                    | 400.00            |
|                                    |                                                                 |                      | 1,620.00                  | 1,050.00          |
| <b>GRAND TOTAL</b>                 |                                                                 |                      | <b>4,749.70</b>           | <b>3,416.08</b>   |
| <b>RECOMMENDED COST OF REPAIRS</b> |                                                                 |                      |                           | <b>3,416.08</b>   |

Report Ref No. CS/FCI18005586/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.