Surveyor: Rasu | REF: | 15977K

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLC 8296C

at Workshop m/s Vermogen

of 6, Benoi Sector

Insured: III

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : **Yes** or **No**

GIA / PR Seen: _____ Consistent? : **Yes** or **No**

Est. Repairs: _____ days Res.: **Yes** or **No**

Lum Sum: _____ % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS

Vehicle: **IN / OUT**

Date: _____ Person Contacted: _____

Veh No: SLC 8296C Yr Regn: 2016 / MAY

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer** or _____

Make: TOYOTA SIENTA 1.5 c.c 1496

Colour WHITE A/C: **Insured / Std / NI / NA**

Sp.Reading 135976 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: NSP170 7025641

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or _____

Brake: **Inorder / Jammed / Leaked / Burnt** or _____

Modi : **Nil / S/Rim / STD A/Rim** or _____

Tyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Bridgestone

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	22/03/18	D.O.I.	22/03/18

Survey held at Vermogen

Des. of Damages : **Frt / Rear / O/S / N/S / U/C / Rooftop** or _____

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction

Date/Time, File **Pass** to? ☐ : **Preli. Report**

1) _____ ☐ : **Final Report**

Date/Time, File **Return** to?

2) _____

Report Format : _____

Lump Sum / I.B.I: ($ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Survey Fee: _____

Transportation: ___S + RS, ___SI

Photos _____

Others _____

TOTAL _____