

Surveyor: Finneth

DOI: 26/7/18

Date / Time: 26/7/18
Registered in Merimen: W/7/18

Pre-assign / CCU / FTE



Insured Vehicle No. : GBH 133J
Name of Insured : WRELAND HOERICHMUTTER PLC
Insured Tel No. : _____ HP: _____
Excess Sec II :SS _____ D.O.A : 26/7/18
Is driver the owner? (YES / NO) Nature of Accident : _____
If NO. Driver Name / Age : BANESH S/O CHANDRASHEKARAN
Driver Tel No. : _____ (V/L: YES / NO)

Claim No. : 1132801654
Policy No. : 1800007086
Make / Model : NISSAN
Place of Accident : KIRIPAT RD

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
Insured Liability : % Final ? Yes / No

SJY 8719D



INSRS: Cheng Hoe
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/Time	STAGE	DATE / PIC
<u>26/7/18</u>	Non-Reporting ltr (1st):	
<u>26/7/18</u>	Non-Reporting ltr (2nd):	
<u>26/7/18</u>	Non-Reporting ltr (Final):	
<u>26/7/18</u>	Notification ltr (if non-pickup):	
<u>26/7/18</u>	Call OI:	<u>28-3 JCY</u>
<u>26/7/18</u>	After call ltr to OI:	
<u>26/7/18</u>	Documentation Check List:	Handler Typist
<u>26/7/18</u>	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/> <input type="checkbox"/>
<u>26/7/18</u>	After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
<u>26/7/18</u>	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
<u>26/7/18</u>	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
<u>26/7/18</u>	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
<u>26/7/18</u>	Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
<u>26/7/18</u>	Towing Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
<u>26/7/18</u>	LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
<u>26/7/18</u>	Medical Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
<u>26/7/18</u>	PIR:	<input checked="" type="checkbox"/> <input type="checkbox"/>
<u>26/7/18</u>	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
<u>26/7/18</u>	LOD:	<input checked="" type="checkbox"/> <input type="checkbox"/>
<u>26/7/18</u>	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
<u>26/7/18</u>	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
<u>26/7/18</u>	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: \$S _____ (_____ days) Reduction: % _____ Email Call

FINAL SETTLEMENT Date/Time: 28-7-18 Confirm with JUNE Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27 If NO or B 28, Ass. Lia: _____

Repair Cost: GST \$S 4,708

Loss of Rental (LOR): \$S _____ (_____ days)
Loss of Use (LOU): \$S 900 (100 x 9 days) TUTOR CAR

Loss of Income (LOI): \$S _____ (_____ x days)
LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search \$S 8.22

Medical: \$S _____
Disbursement: \$S _____ (e.g. Tow/ Independent)
Legal Cost \$S _____

Total: \$S 5,616.24 Global Sum \$S: _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$S 5,616.24 Name 1: CHENG HOE MOTOR PTE LTD
Payee 2: (Strike if N.A.) \$S _____ Name 2: X
Payee 3: (Strike if N.A.) \$S _____ Name 3: _____

COPY SENT
26/7/18


ASS. REC. BY:

REF: AG1

Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OO / TP / WS / TP RES / OO RES / EVA / INV / MY
 To Inspect Vehicle No: _____
 at Workshop n/s Cheng Hee
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 07 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: STY 831PD Yr Regn: 10, 10
 Type: Mc Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toy vios c.c. 1497
 Colour: Br. Silver with ACC Insured / Std / NI / NA
 Sp. Reading: 30888 T/Radio: Insured / Std / NI / NA
 Eng No: _____

C.No: MR0531149305174513
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/60R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kapsen

<u>Front</u>		<u>Rear</u>	
R/Bal. <u>8</u> mm		R/Bal. <u>8</u> mm	
L/Bal. <u>8</u> mm		L/Bal. <u>8</u> mm	
D.O.A. <u>25/3/18</u>		D.O.I. <u>26/3/18</u>	

Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>27/3</u>	<u>File pass to Catherine</u>
<u>2/4</u>	<u>File 61 Log @ 4400 Central Turn (7+2 x 100) <u>Tuition Ca</u></u>

R (\$1,765.35/2990)

Date/Time, File Pass to? : Prell. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	_____
Transportation:	_____ \$ - RS. SI
Photos	_____
Others	_____
TOTAL	_____

Report Format : _____
 Lump Sum / I.B.I: (\$ _____)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SJY8319D
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Estimate No: ES1890303/YISHUN

Date: 26 Mar 2018

Policy No: 5074263429-02

TEL: 64193000

FAX: 64153727

Veh Reg No: SJY8319D

ATTN: Motor Claim Department

Make/Model: TOYOTA VIOS E
MANUAL

WS Ref: TP/AIG/YS

Not Authorized

Chassis No: MR053HY9305174513

Claim Type: Third Party

11 Long @ 4400h

Engine No: 1NZY121007

Accident Date: 25/03/2018

Resony After Point

Reg. Date: 06/10/2010

TP Veh Reg No: GBH133J

7 days

Estimate Repair Cost to Vehicle No :SJY8319D

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	427.50	1 PC	427.50	✓
2 REAR BUMPER RH REFLECTOR	82.80	1 PC	82.80	✓
3 REAR BUMPER SIDE RETAINERS	92.33	2 PCS	184.66	✓
4 REAR BUMPER RH BRACKET	63.77	1 PC	63.77	✓
5 REAR BUMPER CLIPS	3.89	6 PCS	23.34	✓
6 TAILLAMPS <i>old Br</i>	277.62	2 PCS	555.24	✓
7 TAILLAMP PANELS <i>new</i>	105.00	2 PCS	210.00	✓
8 TAILLAMP LOWER GARNISHS	31.22	2 PCS	62.44	X
9 REAR BOOT	510.85	1 PC	510.85	✓
10 REAR BOOT INNER LOCK	95.97	1 PC	95.97	✓ <i>87.68</i>
11 REAR BOOT INNER RUBBER	175.35	1 PC	175.35	✓ <i>50.11</i>
12 REAR BOOT LOGO	50.20	1 PC	50.20	✓
13 REAR BOOT EMBLEM (VIOS)	44.20	1 PC	44.20	✓
14 REAR BOOT EMBLEM (E)	34.37	1 PC	34.37	✓
15 REAR BOOT OUTER GARNISH	198.80	1 PC	198.80	✓
16 REAR BOOT HINGES	154.28	2 PCS	308.56	X
17 TAILLAMP INNER RUBBERS	26.25	2 PCS	52.50	✓
18 REAR CENTRE PANEL	571.89	1 PC	571.89	✓
19 REAR CENTRE PANEL INNER TOP GARNISH	200.76	1 PC	200.76	✓
20 REAR SPARE TYRE SIDE SPONGES	177.57	2 PCS	355.14	✓
21 REAR SPARE TYRE FRT SPONGE	132.80	1 PC	132.80	✓
22 REAR EXHAUST PIPE	595.13	1 PC	595.13	✓
23 REAR RH FENDER INNER GARNISH	224.20	1 PC	224.20	✓
			5,160.47	
		Less 25%	1,290.12	3,870.35

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department

Estimate No: ES1890303/YISHUN
Date: 26 Mar 2018
Policy No: 5074263429-02
Veh Reg No: SJY8319D
Make/Model: TOYOTA VIOS E MANUAL
Chassis No: MR053HY9305174513
Engine No: 1NZY121007
Reg. Date: 06/10/2010

WS Ref: TP/AIG/YS
Claim Type: Third Party
Accident Date: 25/03/2018
TP Veh Reg No: GBH133J

Estimate Repair Cost to Vehicle No :SJY8319D

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Special Net				
24 REAR NUMBER PLATE	35.00	1 PC	35.00 ✓	35.00
Labour				
25 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT & ATTACHMENT, HINGES, TO CUT, WELD & RENEW REAR END PANEL, TAILLAMP PANELS, KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT, REAR BOTH FENDERS & REALIGN THE SAME	1,200.00	1 LA	1,200.00 1000L	
26 PUTTY & RESPRAY ON REAR BOOT, HINGES, REAR SPARE TYRE COMPARTMENT, REAR FENDERS, REAR BUMPER, REAR PANEL & REAR AFFECTED AREAS	1,000.00	1 LA	1,000.00 900L	
27 RUSTPROOFING	60.00	1 LA	60.00 ✓	
			2,260.00	2,260.00
Total				SS 6,165.35
Add GST @ 7%				431.57
Total Amount Payable				SS 6,596.92

For Cheng Hoe Motor Pte Ltd

25/

4614.12
 1153.53

 3460.60
 87.68 SN
 35 SN
 1960

 5543.28
 45 @ 4400/

AUTHORISED SIGNATURE

COR =
 TUTOR COR - 712-929100
 L7A-8
 7 day

SJY/8319D
70/016

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2262D

Vehicle Details

Vehicle No.: SJY8319D
Vehicle to be Exported: No
Intended De-registration Date: 25 Mar 2018
Vehicle Make: TOYOTA
Vehicle Model: VIOS E MANUAL
Primary Colour: White
Manufacturing Year: 2010
Engine No.: 1NZY121007
Chassis No.: MR053HY9305174513
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$11,706.00
Original Registration Date: 06 Oct 2010
First Registration Date: 06 Oct 2010
Transfer Count: 1
Actual ARF Paid: \$11,706.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 05 Oct 2020
PARF Rebate Amount: \$7,023.00

Intended COE Rebate Details

COE Expiry Date: 05 Oct 2020
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$30,001.00
COE Rebate Amount: \$7,582.00
Total Rebate Amount: \$14,605.00

The information contained herein is correct as at 25 Mar 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST-201001158E RCB NO:201001158E

SJY8319D
 TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

WS Ref: TP/AIG/YS
 Claim Type: Third Party
 Accident Date: 25/03/2018
 TP Veh Reg No: GBH133J

Not Authorized
U/Sing B?
Resurvey After Paint

Estimate No: ES1890303/YISHUN
 Date: 26 Mar 2018
 Policy No: 5074263429-02
 Veh Reg No: SJY8319D
 Make/Model: TOYOTA VIOS E
 MANUAL
 Chassis No: MR053HY9305174513
 Engine No: 1NZY121007
 Reg. Date: 06/10/2010

Estimate Repair Cost to Vehicle No :SJY8319D

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	427.50	1 PC	427.50	✓
2 REAR BUMPER RH REFLECTOR	82.80	1 PC	82.80	✓
3 REAR BUMPER SIDE RETAINERS	92.33	2 PCS	184.66	✓
4 REAR BUMPER RH BRACKET	63.77	1 PC	63.77	?
5 REAR BUMPER CLIPS	3.89	6 PCS	23.34	✓
6 TAILLAMPS <i>old Bro</i>	277.62	2 PCS	555.24	✓
7 TAILLAMP PANELS <i>nil sum</i>	105.00	2 PCS	210.00	?
8 TAILLAMP LOWER GARNISHS	31.22	2 PCS	62.44	?
9 REAR BOOT	510.85	1 PC	510.85	✓
10 REAR BOOT INNER LOCK	95.97	1 PC	95.97	✓
11 REAR BOOT INNER RUBBER	175.35	1 PC	175.35	50% sum
12 REAR BOOT LOGO	50.20	1 PC	50.20	✓
13 REAR BOOT EMBLEM (VIOS)	44.20	1 PC	44.20	✓
14 REAR BOOT EMBLEM (E)	34.37	1 PC	34.37	✓
15 REAR BOOT OUTER GARNISH	198.80	1 PC	198.80	✓
16 REAR BOOT HINGES	154.28	2 PCS	308.56	X
17 TAILLAMP INNER RUBBERS	26.25	2 PCS	52.50	?
18 REAR CENTRE PANEL	571.89	1 PC	571.89	✓
19 REAR CENTRE PANEL INNER TOP GARNISH	200.76	1 PC	200.76	?
20 REAR SPARE TYRE SIDE SPONGES	177.57	2 PCS	355.14	?
21 REAR SPARE TYRE FRT SPONGE	132.80	1 PC	132.80	?
22 REAR EXHAUST PIPE	595.13	1 PC	595.13	?
23 REAR RH FENDER INNER GARNISH	224.20	1 PC	224.20	✓
			5,160.47	
		Less 25%	1,290.12	3,870.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurer's Company

Acknowledged by Repairer
 Signature:
 Date:

Cheng Hoe Motor Pte Ltd

Bk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department


WS Ref: TP/AIG/YS
Claim Type: Third Party
Accident Date: 25/03/2018
TP Veh Reg No: GBH133J

Estimate No: ES1890303/YISHUN
Date: 26 Mar 2018
Policy No: 5074263429-02
Veh Reg No: SJY8319D
Make/Model: TOYOTA VIOS E
MANUAL
Chassis No: MR053HY9305174513
Engine No: 1NZY121007
Reg. Date: 06/10/2010

Estimate Repair Cost to Vehicle No :SJY8319D

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Special Net				
24 REAR NUMBER PLATE	35.00	1 PC	<i>nd</i> 35.00 ✓	
			35.00	35.00
Labour				
25 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT & ATTACHMENT, HINGES, TO CUT, WELD & RENEW REAR END PANEL, TAILLAMP PANELS, KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT, REAR BOTH FENDERS & REALIGN THE SAME	1,200.00	1 LA	1,200.00 <i>1000L</i>	
26 PUTTY & RESPRAY ON REAR BOOT, HINGES, REAR SPARE TYRE COMPARTMENT, REAR FENDERS, REAR BUMPER, REAR PANEL & REAR AFFECTED AREAS	1,000.00	1 LA	1,000.00 <i>900L</i>	
27 RUSTPROOFING	60.00	1 LA	60.00 ✓	
			2,260.00	2,260.00
			Total	SS 6,165.35
			Add GST @ 7%	431.57
			Total Amount Payable	SS 6,596.92

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE

PAYMENT ADVICE

Your Ref : AIG Vehicle no.	: GBH133J
Claimant Vehicle No.	: SJY8319D
Date of Accident	: 25/03/2018
Traffic Accident involving vehicle/s No.	: AIRPORT RD TOWARDS MACPHERSON (NEAR CDC)

BREAKDOWN OF PAYMENT/S

<u>S/No.</u>	<u>Items</u>	<u>Amount</u>	<u>Remark</u>
1	Repair cost	\$ 4,708.00	
2	Loss of Income	\$ 1,320.00	\$120 x 11 days (Tuition car)
3	LTA Search	\$ 8.00	
	TOTAL	\$ 6,036.00	

All payment should be made payable to Cheng Hoe Motor Pte Ltd.

Service Adviser : LKK
Contact No. : 6256 3561

Enquire Transfer Fee**Vehicle Details**

Vehicle No. :	SJY8319D
Vehicle Type :	L10 - For Instruction Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	VIOS E MANUAL
Chassis No. :	MR053HY9305174513
Propellant :	Petrol
Engine No. :	1NZY121007
Engine Capacity :	1497 cc
Maximum Power Output :	80.0 kW (107 bhp)
Maximum Laden Weight :	1485 kg
Unladen Weight :	1075 kg
Year Of Manufacture :	2010
Original Registration Date :	06 Oct 2010
Lifespan Expiry Date :	-
COE Category :	A - Car (1600cc & below)
Quota Premium :	\$30,001.00
COE Expiry Date :	05 Oct 2020
Road Tax Expiry Date :	05 Oct 2018
PARF Eligibility Expiry Date :	05 Oct 2020
Inspection Due Date :	05 Oct 2018
Intended Transfer Date :	25 Mar 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG18005596/Kjb3

28 March 2018

GREENLAND HORTICULTURE PTE LTD

153A Serangoon North Ave 1
#02-462
Singapore 551153

Dear Sir/Madam,

ACCIDENT INVOLVING GBH 133J AND SJY 8319D ON 25/03/18

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.


Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,



Joy Irene

Case Handler

DID: 6749 2409

FAX: 6741 4108

Email: joyirene@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT
(AIG Asia Pacific - Express Third Party Claim)

I, Neo Chwee Pah (the third party claimant) of Blk 544 Hougang
Ave 8 #09-1257 S 530544 (address), owner of SJY8319D (vehicle no.) hereby
authorize CHENG HOE MOTOR PTE LTD ("the workshop") to act for me with respect to
my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SJY8319D that
was damaged pursuant to the accident which occurred on 25/3/2018 (date) along Airport Rd Towards
Macpherson (nearby CDC) (location) involving vehicle no/s GBH133J ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the
workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s
being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice
and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is
concerned.

Dated this 26 (day) of March (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)




Signed by "the workshop"
(with chop)

This Discharge Voucher applies strictly for Claimant's claim for property damages only and does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident.

This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

RELEASE VOUCHER

(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

"We/I, CHENG HOE MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$4708.00 (Repair Cost), S\$ 900.00 (Loss of ^{net} income), S\$8.00 (Disbursement), for vehicle no SJY8319D that was damaged pursuant to the accident which occurred 25/3/2018 (date) along Airport Road towards Macpherson (near CDC) (location) involving vehicle no/s GBH133J. This is pursuant to the inspection conducted on 26/3/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Neo Chwee Pah ("the third party claimant") of vehicle no. SJY8319D make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage SJY8319D (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 21 (day) of December (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

NO: CL8181364
Date: 21 Dec 2018
Policy No: 5074263429-02
Veh Reg No: SJY8319D
Make/Model: TOYOTA VIOS E
MANUAL
Job No: JC1598854

WS Ref: TP/AIG/YS
Claim Type: Third Party
Accident Date: 25/03/2018
TP Veh Reg No: GBH133J

Description

To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges.
(As recommended by your appointed surveyor)

Quantity

1 PC

List Price

SS 4,400.00

PAGE:1

Amount

SS 4,400.00

Total SS 4,400.00
Add GST @ 7% 308.00
Total Amount payable SS 4,708.00

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE

A.C. SYED & PARTNERS

ADVOCATES & SOLICITORS

COMMISSIONER FOR OATHS

101A UPPER CROSS STREET, #13-23 PEOPLE'S PARK CENTRE, SINGAPORE 068368

TEL : 6638 7411 & FAX : 6634 1011

TO : CHENG HOE MOTOR PTE LTD	BILL NO: 5032/2018																																																																																																																		
YOUR REF:																																																																																																																			
OUR REF : ACS.CH.LTA.2018 (MARCH 2018)	DATE : 3/4/18																																																																																																																		
TO OUR PROFESSIONAL CHARGES for acting for you in the above matter including where necessary perusal, attendance preparation examination of documents relating thereto; correspondence, attendance, perusal, telephone calls, searches and all other incidental works not specifically mentioned herein to enable us to carry out the work entrusted to us inclusive of all advice.																																																																																																																			
LTANET SEARCHES FOR THE MONTH MARCH 2018																																																																																																																			
<table border="1"><thead><tr><th>S/NO</th><th>TF NO.</th><th>CRM</th><th>DOA</th></tr></thead><tbody><tr><td>1</td><td>1/3/2018</td><td>GHD1664H</td><td>SFH799R</td><td>1/3/2018</td></tr><tr><td>2</td><td>1/3/2018</td><td>FC60P</td><td>SGK1385S</td><td>28/2/2018</td></tr><tr><td>3</td><td>2/3/2018</td><td>SJF7532K</td><td>YN7117G</td><td>23/2/2018</td></tr><tr><td>4</td><td>3/3/2016</td><td>SJF9546H</td><td>SJH2758Z</td><td>3/3/2018</td></tr><tr><td>5</td><td>5/3/2018</td><td>SJM7631X</td><td>SKU3784K</td><td>2/3/2018</td></tr><tr><td>6</td><td>5/3/2018</td><td>SLM9261T</td><td>SKW8135R</td><td>18/12/2017</td></tr><tr><td>7</td><td>5/3/2018</td><td>YN483U</td><td>YK7378H</td><td>5/3/2018</td></tr><tr><td>8</td><td>8/3/2018</td><td>SLH7980R</td><td>SGW1334B</td><td>8/3/2018</td></tr><tr><td>9</td><td>12/3/2018</td><td>PA6296D</td><td>SJT2621X</td><td>9/3/2018</td></tr><tr><td>10</td><td>12/3/2018</td><td>YM7089J</td><td>SLM4462M</td><td>10/3/2018</td></tr><tr><td>11</td><td>13/3/2018</td><td>PA93L</td><td>YP2400K</td><td>7/3/2018</td></tr><tr><td>12</td><td>13/3/2018</td><td>SLM4765P</td><td>SKU7301U</td><td>3/3/2018</td></tr><tr><td>13</td><td>18/3/2018</td><td>SFR6675Y</td><td>SJS1357X</td><td>17/3/2018</td></tr><tr><td>14</td><td>18/3/2018</td><td>YN2879Z</td><td>SKU7038E</td><td>16/3/2018</td></tr><tr><td>15</td><td>19/3/2018</td><td>SKZ2548G</td><td>SJQ1968T</td><td>19/3/2018</td></tr><tr><td>16</td><td>22/3/2018</td><td>SJP8518T</td><td>SLT5791Z</td><td>20/3/2018</td></tr><tr><td>17</td><td>22/3/2018</td><td>SJM7299Y</td><td>SKW7326M</td><td>18/3/2018</td></tr><tr><td>18</td><td>22/3/2018</td><td>SKB3393P</td><td>GBE3570P</td><td>14/2/2018</td></tr><tr><td>19</td><td>22/3/2018</td><td>3Z6870X</td><td>SKE8281X</td><td>21/3/2018</td></tr><tr><td>20</td><td>24/3/2018</td><td>SJV325D</td><td>SGP2702C</td><td>24/3/2018</td></tr><tr><td>21</td><td>25/3/2018</td><td>GBH133J</td><td>SJY8319D</td><td>25/3/2018</td></tr><tr><td>22</td><td>27/3/2018</td><td>SLE1492M</td><td>SLD8483Z</td><td>27/3/2018</td></tr></tbody></table>	S/NO	TF NO.	CRM	DOA	1	1/3/2018	GHD1664H	SFH799R	1/3/2018	2	1/3/2018	FC60P	SGK1385S	28/2/2018	3	2/3/2018	SJF7532K	YN7117G	23/2/2018	4	3/3/2016	SJF9546H	SJH2758Z	3/3/2018	5	5/3/2018	SJM7631X	SKU3784K	2/3/2018	6	5/3/2018	SLM9261T	SKW8135R	18/12/2017	7	5/3/2018	YN483U	YK7378H	5/3/2018	8	8/3/2018	SLH7980R	SGW1334B	8/3/2018	9	12/3/2018	PA6296D	SJT2621X	9/3/2018	10	12/3/2018	YM7089J	SLM4462M	10/3/2018	11	13/3/2018	PA93L	YP2400K	7/3/2018	12	13/3/2018	SLM4765P	SKU7301U	3/3/2018	13	18/3/2018	SFR6675Y	SJS1357X	17/3/2018	14	18/3/2018	YN2879Z	SKU7038E	16/3/2018	15	19/3/2018	SKZ2548G	SJQ1968T	19/3/2018	16	22/3/2018	SJP8518T	SLT5791Z	20/3/2018	17	22/3/2018	SJM7299Y	SKW7326M	18/3/2018	18	22/3/2018	SKB3393P	GBE3570P	14/2/2018	19	22/3/2018	3Z6870X	SKE8281X	21/3/2018	20	24/3/2018	SJV325D	SGP2702C	24/3/2018	21	25/3/2018	GBH133J	SJY8319D	25/3/2018	22	27/3/2018	SLE1492M	SLD8483Z	27/3/2018	
S/NO	TF NO.	CRM	DOA																																																																																																																
1	1/3/2018	GHD1664H	SFH799R	1/3/2018																																																																																																															
2	1/3/2018	FC60P	SGK1385S	28/2/2018																																																																																																															
3	2/3/2018	SJF7532K	YN7117G	23/2/2018																																																																																																															
4	3/3/2016	SJF9546H	SJH2758Z	3/3/2018																																																																																																															
5	5/3/2018	SJM7631X	SKU3784K	2/3/2018																																																																																																															
6	5/3/2018	SLM9261T	SKW8135R	18/12/2017																																																																																																															
7	5/3/2018	YN483U	YK7378H	5/3/2018																																																																																																															
8	8/3/2018	SLH7980R	SGW1334B	8/3/2018																																																																																																															
9	12/3/2018	PA6296D	SJT2621X	9/3/2018																																																																																																															
10	12/3/2018	YM7089J	SLM4462M	10/3/2018																																																																																																															
11	13/3/2018	PA93L	YP2400K	7/3/2018																																																																																																															
12	13/3/2018	SLM4765P	SKU7301U	3/3/2018																																																																																																															
13	18/3/2018	SFR6675Y	SJS1357X	17/3/2018																																																																																																															
14	18/3/2018	YN2879Z	SKU7038E	16/3/2018																																																																																																															
15	19/3/2018	SKZ2548G	SJQ1968T	19/3/2018																																																																																																															
16	22/3/2018	SJP8518T	SLT5791Z	20/3/2018																																																																																																															
17	22/3/2018	SJM7299Y	SKW7326M	18/3/2018																																																																																																															
18	22/3/2018	SKB3393P	GBE3570P	14/2/2018																																																																																																															
19	22/3/2018	3Z6870X	SKE8281X	21/3/2018																																																																																																															
20	24/3/2018	SJV325D	SGP2702C	24/3/2018																																																																																																															
21	25/3/2018	GBH133J	SJY8319D	25/3/2018																																																																																																															
22	27/3/2018	SLE1492M	SLD8483Z	27/3/2018																																																																																																															
	sub-total of	8	176.00																																																																																																																
M/s. A.C. SYED & PARTNERS ADVOCATES & SOLICITORS SINGAPORE																																																																																																																			
We reserved the right to forward a subsequent bill for any disbursements omitted herein. E. & O.E.																																																																																																																			

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Mar 2018 Edit Reg		26 Mar 2018 00:00 Edit Adj Rpt	S\$4,400.00 Edit Estimates	S\$4,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	GREENLAND HORTICULTURE PTE LTD , Co. Reg. No.: A20906904D								
Main Claimant:	NEO CHWEE PAH , ID: S1392262D								
Vehicle Reg. No.:	SJY8319D	Date of Loss:	25/03/2018 00:00 - :59 [89 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1132280116SG	Policy/Cover Note No.:	1800007086 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBH133J	Policy No. (Claimant):	5074263429-02						
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Bldg 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 05/04/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (27/03/2018): TP GIA REPORT									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJY8319D (1132280116SG)**
[GBH133J]
TP
NEO CHWEE PAH
Mar 25 2018 12:00AM
[GREENLAND HORTICULTURE PTE LTD]
Cheng Hoe Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <input type="button" value="View in Browser"/>
Letters/Correspondences										1 per page <input type="button" value="1"/> <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit	
Assessment Reports										1 per page <input type="button" value="1"/> <input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print	
1	27/03/18 15:35	Accident Statement <small>From: GC - Reg. No: GBH133J, Claimant: GREENLAND HORTICULTURE PTE LTD</small>							Load HTM	
Photos/Images										3 per page <input type="button" value="3"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
2	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
3	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
4	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
5	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
6	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
7	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
8	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
9	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
10	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
11	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
12	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
13	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
14	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
15	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
16	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
17	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
18	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
19	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
20	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
21	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
22	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
23	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
24	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
25	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
26	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
27	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
28	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
29	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	
30	28/01/19 14:19	General View							Load JPG <input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	28/01/19 14:19	General View		<input checked="" type="checkbox"/>
32	28/01/19 14:19	General View		<input checked="" type="checkbox"/>
33	28/01/19 14:19	General View		<input checked="" type="checkbox"/>
34	28/01/19 14:19	General View		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/03/18 16:43	EMAIL FROM AIG DD 26032018		<input type="checkbox"/>
2	27/03/18 17:37	TP ESTIMATE- MARKED		<input type="checkbox"/>
3	27/03/18 17:37	TP GIA REPORT		<input type="checkbox"/>
4	30/01/19 15:40	WORKSHOP INVOICE		<input type="checkbox"/>
5	30/01/19 15:40	AUTHORISATION TO ACT FORM		<input type="checkbox"/>
6	30/01/19 15:40	Release Voucher		<input type="checkbox"/>
7	30/01/19 15:40	LTA SEARCH		<input type="checkbox"/>
8	30/01/19 15:40	LETTER TO OI		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin: 5px 0;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	GBH133J (Insd veh)	Model:	TOYOTA VIOS 1.5 E (A)
	SJY8319D (TP veh)		
Date of Accident:	25/03/2018		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	: \$		6,596.92	
Final Repair Cost	: \$		4,708.00	
Loss of Use	: \$		900.00	9.00 days at \$100.00 per day
Rental (if any)	: \$		0.00	days
LTA / GIA Search Fee	: \$		8.00	
Others:	: \$		0.00	
	: \$			
Final Settlement Sum	: \$		5,616.00	

Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____
 _____27____
 BOLA Liability: _____100____ (%) Assessed Liability (*): _____ (%)
 * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown		
1)	Cheng Hoe Motor Pte Ltd	: \$ 5,616.00
2)		: \$
3)		: \$

JOANNE LEE KHANG MIN

 LKK Auto Consultants Pte Ltd

30 Jan
 2019

 Date

Please attach all the supporting documents to the form.
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:196607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18005596/KJB3Q2
Date: 30/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800007086
Claimant Vehicle No : SJY8319D	Insured Vehicle No :	GBH133J
Date of Loss: 25/03/2018	Nature of Claim:	TP
	Claim No:	1132280116SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY8319D	Engine No:	1NZY121007
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305174513
Reg. Date:	06/10/2010 (Man. Year: 2010)	Odometer:	309686 km
Colour:	White		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	KAPSEN 8 mm	Rear Left Side:	KAPSEN 8 mm
Front Right Side:	KAPSEN 8 mm	Rear Right Side:	KAPSEN 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,905.35	3,583.27	322.08	8.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,960.00	300.00	13.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,165.35	5,543.27	622.08	10.09
Approved Total (Overridden) (S\$)		4,400.00		
	(S\$) 6,165.35	4,400.00	1,765.35	28.63
+ GST 7.00/7.00% (S\$)	431.57	308.00	123.57	28.63
Nett Amount (S\$)	6,596.92	4,708.00	1,888.92	28.63
+ Loss of Use (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		5,616.00		

INSPECTION

Date of Assignment:	26/03/2018	
Date Inspected:	26/03/2018 Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial

Park A
Singapore 768761

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	427.50 FL	*427.50 FL
2	1		*REAR BUMPER RH REFLECTOR	Cracked	82.80 FL	*82.80 FL
3	2		*REAR BUMPER SIDE RETAINERS	Distorted	184.66 FL	*184.66 FL
4	1		*REAR BUMPER RH BRACKET	Bent	63.77 FL	*63.77 FL
5	6		*REAR BUMPER CLIPS	Necessary	23.34 FL	*23.34 FL
6	2		*TAILLAMPS	O/S Broken /N/S Cracked	555.24 FL	*555.24 FL
7	2		*TAILLAMP PANELS	Bent	210.00 FL	*210.00 FL
8	2		*TAILLAMP LOWER GARNISHS	Serviceable	62.44 FL	*- FL
9	1		*REAR BOOT	Bent	510.85 FL	*510.85 FL
10	1		*REAR BOOT INNER LOCK	Dented	95.97 FL	*95.97 FL
11	1		*REAR BOOT INNER RUBBER (50%)	Dented / Distorted	131.51 FS	*87.68 FS
12	1		*REAR BOOT LOGO	Necessary	50.20 FL	*50.20 FL
13	1		*REAR BOOT EMBLEM (VIOS)	Necessary	44.20 FL	*44.20 FL
14	1		*REAR BOOT EMBLEM (E)	Necessary	34.37 FL	*34.37 FL
15	1		*REAR BOOT OUTER GARNISH	Warped	198.80 FL	*198.80 FL
16	2		*REAR BOOT HINGES	Repair	308.56 FL	*- FL
17	2		*TAILLAMP INNER RUBBERS	Necessary	52.50 FL	*52.50 FL
18	1		*REAR CENTRE PANEL	Buckled	571.89 FL	*571.89 FL
19	1		*REAR CENTRE PANEL INNER TOP GARNISH	Mtg Distorted	200.76 FL	*200.76 FL
20	2		*REAR SPARE TYRE SIDE SPONGES	Cracked	355.14 FL	*355.14 FL
21	1		*REAR SPARE TYRE FRT SPONGE	Cracked	132.80 FL	*132.80 FL
22	1		*REAR EXHAUST PIPE	Bent	595.13 FL	*595.13 FL
23	1		*REAR RH FENDER INNER GARNISH	Deformed	224.20 FL	*224.20 FL
24	1		*REAR NUMBER PLATE	Dented	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,151.63	4,736.80
- List Item Discount on L Items 25.00/25.00% (S\$)	1,246.28	1,153.53
Total Parts (S\$)	3,905.35	3,583.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMPS ,REAR BOOT & ATTACHMENT ,HINGES ,TO CUT ,WELD & RENEW REAR END PANEL ,TAILLAMP PANELS ,KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT ,REAR BOTH FENDERS & REALIGN THE SAME	New	1,200.00	1,000.00
2	PUTTY & RESPRAY ON REAR BOOT ,HINGES ,REAR SPARE TYRE COMPARTMENT ,REAR FENDERS ,REAR BUMPER,REAR PANEL & REAR AFFECTED AREAS	New	1,000.00	900.00
3	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$\$)			2,260.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >