


FAX COVER SHEET

| | |
|-----------|-------------------------|
| TO | AIG |
| COMPANY | AIG |
| FAXNUMBER | 6564153727 |
| FROM | Zoom Autowerks |
| DATE | 2018-03-25 13:29:27 GMT |
| RE | Pre-Repair Inspection |

COVER MESSAGE

Kindly arrange, thank you.



ZOOM AUTOWERKS PTE LTD

832 Sims Avenue, Eunosville
#12-884 Singapore 400832
Tel: 9450 7920
✉ zoomautowerks@gmail.com

Date: March 25th, 2018

To: **AIG Asia Pacific Insurance Pte. Ltd**
78 Shenton Way
#07-16 Singapore 079120

Attention: Motor Claims Department / Fax: 6415 3727

**RE: Pre-Repair Inspection for SLW 3958 D // Accident on 24/03/2018 @ 21:27HR along
PIE(Changi), after Eunos Exit involving Vehicle Number SLW 3958 D & SDK 395 E**

Dear Sir/Madam,

We are instructed by Derek Ong Tun Jun to notify you of a road traffic accident on 24/03/2018 at about 21:27HR at PIE(Changi), after Eunos Exit involving our client's/customer's vehicle registration number SLW 3958 D and vehicle registration number SDK 395 E driven by your insured at the material time.

A copy of the Singapore accident statement /traffic police report filed is enclosed. As a result of the accident, our client's /customer's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53 Singapore 417808.

Yours Faithfully,

Elin Cai

Zoom Autowerks Pte Ltd