

INS. CASE OWNER

CC 4 UR / AIG 1800 5605, Fwbb

LKK IDAC

Surveyor: Fenneth

DOI: 2/4/18

Date / Time: 23/3/18

Registered in Merimen: 20/3/18

Pre-assign / CCU / FTE

ASSIGNMENT



Insured Vehicle No. : SLF 41032

Claim No. : 59206510x359

Name of Insured : UR

Policy No. : 044645054

Insured Tel No. : _____ HP: _____

Make / Model : HONDA

Excess Sec II :SS _____ D.O.A. : 2/3/18

Place of Accident : 337 LANTONMENT RD

Is driver the owner? (YES NO) Nature of Accident : _____

If NO, Driver Name / Age : HOW WING LAMEN KUKARO

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : _____ (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

GBC 7996R →



INSRS: complete
WSP: vms
Tel: _____
Liability: _____
RMKS: _____



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time		STAGE	DATE / PIC
<u>5/4/18</u>	<u>GBC 7996R - Y</u>	Non-Reporting ltr (1st):	
<u>5/4/18</u>	<u>SLF 41032 - Y</u>	Non-Reporting ltr (2nd):	
<u>5/4/18</u>	<u>Winn</u>	Non-Reporting ltr (Final):	
<u>5/4/18</u>	<u>Email letter to OO</u>	Notification ltr (if non-pickup):	
		Call OI: <u>5/4/18 email.</u>	
		After call ltr to OI: <u>12/4/18</u>	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	<input type="checkbox"/>
		After call ltr to OI:	<input checked="" type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/>
		Towing Invoice:	<input type="checkbox"/>
		LTA / GIA :	<input checked="" type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		PIR:	<input type="checkbox"/>
		Mandate/Reject Instruction:	<input type="checkbox"/>
		LOD	<input checked="" type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: SS (_____ days) Reduction: _____ % Email Call

FINAL SETTLEMENT Date/Time: 13/6/18 Confirm with lly. Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 27. If NO or B.28, Ass. Lia : _____

Repair Cost: SS 3263.50

Loss of Rental (LOR): SS 400.00 (4 days) x 100.00

Loss of Use (LOU): SS (\$ x days)

Loss of Income (LOI): SS (\$ x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search SS 7.45

Medical: SS

Disbursement: SS (e.g. Tow/Independent)

Legal Cost SS

Total: SS 3670.95 Global Sum SS: _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: SS 3670.95 Name 1: Complete vms pte ltd

Payee 2: (Strike if N.A.) SS Name 2: _____

Payee 3: (Strike if N.A.) SS Name 3: _____

0001

REF: LCR

ASSIGNMENT

From: _____ Date: 03042018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBC 7996R

at Workshop m/s: Complete vms

of: Blk 172 Sin Ming Dr #13-14

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: GBC 7996R Yr Regn: 11 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy / Hino c.c. 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 77689 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTKH 702P 300125003

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Normal / Jammed / Leaked / Burnt or _____

Brake: Normal / Jammed / Leaked / Burnt or _____


Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 195/80R15

R: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front	Rear
R/Bal. 6 mm	R/Bal. 5 mm
L/Bal. 6 mm	L/Bal. 5 mm
D.O.A. 2/13/18	D.O.I. 3/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
14	File pass to Carman
12/6/18	confirm U/S \$3050.00 with 4 working days

(Red: #4526.30
60%)

Date/Time: File Pass to? : Prel. Report

1) : Final Report

Date/Time: File Return to? _____

2) _____

Report Format: _____

Lump Sum / I.B.t: (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee: _____

Transportation: _____

5 + RS: \$ _____

Photo: _____

Cited: _____

TOTAL: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/LCR18005605/Kwb3

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 26-03-2018



Code : LCR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLF 4103L	Veh. Inspected	GBC 7996R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	21/03/2018	Inspection Date	03/04/2018
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



COMPLETE VMS PTE LTD - The Premier One-Stop Vehicle Accident Claims Centre
 176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
 (Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihu@completevms.com.sg ()

JARMAY ENTERPRISES PTE LTD
 18 BOON LAY WAY, TRADEHUB 21 #06-119
 SINGAPORE 609966

Estimate : ES006294

Attention : THE OWNER

Contact : 81806724 66590388 90903134

Date : 25/03/2018
 Vehicle Num : GBC7996R
 Make/Model : TOYOTA HIACE-2013
 Chassis/Eng# : JTFHT02P300125005/1KD2333952
 Accident Date : 21/03/2018
 Claim No :
 Reference :
 Policy No :

*Not Authorized
 1-2-1
 Running B4 paint
 1/12/18 83050k 4 days*

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	LIST ITEMS 2051.60		
2.	1	TAIL GATE 359		
3.	1	TAIL GATE INNER LOCK		
4.	1	TAIL GATE LOCK CATCH		
5.	1	TAIL GATE W/SCREEN GLASS MOULDING 68-a		
6.	1	TAIL GATE OUTER HANDLE		
7.	2	TAIL GATE NUMBER PLATE LAMP	67.90	135.80
8.	1	TAIL GATE TOYOTA LOGO		72.20
9.	1	TAIL GATE INNER BOARD		195.80
10.	1	TAIL GATE RUBBER SEAL		405.00
11.	1	HIACE STICKER		49.00
12.	1	TOYOTA STICKER 496-10		48.00
13.	1	REAR BUMPER		597.30
14.	2	REAR BUMPER BRACKET		180.40
15.	6	REAR BUMPER CLIP	90.20	541.20
16.	1	REAR END PANEL INNER	8.50	8.50
17.	1	REAR END PANEL OUTER		943.20
18.	1	REAR END PANEL SCUFF PLATE		581.60
		List Total S\$		6,588.40
		25.00% Discount S\$		1,647.10
				4,941.30
1.	1	SPECIAL NETT ITEMS		
2.	1	TAIL GATE W/SCREEN GLASS SEALANT		65.00
3.	1	TAIL GATE NUMBER PLATE		25.00
4.	1	70KM STICKER		15.00
		Special Nett Total S\$		105.00

CONTINUE / ...

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
 Signature:
 Date:



COMPLETE VMS PTE LTD - The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

JARMAY ENTERPRISES PTE LTD
18 BOON LAY WAY, TRADEHUB 21 #06-119
SINGAPORE 609966

Attention : THE OWNER

Contact : 81806724 66590388 90903134

Estimate : ES006294

Date : 25/03/2018
Vehicle Num. : GBC7996R
Make/Model : TOYOTA HIACE-2013
Chassis/Eng# : JTFHT02P300125005/1KD2333952
Accident Date : 21/03/2018
Claim No. :
Reference :
Policy No. :

S/N Quantity Particular Unit Price Amount S\$

LABOUR :
REMOVE & REINSTALL TAIL GATE W/SCREEN GLASS
TRANSFER TAILGATE COMPONENT TO NEW GATE
RUST PROOFING TREATMENT
SPRAY PAINT DAMAGED AREA AFFECTED
TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR
CHASSIS FRAMES, AND CHANGE ALL NECESSARY PARTS

120
60l 180.00
30l 150.00
480l 1,000.00
1,100.00 *50*
2,530.00

Labour Total S\$:

SingDollars : Seven Thousand Five Hundred Seventy-Six & Cents Thirty Only

Total S\$: 7,576.30

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

JARMAY ENTERPRISES PTE LTD
 18 BOON LAY WAY, TRADEHUB 21 #06-119
 SINGAPORE 609966

Estimate : ES006294

Attention : THE OWNER

Contact : 81806724 66590388 90903134

*NOT Authorized
 1-B.1
 Repair B & paint 4 days*

Date : 25/03/2018
 Vehicle Num. : GBC7996R
 Make/Model : TOYOTA HIACE-2013
 Chassis/Eng# : JTFHT02P300125005/1KD2333952
 Accident Date : 21/03/2018
 Claim No :
 Reference :
 Policy No. :

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	TAIL GATE	BH 2,178.00	✓
2.	1	TAIL GATE INNER LOCK	R 392.30	X
3.	1	TAIL GATE LOCK CATCH	R 103.00	X
4.	1	TAIL GATE W/SCREEN GLASS MOULDING	MC 179.00	✓
5.	1	TAIL GATE OUTER HANDLE	SM 187.20	X
6.	2	TAIL GATE NUMBER PLATE LAMP	SM 67.90	X
7.	1	TAIL GATE TOYOTA LOGO	MC 72.20	✓
8.	1	TAIL GATE INNER BOARD	SM 195.80	X
9.	1	TAIL GATE RUBBER SEAL	SM 405.00	X
10.	1	HIACE STICKER	MC 49.00	✓
11.	1	TOYOTA STICKER	MC 46.00	✓
12.	1	REAR BUMPER	BH 597.30	✓
13.	2	REAR BUMPER BRACKET	SM 90.20	X
14.	6	REAR BUMPER CLIP	8.50	✓
15.	1	REAR END PANEL INNER	MC 51.00	✓
16.	1	REAR END PANEL OUTER	R 943.20	X
17.	1	REAR END PANEL SCUFF PLATE	ND L/SR 581.60	X
			SM 291.60	X
		List Total S\$:		6,588.40
		25.00% Discount S\$:		1,647.10
				4,941.30
SPECIAL NETT ITEMS :				
1.	1	TAIL GATE W/SCREEN GLASS SEALANT	MC 65.00	40% ✓
2.	1	TAIL GATE NUMBER PLATE	SM 25.00	X
3.	1	70KM STICKER	MC 15.00	✓
		Special Nett Total S\$:		105.00

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



(V.V.)

Your Ref : SLF4103L

Our Ref : TPDS18057 - GBC7996R

2nd June 2018

By Postage

AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way #07-16
Charitis Building
Singapore 079120

Attention: Motor Claims Department

Dear OIC,

ACCIDENT INVOLVING VEHICLE: GBC7996R AND SLF4103L ALONG TRAFFIC JUNCTION OF CANTONMENT RD/YAN KIT ROAD ON 21/03/2018

We are the authorized repair workshop for the owner of motor vehicle no. **GBC7996R**, which is involved in the captioned accident with your insured vehicle **SLF4103L**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1	Cost of Repair	S\$ 3,263.50	(inclusive GST)
2	4Days Loss of Rental @ \$150	S\$ 600.00	
3	LTA search fee	S\$ 7.45	
		<u>S\$ 3,870.95</u>	

We enclosed herewith the following documents to support the claims:-

- GIA Report
- Proforma invoice
- Lta search fee

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you
Yours Faithfully

Chiu Siong Lim
6455 0012
For Complete VMS Pte Ltd

Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Thursday, 5 April, 2018 11:49 AM
To: 'eyap@lioncityrentals.com.sg'
Cc: Hsiao Tong (LKKAuto); Joy Irene (LKKAuto)
Subject: ACCIDENT INVOLVING SLF 4103L & GBC 7996R ON 21/03/2018

Our Ref: CC3/LCR18004509/Kwb3

05 April 2018

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SLF 4103L & GBC 7996R ON 21/03/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108


Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


To: Complete VMS Pte Ltd
176, Sin Ming Drive,
#03-14, Sin Ming Autocare Complex
Singapore 575721

LETTER OF AUTHORIZATION

RE: ACCIDENT BETWEEN GBC7996R / SLF4103L (Vehicle Numbers)
ON 21/03/2018 2:15pm (Date of Accident) AT Traffic Junction of automent Road


1. I/We, the owner of vehicle no. GBC7996R hereby appoint you to act for me to repair and recover damages sustained to my vehicle in the above accident from the third party driver and / or his / her insurers.
2. In this respect, I/We have authorized you to repair, correspond, negotiate and settle on my behalf, all claims against the parties involved in the subject accident. All final financial awards in my favor pertaining to the subject accident claim are to be paid to Complete VMS Pte Ltd.
3. By way of this Letter of Authorization, I/We also further authorized you to sign all Discharge Vouchers and any other related documents in settlement of the subject accident claims. I/We hereby undertake to ratify and reaffirm such signing of Discharge Vouchers and/or documents from any third party insurers by us.
4. During the settlement process with the third party insurers / drivers, you may act fully on my behalf and all negotiations and correspondences given by you to the third party insurers / driver are as if given directly from me. With regards to the settlement of the above subject accident claim, I/We agree and undertake to ratify all correspondences and negotiations given by you to the third party insurers / driver and further agree and undertake to be bound by all acts performed or carded out by you.
5. I/We understand that should the subject accident claims fail or not able to reach an amicably settlement with the third party insurers or driver, I/We will have to appointed a solicitors by way of signing a warrant to act in present of the appointed solicitor to further pursue the matter and to commence legal proceedings in Court in my/our name against the third party driver and/or his employers (if applicable). I/We further agrees that should I/We fails or disagrees to appoint a solicitors at that stage, I/We shall be fully liable for all costs incurred to you until that point of time.
6. I/We further confirm my/our understanding that I/We shall render my/our full co-operation pertaining to the settlement of the subject accident and method of repair adopted shall be in accordance to the standard practices of the industry and will be at the full discretion of you.
7. I/We hereby agree that upon settlement of the above subject accident claim, I/We are required to sign Discharge Voucher/s issued by the third party insurers. After which all settlement monies shall be used to settle all costs and fee incurred to carry out the above subject accident repairs and claims. This settlement monies shall constitute a full discharge of your payment obligation to us.
8. Any indemnity / discharge voucher signed by the workshop is without prejudice to my rights to claim for compensation for my personal injury (if any). Complete VMS Pte Ltd is only authorized to negotiate and finalized with Third Party for my property damages

Signature : 


Witness's Name & Signature

Name : Yeo Jm Seng

Date : 2/4/18

----- Company Stamp (if applicable) :  -----

Email: _____

RELEASE VOUCHER
(AIG ASIA PACIFIC-EXPRESS THIRD PARTY CLAIM)

"We/I, COMPLETE VMS PTE LTD (the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 3,263.50 (repair cost), S\$ 400.00 (loss of rental/use), S\$ 7.45 (disbursement), for vehicle no. GBC 7996R that was damaged pursuant to the accident which occurred on 21/03/2018 (date) along 237 CANTONMENT RD (location) involving vehicle no/s SLF 4103L.

This is pursuant to the inspection conducted on 03/04/2018 (date) at "the workshop".


We/I confirm that we/I are/am authorized by the owner JARMAY ENTERPRISE PTE LTD (the third party claimant") of vehicle no. GBC 7996R make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to GBC 7996R (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 13 (day) of June (month) 2018 (year)

CS

Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

This indemnity is signed without prejudice to my rights to claim for compensation for my personal injury.

COMPLETE VMS PTE LTD

176 Sin Ming Drive, #03-14 / 07, Sin Ming Autocare Complex, S575721
Tel: 6455 0012 Fax: 6554 0012 Email: main@completevms.com.sg
Business Reg. No. 200416180E GST Reg. No.: 200416180E



AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16 CHARTIS BUILDING
SINGAPORE 079120

Tax Invoice : VM013477

Invoice Date : 13/06/2018
Vehicle Num. : GBC7996R
Make/Model : TOYOTA HIACE
Mileage(Km) :
PO/WO/RO# :
Ref./Remark : CC4/LCR18005605/Kwb3

S/N	Quantity	Particular	Unit Price	Amount S\$
		COST OF REPAIR AS AGREED AT		3,050.00

SingDollars : Three Thousand Two Hundred Sbdy-Three & Cents Fifty Only

Total S\$: 3,050.00
GST S\$: 213.50
Amount Due S\$: 3,263.50
=====

Terms : 30 Days

A handwritten signature in black ink, appearing to be a stylized 'R' or similar character.

COMPLETE VMS PTE LTD

GBC7996R



35 Eden Grove, Singapore 539085
Co.Reg. No.: 200717924R

VEHICLE RENTAL AGREEMENT

STA No: 002000

<p>HIRER'S PARTICULAR</p> <p>Name : (as in I/C) <u>Jarmay Enterprises Pte Ltd</u></p> <p>NRIC / Passport No: <u>199802825C</u></p> <p>Address: _____</p> <p>ADDITIONAL DRIVER'S PARTICULARS</p> <p>Name : (as in I/C) <u>Yeo Jin sheng</u></p> <p>NRIC / Passport No: <u>S8824581D</u></p> <p>Address: _____</p> <p>REMARKS</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p>	<p>Veh. No: <u>G8G5477P</u> Replace Veh. No: _____</p> <p>Mileage Out: _____ Mileage Out: _____</p> <p>Out : Date <u>2/4/2018</u> Out : Date _____</p> <p>Out : Time <u>2:15 pm</u> Out : Time _____</p> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th colspan="3">RENTAL CHARGES</th> </tr> <tr> <td>Daily</td> <td><u>4 @ \$150/-</u></td> <td><u>\$ 600.00</u></td> </tr> <tr> <td>Monthly</td> <td>@ \$</td> <td></td> </tr> <tr> <td>Delivery Charges</td> <td>@ \$</td> <td><u>For</u></td> </tr> <tr> <td>Others</td> <td>@ \$</td> <td></td> </tr> <tr> <td colspan="2" style="text-align: right;">SUB TOTAL \$</td> <td><u>600.00</u></td> </tr> </table> <p>PETROL: Empty , 1/8 , 1/4 , 3/8 , 1/2 , 5/8 , 3/4 , 7/8 , Full</p> <p>INSURANCE EXCESS PAYABLE ON CLAIM</p> <p>Hirer is responsible for the first \$ <u>\$2500 -</u> excess for Collision / Damages to 1st party (i.e.) COMPLETE LEASING P/L vehicle (inc. windscreen) and also first \$ <u>\$2000 -</u> excess for Collision / Damages to 3rd party's vehicle for each and every accident / damages.</p> <p>Hirer's Signature: <u>[Signature]</u> </p>	RENTAL CHARGES			Daily	<u>4 @ \$150/-</u>	<u>\$ 600.00</u>	Monthly	@ \$		Delivery Charges	@ \$	<u>For</u>	Others	@ \$		SUB TOTAL \$		<u>600.00</u>
RENTAL CHARGES																			
Daily	<u>4 @ \$150/-</u>	<u>\$ 600.00</u>																	
Monthly	@ \$																		
Delivery Charges	@ \$	<u>For</u>																	
Others	@ \$																		
SUB TOTAL \$		<u>600.00</u>																	

I/We agreed to the terms and conditions above, overleaf and that all information given are true & correct in all respect. My/Our driving license(s) is/are current and not disqualified from driving.

IMPORTANT

1. ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORIZED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
2. VEHICLE IS STRICTLY FOR USE IN SINGAPORE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT FROM THE COMPANY COMPLETE LEASING PTE LTD
3. IN THE EVEN OF AN ACCIDENT, THE HIRER OF AUTHORIZED DRIVER;
 - (i) shall report all accidents involving the said vehicle to the owner immediately,
 - (ii) shall NOT admit liability or sign any settlement documents with any 3rd parties
4. THIS AGREEMENT IS SUBJECT TO THE CONDITIONS PRINTED ON THE REVERSE SIDE

EXCESS:
ADDITIONAL \$2500
FOR 22 TO 27 &
ABOVE 65 YEARS OLD

DATE IN	TIME IN	CHECKED BY	
<u>06/04/2018</u>	<u>2.45 pm</u>		 SIGNATURE OF HIRER / DRIVER

[Signature]



Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time : 22 Mar 2018 / 17:39:29

Receipt Date/Time : 22 Mar 2018 / 17:39:29

Tax Invoice/Receipt

Receipt No.: ITNET-00000-180322-001726

Previous Receipt No.:

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLF4103L				
As at 21 Mar 2018/00:00:01				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLF4103L Enquiry Fee 20180322173837578692	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20180322173900603	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Mar 2018 Edit Reg		23 Mar 2018 00:00 Edit Adj Rpt	S\$3,050.00 Edit Estimates	S\$3,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF PTE LTD , Co. Reg. No.: 201624597K								
Main Claimant:	JARMAY ENTERPRISES PTE LTD , Co. Reg. No.: -								
Vehicle Reg. No.:	GBC7996R	Date of Loss:	21/03/2018 00:00 - :59 [52 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5920651077SG	Policy/Cover Note No.:	0999994817 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLF4103L	Policy No. (Claimant):							
		Excess:							
Repairer:	COMPLETE VMS PTE LTD (HQ) 176 Sin Ming Drive #03-14 Sin Ming Autocare Complex, 575721 Sin Ming - Tel: 6455 0012								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kang, Sam-PL] Sam.Kang@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 05/04/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (27/03/2018): TP GIA REPORT									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBC7996R (5920651077SG)
[SLF4103L]
TP**

**JARMAY ENTERPRISES PTE LTD
Mar 21 2018 12:00AM
[LCRF PTE LTD]
COMPLETE VMS PTE LTD**

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View	View in Browser <input type="checkbox"/>
Letters/Correspondences			1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	 Edit	
Assessment Reports			1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/03/18 15:10	Accident Statement From: SC - Reg. No: SLF4103L, Claimant: LCRF PTE LTD	 Load HTM	
Photos/Images			3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/06/18 17:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	13/06/18 17:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	13/06/18 17:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	13/06/18 17:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	13/06/18 17:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	13/06/18 17:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	13/06/18 17:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	13/06/18 17:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	13/06/18 17:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	13/06/18 17:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	13/06/18 17:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	13/06/18 17:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	13/06/18 17:06	Reinspection Photo	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	13/06/18 17:06	Reinspection Photo	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	13/06/18 17:06	Reinspection Photo	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	13/06/18 17:06	Reinspection Photo	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	13/06/18 17:06	Reinspection Photo	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	13/06/18 17:06	Reinspection Photo	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	13/06/18 17:06	Reinspection Photo	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	13/06/18 17:06	Reinspection Photo	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	13/06/18 17:06	Reinspection Photo	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Documentation			1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/03/18 17:10	EMAIL FROM AIG DD 23032018	 Load PDF	
2	26/03/18 17:10	WKSP NOTICE	 Load PDF	
3	04/04/18 17:33	TP ESTIMATE- MARKED	 Load PDF	
4	04/04/18 17:33	TP GIA REPORT	 Load PDF	
5	18/06/18 11:35	WORKSHOP INVOICE	 Load PDF	
6	18/06/18 11:35	AUTHORISATION TO ACT FORM	 Load PDF	
7	18/06/18 11:35	Release Voucher	 Load PDF	
8	18/06/18 11:35	RENTAL RECEIPT	Load PDF	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
9	18/06/18 11:35	LTA SEARCH		Load PDF
10	18/06/18 11:35	LETTER TO OI		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLF4103L (Insd veh)	Model:	ADIVA AD200A 200CC (M)
	GBC7996R (TP veh)		
Date of Accident:	21/03/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$		8,106.64
Final Repair Cost	: \$		3,263.50
Loss of Use	: \$		_____ days at \$0.00 per day
Rental (if any)	: \$	400.00	4 days
LTA / GIA Search Fee	: \$	7.45	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	3,670.95	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	COMPLETE VMS PTE LTD	: \$	3,670.95
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

18 Jun
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR18005605/KWB3Q2

Date: 18/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994817
Claimant Vehicle No : GBC7996R	Insured Vehicle No :	SLF4103L
Date of Loss: 21/03/2018	Nature of Claim:	TP Claim No: 5920651077SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC7996R	Engine No:	1KD2333952
Make & Model:	ADIVA AD200A, 200cc (M)	Chassis No:	JTFHT02P300125005
Reg. Date:	19/11/2013 (Man. Year: 2013)	Odometer:	77689 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,046.30	2,599.67	2,446.63	48.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,530.00	1,190.00	1,340.00	52.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,576.30	3,789.67	3,786.63	49.98
Approved Total (Overridden) (S\$)		3,050.00		
	(S\$)	7,576.30	3,050.00	4,526.30
	+ GST 7.00/7.00% (S\$)	530.34	213.50	316.84
	Nett Amount (S\$)	8,106.64	3,263.50	4,843.14
	+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00	
	+ Doc/Search Fee (S\$)		7.45	
	Nett Liability (S\$)		3,670.95	

INSPECTION

Date of Assignment:	23/03/2018	
Date Inspected:	03/04/2018 Inspected At:	COMPLETE VMS PTE LTD (HQ) 176 Sin Ming Drive #03-14 Sin Ming

Autocare Complex
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	2,178.00 FL	*2,051.60 FL
2	1		*TAIL GATE INNER LOCK	Dented / Jammed	392.30 FL	*359.00 FL
3	1		*TAIL GATE LOCK CATCH	Repair	103.00 FL	*- FL
4	1		*TAIL GATE W/SCREEN GLASS MOULDING	Necessary	179.00 FL	*68.00 FL
5	1		*TAIL GATE OUTER HANDLE	Serviceable	187.20 FL	*- FL
6	2		*TAIL GATE NUMBER PLATE LAMP	Serviceable	135.80 FL	*- FL
7	1		*TAIL GATE TOYOTA LOGO	Necessary	72.20 FL	*72.20 FL
8	1		*TAIL GATE INNER BOARD	Serviceable	195.80 FL	*- FL
9	1		*TAIL GATE RUBBER SEAL	Serviceable	405.00 FL	*- FL
10	1		*HIACE STICKER	Necessary	49.00 FL	*49.00 FL
11	1		*TOYOTA STICKER	Necessary	46.00 FL	*46.00 FL
12	1		*REAR BUMPER	Buckled	597.30 FL	*496.10 FL
13	2		*REAR BUMPER BRACKET	Serviceable	180.40 FL	*- FL
14	6		*REAR BUMPER CLIP	Necessary	51.00 FL	*51.00 FL
15	1		*REAR END PANEL INNER	Repair	943.20 FL	*- FL
16	1		*REAR END PANEL OUTER (LOCAL REPAIR)	Dented	436.20 FS	*150.00 FS
17	1		*REAR END PANEL SCUFF PLATE	Serviceable	291.60 FL	*- FL
18	1		*TAIL GATE W/SCREEN GLASS SEALANT	Necessary	65.00 FS	*40.00 FS
19	1		*TAIL GATE NUMBER PLATE	Serviceable	25.00 FS	*- FS
20	1		*70KM/ STICKER	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,548.00	3,397.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,501.70	798.23
Total Parts (\$\$)	5,046.30	2,599.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REINSTALL TAIL GATE W/SCREEN GLASS	New	180.00	120.00
2	TRANSFER TAILGATE COMPONENT TO NEW GATE	New	150.00	60.00
3	RUST PROOFING TREATMENT	New	100.00	30.00
4	SPRAY PAINT DAMAGED AREA AFFECTED	New	1,000.00	480.00
5	TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR CHASSIS FRAMES ,AND CHANGE ALL NECESSARY PARTS	New	1,100.00	500.00
Gross Labour Cost (S\$)			2,530.00	1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >