

INS CASE OWNER:

Richard

CC 4 / ASM1800

S621, M1WAS

LKK: IDAC 36615

MACT

ASSIGNMENT

DOI: 27/2/18

Date / Time: 26/3/2018

Registered in Merimer:

Pre-assign / CCU / FTE

S821333Y

88M 00BQ N



Insured Vehicle No.: S821333Y
Name of Insured: Mark Van Hous
Insured Tel No.: HP: 9277 2400
Excess Sec II :SS D.O.A: 22/03/2018
Is driver the owner? (YES / NO) Nature of Accident:

Claim No.:
Policy No.: 9A303032
Make / Model: R20W 528
Place of Accident: T/A Truck Block 13082P

If NO, Driver Name / Age: Driver Tel No.: (V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Insured Liability: % Final ? Yes / No

SKU73715



INSRS: WSP: CYS, M
Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/ Time		STAGE	DATE / PIC
27/2/18	SKU73715-X;	Non-Reporting ltr (1st):	
	S821333Y - CYS (AKA) 203639 / 112 X2 2018/1/2	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
	* video uploaded on SMART.	Call OI:	23/5/18 CW
		After call ltr to OI:	UW102
		Documentation Check List:	Handler Typist
14/6/18	File pass to typist type report.	Notification ltr (if non-pickup)	<input type="checkbox"/>
16/10/18	Seek mandate via SMART	After call ltr to OI:	<input checked="" type="checkbox"/>
25/4/19	mandate approved via SMART	Authorisation To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/>
		Towing Invoice:	<input checked="" type="checkbox"/>
		LTA / GIA:	<input checked="" type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		PTR:	<input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
		LOD:	<input checked="" type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: \$5 (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: 25/4/19 Confirm with: Lee Sm Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 24

Repair Cost: \$5510.50

Loss of Rental (LOR): \$5 1650.00 (11 days) X 150.00

Loss of Use (LOU): \$5 (\$ x days)

Loss of Income (LOI): \$5 (\$ x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: \$5 200

Medical: \$5

Disbursement: \$5 (e.g. Tow/ Independent)

Legal Cost: \$5

Total: \$5 7162.50 **Global Sum \$5:**

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: \$5 7162.50 Name 1: Cys Automobile Services Pty Ltd.

Payee 2: (Strike if N.A.) \$5 Name 2: /

Payee 3: (Strike if N.A.) \$5 Name 3: /

COPY SENT 29/4/19 o/c 30/4/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18005621/wa3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 26-03-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SBZ 1333Y	Veh. Inspected	SKU 7371S
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00BQN	Excess (\$)	0.00
Assign From		Assign Date	26/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	22/03/2018	Inspection Date	
Survey held at	CYS AUTOMOBILE SERVICES PTE LTD 38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Your ref: S8M00BQN

Our ref: CC4/ASM18005621/M1wa3

Date: 02.04.2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKU 7371S

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27.03.2018 at the premises of M/s CYS Automobile Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	<u>9,637.60</u>
Revised Estimate Amount	: S\$	<u>4,957.12</u>
"Check" Items Amount	: S\$	<u>1,486.72</u>
Total (Including Check Items)	: S\$	<u>6,443.84</u>

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
N/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6.0 days

Yours faithfully,

MA CHIN FOOK
Licensed Appraiser



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR HGUEN THI HOE
 17 TOH YI DRIVE
 #12-73 (S) 590017

POLICY NO : THIRD PARTY CLAIMS
 YOUR REF : SBZ1333Y (AXA)
 OUR REF : TP5883
 VEHICLE NO : SKU7371S
 MAKE/MODEL : HONDA ODYSSEY
 DATE OF ACCIDENT : 22.3.18

SURVEY BY

DATE : 23.3.18

1 PC FRON BUMPER SIDE RETAINER L/H		SS	X 33.70	SVC
1 PC FRONT FENDER L/H			637.80	alt
1 PC FRONT FENDER INNER SHIELD L/H			219.50	dis
1 PC FRONT DOOR L/H			X 977.70	R
2 PCS FRONT DOOR HINGE L/H	72.10		X 144.20	SM
1 PC FRONT DOOR LOWER GARNISH L/H			X 421.90	SVC
1 PC REAR SLIDING DOOR L/H			X 1,080.90	R
1 PC REAR SLIDING DOOR LOWER GARNISH L/H			407.60	alt
1 PC REAR SLIDING DOOR WEATHERSTRIP L/H			X 571.30	N/A
1 PC FRONT RIM L/H			997.00	alt
1 PC REAR RIM L/H			997.00	alt
1 PC FRONT ABSORBER L/H			434.60	X
1 PC FRONT LOWER ARM L/H			723.90	X
1 PC FRONT KNUCKLE ARM L/H			448.50	X
1 PC FRONT KNUCKLE ARM BEARING L/H			261.40	X
		SS	8,347.00	
	LESS 20%		1,669.40	
		SS	6,677.60	
10 PCS FRONT FENDER INNER SHIELD CLIPS	3.00	SS	X 30.00	"S/NETT"
TO DO COMPUTER WHEEL ALIGNMENT		SS	160.00	80
TO DISMANTEL UNDER CARRIDGE			200.00	180
TO TRANSFER SLIDING DOOR			180.00	X
TO TRANSFER DOOR			100.00	X
TO APPLY RUST PROOFING ON REPAIRED/REPLACED PANELS			160.00	60
TO CHECK WIRING FUNCTION			50.00	30
LABOUR CHARGES			600.00	—
TO PUTTY AND SPRAY PAINTING CHARGES			1,500.00	1400
		SS	9,637.60	

KEY AUTO COMPANY
 The Repairer of the following:
 • To survey before/after spray painting
 • To check damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • All parts to be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*Not Authorised
 R/B Repair
 After Before paint job
 L&K Auto (M)*

SIN DOLLARS: NINE THOUSAND SIX HUNDRED THIRTY-SEVEN AND CENT SIXTY ONLY.

YOUR FAITHFULLY,

38 Woodlands Industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700
 Tel: 6219 2098 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

CYS AUTOMOBILE SERVICES PTE LTD

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Foreign Passport - Country/Region: Viet Nam
Owner ID: 94261

Vehicle Details

Vehicle No.: 58U73715
Vehicle to be Exported: No
Intended Deregistration Date: 07 Mar 2019
Vehicle Make: HONDA
Vehicle Model: ODYSSEY 2.4 EXV-5 CVT SR NAVI RES
Primary Colour: Silver
Manufacturing Year: 2015
Engine No.: K24V73010891
Chassis No.: 8-HMC1890FC203052
Maximum Power Output: 129.04kW (172bhp)
Open Market Value: \$28,769.00
Original Registration Date: 13 Aug 2015
First Registration Date: 13 Aug 2015
Transfer Count: 0
Actual ARF Paid: \$32,277.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 12 Aug 2025
PARF Rebate Amount: \$24,207.00

Intended COE Rebate Details

COE Expiry Date: 12 Aug 2025
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period (Years): 10
QP Paid: \$65,501.00
COE Rebate Amount: \$42,117.00
Total Rebate Amount: \$66,324.00

The information contained herein is correct as at 07 Mar 2019

OK

MV 93 K

CREATIVE TRADING & SERVICES
38 WOODLANDS INDUSTRIAL PARK E1
#02-06 SINGAPORE 757700
TEL: 67601591, 62577207
FAX: 67601592

SKU73715

Work Order: R001410
 Date: 27.3.18 14:20

Factory Japan 2016.0.1 : Honda : Odyssey : RC Series : RC1

Front : Left

Actual	Before	Specified Range
0°00'		-0°45' 0°45'
		4°35' 6°35'
0°47'		-0°05' 0°05'
		12°10' 13°40'
		11°25' 14°25'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°06'		-0°45' 0°45'
		4°35' 6°35'
-0°03'		-0°05' 0°05'
		12°10' 13°40'
		11°25' 14°25'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°06'		-0°45' 0°45'
		-0°45' 0°45'
0°44'		-0°10' 0°10'

Rear : Left

Actual	Before	Specified Range
-1°40'		-2°30' -1°00'
0°20'		0°00' 0°16'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°41'		-2°30' -1°00'
0°01'		0°00' 0°16'

Rear

Cross Camber
 Total Toe
 Thrust Angle
 Axle Offset

Actual	Before	Specified Range
0°01'		
0°21'		0°00' 0°31'
0°09'		
0mm		

CREATIVE TRADING & SERVICES
38 WOODLANDS INDUSTRIAL PARK E1
#02-06 SINGAPORE 757700
TEL: 67601591, 62577207
FAX: 67601592

SKU7371S

Work Order: R001411
 Date: 28.3.18 9:34

Factory Japan 2016.0.1 : Honda : Odyssey : RC Series : RC1

Front : Left

Actual	Before	Specified Range
-0°06'	0°07'	-0°45' 0°45'
		4°35' 6°35'
0°04'	0°13'	-0°05' 0°05'
		12°10' 13°40'
		11°25' 14°25'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°09'	0°09'	-0°45' 0°45'
		4°35' 6°35'
0°04'	0°10'	-0°05' 0°05'
		12°10' 13°40'
		11°25' 14°25'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°15'	-0°02'	-0°45' 0°45'
		-0°45' 0°45'
0°08'	0°23'	-0°10' 0°10'

Rear : Left

Actual	Before	Specified Range
-1°44'	-1°41'	-2°30' -1°00'
0°18'	0°17'	0°00' 0°16'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°35'	-1°36'	-2°30' -1°00'
-0°04'	-0°03'	0°00' 0°16'

Rear

Cross Camber
 Total Toe
 Thrust Angle
 Axle Offset

Actual	Before	Specified Range
-0°09'	-0°05'	
0°14'	0°14'	0°00' 0°31'
0°11'	0°10'	
0mm	0mm	



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR HUYEN THI HOE
 17 TOH YI DRIVE
 #12-73 (S) 590017

POLICY NO : THIRD PARTY CLAIMS
 YOUR REF : SBZ1333Y (AFA)
 OUR REF : TP5883
 VEHICLE NO : SKU7371S
 MAKE/MODEL : HONDA ODYSSEY
 DATE OF ACCIDENT : 22.3.18

SURVEY BY

DATE : 23.3.18

1 PC FRON BUMPER SIDE RETAINER L/H		SS	X 33.70	src
1 PC FRONT FENDER L/H			637.80	alt
1 PC FRONT FENDER INNER SHIELD L/H			219.50	dis
1 PC FRONT DOOR L/H			X 977.70	R
2 PCS FRONT DOOR HINGE L/H	72.10		X 144.20	src
1 PC FRONT DOOR LOWER GARNISH L/H			X 421.90	src
1 PC REAR SLIDING DOOR L/H			X 1,080.90	te
1 PC REAR SLIDING DOOR LOWER GARNISH L/H			407.60	alt
1 PC REAR SLIDING DOOR WEATHERSTRIP L/H			X 571.30	XIN
1 PC FRONT RIM L/H			997.00	src
1 PC REAR RIM L/H			997.00	alt
1 PC FRONT ABSORBER L/H			434.60	
1 PC FRONT LOWER ARM L/H			723.90	
1 PC FRONT KNUCKLE ARM L/H			418.50	
1 PC FRONT KNUCKLE ARM BEARING L/H			281.40	
		SS	8,347.00	
	LESS 20%		1,669.40	
		SS	6,677.60	
10 PCS FRONT FENDER INNER SHIELD CLIPS	3.00	SS	X 30.00	"S/NETT"
TO DO COMPUTER WHEEL ALIGNMENT		SS	150.00	80
TO DISMANTEL UNDER CARRIDGE			200.00	180
TO TRANSFER SLIDING DOOR			180.00	X
TO TRANSFER DOOR			100.00	X
TO APPLY RUST PROOFING ON REPAIRED/REPLACED PANELS			150.00	60
TO CHECK WIRING FUNCTION			50.00	30
LABOUR CHARGES			600.00	—
TO PUTTY AND SPRAY PAINTING CHARGES			1,500.00	1400
		SS	9,637.60	

*Not Authorized
 P/B Repair
 After before paint photo
 HKK Auto part
 22/3/2018
 low days*

Link Auto Centre
 I, the Repairer of the following:
 • To resurvey before/after spray painting
 • To survey damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 This resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SIN DOLLARS: NINE THOUSAND SIX HUNDRED THIRTY-SEVEN AND CENT SIXTY ONLY.

YOUR FAITHFULLY,

38 Woodlands Industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700
 Tel: 6219 2098 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

CYS AUTOMOBILE SERVICES PTE LTD

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Friday, 23 March 2018 2:36 PM
To: assignments
Subject: FW: Acknowledgment Your ref : SKU7371S Our ref : S8M00BQNMTC/TE - KINDLY ARRANGE TAUFIKH (LKK) SURVEY

q.59am @ 26/3/18
vehicle in
person @ Wee Sin

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CYSAUTO [mailto:cysauto@singnet.com.sg]
Sent: Friday, 23 March 2018 2:26 PM
To: 'DHIWAR Namrata' <namrata.dhiwar@axa.com.sg>
Cc: Admin-B <admin-b@lkkauto.com>; earnest.tay@axa.com.sg
Subject: RE: Acknowledgment Your ref : SKU7371S Our ref : S8M00BQNMTC/TE - KINDLY ARRANGE TAUFIKH (LKK) SURVEY

Dear Mr Namrata Dhiwar,

WITHOUT PREJUDICE

We would like request Mr Taufikh (LKK Auto Consultants Pte Ltd) survey this car. Thanks

Dear Ms Katherine,

Kindly arrange TP survey at 38 Woodlands Industrial Park E1 #07-17 S(757700) Thanks

Warm regards,
Ms Tee Wee Sin



CYS AUTOMOBILE SERVICES PTE LTD
38 Woodlands Industrial Park E1 #07-17 S(757700)
Tel: 62192098 Fax: 62192096
Email: cysauto@singnet.com.sg

Namrata [mailto:namrata.dhiwar@axa.com.sg]
Sent: Friday, March 23, 2018 2:16 PM
To: CYS Auto, Woodlands <cysauto@singnet.com.sg>
Cc: TAY Ernest <ernest.tay@axa.com.sg>
Subject: Acknowledgment Your ref : SKU7371S Our ref : S8M00BQNMTC/TE

From: DHIWAR

Dear Sir

Without Prejudice

We want to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list below to conduct the joint pre-repair survey as a single joint expert.

List of our motor surveyors:-

1. Mohd Fadhilah Bin Osman (LBS Automotive Appraisal Pte Ltd)
2. Derek Oh Siong Wee (LBS Automotive Appraisal Pte Ltd)
3. Mohd Noh Bin Sapoh/ Stan See Chee Seng (LBS Automotive Appraisal Pte Ltd)
4. Ricky Teng/ Elgene Teng (RT Appraisal Pte Ltd)
5. Michael Chong (RT Appraisal Pte Ltd)
6. Elson Teng (RT Appraisal Pte Ltd)
7. Simon Ho/ Mohammed Rasul (LKK Auto Consultants Pte Ltd)
8. Ma Chin Fook/ Adrian Ling/ Chua Weijie (LKK Auto Consultants Pte Ltd)
9. Kenneth Kong/ Marcus Chua/ Hendry Ng (LKK Auto Consultants Pte Ltd)
10. Gerard Favacho (A-PAC Investigation Solutions Pte Ltd)

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert. Meanwhile, please furnish us with estimate quotation in order for our surveyor to complete the pre repair survey.

If there be any injury claims by your client, please combine it in one Letter of Demand in light of one cause of action, save as to costs and expenses.

Please send your reply to the in-charge claim handler who is copied in this email.

Regards,
Namrata Dhiwar

From: CYS Auto, Woodlands [<mailto:cysauto@singnet.com.sg>]
Sent: Friday, March 23, 2018 1:37 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Subject: ARRANGE FOR THIRD PARTY SURVEY FOR SKU7371S

Dear Officer ,

ACCIDENT INVOLVING SKU7371S & SBZ1333Y ON 22.MAR.18

Kindly arrange for a third party survey for my client's vehicle number SKU7371S against your insured SBZ1333Y.

I've attached the GIA report and the ESTIMATE for your reference.

Vehicle is in 38, WOODLANDS INDUSTRIAL PARK E1 #07-17 (S) 757700

Kindly also let me have the 10 surveyor firm list to choose from.

Thanks.

Regards,
Esther Lim
CYS AUTOMOBILE SERVICES PTE LTD
TEL: 62192098
FAX: 62192096

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Singapore - Externals or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

Ma C.F (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Friday, 6 April, 2018 1:18 PM
To: cysauto@singnet.com.sg; Ma C.F (LKKAuto); Vivian Lau (LKKAuto)
Cc: Admin A; assignments
Subject: FW: FINALISATION & PHOTOS FOR SKU73715
Attachments: ALIGNMENT.pdf; FINALISATION.tif; PHOTO 1.jpg; PHOTO 2.jpg; PHOTO 3.jpg; PHOTO 4.jpg; PHOTO 5.jpg; AFTER REPAIR PHOTO 1.jpg; AFTER REPAIR PHOTO 2.jpg; AFTER REPAIR PHOTO 3.jpg; AFTER REPAIR PHOTO 4.jpg; AFTER REPAIR PHOTO 5.jpg; AFTER REPAIR PHOTO 6.jpg; AFTER REPAIR PHOTO 7.jpg; AFTER REPAIR PHOTO 8.jpg

Dear Ms Tan,

Thank you for your email.

Dear Mr Ma / Vivian,

FYNA. Our Ref: CC4/ASM18005621/M1wa3

Subject insur's approval.

*12/5/2018 1pm Confirmed LE \$5,150.00 with Dee Sin.
but subject to insurance approval.
She said OK and update her once
insurance approved.*

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CYSAUTO [<mailto:cysauto@singnet.com.sg>]

Sent: Friday, 6 April, 2018 12:04 PM

To: admin-d@lkkauto.com

Subject: FINALISATION & PHOTOS FOR SKU73715

Dear Mr Ma, **WITHOUT PREJUDICE**

Attached herewith estimate and photos for your attention.

We have calculate the repair cost at \$5,150 based on lump sum.

Kindly confirm. Thanks and look forward for your reply.

Warm regards,
Ms Tee Wee Sin



CYS AUTOMOBILE SERVICES PTE LTD

38 Woodlands Industrial Park E1 #07-17 S(757700)

Tel: 62192098 Fax: 62192096

Email: cysauto@singnet.com.sg

⏪ **Re:RE: Re:S8M00BQN- Mandate approval**

Type

🔔 Question

Message

Hi, pls proceed as per mandate. TY.

Reply

CYS AUTOMOBILE SERVICES PTE LTD

38 Woodlands Industrial Park East 1
#07-17 Admiralty Industrial Park
Singapore 757700
Tel: 62192098 (3 lines) Fax: 62192096
E-mail address: cysauto@singnet.com.sg

Our Ref : SKU7371S
Your Ref : S8M00BQNM/TE

26 April 2019

IMMEDIATE ATTENTION
BY EMAIL ONLY

AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811
Attn: Motor Claims Department

Dear Ms,

ACCIDENT INVOLVING SKU7371S AND SBZ1333Y ALONG TOH YI DRIVE ON 22 MARCH 2018

We act for Mr Hyuyen Thi Hoe, the owner of vehicle registration no. SKU7371S.

We are instructed by the abovenamed to claim damages against you in connection with a road traffic accident on 22 March 2019 at 4.30pm along Toh Yi Drive involving our client's vehicle registration number SKU7371S and vehicle registration number SBZ1333Y driven by your insured /insured's authorized driver at the material time.

We are instructed that the accident was caused by your insured /insured's authorized driver negligence driving and/or management of your vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

Cost of Repairs	\$ 5,510.50
Rental Charges (11 days × S\$150.00)	\$ 1,650.00
GIA/ LTA Search Fees	\$ 2.00
TOTAL	<u>\$ 7,162.50</u>

Our Ref : SKU7371S
Your Ref : S8M00BQNMC/TE
Date : 26 April 2019


2

We enclose herewith a copy each of the following documents for your attention:

1. CYS Automobile Services Pte Ltd's Tax invoice no. 7798 for the sum of S\$5,510.50;
2. CYS Car Rental Pte Ltd's Rental Agreement no 3305 for the sum of \$1,980.00;
3. GIA/ LTA Search Fees on vehicle no SBZ1333Y dated 22 March 2018 with tax invoice for the sum of \$2.00;
4. Authorization to Act; and
5. Discharge Voucher;

Please acknowledge receipt and let us have your reply within Seven days (7) days of your receipt of this letter.

Yours Sincerely,
CYS AUTOMOBILE SERVICES PTE LTD


Tee Wee Sinn
Secretary



24 May 2018

MAK YIN HENG
BLK 20 TEBAN GARDENS ROAD,
#26-99,
Singapore 600020

Dear Sir/ Mdm

OUR REF : CC4/ASM18005621/M1wa3
YOUR REF : SBZ 1333Y

**ACCIDENT INVOLVING SBZ 1333Y & SKU 7371S ALONG TOH YI DRIVE ON
22/03/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **CYS Automobile Services Pte Ltd** acting on behalf of the owner of SKU 7371S against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to Vivianlau@lkkauto.com within 7 days if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us 6841 8625 or email us at Vivianlau@lkkauto.com

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c. AXA Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT

I, Nguyen Thi Huu ("the third party claimant") of 20 Sturdee Road #12-05 Terrisdau S(27452) (address), owner of SKU73715 (vehicle no.) hereby authorize CYS AUTOMOBILE SERVICES PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SKU73715 that was damaged pursuant to the accident which occurred on 22.3.18 (date) along Tan Yi Drive (location) involving vehicle no/s SBZ1333Y ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 27 (day) of 03 (month) 2018 (year)

x 
Signed by "the third party claimant"
(with company stamp if applicable)


 遠東威汽車服務私人有限公司
CYS Automobile Services Pte Ltd
38 Woodlands Industrial Park East 1
#07-13 Admiralty Industrial Park
Singapore 757200
Signed by [Signature] on 22.3.18
(with company stamp)



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SBZ 1333Y (Insd veh)	Model:
	SKU 7371S (TP veh)	
Date of Accident/ Time:	22/03/2018	

Repair Estimate	: \$	10,312.23	
Final Repair Cost	: \$	5,510.50	
Loss of Use	: \$		days at \$ per day
Rental (if any)	: \$	1,690.00	11 days at \$ 150.00 per day
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$		
	: \$		
Final Settlement Sum	: \$	7,182.50	

Payee Name : CYS AUTOMOBILE SERVICES PTE LTD

Is Third Party Workshop GIA Registered? [] YES [x] NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability: 100 (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
	BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		

Remarks:

NOTE:


- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / Invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

 进友成汽车服务私人有限公司
 CYS Automobile Services Pte Ltd
 Signature of authorised representative / Workshop stamp
 Name of Representative: Admiralty Industrial Park East 1
 Date: Singapore 757700
 Tel: 6219 2098 (3lines) Fax: 6219 2096

 进友成汽车服务私人有限公司
 CYS Automobile Services Pte Ltd
 Signature of Witness / Workshop stamp (if applicable)
 Name of Witness: Admiralty Industrial Park East 1
 Date: Singapore 757700
 Tel: 6219 2098 (3lines) Fax: 6219 2096

MCF
 Signature of AXA's surveyor/representative:
 Name of AXA's surveyor /Representative:
 Date:





進友成汽車服務私人有限公司

CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

TAX INVOICE

Invoice No

7798

M/S AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
ATTN: MOTOR CLAIMS DEPT.

POLICY NO : THIRD PARTY CLAIM
OUR REF : TP 5883
VEHICLE NO : SKU 7371 S
MAKE/MODEL : HONDA ODYSSEY
DATE OF ACCIDENT : 22-Mar-18
DATE : 26-Apr-19


SURVEY BY

TO AGREE AT THE SUM AT

	S\$	5,150.00
GST 7%		360.50
	<u>S\$</u>	<u>5,510.50</u>

SIN DOLLARS: FIVE THOUSAND FIVE HUNDRED TEN AND CENTS FIFTY ONLY

YOURS FAITHFULLY,


FOR CYS AUTOMOBILE SERVICES PTE LTD

CYS CAR RENTAL PTE LTD

BLK 5 DEFU LANE 10 DEFU INDUSTRIAL PARK C
 #01-582 HOUGANG AVE 3 SINGAPORE 539186
 TEL: 6287 0750 H/P: 9752 1101
 BUSINESS REG. NO: 201205697K

NO: 3305

RENTAL AGREEMENT							
Hirer Nguyen Thi Hoa			Car Regn No. SLS 408R		Make & Model T. Camry		
Address 30 Sturdee Road #13-05			OUT		IN	Expected Return	
Kerrisdale Spwa 207852			Date	23/3/18	3. 4.18		
Occupation	Office	Home Phone	Time	11:10am	10.40-11		
Driving Licence No.	Date of Expiry	Place of Issue	Form of Payment	Cash	Cheque	Credit Card	
NRIC/Passport No. B8594261	Date of Birth	Place of Issue	Deposit		Prepayment		
Driver Kuar Hock Ching			Hour		@5		
Address Blk 17 Tan Y: Drive			11 Day \$		@5 180	1980	
#12-73 Spwa 590017			Week		@5		
Occupation	Office	Home Phone 96274270	Month		@5		
Driving Licence No. S2512839G	Date of Expiry	Place of Issue	By initialing Hirer agrees to pay additional fee for Collision Damage Waiver (CDW)			Rental Charge	
NRIC/Passport No. S2512839G	Date of Birth 1.6.1946	Place of Issue Spwa				Delivery Fee	
Important Notes 1. This rental Vehicle is used within Singapore only. 2. Hirer is liable to pay first \$ 2500.00 under section I & II in any accident plus loss of earnings while damaged vehicle is under repair. 3. When vehicle returns, it must be in a clean condition or \$ 20.00 will be charged 4. No Insurance Coverage if the driver is below 25 yrs old or less than 2 years driving licence 5. For Usage to Malaysia subject to higher excess all claims of S\$5,000.00 and different rental rate. 6. Please notify our office should there be any accident involving this hired vehicle within 24 hrs 7. No refund will be given for petrol left in vehicle. 8. Hirer is liable to pay all parking fee and traffic summonses. 9. Vehicles to be return during office hour only						Collection Fee	
			Sub Total				
			Per Day				
			Total Charge			1980	
E	DO MM YY	Cash	Receipt No	DD MM YY	Cash	Receipt No	Amount Due / Refund
X							
T							
Remarks			I Hereby acknowledged receipt of the sum of \$ _____ being refund due to me as computed above.				

I have read and agree to the terms and conditions on both sides of this agreement if I have presented a charge or credit card for payment. All amount payable under this agreement and for parking and traffic infringement may be billed to the charge or credit card and my signature below will be considered to have been made on this charge or credit card voucher.

Signed by the parties here to on the _____ day of _____

Hirer's Signature : _____

 CYS CAR RENTAL PTE LTD



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
 6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-044199
 Date of Request: 23/03/2018

Your Ref No: Online Purchase

CYS Automobile Services Pte Ltd
 38 Woodlands Industrial Park East 1
 #07-17, Admiralty Industrial Park
 Singapore 757700

Dear Sir/Madam,

Enquiry Date: 23/03/2018
 Enquiry By: LIM XING SU, ESTHER
 TP Vehicle No.: SBZ1333Y
 Accident Date: 22/03/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SBZ1333Y	AXA Insurance Pte Ltd	11/05/2017-10/05/2018	6338 7288
SBZ1333Y	Etiqa Insurance Pte Ltd	09/11/2017-10/11/2018	63360477
SBZ1333Y	AXA Insurance Pte Ltd	05/12/2017-04/12/2018	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-044199
Date of Request: 23/03/2018

Your Ref No: Online Purchase

CYS Automobile Services Pte Ltd
38 Woodlands Industrial Park East 1
#07-17, Admiralty Industrial Park
Singapore 757700

Dear Sir/Madam,

Enquiry Date 23/03/2018
Enquiry By LIM XING SU, ESTHER
TP Vehicle No. SBZ1333Y
Accident Date 22/03/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO Cash Cheque

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18005621/M1wa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:RICHARD ANG

Date : 07-06-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SBZ 1333Y	Veh. Inspected	SKU 7371S
Policy No.	GA303032	Coverage (\$)	0.00
Claim No.	S8M00BQN	Excess (\$)	0.00
Assign From		Assign Date	26/03/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA ODYSSEY	c.c	2356
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JHMRC1890FC202052	Colour	SILVER
Odometer	45466	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	FALKEN	8 mm
L/H Front Tyre	215/55 R17	FALKEN	8 mm
R/H Rear Tyre	215/55 R17	FALKEN	8 mm
L/H Rear Tyre	215/55 R17	FALKEN	8 mm

4. Description of DamagesTHE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.**5. General Information**

Accident Date	22/03/2018	Inspection Date	27/03/2018
Survey held at	CYS AUTOMOBILE SERVICES PTE LTD 38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700		

5a. RemarksA)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 7371S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER SIDE RETAINER L/H (CONSISTENT)	SERVICEABLE	33.70	-
1	FRONT FENDER R/H (CONSISTENT)	DENTED	637.80	637.80
1	FRONT FENDER INNER SHIELD L/H (CONSISTENT)	DISTORTED	219.50	219.50
1	FRONT DOOR L/H (CONSISTENT)	TO REPAIR SEE LABOUR	977.70	-
2	FRONT DOOR HINGE L/H @\$72.10 (CONSISTENT)	SERVICEABLE	144.20	-
1	FRONT DOOR LOWER GARNISH L/H (CONSISTENT)	SERVICEABLE	421.90	-
1	REAR SLIDING DOOR L/H (CONSISTENT)	TO REPAIR SEE LABOUR	1,080.90	-
1	REAR SLIDING DOOR LOWER GARNISH L/H (CONSISTENT)	CUT	407.60	407.60
1	REAR SLIDING DOOR WEATHERSTRIP L/H (CONSISTENT)	NOT NECESSARY	571.30	-
1	FRONT RIM L/H (CONSISTENT)	CUT	997.00	997.00
1	REAR RIM L/H (CONSISTENT)	CUT	997.00	997.00
1	FRONT ABSORBER L/H (CONSISTENT)	DISTORTED	434.60	434.60
1	FRONT LOWER ARM L/H (CONSISTENT)	DISTORTED	723.90	723.90
1	FRONT KNUCKLE ARM L/H (CONSISTENT)	DISTORTED	418.50	418.50
1	FRONT KNUCKLE ARM BEARING L/H (CONSISTENT)	NECESSARY	281.40	281.40
	LESS 20% DISCOUNT		-1,669.40	-1,023.46
			6,677.60	4,093.84
SPECIAL NETT ITEMS				
10	FRONT FENDER INNER SHIELD CLIPS @\$3.00 (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
			30.00	-
LABOUR				
	TO DO COMPUTER WHEEL ALIGNMENT.		150.00	80.00
	TO DISMANTLE UNDER CARRIAGE.		200.00	180.00
	TO TRANSFER SLIDING DOOR .	NOT NECESSARY	180.00	-
	TO TRANSFER DOOR .	NOT NECESSARY	100.00	-
	TO APPLY RUST PROOFING ON REPAIRED /REPLACED PANELS.		150.00	60.00

Report Ref No. CC4/ASM18005621/M1wa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING FUNCTION.		50.00	30.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF FRONT DOOR L/H.		600.00	600.00
	TO PUTTY AND SPRAY PAINTING CHARGES.		1,500.00	1,400.00
			2,930.00	2,350.00
	GRAND TOTAL		9,637.60	6,443.84
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,150.00

Report Ref No. CC4/ASM18005621/M1wa3q2

MA CHIN FOOK

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	SIM0080QN
Reference	CC4/ASM18009621/M1wa3q2
Loss Date	22 March 2018
Report Date	23 Mar 2018 1:59:46 PM
Request Date	21 August 2018
Due Date	
Vendor Name	L&K AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step: Wait for Approve Invoice

Add Process

Vehicle Information	
Incident Vehicle Registration #	SKU73715
Make	TPVD HONDA
Model	ODYSSEY 2.4 (A)
Service Address	
BLK 20 TEBAN GARDENS ROAD, . . . 600020	
Primary Contact/Insured	
MAK YIN HENG BLK 20 TEBAN GARDENS ROAD, #26-199, 600020, Singapore	
pl@mlk.usg	
Claim Handler	
ANG Richard richard_ang@lka.com.sg	

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type

[Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
L&KInvoice 1 (7).pdf	Invoice	Surveyor/ Assessor expense	L&K AUTO CONSULTANTS PTE LTD (TP)	7 June 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
PAYMENT BREAKDOWN_LKK.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	7 June 2019
LKKInspection (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	7 June 2019
LKKAdjustment3a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	7 June 2019
PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	7 June 2019
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	7 June 2019
WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	7 June 2019
Immediate Advice- SKU 73715.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	24 April 2019
YOM4.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	24 April 2019
Letter Op.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	24 April 2019
GIA SEARCH.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 October 2018
RENTAL.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 October 2018
Immediate Advice- SKU 73715.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 October 2018
LKK Recovery Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 October 2018
LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 October 2018

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
■ Preliminary Advice.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	4 April 2018
■ TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	4 April 2018
■ SBZ1333Y - Video 3 - Accident.MP4	Evidence	Videos	TAY Ernest	26 March 2018
■ SBZ1333Y - Video 2 - Accident.MP4	Evidence	Videos	TAY Ernest	26 March 2018
■ SBZ1333Y - Video 1 - Accident.MP4	Evidence	Videos	TAY Ernest	26 March 2018
■ SBZ1333Y / INSD.PDF	Reports & Statement	GIA Report	TAY Ernest	26 March 2018
■ TP SELECT LKK.pdf	Letters and Correspondence	Workshop	TAY Ernest	26 March 2018
■ EMAIL RECEIVED FROM WORKSHOP WITH GIA REPORT AND ESTIMATE.mig	Forms / Claim Documents	Estimate / Quotation	DH(WAR Namuda	22 March 2018