

CC6/1117021132 (Anaz) 2-1

LKK
IDAC

INS CASE OWNER: NATALIE

CC6/1117021132 1 Anaz

Surveyor: ADRIAN

ASSIGNMENT
DOI: 03/11/17

Date/Time: 03/11/17
Registered in Merimen: 06/11/17

Pre-assign / CCU / FTE



Insured Vehicle No: SHC 2344C
Name of Insured: CTPL
Insured Tel No: _____ HP: _____
Excess Sec II : \$5 _____ DOA: 01/11/17
Is driver the owner? (YES ☒ / NO) Nature of Accident: _____
If NO, Driver Name / Age: CHAM WAI HENG
Driver Tel No: _____ (VAL ☒ / NO)

Claim No.: MU17110021
Policy No.: ML000016
Make / Model: HYUNDAI SONATA
Place of Accident: BUKIT TEMAN ROAD TWO'S JUNG KECIL
OI GIA REPORT ☒ YES / NO : TP GIA REPORT ☒ YES / NO
Insured Liability: % Final ? Yes / No

SDU 111E



INSRS:
WSP: Hua meng
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:




INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

07/11/17 (Thurs)

SDU 111E - X
SHC 2344C - 19/10/17 (CC6/1117021132/1117021132)



02 completely chang lane and TP chang into 02 lane.

RECEIVED 03 APR 2018

RECEIVED 14 JAN 2018

STAGE	DATE / PIC	
Non-Reporting ltr (1st)		
Non-Reporting ltr (2nd)		
Non-Reporting ltr (Final)		
Notification ltr (if non-pickup)		
Call OI		
After call ltr to OI		
Documentation Check List:	Handler	Typist
Notification ltr (if non-pickup)	<input type="checkbox"/>	<input type="checkbox"/>
After call ltr to OI	<input type="checkbox"/>	<input type="checkbox"/>
Authorization To Act	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Release Voucher	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Final Repair Bill	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Car Rental Invoice	<input type="checkbox"/>	<input type="checkbox"/>
Towing Invoice	<input type="checkbox"/>	<input type="checkbox"/>
LTA / GIA	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Medical Bill	<input type="checkbox"/>	<input type="checkbox"/>
PIB	<input type="checkbox"/>	<input type="checkbox"/>
Mandate/Reject Instruction:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
LOD	<input type="checkbox"/>	<input type="checkbox"/>
Payment Breakdown Form:	<input type="checkbox"/>	<input type="checkbox"/>
Post-Repair Photos	<input type="checkbox"/>	<input type="checkbox"/>
Others:	<input type="checkbox"/>	<input type="checkbox"/>

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	\$5	(days) Reduction:	%
FINAL SETTLEMENT		Date/Time: <u>6/11/18</u>	Confirm with: <u>JUNIE</u>
Final Liability:	% <u>50</u>	(Agreed / Assessed) BOLA S/N No:	<u>NIL</u>
Repair Cost: (3500.00)	\$5 <u>6750.00</u>		
Loss of Rental (LOR):	\$5 (days)		
Loss of Use (LOU): (1000.00)	\$5 <u>500.00</u> (\$100 x 10 days)		
Loss of Income (LOI):	\$5 (5 x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search	\$5 <u>5.35</u>		
Medical	\$5		
Disbursement	\$5	(e.g. Tow / Independent)	
Legal Cost	\$5		
Total:	\$5 <u>7255.35</u>	Global Sum \$5:	<u>7250.00</u>
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	\$5 <u>7250.00</u>	Name 1:	<u>HUA MENG SPRAY PAINTING WORKSHOP</u>
Payee 2: (Strike if N.A.)	\$5	Name 2:	
Payee 3: (Strike if N.A.)	\$5	Name 3:	

Confirm by: Email ☐ Call ☐
If NO or B 28, Asa Lia:
1) Claim status: Normal ☒ Reject Private Settle
2) Report Format:
3) Survey fee: \$450.
Charge balance - \$150.00
Email ☐ Call ☐

COPY SENT 16/11/18

COPY SENT

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of _____
 Insured _____
 Policy No _____
 Claims No _____
 Sum Insured _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? Yes or No
 GIA / PR Seen: _____ Consistent? Yes or No
 Est. Repairs: 9 days Res: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDU111E Yr Regn: 2011, Nov
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A6 cc 2995
 Colour: White A/C Insured / Std / NI / NA
 Sp. Reading: 63979 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/55R17
225/55R17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

Rear

R/Bal:

R/Bal:

L/Bal:

L/Bal:

D.O.A.

D.O.I.

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 111

LIS - \$ 13500+ (Red: \$ 23479.70)

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ - RE \$

) Photo

) Other

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

MSME17145102 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 02/11/2017 17:13

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 02/11/2017 17:13
Date Of Accident 01/11/2017 19:45
Exact Location Of Accident BUKIT TIMAH ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SDU111E
Insured/Policyholder
Name Of Registered Owner Hianto Dharmaputra Sunardy
NRIC No S2741185A
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-90300330
Alternative Phone No OFFICE-90300330
Vehicle Particulars
Manufacturer AUDI
Model A6
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5090709000
Cover Note Number
Driver
Name of Driver Hianto Dharmaputra Sunardy
NRIC No S2741185A
Date Of Birth 03/01/1960
Occupation INDOOR
Date Of Driving Pass 24/07/2002
Driving Experience 15 YEARS AND 3 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-90300330
Fax Number
Contact Number OFFICE-90300330
E-Mail Address NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/11/2017 09:52
Date Of Accident	01/11/2017 19:45
Exact Location Of Accident	BUKIT TIMAH ROAD TWDS JURONG KECHIL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC3344C
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	TAXI


Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0016
Cover Note Number	

Driver

Name of Driver	CHAM WAI HENG
NRIC No	S1591058E
Date Of Birth	14/11/1963
Occupation	OUTDOOR
Date Of Driving Pass	12/10/1988
Driving Experience	29 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19/11/2017 at about 1945 hrs, I vehicle A was driving along Bukit Timah road toward Jurong Road on the extreme right lane. As a car in front of me is making a right turn I was follow him behind, then I try to shift to middle lane. Suddenly, vehicle B came from my left and brush against my left front portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

2/11/17 Jackson
Jackson Hong
CSO

COMFORT TRANSPORTATION PTE LTD

POLICY NO 19939382-1R

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

10/11/2017 19:45

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

HIANTO DHARMAPUTRA SUNARDY
6 ASH GROVE
S 289787

Date :22.11.2017
Vehicle no :SDU 111 E
Make/Model :AUDI A6
Accident date :01.11.2017

No	Description	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear bumper <i>total</i>	1	\$ 2267.1 ✓
2	Rear bumper side holder @ \$47.30 <i>RM 100</i>	2	\$ 94.6 <i>47.30</i>
3	Rear bumper clips (1set) <i>RM</i>	1	\$ 195.8 <i>30</i>
4	Rear RH fender <i>Repair</i>	1	\$ 2816 <i>x</i>
5	Rear RH fender quarter glass rubber <i>3 items</i>	1	\$ 232.1 <i>x</i>
6	Rear RH fender quarter glass moulding	1	\$ 232.1 <i>x</i>
7	Rear RH door <i>Dented</i>	1	\$ 3612.4 <i>2950</i>
8	Rear RH door inner lock <i>RM</i>	1	\$ 654.5 <i>x</i>
9	Rear RH door top hinge <i>3 items</i>	1	\$ 97.9 <i>x</i>
10	Rear RH door lower hinge	1	\$ 97.9 <i>x</i>
11	Rear RH door stopper	1	\$ 107.8 <i>x</i>
12	Rear RH door inner weather strip <i>RM</i>	1	\$ 221.1 <i>x</i>
13	Rear RH door inner outer weather strip <i>RM</i>	1	\$ 205.7 <i>x</i>
14	Rear RH door inner board <i>RM</i>	1	\$ 2940.3 <i>x</i>
15	Rear RH door power window motor <i>3 items</i>	1	\$ 348.7 <i>x</i>
16	Rear RH door power window regulator	1	\$ 437.8 <i>x</i>
17	Rear RH door glass outer moulding	1	\$ 253 <i>x</i>
18	Front RH door <i>Dented</i>	1	\$ 3612.4 <i>2950</i>
19	Front RH door inner lock <i>Dented</i>	1	\$ 485.1 <i>x</i>
20	Front RH door top hinge <i>3 items</i>	1	\$ 97.9 <i>x</i>
21	Front RH door lower hinge	1	\$ 97.9 <i>x</i>
22	Front RH door stopper	1	\$ 107.8 <i>x</i>
23	Front RH door inner weather strip <i>RM</i>	1	\$ 221.1 <i>x</i>
24	Front RH door inner outer weather strip <i>RM</i>	1	\$ 205.7 <i>x</i>
25	Front RH door inner lower rubber <i>RM</i>	1	\$ 166.1 <i>x</i>
26	Front RH door inner board <i>Coated</i>	1	\$ 2829.2 <i>2760</i>
27	Front RH door power window motor <i>3 items</i>	1	\$ 337.7 <i>x</i>
28	Front RH door power window regulator	1	\$ 437.8 <i>x</i>
29	Front RH door glass outer moulding <i>RM</i>	1	\$ 305.8 <i>x</i>
30	RH rocker panel garnish <i>2 items</i>	1	\$ 781 <i>x</i>
31	RH door centre pillar <i>2 items</i>	1	\$ 3006.3 <i>x</i>
32	Rear RH stay bar <i>2 items</i>	1	\$ 147.4 <i>x</i>

27654

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

HIANTO DHARMAPUTRA SUNARDY
6 ASH GROVE
S 289787

Date :22.11.2017
Vehicle no :SDU 111 E
Make/Model :AUDI A6
Accident date :01.11.2017

No	Description	Qty	Amount (\$\$)
33	Rear RH knuckle arm <i>Det</i>	1 <i>141594</i>	\$ 1380.5 <i>929</i>
34	Rear RH knuckle arm bearing <i>m</i>	1 <i>1961143</i>	\$ 739.2 <i>235</i>
		Total	\$ 29773.7

Special Nett Items

1	Rear RH sport rim <i>Det</i>	1 <i>970</i>	\$ 1776 <i>720</i>
2	Rear RH tyre <i>Det</i>	1	\$ 480 <i>250</i>
		Total	\$ 2256

Labour Cost

1 Remove & reinstall rear RH suspension	\$ 350 220
2 Remove & reinstall door glass filler	\$ 250 160
3 Remove & reinstall petrol tank	\$ 200 x
4 Remove & reinstall boot lid inner garnish	\$ 200 x
5 Remove & reinstall reverse sensor	\$ 150 60
6 Remove ,replace & repair consistent to the accident	\$ 1800 800
7 Respray painting	\$ 1600 1100
8 Tuff kote	\$ 150 40
9 To check wheel alignment	\$ 150 80
10 To reset	\$ 100 x
Total	\$ 4950
Grand Total	\$ 36979.7

LEK Auto Consultants hence notify the Repairer of the following:

- Repairs to be carried out by spray painting
- Third party liability claim during survey
- Parts provided are subject to recommendations
- Third party survey must be "Without Prejudice" basis
- No large modifications to be allowed
- Supplementary work must be authorised and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 1621143
2/5 13.5K
19 Days

Print Received Message

This mail is associated with :

***SDU111E (MCT117110021)
[SHC3344C]**

TP

HIANTO DHARMAPUTRA SUNARDY
Nov 1 2017 7:00PM
[COMFORT TRANSPORTATION PTE LTD]
Hua Meng Spray Painting Workshop

From India International Insurance Pte Ltd (HQ) (IIL_SG), sent on 29/03/2018 15:34 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$7255.35) - SDU111E - Claim Handler: NATALIE LEE

Approved: 7255.35.



華明噴漆廠
HUA MENG SPRAY PAINTING WORKSHOP
AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883
Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680
Reg. No.: 254678/00M



Your Ref : SHC 3344 C

Our Ref : SDU 111 E

Date: 01.02.2018

Attn: Motor Claims Dept

**ACCIDENT ON 01.11.2017 INVOLVING VEHICLE SDU 111 E & SHC 3344 C ALONG
BUKIT TIMAH ROAD**

With regards to the above, we are writing on behalf of the registered owner of vehicle SDU 111 E which was involved in the above mentioned accident.

We are informed that the above accident was caused solely by the negligence of your insured vehicle SHC 3344 C. As a result of the accident, our client's vehicle was damaged and our client had instructed us to submit his claims for loss and expenses, particulars of which are follows:

1) Repair cost	\$	13,500.00
2) Loss of use-200 X 10days (INCLUDED WEEKEND)	\$	2000.00
3) LTA search	\$	5.35
Total	\$	15,505.35

We hereby enclosed herewith the following documents for your consideration of the above claim.

a) Final Repair Bill Of SDU 111 E

c) LTA SEARCH

b) GIA report

d) Owner / Driver NRIC & Driving License

華明噴漆廠
HUA MENG SPRAY PAINTING WORKSH
AUTOBAY@KAKI BUKIT
KAKI BUKIT AVE 6 #01-34 SINGAPORE 4178
TEL: 6747 8064, 6746 5519 FAX: 6743 4896

Yours faithfully,

HUA MENG SPRAY PAINTING WORKSHOP


AUTHORISATION TO ACT


I/We, Hianto Dhamaputra Sunandy ("the third party claimant") of
6 Ash Grove, S(289787) (address),
owner of SDU111E (vehicle no.) hereby authorise **HUA MENG SPRAY PAINTING**
WORKSHOP ("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SDU111E that was damaged pursuant
to the accident which occurred on 01.11.2017 (date) along BUKIT TIMAH ROAD
(location) involving vehicle no/s SHC3344C ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem
fit and the workshop is further authorized to receive payment further to settlement of my claim
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 2 (day) of NOV (month) 20 17 (year)


Signed by "the third party claimant"
(with company stamp if applicable)


Signed by "the workshop"
(with company stamp)

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

WITHOUT PREJUDICE
TO OUR CLIENTS PERSONAL LIABILITY
CLAIM (PRESENT OR FUTURE) WHICH IS
EXPRESSLY RESERVED

India Ref: MCT17110021
Claimant Ref: SDU111E

We/I, Hua Meng Spray Painting Workshop ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 7,250.00 (Global Sum), S\$ -- (loss of use/rental), S\$ -- (search fee), vehicle no. SDU 111E that was damaged pursuant to the accident which occurred on 01/11/2017 (date) at BUKIT TIMAH ROAD (location) involving vehicle no. SHC 3344C (insured vehicle). This is pursuant to the inspection conducted on 03/11/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner HIANTO DHARMAPUTRA SUNARDY ("the third party claimant") of vehicle no. SDU111E to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SDU 111E (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 7,250.00 to Hua Meng Spray Painting Workshop.

Dated this 06 day of April 2018

CLAIMANT:

Signature:



Signed by "the workshop" (with chop)

Name:

June Koh

NRIC:

G0848282W

Address:

新明噴漆廠

HUA MENG SPRAY PAINTING WORKSHOP
MOTOBAYOKARI BUKIT

Nationality:

1 KUALA LUMPUR 50114 SINGAPORE 417685

Occupation:

TEL: 6747 8064 6746 5519 FAX: 6743 4898

WITNESS:

Signature:



Lup

Signed by appointed Surveyor

Name:

LKK Auto Consultants Pte Ltd

NRIC:

199607198R

Address:

Blk 51, Paya Ubi Industrial Park,
Ubi Avenue 1, #02-25 | S(408933)

Nationality:

-

Occupation:

-



華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883
Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680

Reg. No.: 254678/00M



Your Ref : SHC 3344C

Our Ref : SDU 111E

Date: 31/1/2018

VEHICLE NO :SDU 111 E
MAKE / MODEL :AUDI A6
NAME :HIANTO DHARMAPUTRA SUNARDY
ADDRESS :6 ASH GROVE
S 289787

FINAL REPAIR BILL FOR VEHICLE NO:SDU 111 E

TO SUPPLY AND REPLACE PARTS, LABOUR CHARGES FOR
REPAIRING, KNOCKING, WELDING AND TO RESPRAY PAINTING
(LUMP SUM REPAIR)

\$ 13,500.00

SINGAPORE DOLLARS:THIRTEEN THOUSAND AND FIVE HUNDRED ONLY



DAWN ENTERPRISES

21 SELETAR WEST FARMWAY 1

SINGAPORE 798125

TEL: 6383 2661 FAX: 6484 2836

REG. NO. 430058/000

No. 18938

OFFICIAL RECEIPT

Date, 11/11/17

Received from

Hanto Dharma Putra Sunardy

the sum of Dollars

One thousand eight hundred only

being Payment Of

SSP SAFIL (2/11/17 - 11/11/17)

DAWN ENTERPRISES

\$

1800/-

Cash/Cheque No.



DAWN ENTERPRISES

21 Seletar West Farmway 1
Singapore 798125
Tel: 63832661 Fax: 64842836
Reg No.430058/00D

Nº 34249

SDULLIE

RENTAL AGREEMENT

DATE 02.11.2017

HIRER'S PARTICULARS

Name Hianto Sharmaputra Sunandy

Address 6 Ash Grove . S (289787)

I/C or Passport No. S2741185A Country SG

Occupation _____

Date of Birth 03-01-1960 Age _____

Driving Licence No. _____ Date Passed _____

Tel: (HP) _____ (Residence) 9030 0330

DRIVER'S PARTICULARS

Name _____

Address _____

I/C or Passport No. _____ Country _____

Occupation _____

Date of Birth _____ Age _____

Driving Licence No. _____ Date Passed _____

Tel: (Office) _____ (Residence) _____

IMPORTANT NOTES:

1. No insurance coverage if the driver is below 24 yrs old or less than 2 years driving licence.
2. This vehicle is licensed to carry 2000 passengers only.
3. Hirer is liable to pay first \$ 2000 as excess all claims any accident plus loss of earning while damaged vehicle is under repair.
4. For usage to Malaysia subject to higher excess all claims of \$55,000.00 and different rental rate.
5. Please notify our office should there be any accident involving this hired vehicle within 24 hrs.
6. No refund will be given for vehicle returns early.
7. No refund will be given for petrol left in vehicle.
8. Hirer is liable to pay all parking fee and traffic summonses.
9. Vehicles to be return during office hour only.
10. No Service on Public Holiday and Sunday.

CHARGES

9 Day at \$ <u>200.00</u> per days	\$ <u>1800.00</u>
Day at \$ _____ per week	
Day at \$ _____ per month	

TOTAL AMOUNT

\$ 1800.00

AMOUNT PAID

\$ 1800.00

BALANCE DUE

Days Extension From _____ To _____

Amount Deposit (refundable) \$ _____

SCHEDULE

MODEL

SJP 5971L

T/Carry

Date	Time	Mileage
<u>2-11-2017</u>	<u>1710 hrs</u>	
<u>11/11/17</u>		

FROM

2/11/17

TO

11/11/17

I/we have read and understood the terms and conditions above and hereby agreed to abide

Hirer's Signature

Driver/Gurantor's Signature

DAWN ENTERPRISES



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 03 Nov 2017 / 11:34:39

Receipt Date/Time : 03 Nov 2017 / 11:34:39

Tax Invoice/Receipt

Receipt No. : ITNET-00000-171103-000692

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHC3344C				
As at 01 Nov 2017/19:45:00				
Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - SHC3344C Enquiry Fee 20171103113354791317	5.00	0.35	5.35
Sub-Total		5.00	0.35	5.35
Total Before Rounding		5.00	0.35	5.35
Rounding Difference				0.00
Total Amount Payable				5.35
Paid By				
	20171103113403568	Direct Debit: eNETS Debit (Internet Banking)		5.35
Total				5.35
Cash Change				0.00
Tendered Amount				5.35
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING



















































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Nov 2017 Edit Reg		03 Nov 2017 00:00 Edit Adj Rpt	S\$13,500.00 Edit Estimates	S\$13,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	HIANTO DHARMAPUTRA SUNARDY , ID: 52741185A								
Vehicle Reg. No.:	SDU111E	Date of Loss:	01/11/2017 19:00 - :59 [71 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT17110021	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SHC3344C	Policy No. (Claimant):	5090709000						
		Excess:							
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by NATALIE LEE - 63476100 ext 243]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 29/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (29/03/2018): Alert - Adj Mandate Approved (S\$7255.35) - SDU111E - Claim Handler: NATALIE LEE III_SG (15/12/2017): Alert - Adj Mandate Approved (S\$0.00) - SDU111E - Claim Handler: NATALIE LEE III_SG (14/11/2017): Alert - Adj Mandate Approved (S\$0.00) - SDU111E - Claim Handler: NATALIE LEE 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDU111E (MCT17110021)**
[SHC3344C]
TP
HIANTO DHARMAPUTRA SUNARDY
Nov 1 2017 7:00PM
[COMFORT TRANSPORTATION PTE LTD]
Hua Meng Spray Painting Workshop

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	India International Insurance Pte Ltd (HQ)						Thumbnail	Print	
1	14/11/17 15:29	Video - Accident					1	Load MP4		
Letters/Correspondences							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	26/01/18 09:21	Insurer Offer Letter/DV [Offer superseded on 2018/03/27]					1	Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
2	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
3	09/01/18 14:59	Chassis Number					1	Load JPG	<input checked="" type="checkbox"/>	
4	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
5	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
6	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
7	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
8	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
9	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
10	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
11	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
12	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
13	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
14	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
15	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
16	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
17	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
18	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
19	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
20	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
21	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
22	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
23	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
24	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
25	09/01/18 14:59	General View					1	Load JPG	<input checked="" type="checkbox"/>	
26	09/01/18 14:59	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>	
27	09/01/18 14:59	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>	
28	09/01/18 14:59	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>	
29	09/01/18 14:59	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>	
30	09/01/18 14:59	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
31	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	09/01/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	09/01/18 15:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	09/01/18 15:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	09/01/18 15:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	09/01/18 15:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	09/01/18 15:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	09/01/18 15:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	09/01/18 15:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	09/01/18 15:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	09/01/18 15:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	09/01/18 15:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/11/17 14:38	TP GIA REPORT	Load PDF	
2	15/01/18 18:31	email to TP	Load PDF	
3	28/02/18 13:50	SMS from OID	Load JPG	<input checked="" type="checkbox"/>
4	28/02/18 13:50	SMS from OID	Load JPG	<input checked="" type="checkbox"/>
5	27/03/18 15:50	LOD	Load PDF	
6	11/04/18 14:55	WORKSHOP INVOICE	Load PDF	
7	11/04/18 14:55	AUTHORISATION TO ACT FORM	Load PDF	
8	11/04/18 14:55	DISCHARGE VOUCHER	Load PDF	
9	11/04/18 14:55	RENTAL RECEIPT	Load PDF	
10	11/04/18 14:55	LTA SEARCH	Load PDF	
11	11/04/18 14:55	LOD	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	06/11/17 15:44	Singapore Accident Statement-IV	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III17021132/AUA3Q2-1

Date: 11/04/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SDU111E

Insured Vehicle No : SHC3344C

Date of Loss: 01/11/2017

Nature of Claim: TP

Claim No: MCT17110021

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDU111E

Make & Model: AUDI A6, 3.0 (A)

Engine No: CGW017675

Reg. Date: 03/11/2011 (Man. Year: 2011)

Chassis No: WAUZZZ4G0CN017748

Colour: White

Odometer: 63979 km

Engine Capacity: 2995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R12

Rear Tyre Size: 225/55 R12

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,029.70	14,421.43	17,608.27	54.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,950.00	2,460.00	2,490.00	50.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,979.70	16,881.43	20,098.27	54.35
Approved Total (Overridden) (S\$)		13,500.00		
Nett Amount (S\$)	36,979.70	13,500.00	23,479.70	63.49
+ Loss of Use (10.0 x S\$100.00/day) (S\$)		1,000.00		
		14,500.00		
Liable Amount (50.00%) (S\$)		7,250.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		7,255.35		
Global Sum Settlement (S\$)		7,250.00		

INSPECTION

Date of Assignment: 03/11/2017

Date Inspected: 03/11/2017 Inspected At:

Hua Meng Spray Painting Workshop (HQ)
No 1 Kaki Bukit Avenue 6, #01-61
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Jan 2018)
Parts: 143	AUDI A6 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SDU111E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	2,267.10 F	*2,267.10 FL
2	1		*REAR BUMPER SIDE HOLDER	O/S Necessary	94.60 F	*47.30 FL
3	1		*SET REAR BUMPER CLIPS	Necessary	195.80 F	*30.00 FL
4	1		*REAR RH FENDER	Repair	2,816.00 F	*- FL
5	1		*REAR RH FENDER QUARTER GLASS RUBBER	Not Necessary	232.10 F	*- FL
6	1		*REAR RH FENDER QUARTER GLASS MOULDING	Not Necessary	232.10 F	*- FL
7	1		*REAR RH DOOR	Dented	3,612.40 F	*2,950.00 FL
8	1		*REAR RH DOOR INNER LOCK	Not Necessary	654.50 F	*- FL
9	1		*REAR RH DOOR TOP HINGE	Not Necessary	97.90 F	*- FL
10	1		*REAR RH DOOR LOWER HINGE	Not Necessary	97.90 F	*- FL
11	1		*REAR RH DOOR STOPPER	Not Necessary	107.80 F	*- FL
12	1		*REAR RH DOOR INNER WEATHER STRIP	Not Necessary	221.10 F	*- FL
13	1		*REAR RH DOOR INNER OUTER WEATHER STRIP	Necessary	205.70 F	*205.70 FL
14	1		*REAR RH DOOR INNER BOARD	Not Necessary	2,940.30 F	*- FL
15	1		*REAR RH DOOR POWER WINDOW MOTOR	Not Necessary	348.70 F	*- FL
16	1		*REAR RH DOOR POWER WINDOW REGULATOR	Not Necessary	437.80 F	*- FL
17	1		*REAR RH DOOR GLASS OUTER MOULDING	Not Necessary	253.00 F	*- FL
18	1		*FRONT RH DOOR	Dented	3,612.40 F	*2,950.00 FL
19	1		*FRONT RH DOOR INNER LOCK	Damaged	485.10 F	*485.10 FL
20	1		*FRONT RH DOOR TOP HINGE	Not Necessary	97.90 F	*- FL
21	1		*FRONT RH DOOR LOWER HINGE	Not Necessary	97.90 F	*- FL
22	1		*FRONT RH DOOR STOPPER	Not Necessary	107.80 F	*- FL
23	1		*FRONT RH DOOR INNER WEATHER STRIP	Not Necessary	221.10 F	*- FL
24	1		*FRONT RH DOOR INNER OUTER WEATHER STRIP	Necessary	205.70 F	*205.70 FL
25	1		*FRONT RH DOOR INNER LOWER RUBBER	Necessary	166.10 F	*166.10 FL
26	1		*FRONT RH DOOR INNER BOARD	Cracked	2,829.20 F	*2,760.00 FL
27	1		*FRONT RH DOOR POWER WINDOW MOTOR	Not Necessary	337.70 F	*- FL
28	1		*FRONT RH DOOR POWER WINDOW REGULATOR	Not Necessary	437.80 F	*- FL
29	1		*FRONT RH DOOR GLASS OUTER MOULDING	Not Necessary	305.80 F	*- FL
30	1		*RH ROCKER PANEL GARNISH	Deformed	781.00 F	*781.00 FL
31	1		*RH DOOR CENTRE PILLAR	Repair	3,006.30 F	*- FL
32	1		*REAR RH STAY BAR	Bent	147.40 F	*147.40 FL
33	1		*REAR RH KNUCKLE ARM	Damaged	1,380.50 F	*929.00 FL
34	1		*REAR RH KNUCKLE ARM BEARING	Necessary	739.20 F	*235.00 FL
35	1		*REAR RH SPORT RIM	Cut	1,776.00 FS	*720.00 FS
36	1		*REAR RH TYRE	Cut	480.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **32,029.70** **15,129.40**

- List Item Discount on L Items 0.00/5.00% (\$\$) **0.00** **707.97**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					32,029.70	14,421.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REINSTALL REAR RH SUSPENSION	New	350.00	220.00
2	REMOVE & REINSTALL DOOR FITTINGS	New	250.00	160.00
3	REMOVE & REINSTALL PETROL TANK	New	200.00	0.00
4	REMOVE & REINSTALL BOOT LID INNER GARNISH	New	200.00	0.00
5	REMOVE & REINSTALL REVERSE SENSOR	New	150.00	60.00
6	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,800.00	800.00
7	RESPRAY PAINTING	New	1,600.00	1,100.00
8	TUFF KOTE	New	150.00	40.00
9	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
10	TO RESET	New	100.00	0.00
Gross Labour Cost (S\$)			4,950.00	2,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >