

Zan

REF: AU

2466E

COC EXPIRY: 2018/24

ASSIGNMENT

From: Date: 04/04/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJH 747T

at Workshop m/s

Charm's Customcraft

of

Blk 1010 Bukit Merah Lane 3 # 01-105

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

9am - 12pm

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

8K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SJH 747T

Yr Regn: 2008 / Suny

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru IMPREZA 1.5

C.C

1498

Colour:

BLACK

A/C:

Insured / Std / NI / NA

Sp. Reading

177294

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JF1GH3KW48G018116

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Morder / Jammed / Leaked / Burnt or

Brake: Morder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

23/03/18

D.O.I.

04/04/18

Survey held at

Charm's Customcraft

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rgn

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

refer to email

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)