

REF:

NS/INC18005691 / Stbn2

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: YJ 9797BPolicy No. 5089653935 01042017Claims No. MT10986904-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

<input type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No. SMB 1550R Yr Regn: 20/11/2014Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Man NL320F c.c. 10518Colour Mute Colour A/C: Insured / Std / NI / NASp. Reading 305591 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WMAA 2226 XE 7002555

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nif / S/Rim / STD A/Rim orTyre Size: F: 275 / 70R225

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Firestone

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6/6 mmL/Bal. 6 mm L/Bal. 6/6 mmD.O.A. 17/3/18 D.O.I. 26/3/18Survey held at SMART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SMB 1550R - XYJ 9797B - NA/INC18005157 / 64DOA: 17/03/2018lump sum \$1100 (Red: 518 : 32%)

RECEIVED 6 APR 2018

Date/Time File Pass to?  : Preli. Report9/4 Typist  : Final Report

Date/Time File Return to?

Days Of Repair: 1Resurvey No. of Trip: 1

Survey Fee: \_\_\_\_\_

Transportation \_\_\_\_\_

) \$ + RS. \$)

: Photos \_\_\_\_\_

: Others \_\_\_\_\_

TOTAL

160Report Format : TPLump Sum / I.B.I. (\$) 1100Add Fee:  Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18005691/Stb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 27-03-2018

189556



Code: INC4

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YJ 9797B	Veh. Inspected	SMB 1530R
Policy No.	5089653935	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/03/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	19/03/2018	Inspection Date	26/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Hello, NAC\_PAYA\_UBI\_800601

Change Language Change Password Log Out

Policy Query

Policy No.  Date of Accident   
Vehicle No.(For Motor)

Search

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5089653935	THE NEW CHARIS MISSION	T06550166B	GFT	Comprehensive	YJ9797B	YJ9797B	01/04/2017	

Continue

## Denise Tay (LKKAuto)

---

**From:** mtreg <mtreg@income.com.sg>  
**Sent:** Monday, 9 April 2018 9:30 AM  
**To:** Denise Tay (LKKAuto)  
**Subject:** FW: REQUEST CLAIM NUMBER

Hi,

Claim created.

With Regards

Samsia  
Senior Admin Assistant, Motor Insurance  
[www.income.com.sg](http://www.income.com.sg)



---

**From:** Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]  
**Sent:** Friday, April 06, 2018 4:03 PM  
**To:** mtreg <mtreg@income.com.sg>  
**Subject:** REQUEST CLAIM NUMBER

### TP Claims against NTUC Income: Follow-Through Survey

Date : 6/4/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant V
1	MT/0986904-002	SMRT BUSES LTD	SMB 1

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/03/2018 19:35
Date Of Accident	19/03/2018 09:50
Exact Location Of Accident	CHANGI RD AFTER BS: 82049 (JOO CHIAT CPLX)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB1530R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

### Vehicle Particulars

Manufacturer	MAN
Model	MAN A22
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-17087563MFBP
Cover Note Number	

### Driver

Name of Driver	SOON HOCK MING
NRIC No	S2628919Z
Date Of Birth	10/02/1963
Occupation	OUTDOOR
Date Of Driving Pass	04/04/1988
Driving Experience	29 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address NOADDRESS

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 18

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

At the stated date and time while travelling straight along Changi Road, after BS: 82049 (Joo Chiat Cplx), suddenly the bus right mirror was hit by the left body of a lorry (YJ977B). The lorry wanted to filter left to enter the small road ahead.

#### Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? YES

Remarks/ Reasons: PENDING DOWNLOAD

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YJ9797B

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver C V SHANGAR

NRIC/Passport Number S1810060F

Contact Number 91310166

Address

Postcode

Insurance Company Name NTUC INCOME INSURANCE CO-OPERATIVE LTD

Nature Of Damage

No. Of Passenger (Including Driver) 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report accurately the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false statements may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the CA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and true copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
  - I understand, acknowledge, agree and consent that:
    - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
      - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
      - (ii) investigating the accident and/or my claims;
      - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
      - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelop/postal packages); and/or
      - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
    - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
    - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be based outside of Singapore, for one or more of the above Purposes.

Sketch Plan Pg. 1

Policyholder's Signature / Date & Time \_\_\_\_\_  
 Driver's Signature (if driver is not the policyholder) / Date & Time \_\_\_\_\_  
 Witnessed by Receiving Centre Personnel \_\_\_\_\_

20 MAR 2018

① 87661530 E  
 ② Y197976

Sketch Plan

Bus Stop 82049

Changi Road after Bus Stop 82049



## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Owner ID:

### Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended De-registration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

### Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

### Intended COE Rebate Details

COE Rebate Amount:

Total Rebate Amount:

Company

2292D

SMB1530R

No

27 Mar 2018

MAN

NL 320F (A22) 11L AUTO ABS TURBO

Multi-Colour

2014

50338510443851

WMAA22ZZXE7002335

-

\$254,851.00

20 Nov 2014

20 Nov 2014

0

\$0.00

No

-

\$0.00

\$0.00

\$0.00


The information contained herein is correct as at 27 Mar 2018

OK

## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1530R  
Ref. No : BUS/03/18/5020  
Reg. Date : 20/11/2014  
Vehicle Type : BUS -12M  
Make : MAN  
Model : MAN  
Name of Driver : Soon Hock Ming  
Type of Accident : SIDE SWIPE  
Date / Time of Accident : 19/03/2018 09:48:00 AM  
Accident Reported Date / Time : 20/03/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : IDAC  
Vehicle is Towed Back? : No  
Towed Back Date/Time : 01/01/2000  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024095134  
Special Instruction to ARC, if any :  
SMB1530R - RIGHT FRONT PORTION  
YJ9797B (TP) - INSURED WITH NTUC  
Prepared Date : 20/03/2018 07:41:33 PM



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : Mileage : 0  
 Work Shop : Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,060.00	0.00
Total Spray Painting Charges	: 0.00	0.00
Total Material Charges	: 954.68	974.16
Other Charges	: 0.00	0.00
<b>TOTAL</b>	<b>: 954.68</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 2.00	-0.00
Prepared / Adjusted By	: Sim Kim Bock	1 Day
Arc / Surveyor Sing Off Date	: 01/01/1900 12:00:00 AM	01/01/1900 12:00:00 AM


Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/03/2018 04:21:47 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : Invoice No :  
 Quotation Date : Invoice Date :  
 Invoice Amount : Prepared Date :



**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
		6011409	MIRROR,VIEW:FRONT,RH,MAN A22 'C' SERIES	1	1,353.00	10.00	1,217.70	Replace	Replace	No <i>✓ DMG</i>
<b>TOTAL MATERIALS</b>							<b>1,217.70</b>	<b>1,217.70</b>		
<b>TOTAL MATERIALS(Discounted)</b>							<b>954.68</b>	<b>974.16</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**


Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : Mileage : 0  
Work Shop : Repair Completed Date / Time : 01/01/2000

**Summary of Repair Estimates**

	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
Total Labour Charges	: 265.00	132.50
Total Spray Painting Charges	: 0.00	0.00
Total Material Charges	: 974.16	974.16
Other Charges	: 0.00	0.00
<b>TOTAL</b>	<b>: 1,239.16</b>	<b>1,106.66</b>
<b>Lum Sum Total</b>	<b>: 1,250.00</b>	<b>1,100.00</b>
No. of Repair Days	: 2.00	1.00
Prepared / Adjusted By	: Sim Kim Bock	Sebastian Yeang
Arc / Surveyor Sign Off Date	: 26/03/2018 02:31:59 PM	26/03/2018 02:33:25 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/03/2018 04:21:47 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : Invoice No :  
Quotation Date : Invoice Date :  
Invoice Amount : Prepared Date :

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	265.00	132.50
<b>Total Labour</b>	<b>265.00</b>	<b>132.50</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Spray Painting &amp; Panel Beating</b>		

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
		6011409	MIRROR,VIEW:FRONT,RH,MAN A22 'C' SERIES	1	1,353.00	10.00	1,217.70	Replace	Replace	No
<b>TOTAL MATERIALS</b>							<b>1,217.70</b>	<b>1,217.70</b>		
<b>TOTAL MATERIALS(Discounted)</b>							<b>974.16</b>	<b>974.16</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check	
<b>TOTAL SUPPLEMENTARY MATERIALS</b>										

1217.70  
 + 132.50  
 -----  
 1350.20  
 - 20%  
 -----  
 1080.16  
  
 L/S : \$1100

Sebastian  
 27/3/18



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18005691/Stbn2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556	Date: 10-04-2018
	Code: INC4



### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YJ 9797B	Veh. Inspected	SMB 1530R
Policy No.	5089653935	Coverage (\$)	0.00
Claim No.	MT/0986904-002	Excess (\$)	0.00
Assign From		Assign Date	26/03/2018

### 2. Vehicle Particulars & Condition

Make & Model	MAN NL 320F	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WMAA22ZZXE7002335	Colour	MULTI
Odometer	305591	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	FIRENZA	6 mm
L/H Front Tyre	275/70 R22.5	FIRENZA	6 mm
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	6/6 mm
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	6/6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	19/03/2018	Inspection Date	26/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
-------------------------------------	----------------



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 1530R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	MIRROR,VIEW;FRONT,RH,MAN A22 "C" SERIES LESS 10% DISCOUNT	DAMAGED	1,353.00	1,353.00
			-	-135.30
			1,353.00	1,217.70
<b>LABOUR</b>				
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHER DAMAGED AFFECTED AREAS.		265.00	132.50
			265.00	132.50
<b>GRAND TOTAL</b>			<b>1,618.00</b>	<b>1,350.20</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,100.00</b>

Report Ref No. NS/INC18005691/Stbn2

YEANG WAI KEEN  
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.