

ASS. REC BY

REP: CS3/CTI 18005723/R1/d3

varlye x days

Survivor
Menimen

Rasul

ASSIGNMENT (Office)

From (Person): Jowyn Tay

of CTI

Date/Time: 27/3/18 @ 10:44am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBK 9313G

Insured: SCR 2255M

at Workshop m/s Ahfook Motor Com LLP

Tel: 6250 3384

of 5 Soon Lee Street # 01-15

Policy No: DMPCSN3025831703

Claim No: SNM18D01536C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 2/103/2018

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time: 9:20am 28/3/18

Person Contacted: Ivy

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	FBK9313G - X
	SCR2255M - CSI / AXA08027587 / Ach XX
	Dismantle: 6/4/2018
	After repair: 12/4/2018.

D.O.A: 19/8/17

Signature: *[Handwritten Signature]*

REF: CTI

ASSIGNMENT

From: _____ Date: **28/3/18**

Estimated Cost: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **FBK 9313G**

at Workshop m/s **Ahfook Motor Com 4P**

of **5 Soon Lee Street # 01-15**

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record) **Ivy 06250 3384**

Make of Veh: _____

Veh No: **FBK 9313G** Yr Regn: **05 / 12**

Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: **Yamaha FZ16** c.c. **153**

Colour: **RED** A/C: Insured / Std / NI / NA

Sp. Reading: **-** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **ME121C072C 2032327**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: **110/70-17**
R: **140/70-17**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **4** days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **'wp'**

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front		Rear	
R/Bal. 3	mm	R/Bal. 4	mm
L/Bal. _____	mm	L/Bal. _____	mm
D.O.A. 21/03/18		D.O.I. 28/03/18	
Survey held at Ahfook Motor			
Des. of Damages : Frt / Rear / O/S / N/S / UIC / Rooftop or N/S Frt & o/s			
The UIC / Chassis frame / Body Structure affected due to collision.			

Date / Time Action / Instruction

Estimated repair range \$3,500 - \$5,000

[Signature]
18/6/2018

RECEIVED 19 JUN 2018

Date/Time File Pass to? : Preli. Report

1) : Final Report

Date/Time File Return to? _____

2) _____

Report Format : **PRS**

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: **4**

Resurvey No. of Trip: **2**

Survey Fee: **150**

Transportation _____

3) \$ - RS \$ _____

4) Photos _____

5) Others _____

6) _____

TOTAL **150**

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Mar 2018		27 Mar 2018 10:44 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ONG KIM WHA, ID: S2505362A		
Main Claimant:	MUHAMMAD SANIWAHYUDI BIN ADI GUNARTO, ID: S9033481F		
Vehicle Reg. No.:	FBK9313G	Date of Loss:	21/03/2018 18:00 - :59
Claim Type:	TP / SNM18D01536C02	Policy/Cover Note No.:	DMPCSN3025831703 (Comprehensive)
Vehicle Reg. No. (Insured):	SCR2255M	Policy No. (Claimant):	5079047078-01
		Excess:	S\$0.00
Repairer:	Ahfookmotor.com LLP (HQ) 5 Soon Lee Street, #01-15 Pioneer Point, 627607 Jurong West - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/04/2018]		
Driver/Custodian (Insured):	ONG KIM WHA (60 / Male), NRIC: S2505362A		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



RIAZ
L.L.C
ADVOCATES AND SOLICITORS
COMMISSIONER FOR OATHS

ACRA NUMBER : 200911678H

GST REGISTRATION NUMBER : 200911678H

26/03/2018

Our Ref: FBK 9313G (V) AHFOOK

Your Ref: SCR 2255M

RIAZ QAYYUM (LLB HONS) NUS
(DIRECTOR)

TAN KOK SIANG (LLB HONS) LON
(ASSOCIATE)

TO: China Taiping Insurance Co. (Singapore) Pte Ltd
3 Anson Road
#16-00, Springleaf Tower
Singapore 079909
Attn: Motor Claims Department

ABDUL HALIM BIN ROSALAN (LLB HONS) UTAS
(ASSOCIATE)

MUHD RIDHWAN (LLB HONS) LEEDS
(ASSOCIATE)

NOTICE OF ACCIDENT

Dear Sir

We are instructed by our client to *notify* you of a road traffic accident on 21 March 2018 at about 1805 hours along Syed Alwi Road involving our client's vehicle registration number FBK 9313G and vehicle registration number SCR 2255M driven by you or your authorized driver at the material time. A copy of Singapore accident statement / traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop : Ahfookmotor.com LLP

Address : 5 Soon Lee Street
#01-15 Pioneer Point
Singapore 627607

Telephone no. : 6250 3384 Fax No. 6250 6393

Yours faithfully

Riaz

cc Client

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor
(Name & signature)

Date & time of inspection



> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No.:	FBK9313G		
Vehicle Type:	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Normal		
Vehicle Make:	YAMAHA		
Vehicle Model:	FZ 16		
Chassis No.:	ME121C072C2032327		
Propellant:	Petrol		
Engine No.:	21C7031791		
Engine Capacity:	153 cc		
Maximum Power Output:	-		
Maximum Laden Weight:	330 kg		
Unladen Weight:	135 kg		
Year Of Manufacture:	2012		
Original Registration Date:	03 May 2012		
Lifespan Expiry Date:	-		
COE Category:	D - Motorcycle		
Quota Premium:	\$1,924.00		
COE Expiry Date:	02 May 2022		
Road Tax Expiry Date:	02 May 2019		
Inspection Due Date:	02 May 2019		
Intended Transfer Date:	18 Jun 2018		
CO2 Emission:	-		
CO Emission:	-		
HC Emission:	-		
NOx Emission:	-		
PM Emission:	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3481F
Vehicle Details	
Vehicle No.:	FBK9313G
Vehicle to be Exported:	No
Intended De-registration Date:	18 Jun 2018
Vehicle Make:	YAMAHA
Vehicle Model:	FZ 16
Primary Colour:	Red
Manufacturing Year:	2012
Engine No.:	21C7031791
Chassis No.:	ME121C072C2032327
Maximum Power Output:	-
Open Market Value:	\$2,220.00
Original Registration Date:	03 May 2012
First Registration Date:	03 May 2012
Transfer Count:	4
Actual ARF Paid:	\$333.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	02 May 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,924.00
COE Rebate Amount:	\$744.00
Total Rebate Amount:	\$744.00

The information contained herein is correct as at 18 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/03/2018 08:33
Date Of Accident	21/03/2018 18:05
Exact Location Of Accident	SYED ALWI ROAD / TOWNSHEND ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBK9313G
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD SANIWAHYUDI BIN ADI GUNARTO
NRIC No	S9033481F
Email Address	MUHAMMADSANIWAHYUDI@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-92220817
Alternative Phone No	Office-92220817

Vehicle Particulars

Manufacturer	YAMAHA
Model	FZ16-153CC (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5079047078-01
Cover Note Number	

Driver

Name of Driver	MUHAMMAD SANIWAHYUDI BIN ADI GUNARTO
NRIC No	S9033481F
Date Of Birth	15/09/1990
Occupation	INDOOR
Date Of Driving Pass	22/03/2016

Driving Experience	1 YEAR AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92220817
Fax Number	
Contact Number	OFFICE-92220817
E-Mail Address	MUHAMMADSANIWAHYUDI@HOTMAIL.COM
Address	BLK 821 JURONG WEST STREET 81 #04-490
Postcode	640821
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : IRA SURIA BINTI ILYAS Gender: : Female

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ROCHOR N.P.C. 11 KAMPONG KAPOR ROAD, SINGAPORE 208678
Police Station Address	ROAD: 11 KAMPONG KAPOR ROAD , POSTCODE: 208678 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

**Details of Witness 1**

Name NA
 Phone Number NA
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SCR2255M
 Vehicle Make/Model/Colour M/BENZ
 Details Of Properties RIGHT FRONT PORTION
 Vehicle Category PRIVATE CAR
 Name of Driver ONG KIM WHA
 NRIC/Passport Number S2505362A
 Contact Number 98188330
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name IRA SURIA
 Approximate Age
 Injuries Sustain REFER REPORT
 Injured person in which vehicle? FBK9313G
 Were seat belts worn? NO
 Was this injured conveyed to hospital by ambulance? YES
 Address HP 96665185
 Postcode

DETAILS OF INJURED PERSON 2

Name MUHAMMAD SANIWAHYUDI BIN ADI GUNARTO
 Approximate Age 27
 Injuries Sustain REFER REPORT
 Injured person in which vehicle? FBK9313G
 Were seat belts worn? NO
 Was this injured conveyed to hospital by ambulance?
 Address BLK 821 JURONG WEST STREET 81 #04-490
 Postcode 640821

SKETCH PLANIMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (if driver is not the policyholder)

 Reporting Centre Personnel's Signature
 Name: *Mark*


**SINGAPORE
POLICE FORCE**


T/20180321/2170

1 of 3

Police Station Of Origin:
Rochor N.P.C
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999

Report No. T/20180321/2170

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/03/2018 19:57	Vide Report No.: A/20180321/0099	Station Diary No.: 164
--	-------------------------------------	---------------------------

Informant's Particulars

Name of Informant: MUHAMMAD SANIWAHYUDI BIN ADI GUNARTO		Address: APT BLK 821 JURONG WEST STREET 81 #04-490 SINGAPORE 640821	
ID Type / ID No.: NRIC NO / S9033481F		Contact No.: Home/Office: Mobile: 92220617	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 27	Date of Birth: 15/09/1990	Type of Informant: Rider
Race: Javanese		Language: English	Institution / School Name:
Occupation: Customs/Immigration officer		Driving Licence Information: Class: 2B,2A,3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 21/03/2018 18:05	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 SYED ALWI ROAD TOWNSHEND ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBK9313G	Motorcycle	YAMAHA	FZ 16	Red	Seriously Damaged	1
SCR2255M	Car	MERCEDES BENZ	S300L	Brown	Slightly Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBK9313G	NTUC Income Insurance Co-Operative Limited	5079047078-01	03/05/2017	02/05/2018



**SINGAPORE
POLICE FORCE**



T/20180321/2170

2 of 3

Police Station Of Origin:
Rochor N.P.C
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999

Report No. T/20180321/2170

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MUHAMMAD SANIWAHYUDI BIN ADI GUNARTO	ID No.	S9033481F
Related Vehicle	NIL	Contact No.	92220617
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	ONG KIM WHA	ID No.	S2505362A
Related Vehicle	NIL	Contact No.	98188330
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

Earlier today at about 6.08pm, I was riding my motorcycle (FBK9313G) with my girlfriend (Ira Suria, hp: 96665185) as a pillion along Syed Alwi Rd towards Jln Besar, when we are about to reach the junction of Townshend Rd, suddenly one car (SCR2255M) drove out from Townshend Rd wanting to pass Syed Alwi Rd to the next part of Townshend Rd. However I was already near the junction and unable to brake or avoid in time as such collided into the car front right area.

My girlfriend and I then fell in front and my girlfriend sustained pain in her left ankle and was conveyed to TTSH, no injuries for myself for now. The driver came down and rendered assistance to us and we exchanged particulars. My motorcycle was then towed away to Ah Fook Motorcycle Pte Ltd located at 5 Soon Lee St. One witness approached me and sent me the video that he managed to capture.



**SINGAPORE
POLICE FORCE**



T/20180321/2170

Police Station Of Origin:
Rochor N.P.C
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999

3 of 3

Report No. T/20180321/2170

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: A / Sgt 2 LEE ZHENG BIAO	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 21/03/2018 19:57
Officer In Charge Of Case: TP / GIT / Staff Sgt MOHAMED SUFIAN BIN SUDIN Contact No.: 65476367	Classification Of Case:
Authentication Stamp NP168	

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Mar 2018		27 Mar 2018 10:44 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	ONG KIM WHA, ID: S2505362A								
Main Claimant:	MUHAMMAD SANIWAHYUDI BIN ADI GUNARTO, ID: S9033481F								
Vehicle Reg. No.:	FBK9313G	Date of Loss: 21/03/2018 18:00 - :59 [70 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / SNM18D01536C02	Policy/Cover Note No.: DMPCSN3025831703 (Comprehensive)							
Vehicle Reg. No. (Insured):	SCR2255M	Policy No. (Claimant): 5079047078-01							
		Excess: S\$0.00							
Repairer:	Ahfookmotor.com LLP (HQ) 5 Soon Lee Street, #01-15 Pioneer Point, 627607 Jurong West - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 06/04/2018]								
Driver/Custodian (Insured):	ONG KIM WHA (60 / Male), NRIC: S2505362A								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBK9313G (SNM18D01536C02)
[SCR2255M]

TP

MUHAMMAD SANIWAHYUDI BIN ADI GUNARTO

Mar 21 2018 6:00PM

[ONG KIM WHA]

Ahfookmotor.com LLP

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
Video										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)							Thumbnail	Print	
1	24/03/18 08:50	Video - Accident [Linked Accident Report Documents]						Load MP4			
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)							Thumbnail	Print	
1	24/03/18 08:56	Accident Statement						Load HTM			
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)							Thumbnail	Print	
1	24/03/18 08:46	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
2	24/03/18 08:46	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
3	24/03/18 08:46	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
4	24/03/18 08:46	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
5	24/03/18 08:46	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
6	24/03/18 08:46	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
7	24/03/18 08:46	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
8	24/03/18 08:46	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
9	24/03/18 08:46	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
10	24/03/18 08:46	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
11	24/03/18 08:46	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
12	24/03/18 08:46	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	18/06/18 17:00	General View						Load PDF			
2	18/06/18 17:00	Photographs of Damaged Parts						Load PDF			
3	18/06/18 17:01	Photo After Spray						Load PDF			
Documentation										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	27/03/18 10:43	PRS						Load PDF			
2	27/03/18 10:43	OI GIA REPORT						Load PDF			
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)							Thumbnail	Print	
1	24/03/18 08:49	Sketch Plan [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
2	24/03/18 08:49	Sketch Plan #2 [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
3	24/03/18 08:55	Common Statement [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
4	24/03/18 08:55	Common Statement [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
5	24/03/18 08:55	Common Statement [Linked Accident Report Documents]		<input checked="" type="checkbox"/>

Linked Accident Report Documents

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	24/03/18 08:50	Video - Accident		<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	24/03/18 08:56	Accident Statement		<input type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	24/03/18 08:46	Accident Photo		<input checked="" type="checkbox"/>
2	24/03/18 08:46	Accident Photo		<input checked="" type="checkbox"/>
3	24/03/18 08:46	Accident Photo		<input checked="" type="checkbox"/>
4	24/03/18 08:46	Accident Photo		<input checked="" type="checkbox"/>
5	24/03/18 08:46	Accident Photo		<input checked="" type="checkbox"/>
6	24/03/18 08:46	Accident Photo		<input checked="" type="checkbox"/>
7	24/03/18 08:46	Accident Photo		<input checked="" type="checkbox"/>
8	24/03/18 08:46	Accident Photo		<input checked="" type="checkbox"/>
9	24/03/18 08:46	Accident Photo		<input checked="" type="checkbox"/>
10	24/03/18 08:46	Accident Photo		<input checked="" type="checkbox"/>
11	24/03/18 08:46	Accident Photo		<input checked="" type="checkbox"/>
12	24/03/18 08:46	Accident Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	24/03/18 08:49	Sketch Plan		<input checked="" type="checkbox"/>
2	24/03/18 08:49	Sketch Plan #2		<input checked="" type="checkbox"/>
3	24/03/18 08:55	Common Statement		<input checked="" type="checkbox"/>
4	24/03/18 08:55	Common Statement		<input checked="" type="checkbox"/>
5	24/03/18 08:55	Common Statement		<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118005723/R1D3E2

Date: 20/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN3025831703
 Claimant Vehicle No: FBK9313G Insured Vehicle No: SCR2255M
 Date of Loss: 21/03/2018 Nature of Claim: TP Claim No: SNM18D01536C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBK9313G**
 Make & Model: YAMAHA FZ16, 153cc (M) Engine No: 21C7031791
 Reg. Date: 03/05/2012 (Man. Year: 2012) Chassis No: ME121C072C2032327
 Colour: Red Odometer: 0 km
 Engine Capacity: 153 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70-17 Rear Tyre Size: 140/70-17
 Front Left Side: Pirelli 3 mm Rear Left Side: Pirelli 4 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/03/2018
 Date Inspected: 28/03/2018 Inspected At: Ahfookmotor.com LLP (HQ)
 5 Soon Lee Street, #01-15 Pioneer Point
 Singapore 627607
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,800.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 20 Jun 2018)

Parts: N/A YAMAHA FZ16 153cc (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBK9313G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >