

2/10/2008

ASS. REC. BY

REF: CS3/MSG18005724/MD3^{sz}

Special Instruction

Range

Surveyor

Menimen

ASSIGNMENT (Office)

From (Person): Elaine Ngu

of MSLG

Date/Time: 27/3/18 @ 5:24pm

Estimated Cost:

Bill to

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: G1BF 5432Z

Insured: SFZ 880T

at Workshop m/s V-Tech Auto Service

Tel: 6264 6222

of No. 1 Soon Lee Street #06-04

Policy No: 28849438 QMX

Claim No: 553636

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 24/03/2018

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time: 9:26am @ 28/3/18

Person Contacted:

Ms. Chong

Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	G1BF 5432Z - X
	SFZ 880T - CB/AIG 04016152 / WZ1
	Dismantle: 5/4/2018
	After repair: 6/4/2018

D.O.A: 1/3/2006

PRS

REF: MSU7

ASSIGNMENT

From: _____ Date: 03042018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBF 54327

at Workshop m/s: V-Tech

of No. 1 Soon Lee St # 06-04

Insured: _____


Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBF 54327 Tr Regn: DEC, 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA Dyna. c.c 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp.Reading: 4665 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT35490K267008

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/75R15 BS
R: 155R12 FS

BS / DUN / EXNOVA / GY / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 7 mm Rear R/Bal. 8 mm

L/Bal. 7 mm L/Bal. 8 mm

D.O.A. 24/03/2018 D.O.I. 31/4/2018

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	No est upon survey 2500 1/2 - 3000 1/2

RECEIVED 26 APR 2018

Date/Time, File Pass to? : Prell. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: PRE

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: 2

Survey Fee: _____

Transportation: _____

Add Fee: Site Insp (\$ _____)

Interview (\$ _____)

Tech. Invs (\$ _____)

Weekend (\$ _____)

Photos _____

Others _____

TOTAL _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Mar 2018		27 Mar 2018 17:24 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHEUK YAN KIN BENJAMIN, ID: S7574815I		
Main Claimant:	EVERGRO TRADING, Co. Reg. No.: 53143264E		
Vehicle Reg. No.:	GBF5432Z	Date of Loss:	24/03/2018 15:00 - :59
Claim Type:	TP / 553636	Policy/Cover Note No.:	28849438QMX (Comprehensive) Coverage: 05/10/2017 - 04/10/2018
Vehicle Reg. No. (Insured):	SFZ880T	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	V Tech Auto Service (soon Lee) (HQ) NO.1 SOON LEE STREET, #06-04, PIONEER CENTRE, SINGAPORE 627605, 627605 Pioneer - Tel: 62646222		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/03/2018]		
Adj Asg. Remarks:	Workshop : V-Tech Auto Service Address : No. 1 Soon Lee Street, #06-04/05/06/07 Pioneer Centre, Singapore 627605 Contact : Ms. Chong (tel: 6264 6211 / 6264 6233)		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

See you
check

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/03/2018 14:47
Date Of Accident	24/03/2018 15:10
Exact Location Of Accident	ALONG WOODLANDS AVE 3 TWRS BKE- BFR JUNC WDL AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF5432Z
Insured/Policyholder	
Name Of Registered Owner	EVERGRO TRADING
Co Reg No	53143264E
Email Address	VIN15800@YAHOO.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-81123335
Vehicle Particulars	
Manufacturer	TOYOTA
Model	DYNA 150-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VCA/P2029178
Cover Note Number	
Driver	
Name of Driver	ANG ENG CHANG (HONG YONGCHANG)
NRIC No	S7120926A
Date Of Birth	24/06/1971
Occupation	INDOOR
Date Of Driving Pass	03/08/1989
Driving Experience	28 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81123335
Fax Number	
Contact Number	
EEmail Address	VIN15800@YAHOO.COM.SG

Address BLK 167 PETIR RD #13-142 SINAGPORE 670167
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SFZ880T
 Vehicle Make/Model/Colour TOYOTA /BLACK
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver BENJAMIN CHEUK YAN KIN
 NRIC/Passport Number S75748151
 Contact Number 97932732
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have Insured vehicle(s) involved in this accident (all Insurer(s) who have Insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have Insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




 PRO TRADING

 811 111

 811 3335

 811 111

 Policyholder's Signature
 Date & Time:




 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:



 Reporting Centre Personnel's Signature
 Name:
 NRIC/TIN No.:
 Toh Khar Kian

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24.3.2018 @ 15:00hrs, I was travelling along Woodlands Ave 3 towards BKE and my lorry stop behind a blue van before junction of Woodlands Ave 1 due to traffic lights were red. When the traffic lights turned green, all vehicles started to move. The blue van in front of me applied brake when we just moved a short distance. On seeing that, I also applied brake. The next moment, I felt a great impact coming from behind. I came down from my lorry and found motor car SFZ880T had collided into my lorry. Attached with video & photos for reference.

<p>Important: You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), there is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.</p>		- Reporting Only
		- Claim OD
		- Claim TP
	✓	- Claim OD/TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

INGRO TRADING
11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
Tel: 9112 2336

Policyholder's signature
Date & Time


Driver's Signature
(if driver not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name:
Nric/Fin No. Toh Khar Kian

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	3264E
Vehicle Details	
Vehicle No.:	GBF5432Z
Vehicle to be Exported:	No
Intended De-registration Date:	26 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1KD2655484
Chassis No.:	JTFAT35Y90K207008
Maximum Power Output:	-
Open Market Value:	\$24,946.00
Original Registration Date:	01 Dec 2016
First Registration Date:	01 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$1,248.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$44,149.00
COE Rebate Amount:	\$37,943.00
Total Rebate Amount:	\$37,943.00

The information contained herein is correct as at 26 Apr 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Mar 2018		27 Mar 2018 17:24 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHEUK YAN KIN BENJAMIN, ID: S75748151		
Main Claimant:	EVERGRO TRADING, Co. Reg. No.: 53143264E		
Vehicle Reg. No.:	GBF5432Z	Date of Loss:	24/03/2018 15:00 - :59 [15 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 553636	Policy/Cover Note No.:	28849438QMX (Comprehensive) Coverage: 05/10/2017 - 04/10/2018
Vehicle Reg. No. (Insured):	SFZ880T	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	V Tech Auto Service (soon Lee) (HQ) NO.1 SOON LEE STREET, #06-04, PIONEER CENTRE, SINGAPORE 627605, 627605 Pioneer - Tel: 62646222		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 28/03/2018]		
Adj Asg. Remarks:	Workshop : V-Tech Auto Service Address : No. 1 Soon Lee Street, #06-04/05/06/07 Pioneer Centre, Singapore 627605 Contact : Ms. Chong (tel: 6264 6211 / 6264 6233)		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBF5432Z (553636)**
[SFZ880T]
TP
EVERGRO TRADING
Mar 24 2018 3:00PM
[CHEUK YAN KIN BENJAMIN]
V Tech Auto Service (soon Lee)

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			View <input type="button" value="View in Browser"/>
Photos/Images			3 per page <input type="button" value="v"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="button" value="Print"/>
1	26/04/18 10:24	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
2	26/04/18 10:24	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
3	26/04/18 10:24	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
4	26/04/18 10:24	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
5	26/04/18 10:24	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
6	26/04/18 10:24	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
7	26/04/18 10:24	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
8	26/04/18 10:24	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
9	26/04/18 10:24	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
10	26/04/18 10:24	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
11	26/04/18 10:24	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
12	26/04/18 10:24	Photographs of Damaged Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
13	26/04/18 10:24	Photographs of Damaged Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
14	26/04/18 10:24	Photographs of Damaged Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
15	26/04/18 10:24	Photographs of Damaged Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
16	26/04/18 10:24	Photographs of Damaged Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
17	26/04/18 10:24	Photographs of Damaged Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
18	26/04/18 10:24	Photographs of Damaged Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
19	26/04/18 10:24	Photographs of Damaged Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
20	26/04/18 10:24	Photographs of Damaged Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
21	26/04/18 10:24	Photographs of Damaged Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
22	26/04/18 10:24	Photographs of Damaged Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
23	26/04/18 10:24	Photographs of Damaged Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
24	26/04/18 10:24	Photographs of Damaged Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
25	26/04/18 10:24	Photographs of Damaged Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
26	26/04/18 10:24	Photographs of Damaged Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
27	26/04/18 10:24	Photographs of Damaged Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
28	26/04/18 10:25	Photo After Spray	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
29	26/04/18 10:25	Photo After Spray	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
30	26/04/18 10:25	Photo After Spray	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
31	26/04/18 10:25	Photo After Spray	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
32	26/04/18 10:25	Photo After Spray	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
33	26/04/18 10:25	Photo After Spray	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
34	26/04/18 10:25	Photo After Spray	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
35	26/04/18 10:25	Photo After Spray	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	26/04/18 10:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
37	26/04/18 10:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
38	26/04/18 10:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/03/18 17:22	TPD GBF5432Z PRI & GIA REPORT.	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18005724/R1D3S2
Date: 26/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 28849438QMX
Claimant Vehicle No : GBF5432Z **Insured Vehicle No :** SFZ880T
Date of Loss: 24/03/2018 Nature of Claim: TP Claim No: 553636

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF5432Z**
Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2655484
Reg. Date: 01/12/2016 (Man. Year: 2016) Chassis No: JTFAT35Y90K207008
Colour: Silver Odometer: 46615 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75R15 Rear Tyre Size: 155 R12
Front Left Side: Bridgestone 7 mm Rear Left Side: Firestone 8 mm
Front Right Side: Bridgestone 7 mm Rear Right Side: Firestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/03/2018
Date Inspected: 03/04/2018 Inspected At: V Tech Auto Service (soon Lee) (HQ)
NO.1 SOON LEE STREET, #06-04, PIONEER
CENTRE, SINGAPORE 627605
Singapore 627605
Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/26/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 26 Apr 2018)

Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBF5432Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >