

CC 3/CTI1800 5725, F2ub302

LKK:  
IDAC:

INS. CASE OWNER:

Surveyor:

Falin

DOI:

ASSIGNMENT

77/7/18

Date / Time:

14/7/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

PC 43084

Name of Insured:

BT TAN TRANSPORT PTE LTD

Insured Tel No.:

HP:

Excess Sec II : \$

D.O.A.:

20/7/18

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age: HU JIN

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SHL 897T



INSRS:

WSP:

Tel:

Liability:

RMKS:

WUE  
W

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

DATE / PIC

14/7/18

SHL 897T - X

PC 43084 - Y

TH

20/8/18

Spoke to PIC @ 93229966, informed TP claim and he agreed to settle.

RECEIVED 21 SEP 2018

STAGE

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$

(\$

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100%

(Agreed / Assessed) BOLA S/N No.:

N/A

If NO or B 28, Ass. Lia:

Repair Cost:

\$

4815.00

Loss of Rental (LOR):

\$

839.00

(\$

5 days)

x 167.80

Loss of Use (LOU):

\$

250.00

(\$

50 x 5 days)

Loss of Income (LOI):

\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$

2.00

Medical:

\$

Disbursement:

\$

(e.g. Tow/ Independent)

Legal Cost

\$

Total:

\$

5906.00

Global Sum \$:

5900.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$

5900.00

Name 1:

COMFORTDELGRO ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

\$

Name 2:

Payee 3: (Strike if N.A.)

\$

Name 3:

COPY SENT  
20/8/18





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                          |                 |                             |                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------|-----------------|-----------------------------|-------------------------------------------------------------------------------------|
| CHINA TAIPING INSURANCE (S) PTE LTD                                                                                                       |                                                                          |                 | Ref : CC3/CTI18005725/K1ub3 |                                                                                     |
| 3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERS SINGAPORE 079909                                                                                 |                                                                          |                 | Date : 28-03-2018           |  |
|                                                                                                                                           |                                                                          |                 | Code : CTI                  |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                          |                 |                             |                                                                                     |
| Insured Veh.                                                                                                                              | PC 4308G                                                                 | Veh. Inspected  | SHC 897T                    |                                                                                     |
| Policy No.                                                                                                                                |                                                                          | Coverage (\$)   | 0.00                        |                                                                                     |
| Claim No.                                                                                                                                 |                                                                          | Excess (\$)     | 0.00                        |                                                                                     |
| Assign From                                                                                                                               |                                                                          | Assign Date     | 28/03/2018                  |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                          |                 |                             |                                                                                     |
| Make & Model                                                                                                                              |                                                                          | c.c             | 0                           |                                                                                     |
| Engine No.                                                                                                                                | HIDDEN                                                                   | Year of Reg.    |                             |                                                                                     |
| Chassis No.                                                                                                                               |                                                                          | Colour          |                             |                                                                                     |
| Odometer                                                                                                                                  | -                                                                        | Steering        |                             |                                                                                     |
| Brakes                                                                                                                                    |                                                                          | Modification    |                             |                                                                                     |
| General                                                                                                                                   |                                                                          |                 |                             |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                          |                 |                             |                                                                                     |
|                                                                                                                                           | Size                                                                     | Make            | Balance                     |                                                                                     |
| R/H Front Tyre                                                                                                                            |                                                                          |                 | mm                          |                                                                                     |
| L/H Front Tyre                                                                                                                            |                                                                          |                 | mm                          |                                                                                     |
| R/H Rear Tyre                                                                                                                             |                                                                          |                 | mm                          |                                                                                     |
| L/H Rear Tyre                                                                                                                             |                                                                          |                 | mm                          |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                          |                                                                          |                 |                             |                                                                                     |
|                                                                                                                                           |                                                                          |                 |                             |                                                                                     |
| <b>5. General Information</b>                                                                                                             |                                                                          |                 |                             |                                                                                     |
| Accident Date                                                                                                                             | 26/03/2018                                                               | Inspection Date | 27/03/2018                  |                                                                                     |
| Survey held at                                                                                                                            | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |                 |                             |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                        |                                                                          |                 |                             |                                                                                     |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                          |                 |                             |                                                                                     |



Auto  
Consultants  
Pte Ltd

Company Registration No: 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC3/CTI18005725/K1ub3

Date: 28.03.2018

The Motor Claims Department  
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHC897T**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27.03.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

|                          |       |          |
|--------------------------|-------|----------|
| Workshop Estimate Amount | : S\$ | 7,924.52 |
| Revised Estimate Amount  | : S\$ | 5,652.52 |
| "Check" Items Amount     | : S\$ | 1,732.00 |
| Market Value             | : S\$ | -        |
| LTA Reimbursement Value  | : S\$ | -        |
| Nett Value               | : S\$ | -        |

**Description of Damage:**

The vehicle sustained damages at the  
N/S Body



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

KALVIN ANG  
Licensed Appraiser

**Shu Pei (LKKAUTO)**

---

**From:** Lucas Lee <lucas.lee@sg.cntaiping.com>  
**Sent:** Monday, 2 April 2018 3:27 PM  
**To:** Shu Pei (LKKAUTO)  
**Cc:** Irene Tay  
**Subject:** RE: Direct Settlement - Accident Involving PC4308G (OI : CTI - SNM18D01609C02) and SHC897T (TP : LKK REF -CC3/CTI18005725/K1ub3 ) on 26.03.2018  
**Attachments:** leeSZ\_SNM18D01609C02-PC4308G-LKKDirectSettlementAccidentLtr\_CLCR95.668.pdf; MSYH18040487-PC4308G.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Irene Tay

Regards,

**Lucas Lee**

Claims Department (Motor)

**China Taiping Insurance (Singapore) Pte. Ltd.**

3, Anson Road, #16-00

Springleaf Tower,

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6181

Fax: 6224 7175

Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

Email: [lucas.lee@sg.cntaiping.com](mailto:lucas.lee@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

**From:** Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]

**Sent:** Wednesday, 28 March, 2018 6:33 PM

**To:** Claims Dept of CTI

**Cc:** Irene Tay; Admin A; Thin Thin (LKKAUTO)

**Subject:** Direct Settlement - Accident Involving PC4308G (OI : CTI - TBA) and SHC897T (TP : LKK REF - CC3/CTI18005725/K1ub3 ) on 26.03.2018

**WITHOUT PREJUDICE**

Dear Irene,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHC 897T at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Our case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

Thank You.

Best Regards,

**Shu Pei** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [shupe@lkkauto.com](mailto:shupe@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



中国太平  
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Tel: 6389 6111 Fax: 6222 1033  
Website: www.sg.cntaiping.com  
Co. Reg No. 200208384E

Our Reference: **SNM18D01609/C02/8**

Date : **02 APRIL 2018**

via Ordinary & Registered Mail

**BT&TAN TRANSPORT PTE LTD  
7030 ANG MO KIO AVENUE 5  
#03-19 NORTHSTAR @ AMK  
SINGAPORE 569880**

Dear Sir / Madam

**ACCIDENT INVOLVING PC4308G AND SHC897T ON 26 MARCH 2018  
ALONG JUNCTION OF MARINA BLVD & BAYFRONT AVE**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHC897T**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,  
Claims Department

*(This is a computer generated letter and no signature is required.)*

CC : LKK Auto Consultants Pte Ltd  
Attn : THIN THIN  
Ref : CC3/CT118005725/K1UB3  
Contact No : 68412360  
via Email : THINTHIN@LKKAUTO.COM

CC : Agent - (AN0580A) - ODDS & EVEN

F01/LKKDS-2013

Team: ARC Repair TP(CFSO)1

**JOB CARD** Sales Order:

JC NO: 305135496

CUSTOMER  
RMS CITYCAB PTE LTD  
CUSTOMER NO 7010070  
ADDRESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
65551188

L (R) (O)  
(P)

SCOUT CARD NO.

|                                   |                                  |
|-----------------------------------|----------------------------------|
| REGN NO.<br>SHC 897T              | MILEAGE                          |
| MAKE<br>MERCEDES BENZ             | FUEL<br>E.....1/2.....F          |
| MODEL<br>E220CDI (E5)             | DATE/TIME IN<br>26.03.2018 13:20 |
| YR OF MANU<br>17.10.2013          | TARGET DATE                      |
| CHASSIS CODE<br>WDD2120022A759858 | COMPLETION DATE/TIME:            |

JOB DESCRIPTION

Accident Date: 26.03.2018  
NATURE: 3P 26.03.2018

| S/NO | LABOR CODE   | DESCRIPTION        |
|------|--------------|--------------------|
|      | CHINA - taxi | Left Centre Damage |
|      | LRR/         |                    |

CHECKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Vehicle No.: SHC 897T  
Signature: LARRY

Larry Ng

Name of Service Advisor

Signature/Date

Returned to Service Reception upon collection

Exit Pass

Vehicle No.: SHC 897T

Name of Service Advisor

Date

To be kept by Security Guard

### REPAIR ESTIMATE\*

MAKE :

MODEL : MERCEDES

DATE 26/3/2018 15:52

DJA: 26.03.18

| MODEL | : MERCEDES |  | Qty | Parts Description/ Labour                                                                                                                                                                                                                                                                                                                    | Type | Unit Price | Amount      |
|-------|------------|--|-----|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|------------|-------------|
|       |            |  |     | Door Shell, Frt/LH                                                                                                                                                                                                                                                                                                                           |      |            | \$ 2,970.00 |
|       |            |  |     | Door Outer Handle, Frt/LH                                                                                                                                                                                                                                                                                                                    |      |            | \$ 88.15    |
|       |            |  |     | Door Window Regulator, Frt/LH                                                                                                                                                                                                                                                                                                                |      |            | \$ 585.00   |
|       |            |  |     | Door Window Motor, Frt/LH                                                                                                                                                                                                                                                                                                                    |      |            | \$ 1,580.00 |
|       |            |  |     | Door Shell, Rr/LH                                                                                                                                                                                                                                                                                                                            |      |            | \$ 2,870.00 |
|       |            |  |     | SUB TOTAL                                                                                                                                                                                                                                                                                                                                    |      |            | \$ 8,093.15 |
|       |            |  |     | LESS 20%                                                                                                                                                                                                                                                                                                                                     |      |            | \$ 1,618.63 |
|       |            |  |     | DISCOUNTED TOTAL                                                                                                                                                                                                                                                                                                                             |      |            | \$ 6,474.52 |
|       |            |  |     | Rear Door ComfortDelgro Limo Cab Logo                                                                                                                                                                                                                                                                                                        |      |            | \$ 60.00    |
|       |            |  |     | Labour Charge                                                                                                                                                                                                                                                                                                                                |      |            | \$ 300      |
|       |            |  |     | Panel Beating                                                                                                                                                                                                                                                                                                                                |      |            | \$ 400.00   |
|       |            |  |     | Spray Painting Charge                                                                                                                                                                                                                                                                                                                        |      |            | \$ 600.00   |
|       |            |  |     | Wiring Charge                                                                                                                                                                                                                                                                                                                                |      |            | \$ 50.00    |
|       |            |  |     | Tuff Kote                                                                                                                                                                                                                                                                                                                                    |      |            | \$ 100.00   |
|       |            |  |     | Transfer Of Door                                                                                                                                                                                                                                                                                                                             |      | \$ 120.00  | \$ 240.00   |
|       |            |  |     | TOTAL LABOUR                                                                                                                                                                                                                                                                                                                                 |      |            | \$ 1,390.00 |
|       |            |  |     | ESTIMATE TOTAL                                                                                                                                                                                                                                                                                                                               |      |            | \$ 7,924.52 |
|       |            |  |     | <p>Kalvi (Kk)</p> <p>27/3/18 1125h</p> <p>3 Days</p> <p>L/S</p> <p>After Repair photo</p>                                                                                                                                                                                                                                                    |      |            |             |
|       |            |  |     | <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey the vehicle</li> <li>To display damaged parts</li> <li>Paint jobs are subject to approval</li> <li>The repair survey is on a 10% basis</li> <li>The repairer must be approved by the insurance company</li> </ul> |      |            |             |
|       |            |  |     | <p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>                                                                                                                        |      |            |             |

## REPAIR ESTIMATE\*

VEHICLE NO : SHC 897T

MAKE :

**MODEL : MERCEDES**

CHINA

DATE 26/3/2018 15:52

DATA: 26.03.18

| MODEL : MERCEDES |                                                                                                                                                                                                                |      |            |                          |
|------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|------------|--------------------------|
| Qty              | Parts Description/ Labour                                                                                                                                                                                      | Type | Unit Price | Amount                   |
|                  | Door Shell, Frt/LH ✓                                                                                                                                                                                           |      |            | \$ 2,970.00              |
|                  | Door Outer Handle, Frt/LH ✓                                                                                                                                                                                    |      |            | \$ 88.15                 |
|                  | Door Window Regulator, Frt/LH ?                                                                                                                                                                                |      |            | \$ 585.00                |
|                  | Door Window Motor, Frt/LH ?                                                                                                                                                                                    |      |            | \$ 1,580.00              |
|                  | Door Shell, Rr/LH ✓                                                                                                                                                                                            |      |            | \$ 2,870.00              |
|                  | <b>SUB TOTAL</b>                                                                                                                                                                                               |      |            | <b>\$ 8,093.15</b>       |
|                  | <b>LESS 20%</b>                                                                                                                                                                                                |      |            | <b>\$ 1,618.63</b>       |
|                  | <b>DISCOUNTED TOTAL</b>                                                                                                                                                                                        |      |            | <b>\$ 6,474.52</b>       |
|                  | Rear Door ComfortDelgro Limo Cab Logo ✓                                                                                                                                                                        |      |            | <b>\$ 60.00</b> Nett     |
|                  | <b>Labour Charge</b>                                                                                                                                                                                           |      |            | <b>300</b>               |
|                  | Panel Beating                                                                                                                                                                                                  |      |            | <del>\$ 400.00</del>     |
|                  | Spray Painting Charge                                                                                                                                                                                          |      |            | <del>\$ 600.00</del> 400 |
|                  | Wiring Charge                                                                                                                                                                                                  |      |            | <del>\$ 50.00</del> x    |
|                  | Tuff Kote                                                                                                                                                                                                      |      |            | <del>\$ 100.00</del> 50  |
|                  | Transfer Of Door                                                                                                                                                                                               |      | \$ 120.00  | <del>\$ 240.00</del> 100 |
|                  | <b>TOTAL LABOUR</b>                                                                                                                                                                                            |      |            | <b>\$ 1,390.00</b>       |
|                  | <b>ESTIMATE TOTAL</b>                                                                                                                                                                                          |      |            | <b>\$ 7,924.52</b>       |
|                  | Kalwi (Kk)                                                                                                                                                                                                     |      |            |                          |
|                  | 27/3/8 1125h                                                                                                                                                                                                   |      |            |                          |
|                  | 3 Days                                                                                                                                                                                                         |      |            |                          |
|                  | L/S                                                                                                                                                                                                            |      |            |                          |
|                  | After Repair photo                                                                                                                                                                                             |      |            |                          |
|                  | This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. |      |            |                          |

Date: \_\_\_\_\_

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305135496

Date : 6. Apr. 2018

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHC 897T

Date of Accident: 26.03.2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA PC4308G

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

**Total for Part-By-Part Repair Cost**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

**Final Lumpsum Repair cost**

**\$4,500.00**

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount.

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : K. L. M.

Date : 9/4/8

### For Official Use Only

| Item                                                 | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|------------------------------------------------------|--------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day                                 |        | YES                         |                        |         |
| 2. Loss of Income Paid                               |        |                             |                        |         |
| 3. Survey Fees                                       |        |                             |                        |         |
| 4. LTA Search Fee                                    |        |                             |                        |         |
| 5. Medical Fees (on behalf of driver, if applicable) |        |                             |                        |         |
| 6. Overrun                                           |        |                             |                        |         |

Remarks:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18005725/K1ub3n2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 21-09-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                   |                |            |
|--------------|-------------------|----------------|------------|
| Insured Veh. | PC 4308G          | Veh. Inspected | SHC 897T   |
| Policy No.   | DMB1SN3096041700  | Coverage (\$)  | 0.00       |
| Claim No.    | SNM18D01609/C02/8 | Excess (\$)    | 0.00       |
| Assign From  |                   | Assign Date    | 27/03/2018 |

## 2. Vehicle Particulars & Condition

|              |                     |              |                    |
|--------------|---------------------|--------------|--------------------|
| Make & Model | MERCEDES BENZ E 220 | c.c          | 2143               |
| Engine No.   | HIDDEN              | Year of Reg. | 2013               |
| Chassis No.  | WDD2120022A759858   | Colour       | WHITE              |
| Odometer     | 597575              | Steering     | IN ORDER           |
| Brakes       | IN ORDER            | Modification | STANDARD ALLOY RIM |
| General      | FAIR                |              |                    |

## 3. Conditions of Tyres

|                | Size       | Make        | Balance |
|----------------|------------|-------------|---------|
| R/H Front Tyre | 205/60 R16 | BRIDGESTONE | 7 mm    |
| L/H Front Tyre | 205/60 R16 | BRIDGESTONE | 7 mm    |
| R/H Rear Tyre  | 205/60 R16 | BRIDGESTONE | 7 mm    |
| L/H Rear Tyre  | 205/60 R16 | BRIDGESTONE | 7 mm    |

## 4. Description of Damages

|                                                                        |
|------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.<br>DAMAGES SEE DETAILS. |
|------------------------------------------------------------------------|

## 5. General Information

|                |                                                                          |                 |            |
|----------------|--------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 26/03/2018                                                               | Inspection Date | 27/03/2018 |
| Survey held at | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |                 |            |

## 5a. Remarks

|                                                                                                                                           |
|-------------------------------------------------------------------------------------------------------------------------------------------|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|-------------------------------------------------------------------------------------------------------------------------------------------|

## 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 3 Working Days |
|-------------------------------------|----------------|

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 897T**

| Qty | Description of Parts                                                            | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>                                              |               |                           |                   |
| 1   | DOOR SHELL ,FRT /LH                                                             | DENTED        | 2,970.00                  | 2,970.00          |
| 1   | DOOR OUTER HANDLE ,FRT/LH                                                       | CRACKED       | 88.15                     | 88.15             |
| 1   | DOOR WINDOW REGULATOR ,FRT/LH                                                   | SERVICEABLE   | 585.00                    | -                 |
| 1   | DOOR WINDOW MOTOR ,FRT/LH                                                       | SERVICEABLE   | 1,580.00                  | -                 |
| 1   | DOOR SHELL ,RR/LH                                                               | DENTED        | 2,870.00                  | 2,870.00          |
|     | LESS 20% DISCOUNT                                                               |               | -1,618.63                 | -1,185.63         |
|     |                                                                                 |               | 6,474.52                  | 4,742.52          |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                                                |               |                           |                   |
| 1   | REAR DOOR COMFORTDELGRO LIMO CAB LOGO (SN)                                      | NECESSARY     | 60.00                     | 60.00             |
|     |                                                                                 |               | 60.00                     | 60.00             |
|     | <b><u>LABOUR</u></b>                                                            |               |                           |                   |
|     | PANEL BEATING .                                                                 |               | 400.00                    | 300.00            |
|     | SPRAY PAINTING CHARGE.                                                          |               | 600.00                    | 400.00            |
|     | WIRING CHARGE.                                                                  | NOT NECESSARY | 50.00                     | -                 |
|     | TUFF KOTE.                                                                      |               | 100.00                    | 50.00             |
|     | TRANSFER OF DOOR .                                                              |               | 240.00                    | 100.00            |
|     |                                                                                 |               | 1,390.00                  | 850.00            |
|     | <b>GRAND TOTAL</b>                                                              |               | <b>7,924.52</b>           | <b>5,652.52</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS<br/>(TO ITS PRE-ACCIDENT CONDITION)</b> |               |                           | <b>4,500.00</b>   |

Report Ref No. CC3/CT18005725/K1ub3n2

**KALVIN ANG WEI KUN**

Automotive Assessor / Investigator

**HO LEONG CHUAN**

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.