

ASS. REC. BY:

REF: es/msg18005726 / Utd3 n2

Special Instruction:

Surveyor: Merimen

MARUIE

ASSIGNMENT (Office)

From (Person):

Elaine Ngu

of

MSIG

Date/Time: 28/3/18 @ 10.21am

Estimated Cost:

Bill to:

OD / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 8340J

Insured:

SCP 820E

at Workshop m/s

Pegasus Engineering

Tel:

68581846

of

51 Defu Lane 10

Policy No:

27523897 SMP

Claim No:

553355

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/03/2018

CA / REV / REP. / REV 24 HRS

lwp

2/4/18

H.O.D. Endorsement:

Date/Time:

11:00am @ 28/3/18

Person Contacted:

Alvin

Vehicle-IN/ OUT


Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	<u>SLQ 8340J - X</u>
	<u>SCP 820E - X.</u>
<u>05/04/18</u>	<u>@ 9.20 a.m. revised to Elaine Ngu Siau Mei via merimen</u>

REF: MEG

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD (TP / WS / TP RES / OD RES / EVA / INV / MV)
 To inspect Vehicle No: SKQ 8340J
 at Workshop m/s: Pegasus Engineering
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SKQ 8340J Yr Regn: 7 / 17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CAI
 Make: nada 3 c.c. 1496
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 59848 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 Cr/No: JM6BN2VAPHO153493
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modif: Nil / Rim / STD A/Rim or
 Tyre Size: F: 205/60R16
 R: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO YOKO or
 Front 6 mm Rear 6 mm
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 2/4/8
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 1.31 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

13/4/18 Confirmed final fig @ 1.257.00 with william.
 (Red: 425; 25%)

RECEIVED 16 APR 2018

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) 16/4 Typist
 Date/Time, File Return to?

Days Of Repair: 3
 Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	200
Transportation:	10
_____ S+RS _____ \$	
Photos	
Others	
TOTAL	210

Report Format: TP
 Lump Sum / (B): (\$ 1257)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Mar 2018		28 Mar 2018 10:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	KOH TEOW JONG, ID: S1245759F								
Main Claimant:	GRAB RENTALS 2 PTE LTD, Co. Reg. No.: 201701345N								
Vehicle Reg. No.:	SLQ8340J	Date of Loss:	23/03/2018 11:00 - :59						
Claim Type:	TP / 553355	Policy/Cover Note No.:	27523897SMP (Comprehensive) Coverage: 31/05/2017 - 30/05/2018						
Vehicle Reg. No. (Insured):	SCP820E	Policy No. (Claimant):							
		Excess:	S\$750.00						
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/03/2018]								
Driver/Custodian (Insured):	KOH TEOW JONG (61 / Male), NRIC: S1245759F								
Adj Asg. Remarks:	We select LKK Auto - Marcus Chua to survey our client vehicle. Vehicle will send in on 02.04.2018. Please aliase with TP for the appointment of the survey. thanks								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18005726/Utd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 28-03-2018	
Code : MSG			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SCP 820E	Veh. Inspected	SLQ 8340J
Policy No.	27523897SMP	Coverage (\$)	0.00
Claim No.	553355	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	28/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/03/2018	Inspection Date	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 05 Apr 2018

Preliminary Advice

Insured Vehicle No	: SCP820E	Accident Date	: 23/03/2018
TP Vehicle No	: SLQ8340J	Assignment Date	: 28/03/2018
Make	: MAZDA 3	Est. Duration of Repair	: 3 days
Date of Inspection	: 02/04/2018		
Inspection At	: Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10 Singapore 539216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:SS	1,682.00
Revised Amount	:SS	1,160.00
Check Items (Estimated)	:SS	0.00
Total	:SS	1,160.00

Lump Sum Repair :SS

Total Loss Consideration

New for Old Value	:SS
Pre-Accident Value	:SS
COE / PARF Rebate	:SS
Salvage Value	:SS
Margin for Repair	:SS

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
 Owner ID: 1345N

Vehicle Details

Vehicle No.: SLQ8340J
 Vehicle to be Exported: Yes
 Intended De-registration Date: 23 Mar 2018
 Vehicle Make: MAZDA
 Vehicle Model: MAZDA3 SEDAN 1.5 AT EU6
 Primary Colour: Blue
 Manufacturing Year: 2017
 Engine No.: P520445251
 Chassis No.: JM6BN22A8H0153493
 Maximum Power Output: 88.0 kW (118 bhp)
 Open Market Value: \$14,761.00
 Original Registration Date: 24 Jul 2017
 First Registration Date: 24 Jul 2017
 Transfer Count: 0
 Actual ARF Paid: \$9,761.00

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 23 Jul 2027
 PARF Rebate Amount: \$7,320.00

Intended COE Rebate Details

COE Expiry Date: 23 Jul 2027
 COE Category: A - Car up to 1600cc & 97kW (130bhp)
 COE Period(Years): 10
 QP Paid: \$42,801.00
 COE Rebate Amount: \$34,240.00
Total Rebate Amount: \$41,560.00

The information contained herein is correct as at 23 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/03/2018 13:07
Date Of Accident	23/03/2018 11:35
Exact Location Of Accident	OPEN CARPARK OF WHAMPOA HAWKER CENTRE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ8340J
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS 2 PTE LTD
Co Reg No	201701345N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.5 4 DOOR SEDAN SP (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29069774MKF
Cover Note Number	01.02.2018 TO 31.01.2019

Driver

Name of Driver	PHUA BAH CHEE
NRIC No	S0597149G
Date Of Birth	01/11/1947
Occupation	OUTDOOR
Date Of Driving Pass	10/12/1976
Driving Experience	41 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97211681
Fax Number	
Contact Number	
E-Mail Address	ALANPHUA622@GMAIL.COM

Address	BLOCK 629 YISHUN STREET 61 #06-19
Postcode	760629
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 23/03/2018 at about 1135hrs, I was driving my vehicle (A: SLQ8340J) towards the exit at open carpark of Whampoa Hawker Centre. Suddenly I felt an impact from my vehicle's right rear portion and realized that vehicle (B: SCP820E) which beside on my right, make a reversing into a parking lot and hit onto my vehicle's right rear portion. Nobody was injured in this accident. Both vehicles have no passenger on board.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SCP820E
Vehicle Make/Model/Colour	BMW
Details Of Properties	SALOO CAR
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under [d] above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[Handwritten Signature]
23/03/2018 01:50 PM

[Handwritten Signature]
Name: *[Handwritten Name]*
NRIC/FIN No.: *[Handwritten NRIC/FIN No.]*

Sketch Plan Pg. 2

SKETCH PLAN



Car park of
Whampoa
Flowers Centre

A: SLG8340J

B: SCP 820E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to G1A report

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 23/03/2018 @ 15:10h

Reporting Centre Personnel's Signature
Name: Lam Wai Shan
NRIC/FIN No.: G686462R

Shirley

LIST ITEMS

<u>PAY</u>	<u>UNPAID</u>
400.00	35.00
	45.00

NETT ITEMS

<u>PAY</u>	<u>UNPAID</u>
------------	---------------

LABOUR

<u>PAY</u>	<u>UNPAID</u>
280.00	200.00
540.00	110.00

0.00

0.00

400.00

80.00

820.00

310.00

480.00

400.00

80.00

0.00

0.00

0.00

1130.00

820.00

310.00

400.00

60.00 (20% DISC)

340.00 LIST ITEM AFTER DISC (PAY)

0.00 NETT ITEM (PAY)

820.00 LABOUR (PAY)

1160.00

}

CHECK ITEM

0.00

0.00

0.00



PEGASUS

ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Email on 23/03/18
@1650w

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
 C/O 51 DEFU LANE 10
 539216
 Officer in Charge : WEE TZE FAH
 Tel :
 Email :

Customer :
GRAB RENTALS 2 PTE LTD
 28, SIN MING LANE,
 #07-71 MIDVIEW CITY
 SINGAPORE 573969
 Attn :
 Tel :
 Fax :

*males - lkh
02/04/18 @ 1000w*

Quotation No : QO18/03-1223	Quotation Date : 23/03/2018	Terms : 30 DAYS
Vehicle No : SLQ8340J	Chassis No : JM6BN22A8H0153493	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: MSIG, INSURED'S VEH NO: SCP820E, DATE OF ACCIDENT: 23.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR DOOR O/S <i>20/2ul</i>	1	400.0000	<i>380</i> 400.00
2	REAR DOOR OUTER WEATHERSTRIP MOULDING <i>11</i>	1	35.0000	35.00 X
3	REAR WHEEL HUB CAP O/S <i>12</i>	1	45.0000	45.00 X
4	MARK UP 15% (ITEM 1 - 3)	1	72.0000	72.00
5	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. REPAIR REAR AND AND O/S REAR FENDER	1	480.0000	<i>280</i> 480.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	650.0000	<i>540</i> 650.00

820

*NOT APPROVED
 later
 take photo before
 painting.
 2/4/18
 3 day.
 P/P 1257*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Sub Total 1,682.00
 GST(7.00%) 117.74
 Total (SGD) 1,799.74

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939

Arrange By: _____ Driver: MIC

Dept Direct: 6305 9510 Dept Direct: 6305 9611 Dept Direct: 6417 9792
 Dept Direct: 6417 9794 Dept Direct: 6417 9795 Dept Direct: 6417 9796 Dept Direct: 6417 9793


Wiper blade: NWB (Nippon Wiper blades: Siliper (Made in Korea),
Forch (Made in Germany))
Spark plug: Niopan Denso, NGK (Made In Japan)

PEGASUS ENGINEERING & TRADING PTE LTD
TAN LIM MOTOR PTE LTD
51 DEFU LANE 10
ATTN : HUA : 93424525
539216
TEL : 6858 5151 FAX : 63393167
ATTN : KARYAN 81432225

TAX INVOICE : AR201804-00176
DATE : 02/04/2018
CUSTOMER ID : PEG001
VEH REG. NO. : SLQ8340J
TERMS : 60 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : S\$

SM 201802064

SO	STOCKID	DESCRIPTION	StkLoc	QTY	UPRICE	AMOUNT
1.	BJY0-72-02XF MZ3 BM 2014-	RR DOOR RH	PA PL3-H1-040	1	380.00	380.00



SUB-TOTAL : 380.00
ADD GST 7.00 % 26.60

E. & O.E TOTAL AMOUNT S\$: 406.60

[P] 02/04/2018 10:15:06AM
Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 02/04/2018 10:13:46AM

JAE Auto Pte. Ltd.
Sales Executive: SENG



Goods Received in Good Order

This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005726/UTD3N2

Date: 18/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27523897SMP
Claimant Vehicle No :	SLQ8340J	Insured Vehicle No :	SCP820E
Date of Loss:	23/03/2018	Nature of Claim:	TP
		Claim No:	553355

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ8340J	Engine No:	P520445251
Make & Model:	MAZDA 3, 1.5 SEDAN EU6 (A)	Chassis No:	JM6BN22A8H0153493
Reg. Date:	24/07/2017 (Man. Year: 2017)	Odometer:	59848 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	552.00	437.00	115.00	20.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	820.00	310.00	27.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,682.00	1,257.00	425.00	25.27
+ GST 7.00/7.00% (S\$)	117.74	87.99	29.75	25.27
Nett Amount (S\$)	1,799.74	1,344.99	454.75	25.27

INSPECTION

Date of Assignment:	28/03/2018	
Date Inspected:	02/04/2018	Inspected At:
		Pegasus Engineering & Trading Pte Ltd (HQ)
		51 DEFU LANE 10
		Singapore 539216
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2018)
Parts: 143	MAZDA 3 1.5 SEDAN EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLQ8340J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR DOOR O/S (WCP)	Dented/Bent	400.00 F	*380.00 F
2	1	*REAR DOOR OUTER WEATHERSTRIP MOULDING (WCP)	Not Necessary	35.00 F	*- F
3	1	*REAR WHEEL HUB CAP O/S (WCP)	Repair	45.00 F	*- F
F=Franchise part.					
			Sub Total (S\$)	480.00	380.00
			+ Margin on L,N Items 15.00/15.00% (S\$)	72.00	57.00
			Total Parts (S\$)	552.00	437.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.REPAIR REAR AND O/S REAR FENDER	New	480.00	280.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	650.00	540.00
Gross Labour Cost (\$\$)			1,130.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >