

ASS. REC. BY:

REF: ³CS/MSG18005727 / Avd357 ^{range} Special Instruction:

Supervisor: Adrian ASSIGNMENT (Office)

From (Person): Meimen Elaine Ngu of MSIG Date/Time: 28/3/18

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SIR 8098D Insured: XE 1120U

at Workshop m/s: Reliable Carz Tel: 8166 9797

of 8kaki Bkt Ave 4 # 05-50

Policy No: B28636251MICC Claim No: 553599

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 26/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS lwp H.O.D. Endorsement: _____

Date/Time: 11:46am @ 28/3/18 Person Contacted: Jason Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SIR 8098D - NA/INC18065636/24 D.O.A: 26/3/18
	XE 1120U - NA/INC18065636/24 D.O.A: 26/3/18
	Dismantle: 29/3/2018
	After repair: 6/4/2018

ASS. REC. BY: Adrian King

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

/	
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : **Yes** or No

GIA / PR Seen: _____ Consistent? : **Yes** or No

Est. Repairs: 8 days Res.: **Yes** or No

Lum Sum: _____ % 3 Val.: **Yes** or No

CA / REV / REP. / 24 HRS

Vehicle: **IN / OUT**

Date: _____ Person Contacted: _____

Veh No: SLR8098D Yr Regn: 2017 August

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Vezel Hybrid cc 1496

Colour: Silver A/C: **Insured / Std / NI / NA**

Sp. Reading: 52156 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: RU31246756

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **Inorder** / Jammed / Leaked / Burnt or

Brake: **Inorder** / Jammed / Leaked / Burnt or

Modi: **Nil** / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 28/03/18

Survey held at Reliable

Des. of Damages: **Frt** / **Rear** / O/S / N/S / U/C / Rooftop or

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
	<u>TP MS16 PRS</u>
	<u>Estimated Repair Cost : \$2.5k - \$9.5k . 889 . 27/04/18</u>
	<u>08 Days .</u>
RECEIVED 27 APR 2018	

Date/Time, File Pass to? : **Preli. Report**

1) : **Final Report**

Date/Time, File Return to?

2) _____

Days Of Repair: 8

Resurvey No. of Trip: 2

Survey Fee: _____

Transportation: _____

____ \$ + RS. SI

Photos _____

Others _____

TOTAL

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Report Format : PRG

Lump Sum / I.B.I: (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Mar 2018		28 Mar 2018 10:11 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	SAMWOH CORPORATION PTE LTD , Co. Reg. No.: 198502202Z		
Main Claimant:	RELIABLE RIDES PTE LTD , Co. Reg. No.: 201611527N		
Vehicle Reg. No.:	SLR8098D	Date of Loss:	26/03/2018 15:00 - :59
Claim Type:	TP / 553599	Policy/Cover Note No.:	B28636251MKC (Comprehensive) Coverage: 02/11/2017 - 01/11/2018
Vehicle Reg. No. (Insured):	XE1120U	Policy No. (Claimant):	
		Excess:	S\$2,000.00
Repairer:	Reliable Carz Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-50, 415875 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/03/2018]		
Driver/Custodian (Insured):	NIU JIAPU (), NRIC: G8393093X, Tel: +6585757329		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
TIWARY ANURADHA
SHARON PARWANI
ONG BOCK KEE
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
ROCHE ENG KENG LOON
TAY HAO RAN
JANICE HAN JIA LIN

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE. KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.Ins.R28.106259.18 (sj)
Your Ref: XE 1120 U

28 March 2018

MSIG INSURANCE (S'PORE) PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807
Attention: Motor Claims Department – Eileen Goh

BY FAX: 6225-6371
eileen_goh@sg.msig-asia.com
claims@sg.msig-asia.com

Dear Sirs,

ACCIDENT INVOLVING SLR 8098 D & XE 1120 U ON 26 MARCH 2018 ALONG JUNCTION CORPORATION ROAD & LAKEPOINT DRIVE AT ABOUT 1525 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We refer to your email dated 27 March 2018 informing that your wish to conduct a pre-repair survey on our client's vehicle SLR 8098 D.

Please be informed that the said vehicle can be inspected at:

Contact Person:

Reliable Carz Pte Ltd
8 Kaki Bukit Avenue 4
#05-50 Premier @Kaki Bukit
Singapore 415875
Jason 8166-9797

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

Anjali M
(Head Office)

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

cc: SLR 8098 D – by email: reliablecarzpl@gmail.com only

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY
THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIACC Records Management Centre established by the General Insurance Association of Singapore (GIACC) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/03/2018 17:32
Date Of Accident	26/03/2018 15:25
Exact Location Of Accident	JUNC CORPORATION RD & LAKEPOINT DR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR8098D
Insured/Policyholder	
Name Of Registered Owner	RELIABLE RIDES PTE LTD
Co Reg No	201611527N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL HYBRID 1.5X AUTO
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093728301
Cover Note Number	

Driver

Name of Driver	SITI MARIAM BINTE HANIFI
NRIC No	S8509422Z
Date Of Birth	16/04/1985
Occupation	OUTDOOR
Date Of Driving Pass	28/07/2004
Driving Experience	13 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98765956
Fax Number	
Contact Number	OFFICE-98765956
Email Address	NOEMAIL

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1

DETAILS OF INJURED PERSON 1

Name SITI MARIAM BINTE HANIFI
Approximate Age
Injuries Sustain BODY
Injured person in which vehicle? SLR8098D
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name ABISHEK
Approximate Age
Injuries Sustain HEAD
Injured person in which vehicle? SLR8098D
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

Change Language Change Password Log Out

My Desktop
Notice of Loss

Policy Query

Policy No. Date of Accident

Vehicle No (For Motor)

Search

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5093728301	RELIABLE RIDES PTE LTD	201611527N	GPC	drivo CLASSIC	SLR8098D	SLR8098D	29/08/2017	28/08/2018

Continue

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Mar 2018		28 Mar 2018 10:11 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SAMWOH CORPORATION PTE LTD , Co. Reg. No.: 198502202Z								
Main Claimant:	RELIABLE RIDES PTE LTD , Co. Reg. No.: 201611527N								
Vehicle Reg. No.:	SLR8098D	Date of Loss:	26/03/2018 15:00 - :59 [6 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 553599	Policy/Cover Note No.:	B28636251MKC (Comprehensive) Coverage: 02/11/2017 - 01/11/2018						
Vehicle Reg. No. (Insured):	XE1120U	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	Reliable Carz Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-50, 415875 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Imm.Advice due 29/03/2018]								
Driver/Custodian (Insured):	NIU JIAPU (), NRIC: G8393093X, Tel: +6585757329								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLR8098D (553599)**
[XE1120U]
TP
RELIABLE RIDES PTE LTD
Mar 26 2018 3:00PM
[SAMWOH CORPORATION PTE LTD]
Reliable Carz Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/03/18 16:07	Accident Statement From: SC - Reg. No: XE1120U, Claimant: SAMWOH CORPORATION PTE LTD	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
2	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
3	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
4	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
5	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
6	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
7	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
8	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
9	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
10	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
11	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
12	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
13	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
14	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
15	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
16	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
17	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
18	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
19	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
20	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
21	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
22	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
23	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
24	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
25	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
26	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
27	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
28	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
29	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
30	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
31	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
33	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
34	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
35	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
36	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
37	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
38	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
39	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
40	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
41	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
42	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
43	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
44	27/04/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
45	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	27/04/18 17:04	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
80	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	27/04/18 17:04	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
128	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
130	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
131	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
132	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
133	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
134	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
135	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
136	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
137	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
138	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
139	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
140	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
141	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
142	27/04/18 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
143	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
144	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
145	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
146	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
147	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
148	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
149	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
150	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
151	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
152	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
153	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
154	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
155	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
156	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
157	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
158	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
159	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
160	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
161	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
162	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
163	27/04/18 17:04	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/03/18 16:07	TPD SLR8098D GIA REPORT	 Load PDF	
2	28/03/18 10:06	WORKSHOP DETAIL- SLR8098D.	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005727/AVD3S2
Date: 03/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B28636251MKC
Claimant Vehicle No :	SLR8098D	Insured Vehicle No :	XE1120U
Date of Loss:	26/03/2018	Nature of Claim:	TP
		Claim No:	553599

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR8098D	Engine No:	LEB5946773
Make & Model:	HONDA VEZEL, 1.5 X A (A)	Chassis No:	RU31246756
Reg. Date:	29/08/2017 (Man. Year: 2017)	Odometer:	52156 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	28/03/2018		
Date Inspected:	28/03/2018	Inspected At:	Reliable Carz Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-50 Singapore 415875
Estimated Period of Repair:	0.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,500.00 - \$9,500.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 May 2018)
Parts: M1-SUV	HONDA VEZEL 1.5 X A (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR8098D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >