

INS. CASE OWNER:

Sharon.

CC 6/AIG1800

5741, 11/16/18

LKK:

IDAC:

Surveyor:

marlins

DOI:

ASSIGNMENT

26/7/18

Date / Time:

26/7/18

Registered in Merimen:

26/7/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

S7N 7161T

Claim No.:

66987758664

Name of Insured:

UM POH ENH

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

26/7/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

S7N 7161T



INSRS:

WSP:

Tel:

Liability:

RMKS:

Pegasus



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

26/7/18

vinan

4/4/18

S7N 7161T

S7N 7161T

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

4/4/18

After call ltr to OI:

vinan

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with Sharon.

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 0%

Repair Cost:

t66t.

S\$

6045.50

Loss of Rental (LOR):

S\$

960.00

(\$

x 8 days)

x 120

Loss of Use (LOU):

S\$

-

(\$

x 8 days)

Loss of Income (LOI):

S\$

-

(\$

x 8 days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

7.49

Medical:

S\$

-

Disbursement:

S\$

-

Legal Cost

S\$

-

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

7012.99

Global Sum S\$: 7000.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

7000.00

Name 1:

Pegasus Engineering & Trading Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

RECEIVED 08 NOV 2018

COPY SENT



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18005741/Uwb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 28-03-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJU 7161T	Veh. Inspected	SLP 7879J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	28/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/03/2018	Inspection Date	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216
Officer in Charge : WEE TZE FAH Tel : Email :

Customer :
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn : Tel : Fax :

Not Authorized
Mark
1/5#5600/2
To be photo Attn: Rep
28/3/18
Gdy

Quotation No : QO18/03-1276	Quotation Date : 28/03/2018	Terms : 30 DAYS
Vehicle No : SLP7879J	Chassis No : MHFB29F3002011811	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER AIG, INSURED'S VEH NO: SJU7161T, DATE OF ACCIDENT: 28.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	BOOTLID <i>762.47</i>	<i>20/suc1</i>	1,662.4000	1,662.40 <i>✓</i>
2	BOOTLID LOCK	<i>4m/1</i>	90.4000	90.40 <i>✓</i>
3	BOOTLID LOCK STRIKER	<i>11</i>	18.5000	18.50 <i>X</i>
4	BOOTLID WEATHERSTRIP	<i>1m/1</i>	188.8000	188.80 <i>✓</i>
5	BOOTLID CENTRE LOGO BADGE	<i>1m</i>	59.8000	59.80 <i>✓</i>
6	BOOTLID E BADGE	<i>1m</i>	34.4000	34.40 <i>✓</i>
7	BOOTLID VIOS BADGE	<i>1m</i>	44.1000	44.10 <i>✓</i>
8	BOOTLID OUTER GARNISH	<i>1</i>	234.3000	234.30 <i>X</i>
9	BOOTLID INNER TRIM	<i>11</i>	234.3000	234.30 <i>X</i>
10	BOOTLID INNER TRIM CLIPS	<i>11</i>	4.5000	22.50 <i>2</i>
11	BOOTLID HINGE	<i>1</i>	57.8000	115.60 <i>X</i>
12	BOOTLID LOCK CABLE CLIPS	<i>11</i>	4.5000	13.50 <i>X</i>
13	REAR END PANEL	<i>50/sid</i>	694.7000	694.70 <i>✓</i>
14	REAR END PANEL INNER TRIM	<i>1m/1</i>	234.3000	234.30 <i>✓</i>
15	REAR LICENSE PLATE LAMP	<i>11</i>	64.1000	128.20 <i>X</i>
16	REAR LUGGAGE FLOOR FOAM	<i>11</i>	108.2000	108.20 <i>X</i>
17	REAR BUMPER	<i>Dis</i>	502.1000	502.10 <i>✓</i>
18	REAR BUMPER REINFORCEMENT	<i>Dis</i>	379.2000	379.20 <i>✓</i>
19	REAR BUMPER REFLECTOR	<i>11</i>	130.8000	261.60 <i>X</i>
20	REAR BUMPER SIDE RETAINER	<i>3m/1</i>	115.1000	230.20 <i>✓</i>
21	REAR BUMPER SIDE HOLDER	<i>3m/1</i>	42.0000	84.00 <i>✓</i>
22	REAR BUMPER CLIPS	<i>1m</i>	4.5000	45.00 <i>✓</i>
23	REAR BUMPER END SPLASHIELD COVER	<i>11</i>	57.5000	115.00 <i>X</i>

C/F 0.00

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/03-1276	Quotation Date : 28/03/2018	Terms : 30 DAYS
Vehicle No : SLP7879J	Chassis No : MHFB29F3002011811	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER AIG, INSURED'S VEH NO: SJU7161T, DATE OF ACCIDENT: 28.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	REAR LAMP	2 CM	375.8000	751.60 ✓
25	REAR LAMP CLIP HOLDER	4 n1	4.3000	17.20 X
26	REAR LAMP PANEL	2 n1	124.0000	248.00 ✓
27	REAR FENDER n1s	20/1 Ref	969.1000	969.10 ✓
28	REAR FENDER INNER TRIM	20/1 Ref	235.0000	235.00 ✓
29	REAR FENDER INNER TRIM CLIPS	8 n1	4.3000	34.40 X
30	REAR EXHAUST BOX	1 n1	638.8000	638.80 X
31	REAR EXHAUST BOX MOUNT	1 n1	33.0000	33.00 X
32	REAR EXHAUST BOX HEAT SHIELD	1 n1	59.9000	59.90 X
33	LESS 20% (ITEM 1 - 32) 25%	1	-1,697.6200	-1,697.62
34	REAR LICENSE PLATE	1 Ref	80.0000	80.00 40
35	REAR LUGGAGE FLOOR PANEL INSULATOR	1 n1	250.0000	250.00 X
36	REAR WINDSHIELD GLASS SEALANT	1 n1	200.0000	200.00 40
37	REAR WINDSHIELD GLASS SPONGE	1 n1	100.0000	100.00 30
38	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	60.0000	60.00 20
39	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	120.00 50
40	TO RUST-PROOFING OF THE AFFECTED AREAS	1	180.0000	180.00 90
41	TO TRANSFER BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	1	120.0000	120.00 60
42	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	160.0000	160.00 80
43	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1	180.0000	180.00 120
44	TO DROP REAR EXHAUST BOX AND RENEW THE SAME	1	150.0000	150.00 X

C/F 0.00

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/03-1276	Quotation Date : 28/03/2018	Terms : 30 DAYS
Vehicle No : SLP7879J	Chassis No : MHFB29F3002011811	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER AIG, INSURED'S VEH NO: SJU7161T, DATE OF ACCIDENT: 28.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
45	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	2,000.0000	1400 2,000.00
46	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,600.0000	1100 1,600.00

7101.67

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total	11,990.48
GST(7.00%)	839.33
Total (SGD)	12,829.81

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

View Received Message

This mail is associated with :

***SLP7879J (6698729586SG)**
[SJU7161T]

TP
GRAB RENTALS PTE LTD
Mar 28 2018 12:00AM
[Lim Poh Eng]
Pegasus Engineering & Trading Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 29/03/2018 13:50 PM.
To LKK_HQ
Subject No OI GIA Report

Hi

Pls be advice that no OI GIA report received
Pls find OI details below for your further actions

OI name :Lim Poh Eng

Address :
Blk 290B Compassvale Crescent
#02-38
Singapore 542290

Thank you.

Regards
yoke shi

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18005741/Uwb3

02ND APR 2018

Lim Poh Eng

Blk 290B Compassvale Crescent #02-38
Singapore 542290

Dear Sirs,

ACCIDENT INVOLVING SLP 7879J AND SJU 7161T ON 28/03/2018 ALONG AT TPE TOWARDS CTE

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Vivian Lau
Claims
Tel : 6841 8625
Fax: 6741 4108
Email : vivianlau@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/03/2018 16:18
Date Of Accident	28/03/2018 06:45 ✓
Exact Location Of Accident	SLIP ROAD FROM TPE TOWARDS CTE (CITY)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU7161T
Insured/Policyholder	
Name Of Registered Owner	LIM POH ENG
NRIC No	S1597922D
Email Address	WILLELIZ2013@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98155396
Alternative Phone No	OTHERS-98155396
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	AVANTE-1.6 ABS AIRBAG 2WD 4DR (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100179803
Cover Note Number	

Driver

Name of Driver	LIM POH ENG
NRIC No	S1597922D
Date Of Birth	10/02/1963
Occupation	INDOOR
Date Of Driving Pass	08/11/1995
Driving Experience	22 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98155396
Fax Number	
Contact Number	OTHERS-98155396
Email Address	WILLELIZ2013@GMAIL.COM

30.1
2nd.

Address	BLK 290B COMPASSVALE CRESCENT #02-38
Postcode	542290
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	KIM KEAT NPP
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN / POLICE REPORT NO: T/20180328/2147

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN7991Z
Vehicle Make/Model/Colour	LORRY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLP7879J
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LIM POH ENG

Approximate Age

55

Injuries Sustain

LEG

Injured person in which vehicle?

SJU7161T

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

BLK 290B COMPASSVALE CRESCENT #02-38

Postcode

542290

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

29 MAR 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: Jenny Lim
S6927273H

2018-03-29 11:00 AM

2018-03-29 11:00 AM

SKETCH PLAN

Refer to attachment

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report No = T/20180328/2147

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

29 MAR 2018

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Jenny Lim
S6927273H





**SINGAPORE
POLICE FORCE**



T/20180328/2147

Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999

1 of 4

Report No. T/20180328/2147

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/03/2018 16:49		Vide Report No.:		Station Diary No.: 32	
Informant's Particulars:					
Name of Informant: LIM POH ENG			Address: APT BLK 290B COMPASSVALE CRESCENT #02-38 SINGAPORE 542290		
ID Type / ID No.: NRIC NO / S1597922D			Contact No.: Home/Office: Mobile: 98155396		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 55	Date of Birth: 10/02/1963	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Senior Associate			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident:

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 28/03/2018 06:45	Type of Location: Straight Road
Location: Along Road 1 CENTRAL EXPRESSWAY				
Slip road from TPE towards CTE(city)				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SJU7161T	Car	HYUNDAI	AVANTE 1.6 AT ABS D/AB 2WD 4DR	Silver	Seriously Damaged	0
SLP7879J	Car					0
YN7991Z	Lorry					0

Police Report Pg. 2



**SINGAPORE
POLICE FORCE**



T/20180328/2147

Police Station Of Origin:
Kim Keat NPP
231 Lprong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999

2 of 4

Report No. T/20180328/2147

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SJU7161T	AIG ASIA PACIFIC INSURANCE PTE. LTD.	2100179803-08	23/12/2017	22/12/2018

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	LIM POH ENG		ID No.	S1597922D
Related Vehicle	SJU7161T (Car)		Contact No.	98155396
Hospital/Clinic	TAN TOCK SENG HOSPITAL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	28/03/2018		Date Discharge	28/03/2018
No. of Days granted Medical Leave	02		Degree of Injury	Slight
Driver				
Name	HAMZAH		ID No.	S1483152E
Related Vehicle	SLP7879J (Car)		Contact No.	83670334
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	MURAGAN NATARGAN		ID No.	G2278271T
Related Vehicle	YN7991Z (Lorry)		Contact No.	96889939
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20180328/2147

Police Station Of Origin:

Kim Keat NPP

231 Lorong 8 Toa Payoh #01-186

SINGAPORE 310231

Tel No: 1800-2529999

3 of 4

Report No. T/20180328/2147

CONTINUATION OF REPORT

Brief Details.

On 28/03/2018 at about 0645hrs, I was travelling along TPE entering the slip road towards CTE(city). I had enter the slip road and near to the exit, the vehicle infront of me brake light was on therefore I slow down and apply brake. Out of a sudden, I felt a big impact coming from the rear of my vehicle. This impact causes my vehicle to move forward and hit on the vehicle that was infront of me.

I stopped my vehicle and the other two driver came down. The lorry driver did not mention how come he hit on to my vehicle. At that point of time I felt pain at my leg where is my old injury, paramedic made a check however they did not convey me. Shortly, traffic police and ambulance came to attend to us. No one was being convey at that point of time. My car was not in stalled with any in car camera.

I felt pain at my leg area therefore I went to Tan Tock Seng to seek for treatment. I was given 2 days medical leave and was told to go back for check up on 30/04/2018.





**SINGAPORE
POLICE FORCE**



T/20180328/2147

4 of 4

Report No. T/20180328/2147

Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /
Sgt 1 LIM JIAN HONG

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
28/03/2018 16:49

Officer In Charge Of Case:
TP / GIT /
SI THABAGESH JEYATHESH
Contact No.: 65476232

Classification Of Case:

<p>SINGAPORE POLICE FORCE</p>	SN 064
	SIGNATURE

Authentication Stamp
NP168

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Mar 2018 Edit Reg		28 Mar 2018 00:00 Edit Adj Rpt	S\$5,650.00 Edit Estimates	S\$5,650.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Lim Poh Eng, ID: S1597922D		
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Vehicle Reg. No.:	SLP7879J	Date of Loss:	28/03/2018 06:00 - :59 [9 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 6698729586SG	Policy/Cover Note No.:	2100179803 (Comprehensive)
Vehicle Reg. No. (Insured):	SJU7161T	Policy No. (Claimant):	A29069766MKF
		Excess:	
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 09/04/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (29/03/2018): Request To Upload TP GIA Report
- AIG_SG (29/03/2018): No OI GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLP7879J (6698729586SG)**
[SJU7161T]

TP


































GRAB RENTALS PTE LTD











Mar 28 2018 6:45AM

[Lim Poh Eng]

Pegasus Engineering & Trading Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser					
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>					
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print					
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1			Edit					
Photos/Images															3 per page			<input checked="" type="checkbox"/>					
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)															Thumbnail			Print		
1	28/03/18 18:32		Odometer Reading												1			Load JPG			<input checked="" type="checkbox"/>		
2	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
3	28/03/18 18:32		Chassis Number												1			Load JPG			<input checked="" type="checkbox"/>		
4	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
5	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
6	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
7	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
8	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
9	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
10	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
11	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
12	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
13	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
14	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
15	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
16	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
17	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
18	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
19	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
20	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
21	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
22	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
23	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
24	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
25	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
26	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
27	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
28	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
29	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
30	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
31	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		
32	28/03/18 18:32		General View												1			Load JPG			<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
34	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
35	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
36	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
37	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
38	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
39	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
40	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
41	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
42	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
43	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
44	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
45	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
46	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
47	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
48	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
49	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
50	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
51	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
52	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
53	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
54	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
55	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
56	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
57	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
58	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
59	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
60	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
61	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
62	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
63	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
64	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
65	28/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/03/18 15:16	TP ESTIMATE- MARKED	 Load PDF	
2	29/03/18 15:18	TP GIA REPORT	 Load PDF	
3	02/04/18 10:43	Non reporting letter	 Load PDF	
4	28/11/18 09:52	AUTHORISATION TO ACT	 Load PDF	
5	28/11/18 09:52	LETTER TO OI	 Load PDF	
6	28/11/18 09:52	LTA SEARCH	 Load PDF	
7	28/11/18 09:52	RELEASE VOUCHER	 Load PDF	
8	28/11/18 09:52	RENTAL RATE	 Load PDF	
9	28/11/18 09:52	WORKSHOP INVOICE	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/04/18 09:49	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJU7161T (Insd veh)	Model:	TOYOTA VIOS 1.5 E (A)
	SLP7879J (TP veh)		
Date of Accident:	28/03/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	: \$	12,829.81	
Final Repair Cost	: \$	7,000.00	
Loss of Use	: \$	_____ days at \$0.00 per day	
Rental (if any)	: \$	8 days	
LTA / GIA Search Fee	: \$		
Others:	: \$		
	: \$		
Final Settlement Sum (GLOBAL SUM)	: \$	7,000.00	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 0 _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Pegasus Engineering & Trading Pte Ltd	: \$	7,000.00
2)		: \$	
3)		: \$	
4)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

28 Nov
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18005741/UWB3S2
Date: 28/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100179803
Claimant Vehicle No: SLP7879J Insured Vehicle No: SJU7161T
Date of Loss: 28/03/2018 Nature of Claim: TP Claim No: 6698729586SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP7879J
Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 2NRX158372
Reg. Date: 19/06/2017 (Man. Year: 2017) Chassis No: MHFB29F3002011811
Colour: Silver Odometer: 52178 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50R16 Rear Tyre Size: 195/50R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,420.48	4,181.88	3,238.60	43.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,570.00	2,920.00	1,650.00	36.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,990.48	7,101.88	4,888.60	40.77
Approved Total (Overridden) (S\$)		5,650.00		
(S\$)	11,990.48	5,650.00	6,340.48	52.88
+ GST 7.00/7.00% (S\$)	839.33	395.50	443.83	52.88
Nett Amount (S\$)	12,829.81	6,045.50	6,784.31	52.88
+ Car Rental (8.0 x S\$120.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		7,012.99		
Global Sum Settlement (S\$)		7,000.00		

INSPECTION

Date of Assignment: 28/03/2018
Date Inspected: 28/03/2018 Inspected At: Pegasus Engineering & Trading Pte Ltd (HQ)
51 DEFU LANE 10
Singapore 539216
Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Buckled	1,662.40 FL	*762.47 FL
2	1		*BOOTLID LOCK	Twisted	90.40 FL	*90.40 FL
3	1		*BOOTLID LOCK STRIKER	Not Necessary	18.50 FL	*- FL
4	1		*BOOTLID WEATHERSTRIP	Twisted	188.80 FL	*188.80 FL
5	1		*BOOTLID CENTRE LOGO BADGE	Necessary	59.80 FL	*59.80 FL
6	1		*BOOTLID BADGE	Necessary	34.40 FL	*34.40 FL
7	1		*BOOTLID VIOS BADGE	Necessary	44.10 FL	*44.10 FL
8	1		*BOOTLID OUTER GARNISH	Repair	234.30 FL	*- FL
9	1		*BOOTLID INNER TRIM	Not Necessary	234.30 FL	*- FL
10	5		*BOOTLID INNER TRIM CLIPS	Not Necessary	22.50 FL	*- FL
11	2		*BOOTLID HINGE	Repair	115.60 FL	*- FL
12	3		*BOOTLID LOCK CABLE CLIPS	Not Necessary	13.50 FL	*- FL
13	1		*REAR END PANEL	Badly Dented	694.70 FL	*694.70 FL
14	1		*REAR END PANEL INNER TRIM	Twisted	234.30 FL	*234.30 FL
15	2		*REAR LICENCE PLATE LAMP	Not Necessary	128.20 FL	*- FL
16	1		*REAR LUGGAGE FLOOR FOAM	Not Necessary	108.20 FL	*- FL
17	1		*REAR BUMPER	Distorted	502.10 FL	*502.10 FL
18	1		*REAR BUMPER REINFORCEMENT	Dented	379.20 FL	*379.20 FL
19	2		*REAR BUMPER REFLECTOR	Not Necessary	261.60 FL	*- FL
20	2		*REAR BUMPER SIDE RETAINER	Bent	230.20 FL	*230.20 FL
21	2		*REAR BUMPER SIDE HOLDER	Bent	84.00 FL	*84.00 FL
22	10		*REAR BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
23	2		*REAR BUMPER END SPLASHIELD COVER	Not Necessary	115.00 FL	*- FL
24	2		*REAR LAMP	Cracked	751.60 FL	*751.60 FL
25	4		*REAR LAMP CLIP HOLDER	Not Necessary	17.20 FL	*- FL
26	1		*REAR LAMP PANEL	N/S Bent	248.00 FL	*124.00 FL
27	1		*REAR FENDER N/S	Dented / Bent	969.10 FL	*969.10 FL
28	1		*REAR FENDER INNER TRIM	Deformed / Torn	235.00 FL	*235.00 FL
29	8		*REAR FENDER INNER TRIM CLIPS	Not Necessary	34.40 FL	*- FL
30	1		*REAR EXHAUST BOX	Repair	638.80 FL	*- FL
31	1		*REAR EXHAUST BOX MOUNT	Not Necessary	33.00 FL	*- FL
32	1		*REAR EXHAUST BOX HEAT SHIELD	Not Necessary	59.90 FL	*- FL
33	1		*REAR LICENCE PLATE	Bent	80.00 FS	*40.00 FS
34	1		*REAR LUGGAGE FLOOR PANEL INSULATOR	Not Necessary	250.00 FS	*- FS
35	1		*REAR WINDSHIELD GLASS SEALANT	Necessary	200.00 FS	*40.00 FS
36	1		*REAR WINDSHIELD GLASS SPONGE	Necessary	100.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,118.10	5,539.17
- List Item Discount on L Items 20.00/25.00% (S\$)	1,697.62	1,357.29
Total Parts (S\$)	7,420.48	4,181.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	60.00	20.00
2	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	New	120.00	50.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	180.00	90.00
4	TO TRANSFER BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	120.00	60.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	New	160.00	80.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	New	180.00	120.00
7	TO DROP REAR EXHAUST BOX AND RENEW THE SAME.	New	150.00	0.00
8	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	2,000.00	1,400.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	1,600.00	1,100.00
Gross Labour Cost (S\$)			4,570.00	2,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >