

App. REC. BY:

REF: CS/ASM18005764/Und389 Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Kitty Teo of ASM Date/Time: 28/03/2018

Estimated Cost: Bill to:

☒ OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDM 5028Y Insured:

at Workshop m/s SME Motor Tel: 6747 6106

of Blk 1 Kalci Bld Ave 6 # 02-15

Policy No: Claim No: 88M00CSL

Sum Insured: Excess: NIL

Make of Veh: D.O.A. 19/03/2018

(Client's Record)

☒ CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3:41pm @ 28/3/18 Person Contacted: Pei ying Vehicle-IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	Insured has 2nd accident on 22/3/18. Pls authorise the damages which are consistent for this accident.
	SDM 5028Y-X
5/4/18	Send preli revised by SMART claim



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18005764/Uvd3

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 28-03-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SDM 5028Y
Policy No.	Coverage (\$)	0.00
Claim No. S8M00C5L	Excess (\$)	0.00
Assign From SMARTCLAIM (KITTY TEO)	Assign Date	28/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 19/03/2018	Inspection Date 04/04/2018
Survey held at SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883	

5a. Remarks

- A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

◀ Service Request Details

Claim

S8M00C5L

Reference

None 

Loss Date

March 19, 2018

Request Date

March 28, 2018

Due Date

April 5, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SDM5028Y

Make

VOLKSWAGEN

Service Address

1 Kaki Bukit Ave 6 #02-15, , 417883

Primary Contact/Insured

HO NGIAP KUM

52 LORONG G TELOK KURAU, #05-04, 426235, Singapore
96348442

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Additional Instructions
EXCESS NIL

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE



SENT

3/28/18 12:14 PM

FROM

TEO Kitty

SUBJECT

SDM5028Y - VEH @ SME

BODY

Hi Insured has 2nd accident on 22.03.18, please a...





Auto
Consultants
Pte Ltd

Company Registration No. 19960719

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 625643

Your ref: S8M00C5L

Our ref: CS/ASM18005764/Uvd3

Date: 18/4/2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam

PRELIMINARY ADVICE OF VEHICLE NO. SDM 5028Y


We thank for your instruction on 28/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 4/4/2018 at the premises of M/s SME MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$4,590.00 (incl.supplementary \$585.00)
Revised Estimate Amount	: S\$2,725.00 (incl.supplementary \$585.00)
"Check" Items Amount	: S\$
Total	: S\$2,725.00
Market Value	: S\$59,000.00
COE/PARF Rebate	: S\$47,805.00
Nett Value	: S\$11,195.00

Description of Damage:

The vehicle sustained damages at the n/s body



Survey date and time: 4/4/2018 at 3PM

We have authorize repair.

No of days: 3 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser



SDM 5028Y-DOA: 19/3/2018, SUPPLEMENTARY

Type

🔔 Question

Message

Dear Kitty, We have received supplementary of \$585.00 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Best Regards Veron Chen

Reply



Re:IA SUBMITTED FOR SDM 5028Y (DOA: 19/3/2018)

Type

🔗 Question

Message

Hi Veron, There is no additional excess for the driver. Thank you.

Reply



IA SUBMITTED FOR SDM 5028Y (DOA: 19/3/2018)

Type

🔗 Question

Message

Dear Sir/Madam, Please be informed that IA submitted. We have Authorize repair. Please double check on the excess as driver's is 68 year old. Workshop Estimate Amount : S\$4,005.00 Revised Estimate Amount : S\$2,140.00 "Check" Items Amount : S\$145.00 Total : S\$2,285.00 Market Value : S\$59,000.00 COE/PARF Rebate : S\$47,805.00 Nett Value : S\$11,195.00 Thanks Veron Chen

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 19960719

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 625643

Your ref: S8M00C5L

Our ref: CS/ASM18005764/Uvd3

Date: 5/4/2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam

PRELIMINARY ADVICE OF VEHICLE NO. SDM 5028Y


We thank for your instruction on 28/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on
4/4/2018 at the premises of M/s SME MOTOR PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$4,005.00
Revised Estimate Amount	: S\$2,140.00
"Check" Items Amount	: S\$145.00
Total	: S\$2,285.00
Market Value	: S\$59,000.00
COE/PARF Rebate	: S\$47,805.00
Nett Value	: S\$11,195.00

Description of Damage:

The vehicle sustained damages at the
n/s body



Survey date and time: 4/4/2018 at 3PM

We have authorize repair.

No of days: 3 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/03/2018 17:21
Date Of Accident	19/03/2018 10:00
Exact Location Of Accident	52 LORONG G TELOK KURAU CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDM5028Y
Insured/Policyholder	
Name Of Registered Owner	HO NGIAP KUM
NRIC No	S0088037Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96348442
Alternative Phone No	OFFICE-96348442

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	PASSAT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1260551
Cover Note Number	

Driver

Name of Driver	HO NGIAP KUM
NRIC No	S0088037Z
Date Of Birth	28/02/1950
Occupation	INDOOR
Date Of Driving Pass	23/01/1975
Driving Experience	43 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96348442
Fax Number	
Contact Number	OFFICE-96348442
Email Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"); the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



redefining / Insurance

Date: 27/03/2008

To: Owner of Vehicle Number: SDM 50284

The following has been advised to you via your workshop, SDH MOTOR PTE LTD through their staff, _____

Please tick the applicable box if you had been advice on the content as seen below:

☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

☐ You had been advised by the workshop on the liability and merits of the case accordingly.

☒ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.

☐ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.

☒ There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.

☐ The estimated waiting time for the spare parts to arrive is _____. The estimated arrival time does not include the repair period.

☐ You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.

☒ For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.

For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using any combination of genuine original parts and/or original equipment manufacturer (OEM) parts.

☒ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.

☐ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.

☐ Others _____

Signed and acknowledge by:

Name and signature of policyholder/authorised driver

Name and signature of workshop personnel including company stamp

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 8037Z

Vehicle Details

Vehicle No.: SDM5028Y
Vehicle to be Exported: No
Intended De-registration Date: 05 Apr 2018
Vehicle Make: VOLKSWAGEN
Vehicle Model: PASSAT 1.8 TSI AT 3624H7
Primary Colour: Black
Manufacturing Year: 2011
Engine No.: CDA270910
Chassis No.: WVVZZZ3CZCP039921
Maximum Power Output: 118.0 kW (158 bhp)
Open Market Value: \$29,836.00
Original Registration Date: 10 Feb 2012
First Registration Date: 10 Feb 2012
Transfer Count: 0
Actual ARF Paid: \$29,836.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 09 Feb 2022
PARF Rebate Amount: \$19,393.00

Intended COE Rebate Details

COE Expiry Date: 09 Feb 2022
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$73,890.00
COE Rebate Amount: \$28,412.00
Total Rebate Amount: \$47,805.00

The information contained herein is correct as at 05 Apr 2018

OK

VEHICLE NO.: SDM5028Y
MAKE: HYUNDAI
MODEL: SONATA
YEAR OF MAKE: 2011
CHASSIS NO.: WYWZZZ3CZCP039921
SUPPLIERS : HEXING

Authorised
Take photo before repair
4/4/18
3 day.

S/N	Parts Description	QTY	Amount
PARTS			
1	FRT DOOR LH <i>3rd 500</i>	1	\$1,100.00 ✓
2	FRT DOOR CHOME LH <i>2nd</i>	1	\$90.00 ✓
3	FRT DOOR TOP STICKER LH <i>11</i>	1	\$145.00 ✗
4	ROCKER PANEL LH <i>12</i>	1	\$1,300.00 ✗
5	<i>Rocker panel garnish 114</i> <i>2nd</i> ✓		
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
TOTAL PARTS			\$2,635.00
S/N			
1			
2			
TOTAL S/N			\$0.00
LABOUR :			
1	WIRE CHECKING		\$20.00 ✓
2	TRANSFER DOOR COMPONENT FROM OLD TO NEW		\$100.00 50
3	REMOVE & REFIX CUSHION AND SEAT (CARPET)		\$250.00 114x
4	LABOUR CHARGE		\$500.00 - 400
5	SPRAY PAINTING		\$500.00 480
6			
TOTAL LABOUR			\$1,370.00 950
TOTAL			\$4,005.00 4590
GST 7%			\$280.35
Acknowledged by Repairer			\$4,285.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

SDM5028Y
VOLKSWAGEN
PASSAT
2011
SUPPLEMENTARY
HEXING

[illegible]



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
 TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
 DAIHATSU / KIA / SUZUKI / HONDA
 TEL: 6291 2827 FAX: 6296 4390
 A/C: 6291 1886 FAX: 6291 7717
 Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: SME MOTOR PTE LTD

1 KAKI BUKIT AVE 6

#02-15/16/17/18 AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

SDM5028Y

SEBAST

NO: DLI9201946
 PAGE: 1
 DATE: 13/04/2018
 A/C CODE: LIDSM446
 TERMS: CR

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
Our D/O No: DDO9021478					
1 V3AA 831 055	DOOR FR LH	VD-2	1	1,100.00	1,100.00
2 V3AA 854 939 A GRU	DOOR PROT FR LH	VB14-2	1	90.00	90.00
3 V3AA 853 091 C GRU	ROCKER MLDING LH	VBA-31	1	450.00	450.00
Our D/O No: DDO9021483					
1 V3C4 837 701 D 5AP	DOOR SEAL FR RH	VB5-2	1	135.00	135.00
TOTAL QUANTITY			4	TOTAL	SIN 1,775.00
				ADD GST @ 7%	124.25
				GRAND TOTAL	SIN 1,899.25

#02-18

Print / MT / 13/04/2018 10:40:09 AM

SALESMAN: MT

This document is computer generated. No signature required

GOODS SOLD ARE NOT RETURNABLE



GOODS RECEIVED BY



SERVICE REQUESTS MESSAGES CLAIMS

<< Service Request Details

Claim	S8M00C5L
Reference	
None 	Loss Date
March 19, 2018	Request Date
March 28, 2018	Due Date
March 29, 2019	Vendor Name
LKK AUTO CONSULTANTS PTE LOSS LTD (OD)	Type of Services
Own Damage	

Actions

Next Step

Finish the work

Complete Work

More

Vehicle Information

Incident Vehicle Registration #

SDM5028Y

Make

VOLKSWAGEN

Service Address

1 Kaki Bukit Ave 6 #02-15, , 417883

Model

PASSAT 1.8

Primary Contact/Insured

HO NGIAP KUM
52 LORONG G TELOK KURAU,
#05-04, 426235, Singapore
96348442

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
PRELI ADVISED.pdf	Evidence	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	April 5, 2018
MARK ESTIMATE.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	April 5, 2018
SURVEY PHOTOS.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	April 5, 2018
SDM5028Y 1.pdf	Reports & Statement	GIA Report	SME MOTOR PTE LTD	March 28, 2018
SDM5028Y ESTIMATE.pdf	Reports & Statement	GIA Report	SME MOTOR PTE LTD	March 28, 2018
SDM5028Y - Accident on 22.03.PDF	Reports & Statement	GIA Report	TEO Kitty	March 28, 2018

SERVICE REQUESTS

MESSAGES

CLAIMS

<<

Service Request Details

Claim	S8M00C5L
Reference	
None 	Loss Date
March 19, 2018	Request Date
March 28, 2018	Due Date
March 29, 2019	Vendor Name
LKK AUTO CONSULTANTS PTE LOSS LTD (OD)	Type of Services
Own Damage	

Actions

Next Step

Finish the work

Complete Work

More

Vehicle Information

Incident Vehicle Registration #

SDM5028Y

Make

Service Address

Model

VOLKSWAGEN

PASSAT 1.8

Kaki Bukit Ave 6 #02-15, , 417883

1

Primary Contact/Insured

HO NGIAP KUM

52 LORONG G TELOK KURAU, #05-04, 426235, Singapore

96348442

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SDM5028Y

mm/dd/yyyy

Registration State

Registration Date *

SINGAPORE

02/10/2012

Mileage

6
Age of Vehicle

Driver Details

CATEGORY

CATEGORY	Driver Name
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

POLICY INFORMAT... 2012

FNOL INFORMATI... HO NGIAP KUM

ASSESSMENT INFO... 2011

POST SURVEY INF...

ASSESSMENT INFO...

FNOL INFORMATI... 43

CATEGORY

Engine No

POST SURVEY INF...

CATEGORY

Driver License #

POLICY INFORMAT ... CDA270910

FNOL INFORMATI...

ASSESSMENT INFO...

POST SURVEY INF...

CATEGORY

Engine Capacity

CATEGORY

License Type

POLICY INFORMAT ...

FNOL INFORMATI...

ASSESSMENT INFO...

POST SURVEY INF...

CATEGORY

Sum Insured

CATEGORY

License Issue Date

POLICY INFORMAT ... 0

FNOL INFORMATI...

ASSESSMENT INFO...

POST SURVEY INF...

CATEGORY

Market Value

CATEGORY

License Expiration Date

POLICY INFORMAT ... 0

FNOL INFORMATI...

ASSESSMENT INFO...

POST SURVEY INF...

CATEGORY

Address

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Front left side

CONTINENTAL 6mm

Front right side

CONTINENTAL 6mm

Rear left side

CONTINENTAL 6mm

Rear right side

CONTINENTAL 6mm

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Adult	Anytime	Danny
-------	---------	-------

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
	1	1			FRT DOOR LH			Damaged	1100				1100	Review
	2	1			FRT DOOR CHROME LH			Bent	90				90	Review
	3	1			FRONT DOOR TOP STICKER LH			Serviceable	0				0	Review
	4	1			ROCKER PANEL LH			Repair	0				0	Review
	5	1			ROCKER PANEL GARNISH LH			Damaged	450				450	Review
	6	1			FRT DOOR RUBBER (AT DOOR) LH			Necessary	135				135	Review

Acid	Approve	Deny
------	---------	------

Labour

SERVICE REQUESTS

MESSAGES

CLAIMS

<< Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT

SR NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS OF REPAIR

Reviewing

3



SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary Claim Amount \$2,725.00 Claim Amount \$2,725.00

CATEGORY ESTIMATE REVISED AMOUNT

Labour \$950.00 \$950.00

Spare Parts \$1,775.00 \$1,775.00

Submit for Review