

adla.

CC4/1111800 5767, 4 wbr 9

Surveyor:

marcus

DOI:

ASSIGNMENT

24/18

Date / Time:

27/3/18

Registered in Merimen:

28/3/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 3741E

Name of Insured:

UPU

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

25/3/18

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO. Driver Name / Age:

John Kim Bole WASHINGTON

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

MT18020808

Policy No.:

MON0015

Make / Model:

HYUNDAI

Place of Accident:

RAPLES QUAY CROSS ST

OI GIA REPORT: YES / NO

(YES / NO)

TP GIA REPORT: YES / NO

(YES / NO)

Insured Liability: %

Final? Yes / No

SLP 8549P



INSRS:

WSP:

Tel:

Liability:

RMKS:

pegasus



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time		STAGE	DATE / PIC
24/18	SLP 8549P - X	Non-Reporting Itr (1st):	
		Non-Reporting Itr (2nd):	
		Non-Reporting Itr (Final):	
		Notification Itr (if non-pickup):	
		Call OI:	
		After call Itr to OI:	
		Documentation Check List:	Handler Typist
		Notification Itr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
		After call Itr to OI:	<input type="checkbox"/> <input type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Towing Invoice:	<input type="checkbox"/> <input type="checkbox"/>
		LTA / GIA:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
		PIR:	<input type="checkbox"/> <input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		LOD:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
		Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: SS (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: 11/10/18 Confirm with: Sharon Email Call

Final Liability: % 50 (Agreed / Assessed) BOLA S/N No.: Nil

Repair Cost: 2675.00 SS 1337.50

Loss of Rental (LOR): 240.00 SS 100.43 (3 days) x 66.95

Loss of Use (LOU): 120.00 SS 60 (540 x 3 days)

Loss of Income (LOI): SS (\$ x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: SS

Medical: SS

Disbursement: SS (e.g. Tow/Independent)

Legal Cost: SS

Total: 2995.85 SS 1497.93 Global Sum SS: 1600.00

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: SS 1600.00 Name 1: Pegasus Engineering & Trading Pte Ltd

Payee 2: (Strike if N.A.) SS Name 2:

Payee 3: (Strike if N.A.) SS Name 3:

COPIED

REF: III

W

ASSIGNMENT

From: _____ Date: 2/4/18

Estimated Cost: _____

OD TP WS TP RES OD RES EVA INV MV

To inspect Vehicle No: SLP8849P

at Workshop m/s

of 51 Defu Lane 10

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / FR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{1/wp}

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLP8849P Yr Regn: 6 / 17

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA /

Make: mazda 3 CC: 1496

Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 72859 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BN22A8H0154490

Gen. Cond: Good / Fair / Poor / BurntSteering: Harder / Jammed / Leaked / Burnt orBrake: Harder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205 / 60R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 25/3/18 D.O.I: 2/4/18

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S R/L.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

2/4/18 confirmed 2/5 \$2500 with sam.

(Red) = \$1921.44
45%

Date/Time: File Pass to?

 : Preli. Report

Days Of Repair: _____

1)

 : Final Report

Resurvey No. of Trip: _____

Date/Time: File Return to?

Survey Fee: _____

2)

Add Fee: Site Insp \$

Transportation: _____

 Interview \$

) 3-PS \$

 Tech. Insp \$

Phone: _____

 Weekend \$

) 1st: _____

Report Format: _____

Lump Sum / I.B. / \$

) 2nd: _____

) 3rd: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18005767/wb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 28-03-2018	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 3341K	Veh. Inspected	SLP 8849P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	28/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/03/2018	Inspection Date	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/03-1237	Quotation Date : 26/03/2018	Terms : 30 DAYS
Vehicle No : SLP8849P	Chassis No : JM6BN22A8H0154490	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURED : III, TP INSURED VEHICLE NO: SHC3341K, DOA: 25.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
21	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	600.0000	380 600.00
22	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	700.0000	600 700.00

341.6

S.M.K. Auto Care (Pte) Ltd hence notify the Repairer the following:
 • To resurvey and re-spray painting
 • To supply damaged parts and accessories
 • Parts prices are subject to confirmation
 • This survey is on a "Without Prejudice" basis
 • All original documents must be submitted
 • Supplemental terms must be surveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Sub Total	4,421.44
GST(7.00%)	309.50
Total (SGD)	4,730.94

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 1345N

Vehicle Details

Vehicle No.: SLP8849P
Vehicle to be Exported: Yes
Intended De-registration Date: 26 Mar 2018
Vehicle Make: MAZDA
Vehicle Model: MAZDA3 SEDAN 1.5 AT EU6
Primary Colour: Grey
Manufacturing Year: 2017
Engine No.: P520446474
Chassis No.: JM6BN22A8H0154490
Maximum Power Output: 88.0 kW (118 bhp)
Open Market Value: \$14,761.00
Original Registration Date: 21 Jun 2017
First Registration Date: 21 Jun 2017
Transfer Count: 0
Actual ARF Paid: \$9,761.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 20 Jun 2027
PARF Rebate Amount: \$7,320.00

Intended COE Rebate Details

COE Expiry Date: 20 Jun 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$46,489.00
COE Rebate Amount: \$37,191.00
Total Rebate Amount: \$44,511.00

The information contained herein is correct as at 26 Mar 2018

OK

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.Z.400
Cars for Hire

COMMERCIAL VEHICLE - FLEET
Comprehensive

Certificate No. A 29069774 MRF

Excess: SGD2,000

1. Index Mark and Registration Number of Vehicle

SLP8849F

2. Name of Policyholder

Grab Rentals 2 Pte. Ltd.

3. Effective Date of the Commencement of Insurance for the purposes of the Act

01/02/2018

4. Date of Expiry of Insurance

31/01/2019

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use for the carriage of passengers or goods in connection with the Policyholder's business.

Use for social domestic and pleasure purposes.

The Policy does not cover

- (1) Use for racing pace-making reliability trial or speed-testing.
- (2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers



Chief Executive Officer

View Received Message

This mail is associated with :

***SLP8849P (MCT18030808)
[SHC3341K]**

TP

GRAB RENTALS 2 PTE LTD

Mar 25 2018 5:00PM

[COMFORT TRANSPORTATION PTE LTD]
Pegasus Engineering & Trading Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on **01/10/2018 09:19 AM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1600.00) - SLP8849P - Claim Handler: Zuhaidah Bte Samsuri

Approved:1600.00:Vivian, as spoken please proceed to negotiate settlement at global \$1600 (all-in).

DOCUMENTS SUMMARY

There are no documents.



9A Lok Yang Singapore 628628
c/o 51 Defu Lane 10 Singapore 539216

Tel: 6858 1846 / HP 9628 6508
Fax: 6858 0877

Our Ref SLP8849P
Your Ref SAC3341K

Date 05/06/2018

Claims Department - Executive In charge
Inclin Int'l Insurance Pte Ltd

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING SLP8849P/SAC3341K on 25/03/2018
(Pte Hire)

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

- Original survey report/ _____ copies of photographs _____
- Original Tax-invoice number 2018/05-1224 police report / police result
- Certificate Of Insurance _____ Vehicle search result
- Authorization To Act - Owner/Hirer _____

*Survey under insurance instruction / Independent surveyor / No survey.

a) Cost of repair (inclusive GST)	\$ <u>2675.00</u>
b) Survey fees / Photographs as per request	\$ _____
c) Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ _____
d) Loss of rental @ <u>3</u> days <u>\$66.95</u>	\$ <u>200.85</u>
e) Loss of earnings @ <u>3</u> days <u>\$100.00</u>	\$ <u>300.00</u>
f) Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$ <u>200.00</u>
g) _____	\$ _____
Total	\$ <u>3375.85</u>

* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Pegasus Engineering & Trading Pte Ltd" within 28 days.

Yours faithfully,

Sharon Ow

Email: claims@pegasusengrg.com.sg

AUTHORIZATION TO ACT

TO: PEGASUS ENGINEERING & TRADING PTE LTD

FROM: OWNER OF VEHICLE NUMBER SLP 8849A

ACCIDENT INVOLVING SHL 3341K

ALONG/AT Raffles Quay on 25/03/2018

We hereby authorize you to act on our behalf in pursuance of our claim for all damages during the repair arising out of the above accident.

This letter serve as the 'AUTHORITY TO ACT'.

We also hereby authorize all agreed settlement payment be made in favour to PEGASUS ENGINEERING & TRADING PTE LTD.

Name : Grab Rentals 2 Pte Ltd

Co Reg No : 201701345N

Address : 18 Sin Ming Lane #01-08 Midview city Singapore 573960

Contact : 6655 0005

Date : 26/03/2018

Signature



Owner

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18030808
Claimant Ref: SLP 8849P

We/I, Pegasus Engineering & Trading Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 1,600.00 {Global Sum / repair cost}, S\$ _____ (loss of use/rental), S\$ _____ (search fee), vehicle no. SLP 8849P that was damaged pursuant to the accident which occurred on 25/03/2018 (date) at RAFFLES QUAY X CROSS ST (location) involving vehicle no. SHC 3341K (insured vehicle). This is pursuant to the inspection conducted on 02/04/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner GRAB RENTALS 2 PTE LTD ("the third party claimant") of vehicle no. SLP 8849P to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLP 8849P (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 1,600.00 to Pegasus Engineering & Trading Pte Ltd

Dated this 01 day of 10 20 18

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:


Signed by "the workshop" (with )

Sharon CW
S7267542H
40 51 Defu Lane 10
Singapore 53936
Singaporean
clerk

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:


Signed by appointed Surveyor


LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25,
Paya Ubi Industrial Park
Singapore 408933

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Tax Invoice

From :

PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216

Officer in Charge : WEE TZE FAH
Tel :
Email :

Customer :

GRAB RENTALS 2 PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax :

Inv No : IV18/05-1224

Inv Date : 22/05/2018

Term : 30 DAYS

Vehicle No : SLP8849P

Chassis No : JM6BN22A8H0154490

Model : MAZDA 3

Remarks : TP INSURED : III, TP INSURED VEHICLE NO: SHC3341K, DOA: 25.03.2018

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	TO LUMP SUM REPAIR AS RECOMMENDED BY SURVEYOR	1	2,500.0000	2,500.00

Cheques should be made payable to PEGASUS ENGINEERING & TRADING PTE LTD

Sub Total 2,500.00
GST(7.00%) 175.00
Total (SGD) 2,675.00

PEGASUS ENGINEERING & TRADING PTE LTD




Authorised Signature



Our Ref: GR-ACC-2017-02

01 June 2017

Pagagus Engineering & Trading Pte Ltd
No. 51 Defu Lane 10
Singapore 539216

Mailing Address
18 Sin Ming Lane,
#01-08 Midview City,
Singapore 573960
Co. No. 201617200G

To whom it may concern,

Re: Vehicle Rental Rates for Loss of Rental Claims.

With regards to the above subject matter, we are pleased to inform you our Grab Rental rate for our various vehicles which are as follows:

S/No.	Make & Model	Daily Rental Rates (S\$)
01	Toyota Prius 1,798cc, 90kw, 120bhp, Automatic	\$ 79.95
02	Mazda 3 1.5 (A) Sedan	\$ 66.95
03	Nissan Qashqai 1.2L	\$78.95
04	Honda Vezel 1.5L	\$77.95
05	Honda Vezel 1.5L Hybrid	\$84.95
06	Toyota Vios 1.5L	\$66.95

Please note that the above stated rate is our daily rental rate to our drivers. For your necessary actions on third party accident claims on loss of rental.

Yours faithfully,


Tay Chee Wee
Grab Rental Pte Ltd

GRAB Singapore

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Mar 2018 Edit Reg		27 Mar 2018 00:00 Edit Adj Rpt	S\$2,500.00 Edit Estimates	S\$2,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	GRAB RENTALS 2 PTE LTD , Co. Reg. No.: 201701345N								
Vehicle Reg. No.:	SLP8849P	Date of Loss:	25/03/2018 17:00 - :59 [9 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18030808	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC3341K	Policy No. (Claimant):	A29069766MKF						
		Excess:							
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 09/04/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> • III_SG (01/10/2018): Alert - Adj Mandate Approved (S\$1600.00) - SLP8849P - Claim Handler: Zuhaidah Bt... • III_SG (21/09/2018): Alert - Adj Mandate Approved (S\$1600.00) - SLP8849P - Claim Handler: Zuhaidah Bt... • III_SG (16/07/2018): Alert - Adj Mandate Approved (S\$1497.93) - SLP8849P - Claim Handler: Zuhaidah Bt... • III_SG (27/06/2018): Alert - Adj Mandate Maintained - SLP8849P - Claim Handler: Zuhaidah Bte Samsuri • III_SG (20/04/2018): Alert - Adj Mandate Approved (S\$0.00) - SLP8849P - Claim Handler: Zuhaidah Bte S... • III_SG (03/04/2018): Alert - Adj Mandate Maintained - SLP8849P - Claim Handler: Zuhaidah Bte Samsuri 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP8849P (MCT18030808)
[SHC3341K]

TP

GRAB RENTALS 2 PTE LTD

Mar 25 2018 5:00PM

[COMFORT TRANSPORTATION PTE LTD]

Pegasus Engineering & Trading Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Video									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print					
1	03/04/18 11:11	Video - Other(OID)		Load MP4						
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	02/04/18 17:38	Chassis Number		Load JPG	<input checked="" type="checkbox"/>					
2	02/04/18 17:38	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>					
3	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
4	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
5	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
6	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
7	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
8	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
9	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
10	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
11	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
12	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
13	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
14	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
15	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
16	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
17	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
18	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
19	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
20	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
21	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
22	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
23	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
24	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
25	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
26	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
27	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
28	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
29	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
30	02/04/18 17:39	General View		Load JPG	<input checked="" type="checkbox"/>					
31	28/06/18 15:44	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
32	28/06/18 15:44	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
33	28/06/18 15:44	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/03/18 16:01	EMAIL FROM III DD 27032018	Load PDF	
2	28/03/18 16:01	TP ESTIMATE	Load PDF	
3	28/03/18 16:01	TP GIA REPORT	Load PDF	
4	03/04/18 18:52	TP ESTIMATE- MARKED	Load PDF	
5	30/04/18 14:03	Accident scene photo from TP	Load DOCX	
6	21/06/18 08:43	WORKSHOP INVOICE	Load PDF	
7	21/06/18 08:43	RENTAL RECEIPT	Load PDF	
8	21/06/18 08:43	LOD	Load PDF	
9	08/10/18 09:07	AUTHORISATION TO ACT FORM	Load PDF	
10	08/10/18 09:07	DISCHARGE VOUCHER	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	29/03/18 08:59	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18005767/UWB3Q2

Date: 08/10/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No: MCOM0015
Claimant Vehicle No : SLP8849P	Insured Vehicle No : SHC3341K
Date of Loss: 25/03/2018	Nature of Claim: TP
	Claim No: MCT18030808

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP8849P	Engine No: P520446474
Make & Model: MAZDA 3, 1.5 SEDAN L SP.6EAT (A)	Chassis No: JM6BN22A8H0154490
Reg. Date: 21/06/2017 (Man. Year: 2017)	Odometer: 72859 km
Colour: Grey	
Engine Capacity: 1496 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,631.44	2,051.60	579.84	22.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,790.00	1,090.00	700.00	39.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,421.44	3,141.60	1,279.84	28.95
Approved Total (Overridden) (S\$)		2,500.00		
	(S\$) 4,421.44	2,500.00	1,921.44	43.46
+ GST 7.00/7.00% (S\$)	309.50	175.00	134.50	43.46
Nett Amount (S\$)	4,730.94	2,675.00	2,055.94	43.46
+ Loss of Use (3.0 x S\$40.00/day) (S\$)		120.00		
+ Car Rental (3.0 x S\$66.95/day) (S\$)		200.85		
		(S\$) 2,995.85		
Liabe Amount (50.00%) (S\$)		1,497.93		
Global Sum Settlement (S\$)		1,600.00		

INSPECTION

Date of Assignment: 27/03/2018

Date Inspected: 02/04/2018 Inspected At: Pegasus Engineering & Trading Pte Ltd
(HQ)
51 DEFU LANE 10
Singapore 539216

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2018)
Parts: 143	MAZDA 3 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLP8849P)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	825.50 FL	*825.50 FL
2	1		*FRONT BUMPER SIDE RETAINER	Bent	12.00 FL	*12.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	478.80 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT COVER	Not Necessary	67.00 FL	*- FL
5	4		*FRONT BUMPER REINFORCEMENT COVER CLIPS	Not Necessary	20.00 FL	*- FL
6	6		*FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
7	1		*N/S FRONT BUMPER INDICATOR LIGHT	Cracked	140.00 FL	*140.00 FL
8	1		*FRONT BUMPER INDICATOR LIGHT GARNISH	Scratched	55.00 FL	*55.00 FL
9	1		*FRONT BUMPER INDICATOR LIGHT GARNISH EXTENSION	Not Necessary	35.00 FL	*- FL
10	1		*N/S HEAD LAMP	Broken	1,020.00 FL	*1,020.00 FL
11	1		*N/S FRONT FENDER	Dented / Buckled	334.00 FL	*334.00 FL
12	1		*FRONT FENDER INNER LINER	Deformed / Torn	130.00 FL	*130.00 FL
13	4		*FRONT FENDER INNER LINER CLIPS	Necessary	18.00 FL	*18.00 FL
14	1		*N/S FRONT WHEEL HUB CAP (CUT)	Not Consistent With The Impact	124.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,289.30	2,564.50
- List Item Discount on L Items 20.00/20.00% (S\$)	657.86	512.90
Total Parts (S\$)	2,631.44	2,051.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	120.00	60.00
2	TO DISMANTLE AIR-CON ASSY,REMOVE AND RENEWAL OF PARTS ,VACUUM AND CHARGE IN GAS	New	200.00	0.00
3	TO TRANSFER OF N/S FRONT TYRE ,RIM AND ON WHEEL BALANCING	New	30.00	0.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	80.00	30.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	600.00	380.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	700.00	600.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
Gross Labour Cost (S\$)			1,790.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >