

ASS. REC. BY:

REF: CS/ICS18005805/Mlvbmz

Special Instruction:

Supervisor:

Ma

ASSIGNMENT (Office)

From (Person): Janice Goh of ICS Date/Time: 28032018 536pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLM 3615X Insured: SHU 3587K

at Workshop m/s Vermogen Tel: 6904 4596

of 6 Benoi Sector

Policy No: Claim No: DMPC1800112H

Sum Insured: Excess:

Make of Veh: D.O.A. 27032018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' 29032018 H.O.D. Endorsement:

Date/Time: 28032018 545pm Person Contacted: Minoko Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLM 3615X - X
	SHU 3587K - X
26/4/18	LS \$ 1950 confirmed by email (Ref 10,958.53, 85%)

REF: TCS

ASSIGNMENT

From:

Date:

29/03/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLM 3615X

at Workshop m/s

Vermogen

of

6 Benoï Sector

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLM 3615X

Yr Regn:

DET / 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA BENTA

C.C

1496

Colour:

RED

A/C:

Insured / Std / NI / NA

Sp. Reading

80471

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NHP 1707059598

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60/R16.

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Achilles

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

29/03/2018

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The MIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 02 MAY 2018

Date/Time: File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

2/5 - typist

Report Format:

TP

Lump Sum / I.B.I. (\$) 1950

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

\$ + R5 \$

Photos

Others

TOTAL

350
10

360



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS/ICS18005805/M1vb

7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

Date : 28-03-2018



Code : ICS

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGU 3587K	Veh. Inspected	SLM 3615X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JANICE GOH	Assign Date	28/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	27/03/2018	Inspection Date	29/03/2018
Survey held at	6 BENOI SECTOR		
Repairer	VERMOGEN ACE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Veron Chen (LKKAUTO)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Wednesday, 2 May 2018 9:07 AM
To: Veron Chen (LKKAUTO); SUR; ECICS Claims
Subject: RE: ECICS:PLEASE ARRANGE TP SURVEY FOR (OUR REF:SLM3615X) YOUR REF:SGU3587K DOA:27/03/2018

Dear Veron

Our ref DMPC1800112H.
Thank you

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Monday, 30 April, 2018 9:35 AM
To: SUR; ECICS Claims; Janice Goh Siew Geok (ECICS, Claims)
Subject: RE: ECICS:PLEASE ARRANGE TP SURVEY FOR (OUR REF:SLM3615X) YOUR REF:SGU3587K DOA:27/03/2018

Dear Janice,

Please provide us the claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 26 April 2018 5:08 PM
To: SUR <sur@lkkauto.com>; 'ECICS Claims' <claims@ecics.com.sg>; 'Janice Goh Siew Geok (ECICS, Claims)' <Janice_Goh@ecics.com.sg>
Subject: RE: ECICS:PLEASE ARRANGE TP SURVEY FOR (OUR REF:SLM3615X) YOUR REF:SGU3587K DOA:27/03/2018

DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Minoko [<mailto:minokovermogenace@gmail.com>]

Sent: Wednesday, 28 March, 2018 3:45 PM

To: ECICS Claims

Cc: pila.vermogenace@gmail.com; ezelvermogenace@gmail.com; 'juan paulo baldoz'; edmondvermogenace@gmail.com; 'vmg.vermogenace'; vermogenace@gmail.com

Subject: FW: ECICS:PLEASE ARRANGE TP SURVEY FOR (OUR REF:SLM3615X) YOUR REF:SGU3587K
DOA:27/03/2018

Dear Arrange survey dept

Kindly arrange TP survey on 28/03/2018 (Thursday) following detail & attach here GIA report:

Survey before repair

Your Vehicle: SGU3587K

Our Vehicle: SLM3615X

DOA : 27/03/2018

AOL :WOODLANDS RD

Vehicle Location: 6 BENOI SECTOR SINGAPORE 629904

Thank You.

Best Regards,

Minoko

Vermogen Ace Pte Ltd




1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 6904 4596

Fax: 6694 4929

		
---	---	---

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Catherine Chong (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Wednesday, 28 March, 2018 5:36 PM
To: Minoko; assignments@lkkauto.com
Cc: pila.vermogenace@gmail.com; ezelvermogenace@gmail.com; 'juan paulo baldoz'; edmondvermogenace@gmail.com; 'vmg.vermogenace'; vermogenace@gmail.com; ECICS Claims
Subject: RE: ECICS:PLEASE ARRANGE TP SURVEY FOR (OUR REF:SLM3615X) YOUR REF:SGU3587K DOA:27/03/2018
Attachments: SLM3615X 27MAR2018 TP.PDF

Without Prejudice

Dear Minoko

Thank you for your email.
We will appoint LKK for the TP PRI.

Aside to LKK

Please assist to arrange for TP PRI.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

From: Minoko [mailto:minokovermogenace@gmail.com]
Sent: Wednesday, 28 March, 2018 3:45 PM
To: ECICS Claims
Cc: pila.vermogenace@gmail.com; ezelvermogenace@gmail.com; 'juan paulo baldoz'; edmondvermogenace@gmail.com; 'vmg.vermogenace'; vermogenace@gmail.com
Subject: FW: ECICS:PLEASE ARRANGE TP SURVEY FOR (OUR REF:SLM3615X) YOUR REF:SGU3587K DOA:27/03/2018

Dear Arrange survey dept

Kindly arrange TP survey on **28/03/2018 (Thursday)** following detail & attach here GIA report:

Survey before repair

Your Vehicle: SGU3587K

Our Vehicle: SLM3615X

DOA : 27/03/2018

AOL : WOODLANDS RD

Vehicle Location: 6 BENOI SECTOR SINGAPORE 629904

Thank You.

Best Regards,

Minoko

Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 6904 4596

Fax: 6694 4929

		
---	---	---

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 26 April 2018 4:59 PM
To: 'pila@vermogen-group.com'
Cc: 'Baldoz Juan Paulo Bongon'; 'Tejano Exequiel Dawal'; 'Minoko Chan'; SUR
Subject: RE: SLM 3615X-DOA: 27/3/2018

Dear Pila,

Noted with thanks.

Final invoice and all supporting documents sent over to ECICS

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: pila@vermogen-group.com [mailto:pila@vermogen-group.com]
Sent: Thursday, 26 April 2018 3:49 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: 'Baldoz Juan Paulo Bongon' <paulo.b@vermogen-group.com>; 'Tejano Exequiel Dawal' <ezel.t@vermogen-group.com>; 'Minoko Chan' <minoko@vermogen-group.com>
Subject: RE: SLM 3615X-DOA: 27/3/2018

Dear Veron,

Confirmed COR \$1,950.00 , 4 days.

Thanks & regards,
Pila

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Thursday, April 26, 2018 3:43 PM
To: pila.vermogenace <pila.vermogenace@gmail.com>; Minoko <minokovermogenace@gmail.com>
Subject: FW: SLM 3615X-DOA: 27/3/2018

Dear Pila,

Please kindly assist.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

From: Veron Chen (LKKAuto)
Sent: Tuesday, 24 April 2018 5:28 PM
To: 'Minoko' <minokovermogenace@gmail.com>
Subject: RE: SLM 3615X-DOA: 27/3/2018

Dear Minoko,

Offer Lump Sum \$1950 @ 4 working days.

Please confirmed and forward us after paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Friday, 20 April 2018 3:27 PM
To: Minoko <minokovermogenace@gmail.com>
Subject: SLM 3615X-DOA: 27/3/2018

Dear Minoko,

Offer Lump Sum \$1950 @ 4 working days.

Please confirmed and forward us after paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/03/2018 14:52
Date Of Accident	27/03/2018 13:40
Exact Location Of Accident	WOODLANDS RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM3615X
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66944919

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA
Exact Purpose for which vehicle was being used at time of accident	HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995110
Cover Note Number	

Driver

Name of Driver	HAN TECK CHOU (HAN DECHOU)
NRIC No	S7506545J
Date Of Birth	15/02/1975
Occupation	OUTDOOR
Date Of Driving Pass	24/07/1997
Driving Experience	20 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90106639
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	44 BENOI RD BLOCK B
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - U-TURN
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO PHOTOS ATTACHED, THANK YOU.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGU3587K
Vehicle Make/Model/Colour	
Details Of Properties	VEH. B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

3/27/2018

Woodlands Rd - Google Maps

Go gle Maps Woodlands Rd



Image capture: Nov 2017 © 2018 Google

Singapore

Google, Inc.

Street View - Nov 2017

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


Accident Sketch Plan Pg. 2

SKETCH PLAN

Woodlands Rd

(A) SLM 3615 X

(B) SEU 35871C



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Woodlands Rd and I was initiating a U-turn. Upon completing the U-turn a car from minor collided with my left portion and cause the damage. I has video footage in my in car camera.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

YIRA RAHMAN

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLM3615X**
 Vehicle Reg. Date: **28-03-17**
 Make / Model : **T. SIENTA HYBRID 1.5X A**
 Engine No. : **1NZR439809**
 Chassis No. : **NHP1707059598**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	FRONT FENDER LH	X	\$ 690.00	NN.	
2	1	FRONT FENDER EMBLEM - HYBRID	X		NN.	
3	1	Front door LH	X	\$ 1,344.00	at.	
4	1	Front door hinge top	X	\$ 109.00	gnc	
5	1	Front door hinge bottom	X	\$ 109.00	gnc	
6	1	Front door lock LH	X	\$ 855.00	gnc	
7	1	Front door catch LH	X	\$ 44.00	gnc	
8	1	Front door weatherstrip LH	X	\$ 219.00	gnc	
9	1	Front door power window motor LH	X	\$ 647.00	gnc	
10	1	Front door window moulding LH	X	\$ 184.00	gnc	
11	1	Front door window regulator LH	X	\$ 430.00	gnc	
12	1	Front door trim LH	X	\$ 1,500.00	gnc	
13	1set	Front door trim clips	X	\$ 40.00	gnc	
14	1	Front door stopper LH	X	\$ 30.00	gnc	
15	1	REAR SLIDING DOOR LH	X	\$ 1,658.00	R.	
16	1	REAR SLIDING DOOR PROTECTOR LH	X	\$ 247.00	gnc	
17	1	REAR DOOR LOWER GARNISH LH	X	\$ 195.00	gnc	
18	1	REAR SLIDING DOOR CHANNEL LH	X	\$ 189.00	gnc	
19	1	REAR SLIDING DOOR STICKER LH	X	\$ 79.90	gnc	
20	1	REAR SLIDING DOOR RUBBER LH	X	\$ 271.40	gnc	
21	1	REAR FENDER LH	X	\$ 1,510.40	gnc	
22	1	REAR FENDER LOWER GARNISH LH	X	\$ 176.00	gnc	
23	1	REAR FENDER CENTER GARNISH LH	X	\$ 497.00	gnc	
24	0	0				
25	0	0				
26	0	0				
27	0	0				
28	0	0				
29	0	0				
30	0	0				
31	0	0				
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLM3615X
 Vehicle Reg. Date: 28-03-17
 Make / Model : T. SIENTA HYBRID 1.5X A
 Engine No. : 1NZR439809
 Chassis No. : NHP1707059598

PAGE 1

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	To remove and replace damaged parts and to panel beating accident area.	\$ 1,800.00	500
2	To putty and respray replaced parts and accident repair area.	\$ 2,000.00	500
3	To check and rectify wiring after disconnect and connect.	\$ 150.00	30
4	To rustproof accident repair area.	\$ 180.00	40
5	To remove and refit internal part to facilitate repair.	\$ 150.00	60
6	To remove and transfer front door components.	\$ 180.00	
7	To remove and transfer rear door components.	\$ 180.00	X N/m
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p>		<p>X/ot Author PIP Repair Before for A/B/D LKK Auto Consultants 29/3/2018 4 weeks</p> <p><i>[Signature]</i> 3/4/18</p>	

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18005805/M1VBN2

Date: 09/05/2018

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SLM3615X	Insured Vehicle No :	SGU3587K
Date of Loss:	27/03/2018	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM3615X	Engine No:	1NZR439809
Make & Model:	TOYOTA SIENTA, 1.5 (A)	Chassis No:	NHP1707059598
Reg. Date:	28/03/2017 (Man. Year: 2016)	Odometer:	80471 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R16	Rear Tyre Size:	185/60R16
Front Left Side:	Achilles 8 mm	Rear Left Side:	Achilles 8 mm
Front Right Side:	Achilles 8 mm	Rear Right Side:	Achilles 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,268.52	1,310.25	6,958.27	84.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,640.00	1,130.00	3,510.00	75.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,908.52	2,440.25	10,468.27	81.10
Approved Total (Overridden) (S\$)		1,950.00		
(S\$)	12,908.52	1,950.00	10,958.52	84.89
+ GST 7.00/7.00% (S\$)	903.60	136.50	767.10	84.89
Nett Amount (S\$)	13,812.12	2,086.50	11,725.62	84.89

INSPECTION

Date of Assignment: 28/03/2018

Date Inspected: 29/03/2018 Inspected At:

Vermogen Ace Pte Ltd - Benoi (HQ)
44 BENOI ROAD
Singapore 669204

Estimated Period of Repair: 4.0 days

Adjuster: MA CHIN FOOK

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2018)	
Parts: M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SLM3615X)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT FENDER LH	Not Necessary	690.00 FL	*- FL
2	1	*FRONT FENDER EMBLEM-HYBRID (NPA)	Not Necessary	0.00 FL	*- FL
3	1	*FRONT DOOR LH	Dented	1,344.00 FL	*1,344.00 FL
4	1	*FRONT DOOR HINGE TOP	Serviceable	109.00 FL	*- FL
5	1	*FRONT DOOR HINGE BOTTOM	Serviceable	109.00 FL	*- FL
6	1	*FRONT DOOR LOCK LH	Serviceable	855.00 FL	*- FL
7	1	*FRONT DOOR CATCH LH	Serviceable	44.00 FL	*- FL
8	1	*FRONT DORO WEATHERSTRIP LH	Necessary	219.00 FL	*219.00 FL
9	1	*FRONT DOOR POWER WINDOW MOTOR LH	Serviceable	647.00 FL	*- FL
10	1	*FRONT DOOR WINDOW MOULDING LH	Necessary	184.00 FL	*184.00 FL
11	1	*FRONT DOOR WINDOW REGULATOR LH	Serviceable	430.00 FL	*- FL
12	1	*FRONT DOOR TRIM LH	Serviceable	1,500.00 FL	*- FL
13	1	*SET FRONT DOOR TRIM CLIPS	Serviceable	40.00 FL	*- FL
14	1	*FRONT DOOR STOPPER LH	Serviceable	30.00 FL	*- FL
15	1	*REAR SLIDING DOOR LH	Repair	1,658.00 FL	*- FL
16	1	*REAR SLIDING DOOR PROTECTOR LH	Serviceable	247.00 FL	*- FL
17	1	*REAR DOOR LOWER GARNISH LH	Serviceable	195.00 FL	*- FL
18	1	*REAR SLIDING DOOR CHANNEL LH	Serviceable	189.00 FL	*- FL
19	1	*REAR SLIDING DOOR STICKER LH	Serviceable	79.90 FL	*- FL
20	1	*REAR SLIDING DOOR RUBBER LH	Serviceable	271.40 FL	*- FL
21	1	*REAR FENDER LH	Serviceable	1,510.40 FL	*- FL
22	1	*REAR FENDER LOWER GARNISH LH	Serviceable	176.00 FL	*- FL
23	1	*REAR FENDER CENTER GARNISH LH	Serviceable	497.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	11,024.70	1,747.00
- List Item Discount on L Items 25.00/25.00% (S\$)	2,756.18	436.75
Total Parts (S\$)	8,268.52	1,310.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE DAMAGED PARTS AND TO PANEL BEATING ACCIDENT AREA	New	1,800.00	500.00
2	TO PUTTY AND RESPRAY REPLACED PARTS AND ACCIDENT REPAIR AREA	New	2,000.00	500.00
3	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT	New	150.00	30.00
4	TO RUSTPROOF ACCIDENT REPAIR AREA	New	180.00	40.00
5	TO REMOVE AND REFIT INTERNAL PART TO FACILITATE REPAIR }	New	150.00	60.00
6	TO REMOVE AND TRANSFER FRONT DOOR COMPONENTS }	New	180.00	-
7	TO REMOVE AND TRANSFER REAR DOOR COMPONENTS	New	180.00	-
Gross Labour Cost (S\$)			4,640.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >