

ASS. REC. BY:

REF: CS3 / ASM18005806 / M162 Special Instruction:

SUPERVISOR

Smart claim
From (Person):

Ma

Jas Tun

ASSIGNMENT (Office)

of Asm

Date/Time: 28032018 9.43am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

Ym 7739S

Insured:

XE 1506R

at Workshop m/s

Sin Sheng

Tel:

6863 9595

of

3 Teck Park Crescent Tuas Tech Park

Policy No:

Claim No:

S8M00C6E

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26032018

CA / REV / REP. / REV 24 HRS 'wpi'

Date/Time: 28032018 1023am

Person Contacted:

Susan

H.O.D. Endorsement:

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (X) Estimate	'Virtual'
	Ym 7739S - x	
	XE 1506R - CCH/AXA 17005638 / TIm63	D.O.A. = 21032017

PRs

REF: ASM

Smart claim

ASSIGNMENT

From: Date: 29032018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: Ym 77398

at Workshop m/s Sin Sheng

of 3 Teck Park Crescent

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: 'Virtual Acc'

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: 4M77398. Yr Regn: DEC 2007.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MTR FUSE C.C. 2777

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 313270 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: FE83BCA 10658.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 200. 216.

R: 185/14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or AUSTONE

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 29/3/2018

Survey held at

Sin Sheng @ 1:32pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

NO EST upon Survey

Date/Time. File Pass to?

1) 06042018

Date/Time. File Return to?

2)

Report Format: PRs

Lump Sum / I.B.I: (\$)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

☐ S + RS ☐ SI

☐ Photos

☐ Others

TOTAL




Service Request Details

Claim

S8M00C6E

Reference

None 

Loss Date

March 26, 2018

LKK AUTO CONSULTANTS PTE LTD (TP) ▼

Request Date

March 28, 2018

Due Date

April 5, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

YM7739S

Make

TPVD MITSUBISHI

Service Address

...

Primary Contact/Insured

ORIENT NATURAL RESOURCES PTE LTD
24 SIN MING LANE, #02-94 MIDVIEW CITY, 573970, Singapore
63380083
ASPETRA.MOTOR@GMAIL.COM

Claim Handler

TAN Jas
6568804844
jas.tan@axa.com.sg

Additional Instructions

VIRTUAL ACC TP XS \$3000 please conduct PRI only

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/03/2018 14:01
Date Of Accident	26/03/2018 17:15
Exact Location Of Accident	PUNGGOL WAY FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YM7739S	MPA officer: 6880 EPPY (JAS)
Insured/Policyholder		
Name Of Registered Owner	GOLDBELL LEASING PTE LTD	
Co Reg No	199001196N	
Email Address	NOEMAIL	
Mobile Phone No		
Alternative Phone No	OFFICE-64942833	
Vehicle Particulars		
Manufacturer	MITSUBISHI	
Model	FE83BEOSRDEA-3.0 D B31 (A)	
Exact Purpose for which vehicle was being used at time of accident		
Are you claiming under your own insurance policy for repair to your vehicle?	NO	
If No, Please state action to be taken	THIRD PARTY	
Vehicle Category	COMMERCIAL VEHICLE	

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	29004183
Cover Note Number	


Driver

Name of Driver	ISMAS BIN IBRAHIM
NRIC No	S75380251
Date Of Birth	12/12/1975
Occupation	OUTDOOR
Date Of Driving Pass	02/11/2012
Driving Experience	5 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84269348
Fax Number	
Contact Number	
Email Address	NOEMAIL

Vehicle Registration Number	XE1506R
Vehicle Make/Model/Colour	IVECO
Details Of Properties	VEH B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RUSHDI BIN ONIN
NRIC/Passport Number	S7225650F
Contact Number	92452279
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT NO. T/20180327/2006

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NAIC/FIN No.:

Police Report



**SINGAPORE
POLICE FORCE**



T/20180327/2008

2 of 4

Police Station Of Origin:

Sengkang N.P.C

2 Sengkang Square #01-02 SINGAPORE

545025

Tel No: 1800-343 8999

Report No: T/20180327/2008

CONTINUATION OF REPORT

Name	ISMAEL BIN IBRAHIM	IC No	575380251
Related Vehicle	YM7739S (Lorry)	Contact No.	84269348
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 26/03/18 at about 1715hrs, I was driving one lorry with bearing registration number YM7739S, travelling along TPE towards Punggol Way.

While I was at the slope of Punggol Way flyover (left lane), my vehicle was in a stationary position behind a truck (IVECO bearing number XE1506R), waiting for the traffic light to turn green.

However, the said suddenly start reversing from slow to fast speed. I tried to horn multiple times to warn of danger however the said truck still continues to reverse. There were many vehicles horned at the said truck.

I could not able to escape due to hazards and safety to other road users as such, I continue remain in my vehicle when the said vehicle collided on my vehicle.

The impact had caused damages on my vehicle as listed:

- Crack on front windscreen
- Dashboard dented in on the (exterior and interior)
- Difficulty in opening both doors
- Front panel badly dented
- Black oil leaking from the front side of the engine
- Water leaking from the front side of the engine
- Wiper could not be function
- Left passenger side mirror broken
- Believed left front suspension damage

Due to the impact, my chest had hit against the steering wheel.

The said truck then started to move off however I managed to alight from my vehicle and stop the driver.

The driver informed that he is fine however he looks sleepy and dazing.

I then called for Police immediately. Both Traffic Police and Ambulance came and attended to me however I did not wish to be conveyed.

I wish to state that I had notice the said truck earlier while was travelling along KPE as the truck kept

Police Report



**SINGAPORE
POLICE FORCE**



T/20180327/2006

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

4 of 4

Report No. T/20180327/2006

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F /
Sgt 2 MOHAMAD ADAM BIN ROSLAN

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
27/03/2018 01:57

Officer In Charge Of Case:
TP / GIT /
Staff Sgt SHAHRUL NIZAM BIN SAMARRI
Contact No.: 65476904

Classification Of Case:

Authentication Stamp
NP158

[Faint signature and stamp]
Sgt 2 MOHAMAD ADAM BIN ROSLAN