



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

TPVD MITSUBISHI FE83BEOSRDEA-3.0 D B31 (A) (YM7739S)

Date of Loss

26 March 2018

Time of Loss

17.15

Loss Description

XE1506R (INSR) REVERSED ONTO YM7739S (TP)

Comment

Workshop Details

Total Rebate Amount

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Target Date of Completion *



Days of work completion *



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

YM7739S

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

27/12/2007



Mileage

313270

Age of Vehicle

10

Driver Details

CATEGORY

Manufacturing Year

CATEGORY

Driver Name

POLICY INFORMAT...

ASSESSMENT INFO...

2007

FNOL INFORMATI...

BIN IBRAHIM ISMAS

CATEGORY Make

POLICY INFORMAT... TPVD MITSUBISHI

ASSESSMENT INFO... MITSUBISHI

CATEGORY Model

POLICY INFORMAT... FE83BEOSRDEA-3.0 D B31 (A)

ASSESSMENT INFO... FE83BEOSRDEA

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT...

ASSESSMENT INFO...

POST SURVEY INF...

CATEGORY Date of Birth

FNOL INFORMATI... 12 December 1975

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 42

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience



FE83BEA10658

CATEGORY Engine No

POLICY INFORMAT...

ASSESSMENT INFO... 4M42A53248

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 2977

CATEGORY Sum Insured

POLICY INFORMAT...

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT...

ASSESSMENT INFO... 0

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy



CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy



CATEGORY Address

FNOL INFORMATI...BLK 250 YISHUN AVE 9 #02-219,
760250, Singapore

POST SURVEY INF...

CATEGORYAddress type

FNOL INFORMATI...Personal Correspondence

POST SURVEY INF...

CATEGORYGender

FNOL INFORMATI...Male

POST SURVEY INF...

CATEGORYMarital status

FNOL INFORMATI...Unknown

POST SURVEY INF...

CATEGORYIdentification #

FNOL INFORMATI...S7538025I



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

29/03/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

700R16

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

185R14

Front left side

AUSTONE6mm

Front right side

AUSTONE6mm

Rear left side

AUSTONE6mm

Rear right side

AUSTONE6mm



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN : JAS TAN

Ref: CS3/ASM18005806/M1be2

Date: 09-04-2018



Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	XE 1506R	Veh. Inspected	YM 7739S
Policy No.	29004183	Coverage (\$)	0.00
Claim No.	S8M00C6E	Excess (\$)	0.00
Assign From	JAS TAN	Assign Date	28/03/2018

2. Vehicle Particulars & Condition

Make & Model	mitsubishi FE83BEOSRDEA	c.c	2977
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	FE83BEA10658	Colour	WHITE
Odometer	313270 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	700 R16	AUSTONE	6 mm
L/H Front Tyre	700 R16	AUSTONE	6 mm
R/H Rear Tyre	185 R14	AUSTONE	6 mm
L/H Rear Tyre	185 R14	AUSTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.	
---	--

5. General Information

Accident Date	26/03/2018	Inspect Date / Time	29/03/2018 (01:32 PM)
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Report Ref No. CS3/ASM18005806/M1be2

Inspected By

MA CHIN FOOK

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.