

SS. REC. BY:

REF: CS3/MSG18005808/Alber ^{range} Special Instruction:

Survivor:

MURMAN

ASSIGNMENT (Office)

From (Person):

Elaine Ngu

of

MSG

Date/Time: 28/03/2018 4:09pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 1428U

Insured:

SDB 6680P

at Workshop m/s

Uni Automotive

Tel:

67482795

of

Blk 1 Kaki Bukit Ave 6 #01-94

Policy No:

28989744AYW

Claim No:

553677

Sum Insured:

Excess:

Make of Veh:

D.O.A. 20022018

(Client's Record)

CA / REV / REP. / REV 24 HRS 40p

H.O.D. Endorsement:

Date/Time:

28/03/2018 5:05pm

Person Contacted:

Alvin

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SLF 1428U - CS/MSG17013762 / Tivbe2 DCA: 201216
	SDB 6680P - CS/AYA13006188 / Hiebscs DCA: 201413

From: Date: 03042018

Estimated Cost:

OD ☒ TR / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLF 1428U

at Workshop m/s: Uni Automotive

of

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLF 1428U Yr Regn: 2016 / Aug

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda 004554 2.4 G.C. 2356

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 035432 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: J4MRL1850 AC 205216

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / ☒ R/Rim / STD A/Rim or

Tyre-Size: F: 215/55R17 R:

BS ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm


D.O.A. 2002018

Survey held at: Idac Praya Ubi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

* Repair Estimate : S\$ 3500 - 4500

* 2 days

RECEIVED 07 MAY 2018

Date/Time, File Pass to? ☐ : Prel. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format : PRQ

Lump Sum / I.B.I. (\$)

Days Of Repair:

Resurvey No. of Trip: -

Survey Fee: 120

Transportation: 50

S + RS: \$

Photos: 10

Other:

Other:

Weekend (\$)

TOTAL: 180

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Feb 2018		28 Mar 2018 16:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TAN HEE HUA, ID: S0175823C		
Main Claimant:	LEONG GUO WEI ELWIN, ID: S9026544Z		
Vehicle Reg. No.:	SLF1428U	Date of Loss:	20/02/2018 15:00 - :59
Claim Type:	TP / 553679	Policy/Cover Note No.:	28989744AVW (Comprehensive) Coverage: 28/06/2017 - 27/06/2018
Vehicle Reg. No. (Insured):	SDB6680P	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	Uni Automotive Pte Ltd (HQ) NO. 1 KAKI BUKIT AVE 6 #01-94 AUTOBAY@KAKI BUKIT, 417883 Kaki Bukit - Tel: 67482795		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/03/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

28032018 @ 5:15pm
Alvin veh not in

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLF1428U		
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	ODYSSEY 2.4 EX-S CVT		
Chassis No. :	JHMRC1880GC205216		
Propellant :	Petrol		
Engine No. :	K24W72012365		
Engine Capacity :	2356 cc		
Maximum Power Output :	129.0 kW (172 bhp)		
Maximum Laden Weight :	2450 kg		
Unladen Weight :	1769 kg		
Year Of Manufacture :	2016		
Original Registration Date :	15 Aug 2016		
Lifespan Expiry Date :	-		
COE Category :	B - Car above 1600cc or 97kW (130bhp)		
Quota Premium :	\$57,508.00		
COE Expiry Date :	14 Aug 2026		
Road Tax Expiry Date :	14 Aug 2018		
PARF Eligibility Expiry Date :	14 Aug 2026		
Inspection Due Date :	14 Aug 2019		
Intended Transfer Date :	07 May 2018		
CO2 Emission :	184.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6544Z
Vehicle Details	
Vehicle No.:	SLF1428U
Vehicle to be Exported:	No
Intended De-registration Date:	07 May 2018
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EX-S CVT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	K24W72012365
Chassis No.:	JHMRC1880GC205216
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$28,006.00
Original Registration Date:	15 Aug 2016
First Registration Date:	15 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$31,209.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Aug 2026
PARF Rebate Amount:	\$23,406.00
Intended COE Rebate Details	
COE Expiry Date:	14 Aug 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,508.00
COE Rebate Amount:	\$47,552.00
Total Rebate Amount:	\$70,958.00

The information contained herein is correct as at 07 May 2018

OK

22/02/2018 15:35 FAX 0001/001

Upload receipt / email when the claim is received
 Submit your claim to the Police Department
 Submit your claim to the Police Department

Your NCD will be affected due to late reporting
 Actual Filing Submission Date & Time: 22/02/2018 16:12

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder or the Policyholder's Representative.
3. Information provided must be truthful and accurate as possible. Any false information or withholding of material facts may affect insurance companies to investigate policy validity.
4. The Police and Insurance companies are not an advertiser of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be reviewed by the members of the Civil Complaint Management Centre established by the General Insurance Association of Singapore (GIAS) for handling and processing of the report, and, by a fee, be made available upon application by interested parties.
7. By the submission of this report to the Police, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.

ACCIDENT STATEMENT

Date Of Report: 22/02/2018 16:08
 Date Of Accident: 20/02/2018 15:20
 Exact Location Of Accident: 356 TANGLIN RD THE SALVATION ARMY PRIVATE CARPARK
 Country/State of Location: SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number: SLF1428U
 Insured/Policyholder: LEONG GUO WEI ELWIN
 Name Of Registered Owner: LEONG GUO WEI ELWIN
 NRIC No: S9025544Z
 Email Address: NOEMAIL
 Mobile Phone No: (LOCAL) +65-82985522
 Alternative Phone No: OFFICE-82985522

Vehicle Particulars

Manufacturer: HONDA
 Model: ODYSSEY
 Exact Purpose for which vehicle was being used at time of accident: NO
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken: THIRD PARTY
 Vehicle Category: PRIVATE CAR
 Insurance Company: LIBERTY INSURANCE PTE LTD
 Name of Insurance Company: LIBERTY INSURANCE PTE LTD
 Type Of Coverage: COMPREHENSIVE
 Fleet Policy: NO
 Policy Number: C00593359
 Cover Note Number: NO

Driver

Name of Driver: LEONG GUO WEI ELWIN
 NRIC No: S9025544Z
 Date Of Birth: 02/09/1990
 Occupation: INDOOR
 Date Of Driving Pass: 11/10/2016
 Driving Experience: 6 YEARS AND 4 MONTHS
 Gender: MALE
 Mobile Number: (LOCAL) +65-82985522
 Fax Number: NO
 Contact Number: OFFICE-82985522
 Email Address: NOEMAIL

Page 2 of 2

YK13132 FAX 0002/007

DLX 871 YISHUN AVE 4 #12-604
701071

Is the driver an employee of the Insured's Company? NO
What is the relationship of the Driver with the Insured? OWNER
Is the vehicle registered in the Driver's Own Name? -
Is the vehicle a Company or Driver's Own Vehicle? -
Insurance Company of Driver's Own Vehicle: -

General Information

Type of Accident: HIT AND RUN / VANDALISM / DAMAGED WHILE PARKED
Weather Condition: CLEAR
Road Surface: DRY

Details of Accident

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident: NO
Was any body injured in the accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
Have you been approached by unknown person(s) soliciting for legal accident claims assistance? NO
Number of Passengers (including Driver): 0

Details of Police Action

Was the accident reported to the police? YES
In which Police Station? YISHUN SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Name: ROAD: 82 YISHUN ST 81, POSTCODE: 708456, COUNTRY: SINGAPORE
Police Station Address: TEL NO: 1999-6522999 - FAX NO: 85522239
Police Station Contact: NO
Was notice of Intended Prosecution given? NO
If Yes, against whom?

Details of Police Report

REFER TO POLICE REPORT: 1201802212004

Attachment(s)

Are accident photos available for attachment? YES
Were there any video captured by Car Camera? YES
Were there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number: SOB6080P
Vehicle Make/Model/Colour: VEHICLE B
Details of Properties: PRIVATE CAR
Vehicle Category:
Name of Driver:
NRIC/Passport Number:
Contact Number:
Address:
Postcode:
Insurance Company Name:
Nature of Damage:
No. of Passenger (including Driver):

J 16:00 FAX

0506/2017

Sketch Plan #2 Pg. 1

OUTLINE



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO SOURCE REPORT

DECLARATION

I/we declare that the foregoing particulars are true in every respect

Reporter's Signature
Date & Time

1. Name of the vehicle

Driver's Signature
Date & Time

Reporting Officer's Signature
Name
Rank/Position

TSU 16:00 FAX

0005/1

Sketch Plan #3 Pg. 1


**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street #1 SINGAPORE 768456
Tel No: 1800-8522099

1/20100221/12/004

1 of 3
Report No. 1/20100221/12/004

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/02/2018 00:28		Vide Report No.:		Station/Jury No. 8	
Name of Informant: LEONG GUO WEI, ELWIN					
Address: APT BLK 671A YISHUN AVENUE 4 #12-804 SINGAPORE 761671					
ID Type / ID No.:		Contact No.:		Mobile: 82885522	
NRIC NO: S9028544Z		Home/Office:			
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Male	Age: 27	Date of Birth: 03/08/1990	Type of Informant: Driver		
Race: Chinese	Language: English		Institution / School Name:		
Occupation: Social worker (general)		Driving Licence Information: Class: 2B,3		Date of Expiry:	

General Information of the Accident					
Type of Accident: Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 20/02/2018 15:20	Type of Location: Car Park		
Location: Along Road 1 TANGLIN ROAD					
358 Tanglin Road, The Salvation Army private carpark					
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No	

Details of Vehicle Involved					
Vehicle No.:	Make:	Model:	Color:	Year:	Passenger
SDB6880P	Car				0
SLF1428U	Car				Slightly Damaged

THU 16:00 FAX

006/007

Sketch Plan #4 Pg. 1

**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street #1 SINGAPORE 768458
Tel No: 1800-8522999



T/20180221/2004

2 of 2

Report No. T/20180221/2004

CONTINUATION OF REPORT

Brief Details.

I owned the vehicle bearing registration plate number SLF142BU. On 20/02/2018 at about 1930hrs, upon alighting from my vehicle at North point city carpark, I discovered my left front bumper, paint chip off and scratches. I then review my vehicle in built camera.

I discovered that on the same day at about 1521hrs, I saw a vehicle bearing the registration plate number SDB8590P was reversing to the car lot at the left side of my vehicle. This car driver side came very closely to the left side of my vehicle. In the video, I also heard a scraping sound. As such, I believed this car could have scrap onto my car while reversing. There is no any written notes left on my windscreen.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Feb 2018		28 Mar 2018 16:09 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN HEE HUA , ID: S0175823C								
Main Claimant:	LEONG GUO WEI ELWIN , ID: S9026544Z								
Vehicle Reg. No.:	SLF1428U	Date of Loss:	20/02/2018 15:00 - :59 [18 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 553679	Policy/Cover Note No.:	28989744AVW (Comprehensive) Coverage: 28/06/2017 - 27/06/2018						
Vehicle Reg. No. (Insured):	SDB6680P	Policy No. (Claimant):							
		Excess:	S\$1,500.00						
Repairer:	Uni Automotive Pte Ltd (HQ) NO. 1 KAKI BUKIT AVE 6 #01-94 AUTOBAY@KAKI BUKIT, 417883 Kaki Bukit - Tel: 67482795								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 29/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLF1428U (553679)**
[SDB6680P]
TP
LEONG GUO WEI ELWIN
Feb 20 2018 3:00PM
[TAN HEE HUA]
Uni Automotive Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser	
Letters/Correspondences						1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print		
1	28/03/18 16:16	Non Reporting Letter to OI		Load HTM			
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	07/05/18 11:49	General View		Load JPG	☒		
2	07/05/18 11:49	General View		Load JPG	☒		
3	07/05/18 11:49	General View		Load JPG	☒		
4	07/05/18 11:49	General View		Load JPG	☒		
5	07/05/18 11:49	General View		Load JPG	☒		
6	07/05/18 11:49	General View		Load JPG	☒		
7	07/05/18 11:49	General View		Load JPG	☒		
8	07/05/18 11:49	General View		Load JPG	☒		
9	07/05/18 11:49	General View		Load JPG	☒		
10	07/05/18 11:49	General View		Load JPG	☒		
11	07/05/18 11:49	General View		Load JPG	☒		
12	07/05/18 11:49	General View		Load JPG	☒		
13	07/05/18 11:49	General View		Load JPG	☒		
14	07/05/18 11:49	General View		Load JPG	☒		
15	07/05/18 11:49	General View		Load JPG	☒		
16	07/05/18 11:49	General View		Load JPG	☒		
Documentation						1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print		
1	28/03/18 07:38	TPD SLF1428U PRI & GIA REPORT.		Load PDF			
2	28/03/18 16:10	WORKSHOP DETAILS - SLF1428U		Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18005808/R1BE2

Date: 07/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28989744AVW

Claimant Vehicle No : SLF1428U

Insured Vehicle No : SDB6680P

Date of Loss: 20/02/2018

Nature of Claim: TP

Claim No: 553679

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLF1428U

Make & Model: HONDA ODYSSEY, 2.4 EXV-S CVT SR (A)

Engine No: K24W72012365

Reg. Date: 15/08/2016 (Man. Year: 2016)

Chassis No: JHMRC1880GC205216

Colour: Blue

Odometer: 35432 km

Engine Capacity: 2356 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/03/2018

Date Inspected: 02/04/2018 Inspected At:

 Uni Automotive Pte Ltd (HQ)
 NO. 1 KAKI BUKIT AVE 6 #01-94
 AUTOBAY@KAKI BUKIT
 Singapore 417883

Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 -\$4,500.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2018)
Parts: M1-SUV	HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF1428U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >