

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 26/03/2018
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000072 Accident Date : 09/03/2018
Vehicle No : SLG-9872-L Make & Model : BMW 528I EDITION SPORT PRO 2.0 (A)
Excess : 0.00 Add Excess : 0.00

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	REAR FENDER LH	RESTORE	
1	REAR DOOR LH	RESTORE	
1	REAR SPORTS RIM LH	RESTORE	
1	REAR BUMPER	RESTORE	
	Sub Total	0.00	
	Discount 5% On Parts	(0.00)	
<u>Labour & Misc</u>			
	LABOUR TO FACILITATE REPAIR	600.00	500.
	TO RESPRAY AFFECTED AREAS	200.00	700
	RUST PROOFING	50.00	20

Not Authoriz
Labour only.
3w 1 days
29/3/2018
\$1220 / 2
3w 1 days
WAFR print photo

Date : 26/03/2018
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000072 Accident Date : 09/03/2018
Vehicle No : SLG-9872-L Make & Model : BMW 528I EDITION SPORT PRO 2.0 (A)
ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	1550.00	

1,550.00

Remarks:

SUB TOTAL
GST 7.0 % 108.50
TOTAL 1,658.50

Surveyor's name: _____

Principal's name: ETHOZ Group Ltd

Survey Date & Time: _____