

10/2018

INS. CASE OWNER:

MS | CC 4/AXA1800 5840, MI 603 9/

LKK: IDAC:

Surveyor:

MUF

DOI:

ASSIGNMENT

21/3/18

Date / Time:

21/3/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLQ 32312

Claim No.:

88M00661

37299

Name of Insured:

DAVE SIMON LARIS S/O D PHAM SIMON

Policy No.:

CHS37578

Insured Tel No.:

HP:

Make / Model:

TOYOTA

Excess Sec II :SS

D.O.A.:

22/3/18

Place of Accident:

403 ANNE AVE 10

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

PHAM THI THU PHUEN

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L) (YES / NO)

Insured Liability: %

Final? Yes / No

SLH 12794



INSRS:

WSP:

Tel:

Liability:

RMKS:

Urmagm



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

21/3/18
AMH

4/4/18
Smartclaim

STAGE

DATE / PIC

Non-Reporting Itr (1st):
Non-Reporting Itr (2nd):
Non-Reporting Itr (Final):
Notification Itr (if non-pickup):
Call OI:
After call Itr to OI:


Documentation Check List: Handler Typist

Notification Itr (if non-pickup)		
After call Itr to OI		
Authorisation To Act		
Release Voucher		
Final Repair Bill		
Car Rental Invoice		
Towing Invoice		
LTA / GIA :		
Medical Bill		
PIR		
Mandate/Reject Instruction:		
LOD		
Payment Breakdown Form:		
Post-Repair Photos:		
Others:		

4/4/18 (AM) REQUESTED TO REJECT TP CLAIM.

4/4/18 EMAIL REP TO REJECT TP CLAIM.

RECEIVED 04 APR 2018



PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm with:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Repair Cost:	SS	(days) Reduction:	%	
FINAL SETTLEMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Final Liability:	% 0	(Agreed / Assessed) BOLA S/N No.:	NIL	If NO or B 28, Ass. Lia :
Repair Cost:	SS	TP REJECTED PRO THROUGH LTI.		
Loss of Rental (LOR):	SS	(days)		
Loss of Use (LOU):	SS	(\$ x days)		
Loss of Income (LOI):	SS	(\$ x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]			
GLA/LTA Search	SS			
Medical:	SS			1) Claim status: Normal/Reject/Private Settle
Disbursement:	SS	(e.g. Tow/Independent)		2) Report Format:
Legal Cost	SS			3) Survey fee: 380
Total:	SS	Global Sum SS:		
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Payee 1:	SS	Name 1:		
Payee 2: (Strike if N.A.)	SS	Name 2:		
Payee 3: (Strike if N.A.)	SS	Name 3:		

COPY SENT 9/4/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18005840/eb3

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 29-03-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLQ 3231Z	Veh. Inspected	SLH 1279Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	29/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	27/03/2018	Inspection Date	
Survey held at	VERMOGEN ACE PTE LTD 1 BUKIT BATOK CRESCENT #04-54/55 WCEGA PLAZA SINGAPORE 658064		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLH1279Y
 Vehicle Reg. Date: 25-10-16
 Make / Model : TOYOTA SIENTA
 Engine No. : 2NR8684327
 Chassis No. : NSP1707058879

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Headlamp RH	X	\$ 2,300.00		
2	1	Headlamp panel RH	X	\$ 130.00	SVC	
3	1	Front bumper	X	\$ 679.00	det	
4	1set	Front bumper clips	X	\$ 50.00	4pc	
5	1	Front bumper logo	X	\$ 500.00	2pc	
6	1	Front bumper base logo	X	\$ 500.00	2pc	
7	1	Front bumper sponge	X	\$ 97.60	1pc	
8	1	Front bumper reinforcement	X	\$ 489.00		
9	1	Front bumper upper retainer	X	\$ 92.00	dic	
10	1	Front bumper side retainer RH	X	\$ 192.00	dic	
11	1	Front bumper grille	X	\$ 750.00	an	
12	1	Front bumper tow cover	X	\$ 32.00	1pc	
13	1	Front fog lamp RH	X	\$ 147.60	1pc	
14	1	Washer tank	X	\$ 147.00	2pc	
15	1	Washer tank motor	X	\$ 128.00	2pc	
16	0	0				
17	0	0				
18	0	0				
19	0	0				
20	0	0				
21	0	0				
22	0	0				
23	0	0				
24	0	0				
25	0	0				
26	0	0				
27	0	0				
28	0	0				
29	0	0				
30	0	0				
31	0	0				
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SLH1279Y
Vehicle Type :	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	SIENTA 1.5G CVT
Chassis No. :	NSP1707058879
Propellant :	Petrol
Engine No. :	2NR8684327
Engine Capacity :	1496 cc
Maximum Power Output :	80.0 kW (107 bhp)
Maximum Laden Weight :	1705 kg
Unladen Weight :	1320 kg
Year Of Manufacture :	2016
Original Registration Date :	25 Oct 2016
Lifespan Expiry Date :	-
COE Category :	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium :	\$50,000.00
COE Expiry Date :	24 Oct 2026
Road Tax Expiry Date :	24 Apr 2018
PARF Eligibility Expiry Date :	24 Oct 2026
Inspection Due Date :	24 Oct 2019
Intended Transfer Date :	12 Dec 2018
CO2 Emission :	120.00 (g/km)
CEV/VES Rebate Utilised Amount :	\$10,000.00
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 25 Apr 2018 to 24 Oct 2018)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	341.00	-	341.00
Total Amount Payable :			366.00

Amount Payable (From 25 Apr 2018 to 24 Apr 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	682.00	-	682.00
Total Amount Payable :			707.00

You may print this page for reference.

OK

Print

◀ DS

Type

🗨 Question

Message

Hi, please reject TP claim.

Reply

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Friday, 6 April 2018 3:01 PM
To: Minoko; pila.vermogenace@gmail.com
Cc: ezelvermogenace@gmail.com; edmondvermogenace@gmail.com; 'juan paulo baldoz'; 'vmg.vermogenace'; vermogenace@gmail.com
Subject: RE: AXA:PLEASE ARRANGE TP SRUEVY FOR (OUR REF:SLH1279Y) YOUR REF:SLQ3231Z DOA:27/03/2018
Attachments: OI SKETCH PLAN.pdf

Your Ref: SLH 1279Y
Our Ref: CC4/ASM18005440/M1eb3

Without Prejudice

Hi Sir/Mdm,


We refer to the above matter.

ACCIDENT INVOLVING SLH 1279Y AND SLQ 3231Z ON 27/03/2018

We attached here with a copy of our insured's accident statement for your easy reference.

Our principal has reiterated that the accident was caused due to the entire negligence of your client reversed into the parking lot and collided into our insured vehicle.

We are of the opinion that liability is not in your client's favor.

24.	 A diagram illustrating an accident scenario. It shows a horizontal row of four rectangular boxes representing parking spaces. A black arrow points downwards from the second box from the left, indicating a vehicle reversing out of the space. Below this arrow, a white arrow points to the left, and a white arrowhead points to the right, representing the path of another vehicle moving straight through the parking lot.	Vehicle X – Reversing in/out of parking lot – Moving in/out of parking lot Vehicle Y – Going straight Reason: Vehicle reversing in/out or moving in/out of parking lot should exercise greater caution	100%	0%
-----	---	--	------	----

Under such a circumstances, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's claim.

Thank You.

Best Regards,

* Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

* phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Minoko [mailto:minokovermogenace@gmail.com]

Sent: Wednesday, 28 March 2018 3:47 PM

To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>

Cc: pila.vermogenace@gmail.com; ezelvermogenace@gmail.com; edmondvermogenace@gmail.com; 'juan paulo baldoz' <paulovermogenace@gmail.com>; 'vmg.vermogenace' <vmg.vermogenace@gmail.com>; vermogenace@gmail.com

Subject: AXA:PLEASE ARRANGE TP SRUEVY FOR (OUR REF:SLH1279Y) YOUR REF:SLQ3231Z DOA:27/03/2018

Dear Arrange survey dept

Kindly arrange TP survey on 28/03/2018 (Thursday) following detail & attach here GIA report:

Survey before repair

Your Vehicle: SLQ3231Z

Our Vehicle: SLH1279Y

DOA : 27/03/2018

AOL :ANG MO KIO AVE 10 INFRONT OF BLK 403 OSCP

Vehicle Location: 6 BENOI SECTOR SINGAPORE 629904

Thank You.

Best Regards,

Minoko

Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 6904 4596

Fax: 6694 4929