

ASS REC. BY:

REF: CS/CTL18005853 / Grad307 Special Instruction:

Surveyor: GR **ASSIGNMENT (Office)**

From (Person): Adeline Chng of CTL Date/Time: 29032018 752pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SU 9077S Insured: SJM 7799R

at Workshop m/s Allswell Motor Tel: _____

of 25 Defu Lane 9

Policy No: DMCP SN 3084451700 Claim No: SNM18D0157002

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 23032018
(Client's Record)

CA / REV / REP. / REV 24 HRS WP H.O.D. Endorsement: _____

Date/Time: 29032018 2.02pm Person Contacted: _____ Vehicle ID / OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	<u>SU 9077S - X</u>
	<u>SJM 7799R - X</u>

Simulator

End.


REF: CTi

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Allswell motor.
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLU9077S Yr Regn: 18 Dec 2017
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Prius C.C. 1797
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 20831 T/Radio: Insured / Std / NI / NA

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.



Eng/No: _____
 C/No: ZVW400027155
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD / R/Rim or
 Tyre Size: F: 205/60R16
 R: 1"
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front _____ Rear _____
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. _____ D.O.I. 28-03-18
 Survey held at w/s
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
11245

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
16/8	Finalized \$697.38 with Ben. (Red. #79.12, 50%)
RECEIVED 19 AUG 2019	

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 3
 Resurvey No. of Trip: 1

Date/Time, File Return to? _____
 Report Format: TP
 Lump Sum / I.B.: (\$ 697.38)

Add Fee: : Site Insp (\$ _____))
 : Interview (\$ _____))
 : Tech. Invs (\$ _____))
 : Weekend (\$ _____))

Survey Fee:	<u>220</u>
Transportation:	_____
_____ S + RS. _____ SI	_____
) Photos	_____
) Others	_____
TOTAL	<u>220</u>

Estimate repair

Vehicle No.

Make & Model

Chassis No.

Date of survey

SU 90775
Toyota Prous Alpha

Submitted by
COE expiry
Engine No.

BEM
17-DEC-2021

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	Rear antenna / DM	01	#196.5		
02	Rear bumper x repair	01	-	* repaired (no stock)	
(labour description)					
01	Dismantle / Assembly of damaged parts	01	#240.0	100	
				150	
02	Spray painting on affected parts.	01	#360.0	200	
3.	Knocking of end panel	01	#120	100	
4.	Repair / patch / sandpaper rear bumper	01	#560.0	* repaired 200	

Total: 697.38

1476.50

3 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and approved by the repairer.

Known/Agreed by Repairer

Signature: _____

Date: _____

any of the quoted parts are recommended to be repaired, then an additional labour cost charged accordingly under supplementary

ent of death)

(to be shared among the passengers up to a maximum of 4 passengers)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18005853/Grb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 29-03-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJN 7799R	Veh. Inspected	SLU 9077S
Policy No.	DMCPSN3084451700	Coverage (\$)	0.00
Claim No.	SNM18D01570C02	Excess (\$)	0.00
Assign From	MERIMEN (ADELINE CHNG)	Assign Date	29/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	23/03/2018	Inspection Date	29/03/2018
Survey held at	25 DEFU LANE 9		
Repairer	ALLSWELL MOTOR TRADERS		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Mar 2018		29 Mar 2018 13:52 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	TEO YUET SHANG BRIDGET, ID: S7642642B		
Main Claimant:	ALLSWELL MOTOR TRADERS, Co. Reg. No.: 53192889J		
Vehicle Reg. No.:	SLU9077S	Date of Loss:	23/03/2018 17:00 - :59
Claim Type:	TP / SNM18D01570C02	Policy/Cover Note No.:	DMCPSN3084451700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJN7799R	Policy No. (Claimant):	5068430889-03
		Excess:	S\$0.00
Repairer:	Allswell Motor Traders (HQ) 25 Defu Lane 9, 539266 Defu Lane - Tel: 66791146		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/04/2018]		
Driver/Custodian (Insured):	TEO YUET SHANG BRIDGET (41 / Female), NRIC: S7642642B		
Adj Asg. Remarks:	NO EST, ASSIGN XING GUO QIANG AS SJE.		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
<input type="checkbox"/> ALL ASSOCIATED TASKS			
		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	2889J
Vehicle Details	
Vehicle No.:	SLU9077S
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS ALPHA HYBRID 1.8S CVT
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	2ZR0A22644
Chassis No.:	ZVW400027155
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,354.00
Original Registration Date:	18 Dec 2017
First Registration Date:	18 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$18,096.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Dec 2027
PARF Rebate Amount:	\$13,572.00
Intended COE Rebate Details	
COE Expiry Date:	17 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,711.00
COE Rebate Amount:	\$49,292.00
Total Rebate Amount:	\$62,864.00

The information contained herein is correct as at 13 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/03/2018 12:17
Date Of Accident	23/03/2018 17:40
Exact Location Of Accident	ALONG COMMONWEALTH AVE WEST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU9077S
Insured/Policyholder	
Name Of Registered Owner	ALLSWELL MOTOR TRADERS
Co Reg No	53192889J
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64625405
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS ALPHA HYBRID-1.8 S CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5068430889-03
Cover Note Number	

Driver

Name of Driver	GOH LIANG MENG
NRIC No	S1778316E
Date Of Birth	29/10/1966
Occupation	OUTDOOR
Date Of Driving Pass	13/07/1984
Driving Experience	33 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91212911
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 613 BUKIT PANJANG RING RD #03-854
Postcode	670613
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER & LEASEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

While waiting for traffic turns green , I moved forward and a vehicle SJN7799R hit onto my rear damaging my rear bumper . That's all.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJN7799R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

23/03

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Chai Yee

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Mar 2018		29 Mar 2018 13:52 Edit Adj Rpt	S\$697.37 Edit Estimates	S\$697.37 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TEO YUET SHANG BRIDGET , ID: S7642642B								
Main Claimant:	ALLSWELL MOTOR TRADERS , Co. Reg. No.: 53192889J								
Vehicle Reg. No.:	SLU9077S	Date of Loss:	23/03/2018 17:00 - :59 [3 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D01570C02	Policy/Cover Note No.:	DMCPSN3084451700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJN7799R	Policy No. (Claimant):	5068430889-03						
		Excess:	S\$0.00						
Repairer:	Allswell Motor Traders (HQ) 25 Defu Lane 9, 539266 Defu Lane - Tel: 66791146								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 10/04/2018]								
Driver/Custodian (Insured):	TEO YUET SHANG BRIDGET (41 / Male), NRIC: S7642642B Email:								
Adj Asg. Remarks:	NO EST, ASSIGN XING GUO QIANG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLU9077S (SNM18D01570C02)
[SJN7799R]
TP
ALLSWELL MOTOR TRADERS
Mar 23 2018 5:00PM
[TEO YUET SHANG BRIDGET]
Allswell Motor Traders

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Video									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Allswell Motor Traders (HQ)		Thumbnail	Print					
1	24/03/18 12:27	Video - Accident [Linked Accident Report Documents]		Load MP4						
Assessment Reports									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Allswell Motor Traders (HQ)		Thumbnail	Print					
1	24/03/18 12:27	Accident Statement		Load HTM						
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Allswell Motor Traders (HQ)		Thumbnail	Print					
1	24/03/18 12:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
2	24/03/18 12:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
3	24/03/18 12:27	Identification Card [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
4	24/03/18 12:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
5	24/03/18 12:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
6	24/03/18 12:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
7	24/03/18 12:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
8	24/03/18 12:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
9	24/03/18 12:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
10	24/03/18 12:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
11	24/03/18 12:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
12	24/03/18 12:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
13	24/03/18 12:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
14	24/03/18 12:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	15/04/19 08:47	General View		Load JPG	<input checked="" type="checkbox"/>					
2	15/04/19 08:47	General View		Load JPG	<input checked="" type="checkbox"/>					
3	15/04/19 08:47	General View		Load JPG	<input checked="" type="checkbox"/>					
4	15/04/19 08:47	General View		Load JPG	<input checked="" type="checkbox"/>					
5	15/04/19 08:47	General View		Load JPG	<input checked="" type="checkbox"/>					
6	15/04/19 08:47	General View		Load JPG	<input checked="" type="checkbox"/>					
7	15/04/19 08:47	General View		Load JPG	<input checked="" type="checkbox"/>					
8	15/04/19 08:47	General View		Load JPG	<input checked="" type="checkbox"/>					
9	15/04/19 08:47	General View		Load JPG	<input checked="" type="checkbox"/>					
10	15/04/19 08:47	General View		Load JPG	<input checked="" type="checkbox"/>					

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Allswell Motor Traders (HQ)	Thumbnail	Print
11	15/04/19 08:47	General View		Load JPG <input checked="" type="checkbox"/>
12	15/04/19 08:47	General View		Load JPG <input checked="" type="checkbox"/>
13	15/04/19 08:47	General View		Load JPG <input checked="" type="checkbox"/>
14	15/04/19 08:47	General View		Load JPG <input checked="" type="checkbox"/>
15	15/04/19 08:47	General View		Load JPG <input checked="" type="checkbox"/>
16	15/04/19 08:47	General View		Load JPG <input checked="" type="checkbox"/>
17	15/04/19 08:47	General View		Load JPG <input checked="" type="checkbox"/>
18	15/04/19 08:47	General View		Load JPG <input checked="" type="checkbox"/>
19	15/04/19 08:47	General View		Load JPG <input checked="" type="checkbox"/>
20	15/04/19 08:47	General View		Load JPG <input checked="" type="checkbox"/>
21	15/04/19 08:47	General View		Load JPG <input checked="" type="checkbox"/>
22	15/04/19 08:48	Chassis Number		Load JPG <input checked="" type="checkbox"/>
23	15/04/19 08:48	Odometer Reading		Load JPG <input checked="" type="checkbox"/>
24	16/08/19 12:11	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
25	16/08/19 12:11	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
26	16/08/19 12:11	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
27	16/08/19 12:11	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/03/18 13:51	PRS		Load PDF
2	29/03/18 13:52	OI GIA REPORT		Load PDF

Allswell Motor Traders (HQ)			Thumbnail	Print
1	24/03/18 12:27	Sketch Plan [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
2	24/03/18 12:27	Sketch Plan #2 [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>

Linked Accident Report Documents

			View	View in Browser
			<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Allswell Motor Traders (HQ)	Thumbnail	Print
1	24/03/18 12:27	Video - Accident		Load MP4

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Allswell Motor Traders (HQ)	Thumbnail	Print
1	24/03/18 12:27	Accident Statement		Load HTM

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Allswell Motor Traders (HQ)	Thumbnail	Print
1	24/03/18 12:27	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	24/03/18 12:27	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	24/03/18 12:27	Identification Card		Load JPG <input checked="" type="checkbox"/>
4	24/03/18 12:27	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	24/03/18 12:27	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	24/03/18 12:27	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	24/03/18 12:27	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	24/03/18 12:27	Accident Photo		Load JPG <input checked="" type="checkbox"/>
9	24/03/18 12:27	Accident Photo		Load JPG <input checked="" type="checkbox"/>
10	24/03/18 12:27	Accident Photo		Load JPG <input checked="" type="checkbox"/>
11	24/03/18 12:27	Accident Photo		Load JPG <input checked="" type="checkbox"/>
12	24/03/18 12:27	Accident Photo		Load JPG <input checked="" type="checkbox"/>
13	24/03/18 12:27	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Allswell Motor Traders (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
14	24/03/18 12:27	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Allswell Motor Traders (HQ)	Thumbnail	Print
1	24/03/18 12:27	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	24/03/18 12:27	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CT118005853/GCD3E2**Date:** 19/08/2019REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCP3N3084451700

Claimant Vehicle No : SLU9077S **Insured Vehicle No :** SJN7799R

Date of Loss: 23/03/2018 Nature of Claim: TP Claim No: SNM18D01570C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU9077S**

Make & Model: TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A) Engine No: 2ZR0A22644

Reg. Date: 18/12/2017 (Man. Year: 2017) Chassis No: ZVW400027155

Colour: Black Odometer: 20831 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	196.50	147.37	49.13	25.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	550.00	730.00	57.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,476.50	697.37	779.13	52.77
+ GST 7.00/7.00% (S\$)	103.36	48.82	54.54	52.77
Nett Amount (S\$)	1,579.86	746.19	833.67	52.77

INSPECTION

Date of Assignment: 29/03/2018

Date Inspected: 29/03/2018 Inspected At: Allswell Motor Traders (HQ)
25 Defu Lane 9
Singapore 539266

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$697.38

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Aug 2019)
Parts: 144	TOYOTA PRIUS ALPHA HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLU9077S)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR ANTENNA	Damaged	196.50 F	*196.50 FL
2	1		*REAR BUMPER (NPA)	Repair	0.00 F	*- FL
					Sub Total (S\$)	196.50
					- List Item Discount on L Items 0.00/25.00% (S\$)	49.13
					Total Parts (S\$)	147.37

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DISMANTLE / ASSEMBLY OF DAMAGED PARTS	New	240.00	100.00
2	SPRAY PAINTING ON AFFECTED PARTS	New	360.00	150.00
3	KNOCKING OF END PANEL	New	120.00	100.00
4	REPAIR / PUTTY / SANDPAPER REAR BUMPER	New	560.00	200.00
Gross Labour Cost (\$\$)			1,280.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >