

ASS. REC. BY:

REF: C93 / Lpc18005854 / Cttber2 Special Instruction:

Surveyor: 62 ASSIGNMENT (Office)From (Person): Ony Li Li of Lpc Date/Time: 29032018 958am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJP 2050P Insured: SJM 9169Bat Workshop m/s Huat Hock Motor Tel: _____of Blk 3012 Bedok Ind Park E # 01-2054Policy No: _____ Claim No: 18/18/18 / VP05 / 0201196

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 28032018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

02042018

H.O.D. Endorsement: _____

Date/Time: 29032018 1035am Person Contacted: David Vehicle IN / OUT OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SJP 2050P - X</u>
	<u>SJM 9169B - CS / 01/12/2017 465 / Km</u> DCA: 3008/2
<u>214-</u>	<u>Resurvey</u>
<u>314-</u>	<u>After repair</u>
	<u>Submit PRS Report.</u>

PR5
Signature: *[Signature]*

REF:

LPC

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJP 2050P
 at Workshop m/s Huat Hock
 of BIR 3012 Bedok Ind Pk E # 01-2054
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJP 2050P Yr Regn: _____
 Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai C.C. _____
 Colour: white A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA
 Sp. Reading: 124679 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA
 Eng/No: _____
 C/No: KMH0U41BR 54712803
 Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Modi: ☐ Nil / ☐ S/Rim / ☒ STD / ☐ Rim or

Tyre Size: F: 195/60R15
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 02-04-18
 Survey held at w/s 11:30 AM

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PRE.

RECEIVED 17 APR 2018

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair: -

Resurvey No. of Trip: 2

Survey Fee: 450

Transportation: _____

) \$ + RS. _____

) Photos

) Others

TOTAL

450

Report Format: PR5-TP

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS/LPC18005854/Gtb

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 29-03-2018



Code : LPC2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	SJM 9169B	Veh. Inspected	SJP 2050P
Policy No.		Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020496	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	29/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	28/03/2018	Inspection Date	02/04/2018
Survey held at	HUAT HOCK MOTOR WORKSHOP BLK 3012 BEDOK NORTH AVE 4 BEDOK INDUSTRIAL PARK E #01-2054 SINGAPORE 489978		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 29 March, 2018 9:58 AM
To: Doreen; assignments@lkkauto.com; 'SUR' (sur@lkkauto.com); Catherine Chong (LKK Auto)
Cc: MT_Claim_SG
Subject: RE: Your Ref: 18/18/18/VP05/020496 - Accident involving SJP2050P & SJM 9169B on 28/03/2018

Without Prejudice

Dear Doreen

We are not agreeable to your list of proposed surveyors. We shall appoint LKK Auto Consultants Pte Ltd to conduct the pre-repair survey.

Dear Catherine

fya

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Doreen [mailto:doreen@crlpractice.com]
Sent: Thursday, 29 March, 2018 9:47 AM
To: ONG LI LI
Cc: MT_Claim_SG
Subject: Your Ref: 18/18/18/VP05/020496 - Accident involving SJP2050P & SJM 9169B on 28/03/2018

Without Prejudice

Dear Li Li

Thank you for your reply on 28.03.2018.

Our client is not agreeable to your list of surveyors and would like to propose the following surveyors listed below. Considering the fact that our client's repairer is a modest workshop, they are only able to nominate 6 surveyors.

List of surveyors:

1. T T Rajan
2. Andrew How
3. Shandy Low
4. Candy Tan

5. Kris Ang
6. Errol Tan

We look forward to your agreement to any one of the said 6 surveyors to be the mutual surveyor (single joint expert).
Please let us have your reply within 2 days. Thank you.

Please be informed that our client's vehicle is available for your PRS located at:

M/S HUAT HOCK MOTOR WORKSHOP AT BLK 3012, BEDOK INDUSTRIAL PARK E, #01-2054, SINGAPORE 489978.

Please contact MR DAVID MONG AT H/P: 8161 6988 to confirm the time and date of your pre-repair survey.

We will submit our client's claim once all the relevant supporting documents are in order.

Doreen Tan

C RAMESH LAW PRACTICE
31 SAM LEONG ROAD #01-01
SINGAPORE 207921
TEL: 62914086

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT

LONPAC INSURANCE BHD

Ref: CS3/LPC18005854/Gtbe2

300 BEACH ROAD

Date: 17-04-2018

#17-04/07 THE CONCOURSESINGAPORE 199555



Code: LPC2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJM 9169B	Veh. Inspected	SJP 2050P
Policy No.		Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020496	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	29/03/2018

2. Vehicle Particulars & Condition


Make & Model	HYUNDAI	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	KMHU41BR9U712803	Colour	WHITE
Odometer	124679 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	MICHELIN	6 mm
L/H Front Tyre	195/60 R15	MICHELIN	6 mm
R/H Rear Tyre	195/60 R15	MICHELIN	6 mm
L/H Rear Tyre	195/60 R15	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

**5. General Information**

Accident Date	28/03/2018	Inspect Date / Time	02/04/2018 (11:30 PM)
Survey held at	HUAT HOCK MOTOR WORKSHOP BLK 3012 BEDOK NORTH AVE 4 BEDOK INDUSTRIAL PARK E #01-2054 SINGAPORE 489978		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
 THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Report Ref No. CS3/LPC18005854/Gtbe2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.