

ASS. REC. BY:

REF: CS/ASM18005855 / Uv69² Special Instruction:

SURVEYOR

ASSIGNMENT (Office)

From (Person):

Peter Wang

of

ASM

Date/Time:

28032018 140pm

Estimated Cost:

Bill to:

TP / FWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SOM 5028Y

Insured:

at Workshop m/s

SME Motor

Tel:

of

Blk 1 Kaki Bukit Ave 6 # 02-15

Policy No:

Claim No:

S8M00C50

Sum Insured:

Excess:

NTL

Make of Veh:

D.O.A.

2203 2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

28032018 9:10am

Person Contacted:

Pei Ying

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SOM 5028Y - CS/ASM18005764 / yds
5/4/18	Send preli revised by SMART claim

DA: 19032018

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SOM 502fy

at Workshop m/s: Sme

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 5.9

IDAC / Accident Rpt: ✓ Consistent?: Yes or No

GI / PR Seen: ✓ Consistent?: Yes or No 29836
1451F

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SOM 502fy Yr Regn: 2 / 12

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or car

Make: Volkswagen passat c.c. 1798

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: B7472 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZZZ3CXCPO39921

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inop / Jammed / Leaked / Burnt or

Brake: Inop / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or continental

Front: 6 mm Rear: 6 mm

R/Bal. 0 mm L/Bal. 0 mm

D.O.A. 22/3/18 D.O.I. 4/4/18

Survey held at _____ @ 3:15pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 47827 3yrs 11mth. 22/11

check excess of 6yrs.

17/4/18 cont. work final by \$1680 with AH Yang (Ref 365, 189)

2/18/18

RECEIVED 18 APR 2018

Date/Time, File Pass to?

: Prel. Report
 : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee: 150

Date/Time, File Return to?

1) _____
2) 19/4 - typist

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Transportation: _____

Photos: _____

Others: _____

TOTAL

Report Format: SMART claim

Lump Sum / I.B.I: (\$ 1680)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CS/ASM18005855/Uvb	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 29-03-2018	
		Code : ASM	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SDM 5028Y
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00C50	Excess (\$)	0.00
Assign From	SMART CLAIM (PETER WANG)	Assign Date	28/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	22/03/2018	Inspection Date	04/04/2018
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

◀ Service Request Details

Claim

S8M00C50

Reference

None ✎

Loss Date

March 22, 2018

Request Date

March 28, 2018

Due Date

April 5, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SDM5028Y

Make

VOLKSWAGEN

Service Address

1 Kaki Bukit Ave 6 #02-15, , 417883

Primary Contact/Insured

HO NGIAP KUM
52 LORONG G TELOK KURAU, #05-04, 426235, Singapore
96348442

Claim Handler

WANG Peter

peter.xiao@axa.com.sg

Additional Instructions
Wkshop: SME Excess: Nil

- [Messages](#)
 - [Invoices](#)
 - [History](#)
 - [Documents](#)
 - [Assessment](#)
 - [Metrics](#)
 - [Notes](#)
-

New Message

TYPE



SENT

3/28/18 1:42 PM

FROM

WANG Peter

SUBJECT

Authorize only the related parts

BODY

There were two accidents causing damage to differe...



◀ **OD Excess: Nil**

Type

🔗 Question

Message

Please refer to the CI and schedule linked to you. Driver is car owner, and OD excess is 0.

Reply



IA SUBMITTED FOR SDM 5028Y (DOA: 22/3/2018)

Type

🔍 Question

Message

Dear Sir/Madam, Please be informed that IA submitted. We have Authorize repair. Kindly re-confirmed on the excess as driver's is 68 years old. Workshop Estimate Amount : S\$2,045.00 Revised Estimate Amount : S\$1,590.00 "Check" Items Amount : S\$90.00 Total : S\$1,680.00 Market Value : S\$59,000.00 COE/PARF Rebate : S\$47,805.00 Nett Value : S\$11,195.00 Thanks Veron Chen

Reply

Your ref: S8M00C5O

Our ref: CS/ASM18005855/Uvb

Date: 5/4/2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam

PRELIMINARY ADVICE OF VEHICLE NO. SDM 5028Y


We thank for your instruction on 28/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 4/4/2018 at the premises of M/s SME MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$2,045.00
Revised Estimate Amount	: S\$1,590.00
"Check" Items Amount	: S\$90.00
Total	: S\$1,680.00
Market Value	: S\$59,000.00
COE/PARF Rebate	: S\$47,805.00
Nett Value	: S\$11,195.00

Description of Damage:

The vehicle sustained damages at the n/s rear portion



Survey date and time: 4/4/2018 at 3.15PM

We have authorize repair.

No of days: 2 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/03/2018 17:29
Date Of Accident	22/03/2018 19:45
Exact Location Of Accident	52 LORONG G TELOK KURAU CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDM5028Y
Insured/Policyholder	
Name Of Registered Owner	HO NGIAP KUM
NRIC No	S0088037Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96348442
Alternative Phone No	OFFICE-96348442

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	PASSAT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1260551
Cover Note Number	

Driver

Name of Driver	HO NGIAP KUM
NRIC No	S0088037Z
Date Of Birth	28/02/1950
Occupation	INDOOR
Date Of Driving Pass	23/01/1975
Driving Experience	43 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96348442
Fax Number	
Contact Number	OFFICE-96348442
EMail Address	NOEMAIL

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



redefining/Insurance

Date: 29/03/2018

To: Owner of Vehicle Number: SDM 50284

The following has been advised to you via your workshop, SME MOTOR PTE LTD through their staff.

Please tick the applicable box if you had been advice on the content as seen below:

You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

You had been advised by the workshop on the liability and merits of the case accordingly.

You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.

There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.

There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.

The estimated waiting time for the spare parts to arrive is _____. The estimated arrival time does not include the repair period.

You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.

For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.

For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using any combination of genuine original parts and/or original equipment manufacturer (OEM) parts.

You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.

For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.

Others _____

Signed and acknowledge by _____

Name and signature of policyholder/authorised driver

Name and signature of workshop personnel including company stamp

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8037Z
Vehicle Details	
Vehicle No.:	SDM5028Y
Vehicle to be Exported:	No
Intended De-registration Date:	05 Apr 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	PASSAT 1.8 TSI AT 3624H7
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	CDA270910
Chassis No.:	WVWZZZ3CZCP039921
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$29,836.00
Original Registration Date:	10 Feb 2012
First Registration Date:	10 Feb 2012
Transfer Count:	0
Actual ARF Paid:	\$29,836.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Feb 2022
PARF Rebate Amount:	\$19,393.00
Intended COE Rebate Details	
COE Expiry Date:	09 Feb 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$73,890.00
COE Rebate Amount:	\$28,412.00
Total Rebate Amount:	\$47,805.00

The information contained herein is correct as at 05 Apr 2018

OK

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Toyota Hiace Commuter GL 3.0A



Top Top Conditions,
 Direct Owner StarAd



Post an Ad Advertiser Login Ways of Selling

Browse by Category ▾

Sort by

13 vehicles

volkswagen passat

Advanced

Make Model Price Depreciation Reg Date Eng Cap Mil

Search Selection

volkswagen passat Any Any 2012 Any



Volkswagen Passat 1.4A TSI \$60,800 \$10,480 /yr 24-Sep-2012 1,390 cc 98

1.4L Turbo Engine Provides You With Sufficient To Get Around Daily, Spacious And Large German Family Sedan For Your And Low Road Tax! All Trade In Welcome, Various Loan Sc...

Creative Auto

Posted: 04-Apr-2018 Tags: 2012 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen



Volkswagen Passat 1.8A TSI \$57,800 \$11,100 /yr 14-Feb-2012 1,798 cc 98

\$7K Down Payment. One Owner Only! Not To Be Miss This Rare Beauty! Brilliant Driving Dynamic With Fantastic Fuel Ef The Previous Owner! Low Mileage Done! Flawless Interior ...

SmartCars Boutique Pte Ltd

Posted: 04-Apr-2018 Tags: 2012 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen



Volkswagen Passat 1.8A TSI \$58,988 \$11,620 /yr 19-Jan-2012 1,798 cc 15

1 Owner, Fully Maintained And Serviced By Volkswagen Centre Singapore. Last Service At 150k Km. New Clutch (Warran Battery Replaced Q4 2016. Groomed Regularly By Detail Lab. ...

Posted: 04-Apr-2018 Tags: 2012 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen



Volkswagen Passat CC 1.8A TSI \$62,800 \$12,550 /yr 17-Jan-2012 1,798 cc 55

Elegant White, Low Mileage Done, Powerful Drive, Serviced By Agent, With Navigation System, Very Well Maintained, Dr Payment, Flexible In House Loan Packages Available.

Prime Motor & Leasing

Posted: 02-Apr-2018 Tags: 2012 Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Used Volkswagen

Car Buying

Car Selling

Car Ownership

Compare



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
 TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
 DAIHATSU / KIA / SUZUKI / HONDA
 TEL: 6291 2827 FAX: 6296 4390
 A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: SME MOTOR PTE LTD

1 KAKI BUKIT AVE 6
 #02-15-16 1718 AUTOBAY @ KAKI BUKIT
 SINGAPORE 417885
 SDMS9285
 SEBAST

NO: DL19201943
 PAGE: 1
 DATE: 13/04/2018
 ACC CODE: LDSM446
 TERMS: CR

Part No	Description	Location	Qty	Unit Price	Amount	
				SIN	SIN	
Our D/O No: DDO9021479						
1	V3AE 807 417 F GRU	RR BUMPER	VBA-20	1	850.00	850.00
2	V3AE 807 459 2ZZ	RR BUMPER CHROME LH	DST248	1	90.00	90.00
3	V3AE 945 095 F	TAILLIGHT LH	VB-13	1	210.00	210.00
4	VN 909 747 01	BUMPER CLIP	DDS	10	3.00	30.00
			TOTAL QUANTITY:	13	TOTAL	SIN 1,180.00
					ADD GST @ 7%	82.60
					GRAND TOTAL	<u>SIN 1,262.60</u>

#02-18

Print / MT / 13/04/2018 10:36:52 AM

SALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



GOODS RECEIVED BY



<< **Service Request Details**

Claim	S8M00C50
Reference	
None	Loss Date
March 22, 2018	Request Date
March 28, 2018	Due Date
March 29, 2019	Vendor Name
LKK AUTO CONSULTANTS PTE LTD (OD)	Type of Loss
Own Damage	Services

Actions

Next Step Finish the work Complete Work More

Vehicle Information

Incident Vehicle	SDM5028Y
Registration n #	VOLKSWAGEN 1
Make	PASSAT 1.8
Address	Kaki Bukit Ave 6 #02-15, , 417883

Primary Contact/Insured

HO NGIAP KUM
 52 LORONG G TELOK KURAU,
 #05-04, 426235, Singapore
 96348442

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
MARK ESTIMATE.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	April 5, 2018
PRELI ADVISED.pdf	Evidence	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	April 5, 2018
OI GIA - Previous accident on 19 Mar.PDF	Reports & Statement	GIA Report	WANG Peter	March 28, 2018
Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	WANG Peter	March 28, 2018
CI.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	WANG Peter	March 28, 2018
SDM5028Y REPORT.pdf	Reports & Statement	GIA Report	SME MOTOR PTE LTD	March 28, 2018
SDM5028Y ESTIMATE (2).pdf	Reports & Statement	GIA Report	SME MOTOR PTE LTD	March 28, 2018

Service Request Details

Claim	S8M00C50
Reference	
None 	Loss Date
March 22, 2018	Request Date
March 28, 2018	Due Date
March 29, 2019	Vendor Name
LKK AUTO CONSULTANTS PTE LOSS LTD (OD)	Type of Services
Own Damage	Services

Vehicle Information

Incident Vehicle: SDM5028Y
 Registration #: [Redacted]
 Make: VOLKSWAGEN
 Model: PASSAT 1.8
 Address: Kaki Bukit Ave 6 #02-15, , 417883

Actions

- Next Step: Finish the work
- Complete Work
- More

Primary Contact/Insured

HO NGIAP KUM
 52 LORONG G TELOK KURAU,
 #05-04, 426235, Singapore
 96348442

- HOME
- SERVICE REQUESTS
- MESSAGES
- CLAIMS

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SDM5028Y

Registration State
SINGAPORE

Mileage
87472

Purchase Date
mm/dd/yyyy

Registration Date *
02/10/2012

Age of Vehicle
6

Driver Details

CATEGORY
POLICY INFORMAT... 2012

Driver Name
CATEGORY

ASSESSMENT INFO...
2011

FNOL INFORMATI...
HO NGIAP KUM

POST SURVEY INF ...

ASSESSMENT INFO ... WWWZZZ3CZCP039921

FNOL INFORMATI... 43

CATEGORY Engine No

POST SURVEY INF ...

Driver License #

POLICY INFORMAT ... CDA270910

FNOL INFORMATI...

ASSESSMENT INFO ... CDA270910

POST SURVEY INF ...

CATEGORY Engine Capacity

License Type

POLICY INFORMAT ...

FNOL INFORMATI...

ASSESSMENT INFO ... 1798 cc

POST SURVEY INF ...

CATEGORY Sum Insured

License Issue Date

POLICY INFORMAT ... 0

FNOL INFORMATI...

ASSESSMENT INFO ... 0

POST SURVEY INF ...

CATEGORY Market Value

License Expiration Date

POLICY INFORMAT ... 0

FNOL INFORMATI...

ASSESSMENT INFO ... 59000

POST SURVEY INF ...

CATEGORY Address

POST SURVEY INF...

-  SERVICE REQUESTS
- MESSAGES
- CLAIMS

 **Assessment Details**

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Front left side

CONTINENTAL 6mm

Front right side

CONTINENTAL 6mm

Rear left side

CONTINENTAL 6mm

Rear right side

CONTINENTAL 6mm

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary Parts

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BITTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART)
<input type="checkbox"/>	1	1			REAR BUMPER			Cut	850				850	Revie
<input type="checkbox"/>	2	1			REAR BUMPER SIDE RETAINER LH			Serviceable	0				0	Revie
<input type="checkbox"/>	3	10			REAR BUMPER CLIP			Necessary	3				30	Revie
<input type="checkbox"/>	4	1			REAR BUMPER CHROME LH			Cracked	90				90	Revie
<input type="checkbox"/>	5	1			REAR TAIL LAMP LH			Damaged	210				210	Revie
<input type="checkbox"/>	6	1			REAR REVERSE SENSOR LH			Serviceable	0				0	Revie

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	R
<input type="checkbox"/>									

- SERVICE REQUESTS
- MESSAGES
- CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary Claim Amount \$1,680.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$500.00	\$500.00
Spare Parts	\$1,180.00	\$1,180.00

Submit for Review