

VEHICLE NO.: SDM5028Y
 MAKE: VOLKSWAGEN
 MODEL: PASSAT
 YEAR OF MAKE: 2011
 CHASSIS NO.: WVWZZZ3CZCP039921
 SUPPLIERS : HEXING

Approval
 with
 Excess Nil
 2 day.
 take photo before repair
 4/4/18

S/N	Parts Description	QTY	Amount	
PARTS				
1	REAR BUMPER <i>Deep cut</i>	1	\$850.00	✓
2	REAR BUMPER SIDE RETAINER LH <i>17</i>	1	\$35.00	X
3	REAR BUMPER CLIP <i>new</i>	10	\$30.00	✓
4	REAR BUMPER CHROME LH	1	\$90.00	?
5	REAR TAIL LAMP LH <i>scr</i>	1	\$210.00	✓
6	REAR REVERSE SENSOR LH <i>17</i>	1	\$110.00	X
7				
8				
9				
10				
11				
12				
13				
14				
15				
TOTAL PARTS			\$1,325.00	
S/N				
1				
2				
TOTAL S/N			\$0.00	
LABOUR :				
1	WIRE CHECKING		\$20.00	✓
2	LABOUR CHARGE		\$400.00	200
3	SPRAY PAINTING		\$300.00	280
4				
5				
6				
TOTAL LABOUR			\$720.00	
TOTAL			\$2,045.00	
GST 7%			\$143.15	
TOTAL			\$2,188.15	

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____