

ASS. REC. BY:

REF: CG/MS618005862/R146

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person):

Mammala

of

msl

Date/Time:

29/03/2018 5:13am

Estimated Cost:

Bill to:

OB / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SD0 6600K

Insured:

at Workshop m/s

Performance

Tel:

91165200

of

303 Alexandra Rd

Policy No:

827312999mTR

Claim No:

553889

Sum Insured:

Excess:

1500.00

Make of Veh:

D.O.A.

28/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

29/03/2018 10:08am

Person Contacted:

Chua

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SD0 6600K - CG/MS618005862/Avg1
2/4	Revert via menmen
3/4/18	10:13 authorise repair by kenny Ong
3/4/18	@11:20am inform Chua authorise repair.
	Part by part \$5268/- (Red. 3411.85 139%)

GIVE DATE

REF:

1559w

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDD 6600K

at Workshop m/s PERFORMANCE

of _____

Insured: M316/00

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 1500


(Client's Record)

Make of Veh: _____

(Policy Condition)

CHINA

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 250k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SDD 6600K Yr Regn: 11 / 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 740L2 cc 1593

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 30463 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NBA7E220806099675

Gen. Cond: Good (Fair) / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45R19

R: 1-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 28/03/18 D.O.I. 29/03/18

Survey held at PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 02 MAY 2018

Date/Time: File Pass to?

1) 215 Typist

Date/Time: File Return to?

2)

☐ : Prel. Report☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: 00

Lump Sum / I.B.I: (\$ 52681)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18005862/R1tb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 29-03-2018	
			Code : MSG	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.			Veh. Inspected	SDD 6600K
Policy No.	B27392999MTR		Coverage (\$)	0.00
Claim No.	553889		Excess (\$)	1,500.00
Assign From	MERIMEN (VIMMALA)		Assign Date	29/03/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/03/2018		Inspection Date	29/03/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Mar 2018		29 Mar 2018 09:13 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	PERFORMANCE MOTORS LIMITED, Co. Reg. No.: 197401559W		
Vehicle Reg. No.:	SDD6600K	Date of Loss:	28/03/2018 09:00 - :59
Claim Type:	OD / 553889	Policy/Cover Note No.:	B27392999MTR (Comprehensive) Coverage: 01/10/2017 - 30/09/2018
		Excess:	S\$1,500.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmaia D/O Raja Singam - 65942471]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/03/2018]		
Driver/Custodian:	LEE THIAM HOR (53 / Male), NRIC: S1634003J, Tel: +6597873628		
Adj Asg. Remarks:	Please revert and arrange for survey by today. Thank you.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 3 April 2018 11:20 AM
To: 'Chua Kee Sin'
Cc: 'Han Kwan Yong'; Gary Poh Chai Hoon; SUR
Subject: SDD 6600K MSIG OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SDD6600K (Excess \$1,500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SDD6600K (553889)**

OD

Mar 28 2018 9:00AM

[PERFORMANCE MOTORS LIMITED]

Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 03/04/2018 10:13 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$7594.85) - SDD6600K - Claim Handler: Vimmala D/O Raja Singam

Approved:7594.85:a if c

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	28/03/2018 11:40
Date Of Accident	28/03/2018 09:40
Exact Location Of Accident	SCIENCE PARK DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SDD6600K
Insured/Policyholder	
Name Of Registered Owner	PERFORMANCE MOTORS LIMITED
Co Reg No	197401559W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97873628
Vehicle Particulars	
Manufacturer	BMW
Model	740
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B27392999MTR
Cover Note Number	
Driver	
Name of Driver	LEE THIAM HOR
NRIC No	S1634003J
Date Of Birth	29/11/1964
Occupation	INDOOR
Date Of Driving Pass	23/03/1984
Driving Experience	34 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97873628
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address: NOTAVAIL

Postcode:

Was driver an employee of the Insured's Company: NO

If No, Relationship of the Driver with the Insured: OTHER - TESTER

Vehicle Registration Number of Driver's Own Vehicle: -

Insurance Company of Driver's Own Vehicle: -

General Information of the Accident

Type Of Accident: COLLISION - HEAD TO REAR

Weather Conditions: CLEAR

Road Surface: DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident: 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance: NO

Number of Passengers (Including Driver): 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number: SLF7550J

Vehicle Make/Model/Colour: TOYOTA HARRIER WHITE

Details Of Properties:

Vehicle Category: PRIVATE CAR

Name of Driver: TING YING CHAO

NRIC/Passport Number: S7931952Z

Contact Number: 97549161/98266609

Address:

Postcode:

Insurance Company Name: EQ INSURANCE COMPANY LTD

Nature Of Damage:

No. Of Passenger (Including Driver):

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

INSURANCE MOTORS LIMITED
532 Jooeoon Road
Sino Dairy Farm, #01-01/02
Singapore 108011
TEL: 62101100 (3 lines)
62102111 (3 lines)


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PRN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

at Science park drive
ON 28/3/2018 at 9:40 Am while stopping at pedestrian crossing for
pedestrian to cross the road suddenly a white Toyota Hawkeye ran into
the rear of the van I'm driving SAD 6600 K.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRC/PIN No.:

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 069807
 Tel +65 6927 7888, Fax +65 6927 7800
 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

MOTOR TRADE INSURANCE**ENDORSEMENT**

Policy Number	Period of Insurance	Place of Issue
B 27392999 MTR	01/10/2017 to 30/09/2018	SINGAPORE
Name and Address of Insured	Date of Issue	Account Number
Performance Motors Limited 303 Alexandra Road Singapore 159941	26/10/2017	212668
Premium	GST	Total Due
SGD0.00	SGD0.00	SGD0.00

RISK NUMBER 1**COMMERCIAL VEHICLE****BUSINESS**

All activities of the Insured including but not limited to
 Motor Vehicles Dealership, Sales, Services, Repairs,
 Maintenance and Property Owners

SCOPE OF COVER Comprehensive**INTEREST INSURED**

ITEM 0001

REGISTRATION NO. -

MAKE/MODEL TradePlate

ENGINE NUMBER -

CHASSIS NUMBER -

YEAR OF MFG -

CAPACITY -

SEATING CAPACITY -

SUM INSURED SGD500,000.00

NO CLAIM DISCOUNT 20.00% (or F/D)

EXCESS SGD1,500

WINDSCREEN UNLIMITED

ANNUAL PREMIUM SGD76,161.60

AUTHORISED DRIVERS

123 Authorised Drivers

Any other person provided he is in the Insured's employ and is driving on the
 Insured's order or with the Insured's permission.

LIMITATION AS TO USE

Use only for Motor Trade purposes.

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait of a man

Licence Number: **S1634003J**
 Name: **LEE THIAM HOR**
 Birth Date: **29 Nov 1964**
 Issue Date: **22 Feb 2003**

Barcode: 000226968E

REPUBLIC OF SINGAPORE
IDENTIFICATION CARD NO. **S1634003J**



LEE THIAM HOR

李添和

CHINESE

29-11-1964 M

SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 2B Motorcycles not exceeding 200 cc
 Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE
 01 Jun 1990
 23 Mar 1984



2216483

S1634003J



Blood Group: **B+**
 Date of Issue: **02-07-1994**

APT BLK 150 ANG MO KIO AVENUE 5
 #10-3088
 SINGAPORE 2088

NP 428A



Licence No: S1634003J

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559M GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63448773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46406
Date Estimated : 28/03/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Lim Boon Eng
19 Camden Park

Singapore 299812

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDD6600K	GD99675	25/11/2015	740LiA	0

DESCRIPTION

Replace rear bumper and remove attachment etc include knock on accident dent

VALUE

1275 2,125.00

Spray painting rear bumper and rear boot lid

1868 2,076.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

80.00

Repairs take 3 - 4 working day s
quoted for cash job repair only

0.00

Any addition recommend will be inform before proceed

Total Labour 1: 4,458.00

DESCRIPTION

REAR BUMPER CARRIER
REAR LH MOUNT LATERAL
REAR RH MOUNT LATERAL
REAR LH MOULDING ROCKER PANEL
REAR RH MOULDING ROCKER PANEL
REAR BUMPER CENTRE GUARD
BUMPER GUARD REAR
RUBBER STRIP LH
RUBBER STRIP RH
REAR BUMPER COVER
TRIM REAR PRIMED
REAR BUMPER PANEL PRIMED (PDC/PMA)
EMBLEM GROMMET
LETTERING 740Li
BMW EMBLEM
PLUG
ULTRASONIC SENSOR BLACK
DECOUPING RING PDC TORQUE CONVERTER

QTY PRIC

1 898.50
1 142.55
1 142.55
1 51.50
1 51.50
1 84.20
1 102.95
1 85.05
1 85.05
1 107.05
1 216.45
1 1,586.85
2 0.80
1 62.55
1 69.50
6 1.05
2 248.70
6 5.05

VALUE

898.50
142.55
142.55
51.50
51.50
84.20
102.95
85.05
85.05
107.05
216.45
1,586.85
1.60
62.55
69.50
6.30
497.40
30.30



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

318, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190518 (AfterSales)
63190533/335 (Motorrad)
Fax. 64794601 (AfterSales)
64794624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46406
Date Estimated : 28/03/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDD6600K	GD99675	25/11/2015	740LiA	0

Total Parts : 4,221.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No.	Claim No.
Date&Time 29/03/18 @ 14:00	Excess S\$ 1500
Surveyor's Name P. M. M.	Sign
Surveyor's Tel 90000068	Authorised Yes/No ☒ Yes
Authorised Date	Time
RESURVEY PARTS PHOTO BY SURVEYOR Yes/No ☒ Yes	
Surveyor's E-mail	
No. of Working Days Recommend 4-5 days	

Signature
3/4/18

Labour 1	:	4,458.00
Parts	:	4,221.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	607.59
Grand Total	:	9,287.44

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0000081-X



FINAL REPORT

Estimate No. : b1 46406
Date Estimated : 28/03/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Lim Boon Eng
19 Camden Park

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 299812

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SDD6600K	GD99675	25/11/2015	740LiA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include making good the boot lid, tail end panel and knocking out dents caused by the accident	1275.00		1,275.00	
To spray paint rear bumper, boot lid and tail end panel	1868.00		1,868.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR BUMPER CENTRE GUIDE *	51.50	1.00		51.50
RUBBER STRIP RH	85.05	1.00		85.05
REAR BUMPER PANEL PRIMED (PDC/PMA)	1,586.85	1.00		1,586.85
EMBLEM GROMMET	0.80	2.00		1.60
LETTERING 740LI	62.55	1.00		62.55
BMW EMBLEM	69.50	1.00		69.50
# RH WATER CHANNEL *	37.95	1.00		37.95

SUPPLEMENTARY ITEMS

Total Labour :	3,373.00
Total Parts :	1,895.00
Total Labour & Parts :	5,268.00
Deduction for Excess :	1,500.00
Total Repair Costs less Excess:	3,768.00
GST @7%:	263.76
Grand Total :	4,031.76

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M3-0020081-X



SUPPLEMENTARY

Estimate No. : b1 46406
Date Estimated : 28/03/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Lim Boon Eng
19 Camden Park

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 299812

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SDD6600K	GD99675	25/11/2015	740LiA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR BUMPER CENTRE GUIDE *	51.50	1.00		51.50
# RH WATER CHANNEL *	37.95	1.00		37.95

Total Labour :
Total Parts : 89.45
Total Labour & Parts : 89.45

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Mar 2018		29 Mar 2018 09:13 Edit Adj Rpt	\$5,268.00 Edit Estimates	\$5,268.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	PERFORMANCE MOTORS LIMITED , Co. Reg. No.: 197401559W								
Vehicle Reg. No.:	SDD6600K	Date of Loss:	28/03/2018 09:00 - :59 [28 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 553889	Policy/Cover Note No.:	B27392999MTR (Comprehensive) Coverage: 01/10/2017 - 30/09/2018						
		Excess:	\$1,500.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 28/04/2018]								
Driver/Custodian:	LEE THIAM HOR (53 / Male), NRIC: S16340033, Tel: +6597873628								
Adj Asg. Remarks:	Please revert and arrange for survey by today. Thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (02/05/2018): Alert - Adj Mandate Approved (\$5268.00) - SDD6600K - Claim Handler: Vimmala D/O... - MSIG_SG (03/04/2018): Alert - Adj Mandate Approved (\$7594.85) - SDD6600K - Claim Handler: Vimmala D/O...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDD6600K (553889)
 OD
 Mar 28 2018 9:00AM
 [PERFORMANCE MOTORS LIMITED]
 Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Video									1 per page		☒			
No	Finalized On	Performance Motors Limited (Alexandra)						Thumbnail		Print				
1	28/03/18 14:08	Video - Accident [Linked Accident Report Documents]								Load AVI		☒		
Assessment Reports									1 per page		☒			
No	Finalized On	Performance Motors Limited (Alexandra)						Thumbnail		Print				
1	28/03/18 14:16	Accident Statement								Load HTM		☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print				
1	02/04/18 17:09	Adjuster Immediate Advice								Load HTM		☒		
2	30/04/18 16:50	Adjuster Immediate Advice								Load HTM		☒		
Photos/Images									3 per page		☒			
No	Finalized On	Performance Motors Limited (Alexandra)						Thumbnail		Print				
1	28/03/18 11:45	Accident Photo [Linked Accident Report Documents]								Load JPG		☒		
2	28/03/18 11:45	Accident Photo [Linked Accident Report Documents]								Load JPG		☒		
3	28/03/18 11:45	Accident Photo [Linked Accident Report Documents]								Load JPG		☒		
4	28/03/18 11:45	Accident Photo [Linked Accident Report Documents]								Load JPG		☒		
5	28/03/18 11:45	Accident Photo [Linked Accident Report Documents]								Load JPG		☒		
6	28/03/18 11:45	Accident Photo [Linked Accident Report Documents]								Load JPG		☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print				
1	30/04/18 16:46	General View								Load JPG		☒		
2	30/04/18 16:46	General View								Load JPG		☒		
3	30/04/18 16:46	General View								Load JPG		☒		
4	30/04/18 16:46	General View								Load JPG		☒		
5	30/04/18 16:46	General View								Load JPG		☒		
6	30/04/18 16:46	General View								Load JPG		☒		
7	30/04/18 16:46	General View								Load JPG		☒		
8	30/04/18 16:46	General View								Load JPG		☒		
9	30/04/18 16:46	General View								Load JPG		☒		
10	30/04/18 16:46	General View								Load JPG		☒		
11	30/04/18 16:46	General View								Load JPG		☒		
12	30/04/18 16:46	General View								Load JPG		☒		
13	30/04/18 16:46	General View								Load JPG		☒		
14	30/04/18 16:46	General View								Load JPG		☒		
15	30/04/18 16:46	General View								Load JPG		☒		
16	30/04/18 16:46	General View								Load JPG		☒		
17	30/04/18 16:46	General View								Load JPG		☒		
18	30/04/18 16:46	General View								Load JPG		☒		
19	30/04/18 16:46	General View								Load JPG		☒		
20	30/04/18 16:46	General View								Load JPG		☒		

Video			1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
21	30/04/18 16:46	General View	 Load JPG	☒
22	30/04/18 16:46	General View	 Load JPG	☒
23	30/04/18 16:46	General View	 Load JPG	☒
24	30/04/18 16:46	General View	 Load JPG	☒
25	30/04/18 16:47	Reinspection Photo	 Load JPG	☒
26	30/04/18 16:47	Reinspection Photo	 Load JPG	☒
27	30/04/18 16:47	Reinspection Photo	 Load JPG	☒
28	30/04/18 16:47	Reinspection Photo	 Load JPG	☒
29	30/04/18 16:47	Reinspection Photo	 Load JPG	☒
30	30/04/18 16:47	Reinspection Photo	 Load JPG	☒
31	30/04/18 16:47	Reinspection Photo	 Load JPG	☒
32	30/04/18 16:47	Reinspection Photo	 Load JPG	☒
33	30/04/18 16:47	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/03/18 08:45	Estimate from Performance Motors/CI/NRIC/Driving licence	 Load PDF	
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	28/03/18 11:45	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/04/18 16:45	SUPPLEMENTARY	 Load PDF	

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	28/03/18 14:08	Video - Accident	 Load AVI	
Assessment Reports			1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	28/03/18 14:16	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	28/03/18 11:45	Accident Photo	 Load JPG	☒
2	28/03/18 11:45	Accident Photo	 Load JPG	☒
3	28/03/18 11:45	Accident Photo	 Load JPG	☒
4	28/03/18 11:45	Accident Photo	 Load JPG	☒
5	28/03/18 11:45	Accident Photo	 Load JPG	☒
6	28/03/18 11:45	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	28/03/18 11:45	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18005862/R1TBQ2

Date: 03/05/2018

REFERENCE

Insured/Claimant: PERFORMANCE MOTORS LIMITED

Policy No: B27392999MTR

Date of Loss: 28/03/2018

Nature of Claim: OD

Claim No: 553889

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDD6600K

Make & Model: BMW 740i, 3.0 (A)

Engine No: HIDDEN

Reg. Date: 25/11/2015 (Man. Year: 2015)

Chassis No: MBA7E22080GD99675

Colour: Black

Odometer: 30463 km

Engine Capacity: 1593 cc

Market Value/New Car Price: S\$250,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R19

Rear Tyre Size: 245/45 R19

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,391.30	1,975.00	2,416.30	55.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,378.00	3,293.00	1,085.00	24.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,769.30	5,268.00	3,501.30	39.93
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	7,269.30	3,768.00	3,501.30	48.17
+ GST 7.00/7.00% (S\$)	508.85	263.76	245.09	48.17
Nett Amount (S\$)	7,778.15	4,031.76	3,746.39	48.17

INSPECTION

Date of Assignment: 29/03/2018

Date Inspected: 29/03/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 May 2018)
Parts:	143	BMW 740I 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDD6600K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*REAR BUMPER CARRIER	Serviceable	898.50 FS	*- FS
3	1		*REAR LH MOUNT LATERAL	Serviceable	142.55 FS	*- FS
4	1		*REAR RH MOUNT LATERAL	Serviceable	142.55 FS	*- FS
5	1		*REAR LH MOULDING ROCKER PANEL	Serviceable	51.50 FS	*- FS
6	1		*REAR RH MOULDING ROCKER PANEL	Serviceable	51.50 FS	*- FS
7	1		*REAR BUMPER CENTRE GUARD	Serviceable	84.20 FS	*- FS
8	1		*BUMPER GUARD REAR	Serviceable	102.95 FS	*- FS
9	1		*RUBBER STRIP LH	Serviceable	85.05 FS	*- FS
10	1		*RUBBER STRIP RH	Scratched	85.05 FS	*85.05 FS
11	1		*REAR BUMPER COVER	Serviceable	107.05 FS	*- FS
12	1		*TRIM REAR PRIMED	Serviceable	216.45 FS	*- FS
13	1		*REAR BUMPER PANEL PRIMED (PDC/PMA)	Deformed	1,586.85 FS	*1,586.85 FS
14	2		*EMBLEM GROMMET	Necessary	1.60 FS	*1.60 FS
15	1		*LETTERING 740LI	Necessary	62.55 FS	*62.55 FS
16	1		*BMW EMBLEM	Necessary	69.50 FS	*69.50 FS
17	6		*PLUG	Not Necessary	6.30 FS	*- FS
18	2		*ULTRASONIC SENSOR BLACK	Serviceable	497.40 FS	*- FS
19	6		*DECOUPING RING PDC TORQUE CONVERTER	Serviceable	30.30 FS	*- FS
20	1		*REAR BUMPER CENTRE GUIDE	Cracked	51.50 FS	*51.50 FS
21	1		*RH WATER CHANNEL	Scratched	37.95 FS	*37.95 FS
Total Parts (S\$)					4,391.30	1,975.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE REAR BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT	New	2,125.00	1,275.00
2	SPRAY PAINTING REAR BUMPER AND REAR BOOT LID	New	2,076.00	1,868.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			4,378.00	3,293.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >