

*1hr:10min*

CC 6, LOR 1800 5885, Ujaz 7/

Survivor: Myrus DOI: 29/3/18 Date/Time: 29/3/18  
Registered in Merimen: 29/3/18

Pre-assign / CCU / FTE

SUM 8396U



Insured Vehicle No. : SUM 8396U

Claim No. : 65304 2342756

Name of Insured : LAPP PLC

Policy No. : 99995174

Insured Tel No. : \_\_\_\_\_ HP: \_\_\_\_\_

Make / Model : 7. PEAR

Excess Sec II :SS \_\_\_\_\_ D.O.A: 29/03/18

Place of Accident : MD - Southern Rd

Is driver the owner? ( YES / NO ) \_\_\_\_\_ Nature of Accident : \_\_\_\_\_

If NO, Driver Name / Age : Fong Ian Whist

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : \_\_\_\_\_ (V/L: YES / NO)

Insured Liability: % Final ? Yes / No

SLP 7812B



INSRS: WSP: Pegasus  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_

RECEIVED 21 MAY 2018

COPIES SENT

Date/Time	STAGE	DATE / PIC
<u>3/4 Jony</u>	Non-Reporting ltr (1st):	} NA
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	<u>JDY 4-4-18</u>
	After call ltr to OI:	
	<b>Documentation Check List:</b>	<b>Handler</b> <b>Typist</b>
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>
<b>PRELIMINARY ADVICE</b> Date/Time: _____ Sent By: _____		
<b>FINALIZATION</b> Date/Time: _____ Confirm with: _____ Confirm by: _____		
Repair Cost: SS _____ days) Reduction: _____ % Email <input type="checkbox"/> Call <input type="checkbox"/>		
<b>FINAL SETTLEMENT</b> Date/Time: <u>17/5-18</u> Confirm with <u>SHARON</u> Email <input type="checkbox"/> Call <input type="checkbox"/>		
Final Liability: % <u>100</u> (Agreed/ Assessed) BOLA S/N No. : <u>27</u> If NO or B 28, Ass. Lia :		
Repair Cost: <u>GS</u> SS <u>2,144.46</u>		<u>OI #17 TP FROM</u>
Loss of Rental (LOR): SS <u>468.65</u> 7 days) <u>66.95</u>		<u>REAR</u>
Loss of Use (LOU): SS _____ (\$ x days)		
Loss of Income (LOI): SS <u>X</u> (\$ x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]		
GIA/LTA Search SS <u>X</u>		
Medical: SS <u>X</u>		1) Claim status: Normal/Reject/Private Settle
Disbursement: SS _____ (e.g. Tow/ Independent)		2) Report Format:
Legal Cost SS _____		3) Survey fee:
Total: SS <u>2,613.11</u> Global Sum SS: _____		
<b>FINAL PAYMENT</b> Date/Time: _____ Confirm with: _____ Email <input type="checkbox"/> Call <input type="checkbox"/>		
Payee 1: SS <u>2,613.11</u> Name 1: <u>PEGASUS ENGINEERING &amp; TRADING PTE LTD</u>		
Payee 2: (Strike if N.A.) SS <u>X</u> Name 2: <u>X</u>		
Payee 3: (Strike if N.A.) SS _____ Name 3: _____		

DATE: 29/03/18

REF: AL6

ASSIGNMENT

From: Date: 29-03-2018

Veh No: SLP 7812B Yr Regn: 6 / 17

Estimated Cost:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or CA

To inspect Vehicle No: SLP 7812B

Make: Toyota vios c.c 1496

at Workshop m/s: Pegasus

Colour: Silver A/C: Insured / Std / NI / NA

of: 51 Defu Lane 10

Sp. Reading: 54983 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No: SLM 83964

C/No: MHFB29F3802011992

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 195/50R16

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or must take

Bal. or Market Value:

Front R/Bal: 6 mm Rear R/Bal: 6 mm

IDAC Accident Rpt: Consistent? : Yes or No

L/Bal: 6 mm L/Bal: 6 mm

CA / PR Seen: 2 Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

D.O.A: 27/3/18 D.O.I: 29/3/18

Lum Sum: 1.31 % 3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS

72006

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Date: Person Contacted:

Vehicle: IN / OUT

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

29/3/18 continued final by 2004.17 with william

R (\$4,415.37 / 68%)

Date/Time, File Return to/  : Prol. Report

Days Of Repair:

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

Survey Fee:

Report Format :

Add Fee:  : Site Insp (\$)

Transportation:

Lump Sum / I.B.I. (\$)

: Interview (\$)

(\$ + PC \$)

: Tech. Invs (\$)

) Photos

: Weekend (\$)

) Other

TOTAL



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/LCR18005885/Uja3

78 SHENTON WAY #08-16  
CHARTIS BUILDINGS SINGAPORE 079120

Date : 29-03-2018



Code : LCR

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLM 8396U	Veh. Inspected	SLP 7812B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	29/03/2018

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	27/03/2018	Inspection Date	29/03/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

**From :**  
**PEGASUS ENGINEERING & TRADING PTE LTD**  
 C/O 51 DEFU LANE 10  
 539216  
 Officer in Charge : ALVIN LOW WAI LUN  
 Tel :  
 Email :

**Customer :**  
**GRAB RENTALS PTE LTD**  
 18 SIN MING LANE  
 #01-08 MIDVIEW CITY  
 SINGAPORE 573960  
 Attn : *Confidential*  
 Tel :  
 Fax :  
*on 29/03/18*

*not added*  
*the*  
*29/3/18*  
*P/P 2004.17*  
*3 ty.*  
*order party.*

Quotation No : QO18/03-1298	Quotation Date : 28/03/2018	Terms : 30 DAYS
Vehicle No : SLP7812B	Chassis No : MHFB29F3802011992	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: AIG, TP VEHICLE NO: SLM8396U, DATE OF ACCIDENT: 27.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER	1 <i>DD/De</i>	504.9000	504.90 ✓
2	REAR BUMPER REINFORCEMENT	1 <i>TD</i>	135.0000	135.00 ✓
3	REAR BUMPER SIDE RETAINER	2 <i>ty</i>	50.0000	100.00 ✓
4	REAR BUMPER SIDE HOLDER	2 <i>ty</i>	22.3000	44.60 ✓
5	REAR BUMPER CLIPS	8 <i>ty</i>	4.3000	34.40 ✓
6	REAR BUMPER REFLECTOR	2 <i>ty</i>	130.5000	261.00 X
7	REAR END PANEL	1 <i>ty</i>	694.7000	694.70 ✓
8	REAR END PANEL INNER TRIM	1 <i>ty</i>	234.3000	234.30 ✓
9	REAR LAMP	2 <i>ty</i>	375.8000	751.60 ✓
10	REAR LAMP CLIP HOLDER	4 <i>ty</i>	9.5000	38.00 X
11	BOOTLID E BADGE	1 <i>ty</i>	39.4000	39.40 X
12	BOOTLID VIOS BADGE	1 <i>ty</i>	44.1000	44.10 X
13	BOOTLID CENTRE LOGO BADGE	1 <i>ty</i>	59.8000	59.80 X
14	REAR EXHAUST BOX	1 <i>ty</i>	638.8000	638.80 X
15	REAR EXHAUST BOX HEAT SHIELD	1 <i>ty</i>	46.6000	46.60 X
16	REAR EXHAUST MOUNT	1 <i>ty</i>	78.9000	78.90 X
17	LESS 25% (ITEMS 1-16)	1	-926.5300	-926.53
18	REAR BUMPER PARKING SENSOR	2/100 <i>ty</i>	450.0000	900.00 ✓ <i>200</i>
19	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	900.0000	900.00 ✓ <i>480</i>
20	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	800.0000	800.00 ✓ <i>580</i>
21	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	120.0000	120.00 ✓ <i>50</i>

*818.90*  
*614.92*  
*2004.12*

C/F 0.00

*819.90*  
*614.92*  
*2004.52*

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

<b>From :</b>
PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216
Officer in Charge : ALVIN LOW WAI LUN Tel : Email :

<b>Customer :</b>
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn : Tel : Fax :

Quotation No : QO18/03-1298	Quotation Date : 28/03/2018	Terms : 30 DAYS
Vehicle No : SLP7812B	Chassis No : MHFB29F3802011992	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: AIG, TP VEHICLE NO: SLM8396U, DATE OF ACCIDENT: 27.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
22	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	150.0000	150.00 <span style="float: right;">60</span>
23	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	150.0000	150.00 <span style="float: right;">X</span>
24	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	50.0000	50.00 <span style="float: right;">20</span>
25	TO DROP REAR EXHAUST BOX AND RENEW THE SAME.	1	150.0000	150.00 <span style="float: right;">X</span>

**LKK Auto** Insurers hence notify the Repairer the following:

- To resurvey and/or spray painting
- To display (spray) during resurvey.
- Parts replacement subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplier warranty items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

<b>Sub Total</b>	5,999.57
<b>GST(7.00%)</b>	419.97
<b>Total (SGD)</b>	6,419.54

Please conduct the survey at  
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



9A Lok Yang Singapore 628628  
c/o 51 Defu Lane 10 Singapore 539216

Tel: 6858 1846 / HP 9628 6508  
Fax: 6858 0877

Our Ref SM352032018  
Your Ref SLM83964

Date 08-05-2018

WITHOUT PREJUDICE

Claims Department -Executive In Charge  
AIG Asia Pacific Insurance Pte Ltd

Dear Sir/Madam,

**ACCIDENT INVOLVING** SLP7812B / SLM83964 ON 27.03.2018

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

Original survey report / \_\_\_\_\_ copies of photographs \_\_\_\_\_  
 Original Tax-invoice number IV18/04-1080  police report / police result  
 Certificate Of Insurance \_\_\_\_\_  Vehicle search result  
 Authorization To Act - Owner/Hirer  Rental Tariff

\*Survey under insurance instruction / Independent surveyor / No survey.

a)	Cost of repair (inclusive GST)	\$ <u>2144.46</u>
b)	Survey fees / Photographs as per request	\$ <u>-</u>
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ <u>-</u>
d)	Loss of rental <u>7</u> days @ \$ <u>66.95</u>	\$ <u>468.65</u>
e)	Loss of earnings /rental fees _____ days @ \$ _____	\$ <u>-</u>
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$ <u>200.00</u>
g)	_____	\$ <u>-</u>
	Total	\$ <u>2,813.11</u>

\* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Pegasus Engineering & Trading Pte Ltd" within 28 days.

Yours faithfully,

**S Sharon Ow**

Email: claims@pegasusengrg.com.sg



MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807  
Tel +65 6827 7888, Fax +65 6827 7800  
Co. Reg. No. 200412212G GST Reg. No. 20-041221G

## Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)  
(REPUBLIC OF SINGAPORE)  
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)  
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.Z.400  
Cars for Hire

COMMERCIAL VEHICLE - FLEET  
Comprehensive

Certificate No. A 29069766 MKF

Excess : SGD2,000

**1. Index Mark and Registration Number of Vehicle**

SLP7812B

**2. Name of Policyholder**

Grab Rentals Pte. Ltd.

**3. Effective Date of the Commencement of Insurance for the purposes of the Act**

01/02/2018

**4. Date of Expiry of Insurance**

31/01/2019

**5. Persons or Classes of Persons entitled to drive\***

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

**6. Limitations as to use\***

Use for the carriage of passengers or goods in connection with the Policyholder's business.

Use for social domestic and pleasure purposes.

The Policy does not cover

(1) Use for racing pace-making reliability trial or speed-testing.

(2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers

Chief Executive Officer

**Joy Irene (LKKAuto)**

---

**From:** Joy Irene (LKKAuto)  
**Sent:** Wednesday, 4 April 2018 5:56 PM  
**To:** 'Eileen, May Hwee Yap'  
**Cc:** Vivian Lau (LKKAuto); Admin A  
**Subject:** ACCIDENT INVOLVING SLM 8396U (LCRF) & SLP 7812B ON 27/03/2018(19:30) ALONG MOHAMAD SULTAN ROAD

04 April 2018

**LION CITY RENTALS PTE LTD**

Policy Holder

LKK : CC6/LCR18005855/Ujb3

Dear Sir/Madam,

**ACCIDENT INVOLVING SLM 8396U (LCRF) & SLP 7812B ON 27/03/2018(19:30) ALONG MOHAMAD SULTAN ROAD**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SLP 7812B against your insurance policy.

Based on the information on hand, we are of the opinion that we cannot be absolved from liability. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,  
Joy Irene | Case Handler  
LKK Auto Consultants Pte Ltd  
DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

## AUTHORIZATION TO ACT

TO: PEGASUS ENGINEERING & TRADING PTE LTD

FROM: OWNER OF VEHICLE NUMBER SLP7812B

ACCIDENT INVOLVING SLM83964

ALONG/AT Slip Road of Mohamed Sultan Road & Sirboon Street ON 27.03.2018

We hereby authorize you to act on our behalf in pursuance of our claim for all damages during the repair arising out of the above accident.

This letter serve as the 'AUTHORITY TO ACT'.

We also hereby authorize all agreed settlement payment be made in favour to PEGASUS ENGINEERING & TRADING PTE LTD.

Name : Grab Rentals Pte Ltd

Co Reg No : 2016172006

Address : 18 Sin Ming Lane #01-08 Midview City Singapore 573960

Contact : 6655 0005

Date : 03.05.2018

Signature



Owner

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, PEGASUS ENGINEERING & TRADING PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$2,144.46 (Repair Cost), S\$468.65 (Loss of Rental) -      (Disbursement) for vehicle no. SLP 7812B that was damaged pursuant to the accident which occurred on 27/03/2018 (date) along SLIP ROAD OF MOHAMMAD SULTAN RD TO SAIBOO STREET (location) involving vehicle no/s SLM 8396U. This is pursuant to the inspection conducted on 29/03/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner GRAB RENTALS PTE LTD ("the third party claimant") of vehicle no. SLP 7812B make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".


We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLP 7812B (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 17 (day) of MAY (month) 2018 (year)

  
Signed by appointed surveyor

  
Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Tax Invoice

<b>From :</b> PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216  Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	<b>Customer :</b> GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960  Attn : Tel : Fax :
--	--

Inv No : IV18/04-1080	Inv Date : 06/04/2018	Term : 30 DAYS
Vehicle No : SLP7812B	Chassis No : MHFB29F3802011992	
Model : VIOS		
Remarks : TP INSURER: AIG, TP VEHICLE NO: SLM8396U, DATE OF ACCIDENT: 27.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	TO PART BY PART REPAIR AS RECOMMENDED BY SURVEYOR	1	2,004.1700	2,004.17

Cheques should be made payable to PEGASUS ENGINEERING & TRADING PTE LTD

Sub Total	2,004.17
GST(7.00%)	140.29
<b>Total (SGD)</b>	<b>2,144.46</b>

PEGASUS ENGINEERING & TRADING PTE LTD

Alexander Lee



\_\_\_\_\_  
Authorised Signature



Our Ref: GR-ACC-2017-02

01 June 2017

Pagasus Engineering & Trading Pte Ltd  
No. 51 Defu Lane 10  
Singapore 539216

Mailing Address  
18 Sin Ming Lane,  
#01-08 Midview City,  
Singapore 573960  
Co. No. 201617200G

To whom it may concern,

Re: Vehicle Rental Rates for Loss of Rental Claims.

With regards to the above subject matter, we are pleased to inform you our Grab Rental rate for our various vehicles which are as follows:

S/No.	Make & Model	Daily Rental Rates (S\$)
01	Toyota Prius 1,798cc, 90kw, 120bhp, Automatic	\$ 79.95
02	Mazda 3 1.5 (A) Sedan	\$ 66.95
03	Nissan Qashqai 1.2L	\$78.95
04	Honda Vezel 1.5L	\$77.85
05	Honda Vezel 1.5L Hybrid	\$84.95
06	Toyota Vios 1.5L	\$66.95

Please note that the above stated rate is our daily rental rate to our drivers. For your necessary actions on third party accident claims on loss of rental.

Yours faithfully,

  
Tay Chee Wee  
Grab Rental Pte Ltd

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Apr 2018 <a href="#">Edit Reg</a>		29 Mar 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$2,004.17</b> <a href="#">Edit Estimates</a>	<b>S\$2,004.17</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		[Created by adjuster]							
Insured:	LCRF PTE LTD, Co. Reg. No.: 201604597K								
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Vehicle Reg. No.:	SLP7812B	Date of Loss:	27/03/2018 00:00 - :59 [9 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6538423457SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SLM8396U	Policy No. (Claimant):	A29069766MKF						
		Excess:							
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ng, Hai-Chuan] Hai-Chuan.Ng@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 10/04/2018]								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
• AIG_SG (02/04/2018): TP GIA REPORT									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SLP7812B (6538423457SG)  
[SLM8396U]**

TP

**GRAB RENTALS PTE LTD**

**Mar 27 2018 12:00AM**

**[LCRF PTE LTD]**

**Pegasus Engineering & Trading Pte Ltd**

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <span style="float: right;">View in Browser <input type="button" value="v"/></span>	
<b>Letters/Correspondences</b>										1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	<b>Third Party Express Settlement - Payment Breakdown</b>							Edit		
<b>Photos/Images</b>										3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	29/03/18 17:45	<b>Odometer Reading</b>							Load JPG	<input checked="" type="checkbox"/>	
2	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
3	29/03/18 17:45	<b>Chassis Number</b>							Load JPG	<input checked="" type="checkbox"/>	
4	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
5	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
6	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
7	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
8	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
9	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
10	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
11	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
12	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
13	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
14	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
15	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
16	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
17	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
18	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
19	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
20	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
21	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
22	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
23	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
24	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
25	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
26	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
27	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
28	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
29	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
30	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
31	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
32	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
33	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
34	29/03/18 17:45	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	29/03/18 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
36	29/03/18 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
37	29/03/18 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
38	29/03/18 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
39	29/03/18 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
40	29/03/18 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
41	29/03/18 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
42	29/03/18 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
43	29/03/18 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
44	29/03/18 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
45	29/03/18 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
46	29/03/18 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
47	29/03/18 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
48	29/03/18 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
49	29/03/18 17:45	General View	Load JPG	<input checked="" type="checkbox"/>
50	29/03/18 17:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	29/03/18 17:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	29/03/18 17:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	29/03/18 17:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/04/18 17:58	LETTER TO LCRF	Load PDF	
2	05/04/18 00:53	TP ESTIMATE - MARKED	Load PDF	
3	05/04/18 00:53	TP GIA REPORT	Load PDF	
4	28/05/18 11:04	WORKSHOP INVOICE	Load PDF	
5	28/05/18 11:04	AUTHORISATION TO ACT FORM	Load PDF	
6	28/05/18 11:04	Release Voucher	Load PDF	
7	28/05/18 11:04	RENTAL RATES	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	02/04/18 09:53	OI GIA REPORT	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SLM8396U (Insd veh)	Model:	TOYOTA VIOS 1.5 E (A)
	SLP7812B (TP veh)		
Date of Accident:	27/03/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$		<b>6,419.54</b>
Final Repair Cost	: \$		2,144.46
Loss of Use	: \$		_____ days at \$0.00 per day
Rental (if any)	: \$		468.65    7    days
LTA / GIA Search Fee	: \$		0.00
Others:	: \$		0.00
	: \$		
Final Settlement Sum	: \$		2,613.11
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO    (Kindly indicate below)			
A) For <b>Non GIA Registered Workshop:</b>		Agreed Liability _____ 100 _____ (%)	
B) For <b>GIA Registered Workshop:</b>		BOLA Applicable: Yes/ No    BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Pegasus Engineering & Trading Pte Ltd	: \$	2,613.11
2)		: \$	

\_\_\_\_\_  
JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

\_\_\_\_\_  
28 May  
2018

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/LCR18005885/UJA3Q2

**Date:** 28/05/2018

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:		
<b>Claimant Vehicle No :</b> SLP7812B	<b>Insured Vehicle No :</b> SLM8396U		
Date of Loss: 27/03/2018	Nature of Claim: TP	Claim No: 6538423457SG	

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLP7812B</b>		
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No:	2NRX159458
Reg. Date:	19/06/2017 (Man. Year: 2017)	Chassis No:	MHFB29F3802011992
Colour:	Silver	Odometer:	54983 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,679.57	814.17	2,865.40	77.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,190.00	1,130.00	48.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,999.57</b>	<b>2,004.17</b>	<b>3,995.40</b>	<b>66.59</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>419.97</b>	<b>140.29</b>	<b>279.68</b>	<b>66.60</b>
<b>Nett Amount (S\$)</b>	<b>6,419.54</b>	<b>2,144.46</b>	<b>4,275.08</b>	<b>66.59</b>
<b>+ Car Rental (7.0 x S\$66.95/day) (S\$)</b>		<b>468.65</b>		
		<b>2,613.11</b>		
		<b>Nett Liability (S\$)</b>		

#### INSPECTION

Date of Assignment:	29/03/2018	
Date Inspected:	29/03/2018 Inspected At:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10 Singapore 539216
Estimated Period of Repair:	3.0 days	

---

**Adjuster:** MARCUS CHUA

**Manager:** Joy Irene Bascao

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	504.90 FL	*504.90 FL
2	1		*REAR BUMPER REINFORCEMENT	Dented	135.00 FL	*135.00 FL
3	2		*REAR BUMPER SIDE RETAINER	Bent	100.00 FL	*100.00 FL
4	2		*REAR BUMPER SIDE HOLDER	Necessary	44.60 FL	*44.60 FL
5	8		*REAR BUMPER CLIPS	Necessary	34.40 FL	*34.40 FL
6	2		*REAR BUMPER REFLECTOR	Not Necessary	261.00 FL	*- FL
7	1		*REAR END PANEL	Repair	694.70 FL	*- FL
8	1		*REAR END PANEL INNER TRIM	Not Necessary	234.30 FL	*- FL
9	2		*REAR LAMP	Not Necessary	751.60 FL	*- FL
10	4		*REAR LAMP CLIP HOLDER	Not Necessary	38.00 FL	*- FL
11	1		*BOOTLID BADGE	Not Necessary	39.40 FL	*- FL
12	1		*BOOTLID VIOS BADGE	Not Necessary	44.10 FL	*- FL
13	1		*BOOTLID CENTRE LOGO BADGE	Not Necessary	59.80 FL	*- FL
14	1		*REAR EXHAUST BOX	Not Necessary	638.80 FL	*- FL
15	1		*REAR EXHAUST BOX HEAT SHIELD	Not Necessary	46.60 FL	*- FL
16	1		*REAR EXHAUST MOUNT	Not Necessary	78.90 FL	*- FL
17	1		*SET REAR BUMPER PARKING SENSOR	Shorted	900.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,606.10</b>	<b>1,018.90</b>
- List Item Discount on L Items 25.00/25.00% (\$\$)	926.53	204.73
<b>Total Parts (\$\$)</b>	<b>3,679.57</b>	<b>814.17</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	900.00	480.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	800.00	580.00
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	150.00	60.00
5	TO RUST- PROOFING OF THE AFFECTED AREAS	New	150.00	0.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	50.00	20.00
7	TO DROP REAR EXHAUST BOX AND RENEW THE SAME	New	150.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,320.00</b>	<b>1,190.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >